



Lead Service Line Inventory Template

Water System Name:	Mattoon	System ID Number:	IL0290250	Current Inventory Date:	04/15/2026	Previous Inventory Date:	04/15/2025	Has Funding Assistance Been Requested?:	YES
--------------------	---------	-------------------	-----------	-------------------------	------------	--------------------------	------------	---	-----

*Please enter information in the empty box next to each section	Water System Name		Mattoon			System ID Number:		IL0290250		Current Inventory Date:		4/15/2026						
*Please enter totals in the empty box next to each category	Total Service lines:		8012		Total Lead:	0		Total Non-Lead:	8012		Total Galvanized Requiring replacement:	1378		Total Unknown:	0		Website link to Material Inventory:	

Total Service Lines - Residential - 7021/Commercial - 991

[illegible]

100 AMBROSE	N/A	N	Y		2023	2023	Maintenance Records	U	C	P	NL	u	4/1/2020	Y		2/10/2023	C	N		
104 AMBROSE DR	N/A	Y	Y		2008	2008	Construction Records	U	C	P	NL	u		N/R	N			N		
105 AMBROSE DR	N/A	N	Y		1997	1990	Historical Records	U	C	P	NL	u		N/R	N			N		
108 AMBROSE DR	N/A	N	Y		1997	1997	Maintenance Records	U	C	P	NL	u		N/R	N			N		
109 AMBROSE DR	N/A	N	Y		1997	1997	CUSTOMER SURVEY	U	C	C	NL	u		N/R	N			N		
113 AMBROSE DR	N/A	N	Y		2004	2004	Maintenance Records	U	C	P	NL	u		N/R	N			N		
900 ANNIS	N/A	N	Y		1998	1998	CUSTOMER SURVEY	U	C	C	NL	u		N/R	N			N		
901 ANNIS	N/A	N	Y		1962	1962	Maintenance Records	U	C	C	NL	u		N/R	N			N		
904 ANNIS	N/A	N	Y		1961	1961	MAINTENANCE RECORDS	U	C	C	NL	u		N/R	N			N		
905 ANNIS	N/A	N	Y		1961	1961	CUSTOMER SURVEY	U	C	C	NL	u		N/R	N			N		
908 ANNIS	N/A	N	Y		1961	1961	Maintenance Records	U	C	C	NL	u		N/R	N			N		
909 ANNIS	N/A	N	Y		1960	1960	MAINTENANCE RECORDS/CUST	U	C	C	NL	u		N/R	N			N		
912 ANNIS	N/A	N	Y		1961	1961	Maintenance Records	U	C	P	NL	u		N/R	N			N		
913 ANNIS	N/A	N	Y		1960	1960	Maintenance Records	U	C	C	NL	u		N/R	N			N		
916 ANNIS	N/A	N	Y		1963	1963	MAINTENANCE RECORDS	U	C	C	NL	u		N/R	N			N		
917 ANNIS	N/A	N	Y		1967	1967	Maintenance Records	U	C	C	NL	u		N/R	N			N		
1000 ANNIS	N/A	N	Y		1962	1962	Maintenance Records	U	C	C	NL	u		N/R	N			N		
1001 ANNIS	N/A	N	Y		1963	1963	Maintenance Records	U	C	G	GRR	u		N/R	N			N		
1004 ANNIS	N/A	N	Y		1960	1960	Maintenance Records	U	C	C	NL	u		N/R	N			N		
1008 ANNIS	N/A	N	Y		1962	1962	Maintenance Records	U	C	P	NL	u		N/R	N			N		
1009 ANNIS	N/A	N	Y		1963	1963	Maintenance Records	U	C	P	NL	u		N/R	N			N		
1012 ANNIS	N/A	N	Y		1960	1960	Maintenance Records	U	C	P	NL	u		N/R	N			N		
1013 ANNIS	N/A	N	Y		1960	1960	Maintenance Records	U	C	P	NL	u		N/R	N			N		
1016 ANNIS	N/A	N	Y		1965	1965	Maintenance Records	U	C	P	NL	u		N/R	N			N		
1017 ANNIS	N/A	N	Y		1962	1962	Maintenance Records	U	C	P	NL	u		N/R	N			N		
1100 ANNIS	N/A	N	Y		1963	1963	Maintenance Records	U	C	C	NL	u		N/R	N			N		
1101 ANNIS	N/A	N	Y		1962	1962	Maintenance Records	U	C	P	NL	u		N/R	N			N		
1104 ANNIS	N/A	N	Y		1962	1962	Maintenance Records	U	C	C	NL	u		N/R	N			N		
1105 ANNIS	N/A	N	Y		1962	1962	Maintenance Records	U	C	P	NL	u		N/R	N			N		
1108 ANNIS	N/A	N	Y		1962	1962	Maintenance Records	U	C	P	NL	u		N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)								
1109 ANNIS	N/A	N	Y	1973	1973	Maintenance Records	U	C	C	NL	u	N/R	N		Leave blank if no Lead	N	
1112 ANNIS	N/A	N	Y	1963	1963	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1113 ANNIS	N/A	N	Y	1963	1963	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1116 ANNIS	N/A	N	Y	1961	1961	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1117 ANNIS	N/A	N	Y	1965	1965	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
1200 ANNIS	LC3T024	N	Y	1961	1961	Maintenance Records/CUST	U	C	G	GRR	u	N/R	N			N	
1201 ANNIS	N/A	N	Y	1963	1963	Maintenance Records	U	C	C	NL	u	N/R	N			N	
1206 ANNIS	N/A	N	Y	1963	1963	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1207 ANNIS	N/A	N	Y	1963	1963	Maintenance Records	U	C	C	NL	u	N/R	N			N	
1212 ANNIS	N/A	N	Y	1961	1961	Maintenance Records	U	C	C	NL	u	N/R	N			N	
1213 ANNIS	N/A	N	Y	1964	1964	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1220 ANNIS	N/A	N	Y	1964	1964	Maintenance Records	U	C	C	NL	u	N/R	N			N	
1221 ANNIS	N/A	N	Y	1963	1963	Maintenance Records	U	C	G	GRR	u	N/R	N			N	
1300 ANNIS	N/A	N	Y	2009	2009	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1301 ANNIS	LC3T001	N	Y	1964	1964	Maintenance Records	U	C	G	GRR	u	N/R	N			N	
1310 ANNIS	N/A	N	Y	1961	1961	Maintenance Records/CUST	U	C	P	NL	u	N/R	N			N	
1311 ANNIS	N/A	N	Y	1961	1961	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	
1320 ANNIS	N/A	N	Y	1961	1961	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1321 ANNIS	N/A	N	Y	1960	1960	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1400 ANNIS	N/A	N	Y	1963	1963	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1401 ANNIS	N/A	N	Y	1960	1960	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1408 ANNIS	N/A	N	Y	1961	1961	Maintenance Records	U	C	C	NL	u	N/R	N			N	
1411 ANNIS	N/A	N	Y	1962	1962	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1415 ANNIS	N/A	N	Y	1963	1963	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1416 ANNIS	N/A	N	Y	1962	1962	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1424 ANNIS	N/A	N	Y	1962	1962	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1425 ANNIS	N/A	N	Y	1964	1964	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	
1500 ANNIS	N/A	N	Y	1965	1965	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1501 ANNIS	N/A	N	Y	1968	1968	Maintenance Records	U	C	C	NL	u	N/R	N			N	
1508 ANNIS	N/A	N	Y	1965	1965	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N	
1509 ANNIS	N/A	N	Y	1965	1965	Maintenance Records/CUST	U	C	C	NL	u	N/R	N			N	
1516 ANNIS	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	
1517 ANNIS	N/A	N	Y	1966	1966	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1524 ANNIS	N/A	N	Y	1965	1965	Maintenance Records	U	C	C	NL	u	N/R	N			N	
1525 ANNIS	N/A	N	Y	2002	2002	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1600 ANNIS	N/A	N	Y	1966	1966	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N	
1601 ANNIS	N/A	N	Y	1966	1966	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1608 ANNIS	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
1616 ANNIS	N/A	N	Y	1965	1965	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1617 ANNIS	N/A	N	Y	1966	1966	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N	
1624 ANNIS	N/A	N	Y	1965	1965	Maintenance Records	U	C	C	NL	u	N/R	N			N	
1625 ANNIS	N/A	N	Y	1967	1967	Maintenance Records	U	C	P	NL	u	N/R	N			N	
31 APPLE CT	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N	
34 APPLE CT	N/A	N	Y	1973	1973	Maintenance Records	U	C	C	NL	u	N/R	N			N	
35 APPLE CT	N/A	N	Y	1973	1973	Maintenance Records	U	C	C	NL	u	N/R	N			N	

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
38 APPLE CT	N/A	N	Y	1998	1998	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
40 APPLE CT	DAYCARE002A	N	Y	1996	1996	Maintenance Records	U	C	P	NL	u	N/R	N			N		
43 APPLE CT	N/A	N	Y	1973	1973	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
44 APPLE CT	N/A	N	Y	1995	1995	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
45 APPLE CT	N/A	N	Y	1973	1973	Maintenance Records	U	C	P	NL	u	N/R	N			N		
46 APPLE CT	N/A	N	Y	1994	1994	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
47 APPLE CT	N/A	N	Y	1996	1996	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
48 APPLE CT	N/A	N	Y	1997	1997	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
49 APPLE CT	N/A	N	Y	1995	1995	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
50 APPLE CT	N/A	N	Y	1998	1998	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
51 APPLE CT	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
52 APPLE CT	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
53 APPLE CT	N/A	N	Y	1996	1996	Maintenance Records	U	C	C	NL	u	N/R	N			N		
55 APPLE CT	N/A	N	Y	1974	1974	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
56 APPLE CT	N/A	N	Y	1996	1996	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
57 APPLE CT	N/A	N	Y	1996	1996	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
58 APPLE CT	N/A	N	Y	1996	1996	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
59 APPLE CT	N/A	N	Y	1999	1999	VISUAL INSPECTION/CUSTO	U	C	P	NL	u	N/R	N			N		
61 APPLE CT	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
62 APPLE CT	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
65 APPLE CT	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
67 APPLE CT	N/A	N	Y	1974	1974	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1 APPLE DR A	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1 APPLE DR B	N/A	N	Y	1974	1974	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
3 APPLE DR	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
4 APPLE DR	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
5 APPLE DR	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
6 APPLE DR	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
7 APPLE DR	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
8 APPLE DR	N/A	N	Y	1972	1972	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
9 APPLE DR	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
10 APPLE DR	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
11 APPLE DR	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
12 APPLE DR	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
13 APPLE DR	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
14 APPLE DR	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
15 APPLE DR	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
16 APPLE DR	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
17 APPLE DR	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
18 APPLE DR	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
19 APPLE DR	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
21 APPLE DR	N/A	N	Y	1974	1974	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
22 APPLE DR	N/A	N	Y	1974	1974	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
23 APPLE DR	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
24 APPLE DR	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)								
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)									
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)															
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)				Leave blank if no Lead											
26 APPLE DR	N/A	N	Y	1973	1973	Maintenance Records	U	C	P	NL	u	N/R	N			N	
27 APPLE DR	N/A	N	Y	1973	1973	Maintenance Records	U	C	P	NL	u	N/R	N			N	
28 APPLE DR	N/A	N	Y	1974	1974	Maintenance Records	U	C	P	NL	u	N/R	N			N	
30 APPLE DR	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N	
31 APPLE DR	N/A	N	Y	1974	1974	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N	
32 APPLE DR	N/A	N	Y	1974	1974	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N	
34 APPLE DR	N/A	N	Y	1974	1974	Maintenance Records	U	C	P	NL	u	N/R	N			N	
36 APPLE DR	N/A	N	Y	1974	1974	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N	
65 APPLE DR	N/A	N	Y	1974	1974	Maintenance Records	U	C	P	NL	u	N/R	N			N	
68 APPLE DR	N/A	N	Y	1977	1977	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N	
69 APPLE DR	N/A	N	Y	1999	1999	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N	
70 APPLE DR	N/A	N	Y	2000	2000	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N	
71 APPLE DR	LC3T002	N	Y	1974	1974	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N	
72 APPLE DR	N/A	N	Y	1974	1974	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N	
86 APPLE DR	N/A	N	Y	1984	1984	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N	
99 APPLE DR	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N	
108 APPLE DR	N/A	N	Y	1997	1997	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N	
104 ARBOR LN	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N	
105 ARBOR LN	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N	
106 ARBOR LN	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N	
107 ARBOR LN	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N	
108 ARBOR LN	N/A	N	Y	1994	1994	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	
109 ARBOR LN	N/A	N	Y	1994	1994	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N	
110 ARBOR LN	N/A	N	Y	1994	1994	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N	
111 ARBOR LN	N/A	N	Y	1994	1994	Visual Inspection	U	C	P	NL	u	N/R	N			N	
112 ARBOR LN	N/A	N	Y	1994	1994	Visual Inspection	U	C	P	NL	u	N/R	N			N	
113 ARBOR LN	N/A	N	Y	1995	1995	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
114 ARBOR LN	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N	
115 ARBOR LN	N/A	N	Y	1995	1995	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
116 ARBOR LN	N/A	N	Y	1994	1994	Visual Inspection	U	C	P	NL	u	N/R	N			N	
117 ARBOR LN	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N	
118 ARBOR LN	N/A	N	Y	1994	1994	Visual Inspection	U	C	P	NL	u	N/R	N			N	
119 ARBOR LN	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N	
120 ARBOR LN	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N	
121 ARBOR LN	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N	
123 ARBOR LN	N/A	N	Y	1994	1994	Visual Inspection	U	C	P	NL	u	N/R	N			N	
124 ARBOR LN	N/A	N	Y	1994	1994	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
125 ARBOR LN	N/A	N	Y	2001	2001	Visual Inspection	U	C	P	NL	u	N/R	N			N	
131 ARBOR LN	N/A	N	Y	1998	1998	Visual Inspection	U	C	P	NL	u	N/R	N			N	
135 ARBOR LN	N/A	N	Y	1997	1997	Visual Inspection	U	C	P	NL	u	N/R	N			N	
201 ARBOR LN	N/A	N	Y	1997	1997	Visual Inspection	U	C	P	NL	u	N/R	N			N	
101 ARBORGATE	N/A	N	Y	2009	2009	Visual Inspection	U	C	P	NL	u	N/R	N			N	
104 ARBORGATE DR	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N	
105 ARBORGATE DR	N/A	N	Y	1997	1997	Visual Inspection	U	C	P	NL	u	N/R	N			N	
108 ARBORGATE DR	N/A	N	Y	1995	1995	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
109 ARBORGATE DR	N/A	N	Y	2006	2006	Visual Inspection	U	C	P	NL	u	N/R	N			N		
112 ARBORGATE DR	N/A	N	Y	1994	1994	Maintenance Records	U	C	P	NL	u	N/R	N			N		
113 ARBORGATE DR	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N		
116 ARBORGATE DR	N/A	N	Y	1994	1994	Visual Inspection	U	C	C	NL	u	N/R	N			N		
117 ARBORGATE DR	N/A	N	Y	1995	1995	Maintenance Records	U	C	P	NL	u	N/R	N			N		
120 ARBORGATE DR	N/A	N	Y	2005	2005	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
125 ARBORGATE DR	N/A	N	Y	1995	1995	Maintenance Records	U	C	P	NL	u	N/R	N			N		
900 ARTHUR	N/A	N	Y	1957	1957	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
19 AUGUSTA CT	N/A	N	Y	1976	1976	Maintenance Records	U	C	P	NL	u	N/R	N			N		
21 AUGUSTA CT	N/A	N	Y	1990	1990	Maintenance Records	U	C	C	NL	u	N/R	N			N		
23 AUGUSTA CT	N/A	N	Y	1975	1975	Maintenance Records	U	C	C	NL	u	N/R	N			N		
900 BELL	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
901 BELL	N/A	N	Y	1958	1958	Maintenance Records	U	C	P	NL	u	N/R	N			N		
904 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	P	NL	u	N/R	N			N		
905 BELL	N/A	N	Y	1960	1960	Maintenance Records	U	C	C	NL	u	N/R	N			N		
908 BELL	N/A	N	Y	1960	1960	Maintenance Records	U	C	P	NL	u	N/R	N			N		
909 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
912 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
913 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	P	NL	u	N/R	N			N		
916 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
917 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1000 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1001 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1004 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1005 BELL	N/A	N	Y	1959	1959	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1008 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1009 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1012 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1013 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1016 BELL	N/A	N	Y	1960	1960	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1017 BELL	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1100 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1101 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1104 BELL	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1105 BELL	N/A	N	Y	1959	1959	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1108 BELL	N/A	N	Y	1963	1963	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1109 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1112 BELL	N/A	N	Y	1960	1960	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1113 BELL	N/A	N	Y	1960	1960	Maintenance Records/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1116 BELL	N/A	N	Y	1966	1966	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1117 BELL	N/A	N	Y	1965	1965	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1200 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1201 BELL	N/A	N	Y	1959	1959	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1206 BELL	N/A	N	Y	1958	1958	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1207 BELL	N/A	N	Y	1959	1959	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Galvanized (G)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Plastic - PVC, HDPE, PEX (P)								
Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)			Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)	Plastic - PVC, HDPE, PEX (P)	Unknown (U)						Leave blank if no Lead				
1213 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1220 BELL	N/A	N	Y	1999	1999	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1221 BELL	N/A	N	Y	1957	1957	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1300 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1301 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1310 BELL	N/A	N	Y	1959	1959	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1311 BELL	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1320 BELL	N/A	N	Y	1959	1959	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1321 BELL	N/A	N	Y	1958	1958	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1400 BELL	DAYCARE007A	N	Y	1956	1956	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1401 BELL	N/A	N	Y	1958	1958	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1406 BELL	N/A	N	Y	1957	1957	Maintenance Records/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1407 BELL	N/A	N	Y	1957	1957	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1412 BELL	N/A	N	Y	1956	1956	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1413 BELL	N/A	N	Y	1956	1956	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1418 BELL	N/A	N	Y	1956	1956	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1419 BELL	N/A	N	Y	1957	1957	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1424 BELL	N/A	N	Y	1956	1956	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1425 BELL	N/A	N	Y	1956	1956	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1500 BELL	N/A	N	Y	1956	1956	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1501 BELL	N/A	N	Y	1957	1957	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1506 BELL	N/A	N	Y	1957	1957	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1507 BELL	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1512 BELL	N/A	N	Y	1956	1956	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1513 BELL	N/A	N	Y	1957	1957	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1518 BELL	N/A	N	Y	1957	1957	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1519 BELL	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1524 BELL	N/A	N	Y	1957	1957	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1525 BELL	N/A	N	Y	1958	1958	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1600 BELL	N/A	N	Y	1956	1956	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1601 BELL	N/A	N	Y	1957	1957	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1606 BELL	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1607 BELL	N/A	N	Y	1957	1957	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1612 BELL	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N		
1613 BELL	N/A	N	Y	1957	1957	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1618 BELL	N/A	N	Y	1956	1956	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1619 BELL	N/A	N	Y	1957	1957	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1624 BELL	N/A	N	Y	1956	1956	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1625 BELL	N/A	N	Y	1957	1957	Maintenance Records	U	C	P	NL	u	N/R	N			N		
4 BRIAN DR	N/A	N	Y	1969	1969	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
5 BRIAN DR	N/A	N	Y	1967	1967	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
6 BRIAN DR	N/A	N	Y	1967	1967	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
7 BRIAN DR	N/A	N	Y	1973	1973	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
8 BRIAN DR	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
417 BRIAR LN	N/A	N	Y	2009	2009	Maintenance Records	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
202 BRIAR LN	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
204 BRIAR LN	N/A	N	Y	1967	1967	Visual Inspection	U	C	C	NL	u	N/R	N			N		
205 BRIAR LN	N/A	N	Y	1965	1965	Visual Inspection	U	C	C	NL	u	N/R	N			N		
208 BRIAR LN	N/A	N	Y	1961	1961	Maintenance Records	U	C	C	NL	u	N/R	N			N		
209 BRIAR LN	N/A	N	Y	1966	1966	Visual Inspection	U	C	C	NL	u	N/R	N			N		
212 BRIAR LN	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
213 BRIAR LN	N/A	N	Y	1967	1967	Visual Inspection	U	C	C	NL	u	N/R	N			N		
215 BRIAR LN	N/A	N	Y	1969	1969	Visual Inspection	U	C	C	NL	u	N/R	N			N		
217 BRIAR LN	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	G	C	GRR	u	N/R	N			N		
221 BRIAR LN	N/A	N	Y	1961	1961	Visual Inspection	U	C	P	NL	u	N/R	N			N		
300 BRIAR LN	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N		
301 BRIAR LN	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
304 BRIAR LN	N/A	N	Y	1961	1961	Visual Inspection	U	C	P	NL	u	N/R	N			N		
305 BRIAR LN	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
308 BRIAR LN	N/A	N	Y	1961	1961	Maintenance Records	U	C	P	NL	u	N/R	N			N		
309 BRIAR LN	N/A	N	Y	1959	1959	Visual Inspection	U	C	C	NL	u	N/R	N			N		
312 BRIAR LN	N/A	N	Y	1961	1961	Visual Inspection	U	C	P	NL	u	N/R	N			N		
313 BRIAR LN	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
316 BRIAR LN	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N		
317 BRIAR LN	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N		
321 BRIAR LN	N/A	N	Y	1998	1998	Visual Inspection	U	C	C	NL	u	N/R	N			N		
400 BRIAR LN	N/A	N	Y	2001	2001	VISUAL INSPECTION/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
401 BRIAR LN	N/A	N	Y	1999	1999	Visual Inspection	U	C	C	NL	u	N/R	N			N		
404 BRIAR LN	N/A	N	Y	2005	2005	Maintenance Records	U	C	P	NL	u	N/R	N			N		
405 BRIAR LN	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N		
409 BRIAR LN	N/A	N	Y	1999	1999	Visual Inspection	U	C	P	NL	u	N/R	N			N		
412 BRIAR LN	N/A	N	Y	1995	1995	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
413 BRIAR LN	N/A	N	Y	2010	2010	Visual Inspection	U	C	P	NL	u	N/R	N			N		
417 BRIAR LN	N/A	N	Y	2009	2009	VISUAL INSPECTION/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
420 BRIAR LN	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N		
421 BRIAR LN	N/A	N	Y	1997	1997	Visual Inspection	U	C	P	NL	u	N/R	N			N		
422 BRIAR LN	N/A	N	Y	1996	1996	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
501 BRIAR LN	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N		
505 BRIAR LN	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N		
509 BRIAR LN	N/A	N	Y	2000	2000	Visual Inspection	U	C	P	NL	u	N/R	N			N		
513 BRIAR LN	N/A	N	Y	1999	1999	Visual Inspection	U	C	P	NL	u	N/R	N			N		
525 BRIAR LN	N/A	N	Y	1997	1997	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1500 BROADMOOR	N/A	N	Y	1995	1995	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1508 BROADMOOR	N/A	N	Y	1996	1996	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1516 BROADMOOR	N/A	N	Y	1998	1998	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1517 BROADMOOR	N/A	N	Y	1997	1997	CUSTOMER SURVEY/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1520 BROADMOOR	N/A	N	Y	1999	1999	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1521 BROADMOOR	N/A	N	Y	1996	1996	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1600 BROADMOOR	N/A	N	Y	2002	2002	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1601 BROADMOOR	N/A	N	Y	1999	1999	Maintenance Records	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
1604 BROADMOOR	N/A	N	Y	1996	1996	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1605 BROADMOOR	N/A	N	Y	2001	2001	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1608 BROADMOOR	N/A	N	Y	1999	1999	CUSTOMER SURVEY/VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
1609 BROADMOOR	N/A	N	Y	2018		Maintenance Records/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1612 BROADMOOR	N/A	N	Y	1996	1996	CUSTOMER SURVEY/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1616 BROADMOOR	N/A	N	Y	2000	2000	CUSTOMER SURVEY/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1620 BROADMOOR	N/A	N	Y	2004		Maintenance Records/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1621 BROADMOOR	N/A	N	Y	2012	2012	Maintenance Records/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1700 BROADMOOR	N/A	N	Y	2020	2020	Maintenance Records/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1701 BROADMOOR	N/A	N	Y	1998	1998	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1705 BROADMOOR	N/A	N	Y	2005	2005	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1709 BROADMOOR	N/A	N	Y	2003	2003	Maintenance Records/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1713 BROADMOOR	N/A	N	Y	1996		Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1721 BROADMOOR	N/A	N	Y	2005	2005	Maintenance Records	U	C	P	NL	u	N/R	N			N		
301 BROADWAY	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
305 BROADWAY	N/A	N	Y	1997	1997	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
313 BROADWAY	N/A	N	Y	1997	1997	Maintenance Records/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
317 BROADWAY	N/A	N	Y	1915	1915	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
321 BROADWAY	N/A	N	Y	1915	1915	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
401 BROADWAY	N/A	N	Y	1954	1954	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
405 BROADWAY	N/A	N	Y	1994	1994	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
409 BROADWAY	N/A	N	Y	1994	1994	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
413 BROADWAY	N/A	N	Y	1920	1920	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
417 BROADWAY	N/A	N	Y	1908	1908	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
421 BROADWAY	N/A	N	Y	1938	1938	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
503 BROADWAY LAUN	N/A	N	Y	1970	1970	Maintenance Records/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
612 BROADWAY	N/A	N	Y	1924	1924	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
709 BROADWAY	N/A	N	Y	1912	1912	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
713 BROADWAY	N/A	N	Y	1991	1991	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
717 BROADWAY	N/A	N	Y	1900	1900	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
800 BROADWAY	N/A	N	Y	1951	1951	Maintenance Records/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
808 BROADWAY	N/A	N	Y	1913	1913	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
812 BROADWAY	N/A	N	Y	1921	1921	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
905 BROADWAY	N/A	N	Y	1989	1989	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
912 BROADWAY	N/A	N	Y	1911	1911	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
913 BROADWAY	N/A	N	Y	1913	1913	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
916 BROADWAY	N/A	N	Y	1924	1924	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1001 BROADWAY	N/A	N	Y	1996	1996	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1005 BROADWAY	N/A	N	Y	1909	1909	Maintenance Records/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1009 BROADWAY	N/A	N	Y	1903	1903	CUSTOMER SURVEY	U	G	C	GRR	u	N/R	N			N		
1013 BROADWAY	N/A	N	Y	1941	1941	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1111 BROADWAY	N/A	CHURCH	Y	1985	1985	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1120 BROADWAY	N/A	N	Y	1961	1961	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1512 BROADWAY	N/A	N	Y	1909	1909	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1522 BROADWAY	N/A	N	Y	1895	1895	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
1819 BROADWAY	N/A	N	Y	1890	1890	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1821 BROADWAY	N/A	N	Y	1890	1890	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2133 BROADWAY	N/A	N	Y	1923	1923	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2201 BROADWAY	N/A	N	Y	1947	1947	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2205 BROADWAY	N/A	N	Y	1929	1929	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2209 BROADWAY	N/A	N	Y	1945	1945	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
2221 BROADWAY	N/A	N	Y	1897	1897	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2225 BROADWAY	N/A	N	Y	1933	1933	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2401 BROADWAY	N/A	N	Y	1923	1923	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2405 BROADWAY	N/A	N	Y	1995	1995	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2405 BROADWAY 1/2	N/A	N	Y	1995	1995	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2408 BROADWAY	N/A	N	Y	1995	1995	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2409 BROADWAY	N/A	N	Y	1946	1946	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2413 BROADWAY	N/A	N	Y	1948	1948	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2417 BROADWAY	N/A	N	Y	1997	1997	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2421 BROADWAY	N/A	N	Y	1945	1945	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2429 BROADWAY	N/A	N	Y	1931	1931	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2513 BROADWAY	N/A	N	Y	1957	1957	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2517 BROADWAY	N/A	N	Y	1963	1963	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2521 BROADWAY	N/A	N	Y	1997	1997	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2525 BROADWAY	N/A	N	Y	1997	1997	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
2529 BROADWAY	N/A	N	Y	2016	2016	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
3201 BROADWAY	N/A	N	Y	1939	1939	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
3209 BROADWAY	N/A	N	Y	1916	1916	CUSTOMER SURVEY	U	G	C	GRR	u	N/R	N			N		
3213 BROADWAY	N/A	N	Y	1938	1938	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
3225 BROADWAY	N/A	N	Y	1900	1900	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3229 BROADWAY	N/A	N	Y	1911	1911	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3233 BROADWAY	N/A	N	Y	1901	1901	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
701 BROADWAY APT 1	N/A	N	Y	1979	1979	Maintenance Records	U	C	P	NL	u	N/R	N			N		
503 BROADWAY APT 101	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
503 BROADWAY APT 102	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
503 BROADWAY APT 103	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
503 BROADWAY APT 104	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
701 BROADWAY APT 2	N/A	N	Y	1980	1980	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
503 BROADWAY APT 201	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
503 BROADWAY APT 202	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
503 BROADWAY APT 203	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
503 BROADWAY APT 204	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
701 BROADWAY APT 3	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
503 BROADWAY APT 301	N/A	N	Y	1970	1970	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
503 BROADWAY APT 302	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
503 BROADWAY APT 303	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
503 BROADWAY APT 304	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
701 BROADWAY APT 4	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1 BROWN CT	N/A	N	Y	2009	2009	maintenance Records	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
2 BROWN CT	N/A	N	Y	1942	1942	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
3 BROWN CT	N/A	N	Y	1942	1942	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
4 BROWN CT	N/A	N	Y	1942	1942	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
5 BROWN CT	N/A	N	Y	1942	1942	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
6 BROWN CT	N/A	N	Y	1942	1942	Visual Inspection	U	C	C	NL	u	N/R	N			N		
7 BROWN CT	N/A	N	Y	1942	1942	Visual Inspection	U	C	C	NL	u	N/R	N			N		
8 BROWN CT	LC3T003	N	Y	1942	1942	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
13 CAMBRIDGE	N/A	N	Y	2000	2000	Maintenance Records	U	c	P	NL	u	N/R	N			N		
14 CAMBRIDGE	N/A	N	Y	1999	1999	VISUAL INSPECTION	U	C	p	NL	u	N/R	N			N		
15 CAMBRIDGE	N/A	N	Y	1999	1999	Maintenance Records	U	C	P	NL	u	N/R	N			N		
16 CAMBRIDGE	N/A	N	Y	1999	1999	CUSTOMER SURVEY	U	C	p	NL	u	N/R	N			N		
17 CAMBRIDGE	N/A	N	Y	2002	2002	Maintenance Records	U	C	P	NL	u	N/R	N			N		
18 CAMBRIDGE	N/A	N	Y	2004	2004	Maintenance Records	U	c	p	NL	u	N/R	N			N		
19 CAMBRIDGE	N/A	N	Y	2001	2001	CUSTOMER SURVEY	U	C	c	NL	u	N/R	N			N		
24 CAMBRIDGE	N/A	N	Y	2002	2002	Maintenance Records	U	C	P	NL	u	N/R	N			N		
25 CAMBRIDGE	N/A	N	Y	2018	2018	CUSTOMER SURVEY	U	c	C	NL	u	N/R	N			N		
26 CAMBRIDGE	N/A	N	Y	1998	1998	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2700 CEDAR	N/A	N	Y	1946	1946	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
2704 CEDAR	N/A	N	Y	1941	1941	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2708 CEDAR	N/A	N	Y	1941	1941	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2712 CEDAR	N/A	N	Y	1938	1938	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2716 CEDAR	N/A	N	Y	1938	1938	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2720 CEDAR	N/A	N	Y	1930	1930	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2800 CEDAR	N/A	N	Y	1941	1941	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2812 CEDAR	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2817 CEDAR	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2820 CEDAR	N/A	N	Y	1949	1949	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2821 CEDAR	N/A	N	Y	1911	1911	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2901 CEDAR	N/A	N	Y	1895	1895	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2904 CEDAR	N/A	N	Y	1942	1942	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2905 CEDAR	N/A	N	Y	1872	1872	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2908 CEDAR	N/A	N	Y	1949	1949	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2912 CEDAR	LC3T004	N	Y	1954	1956	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
2913 CEDAR	N/A	N	Y	1987	1987	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2917 CEDAR	N/A	N	Y	1987	1987	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2921 CEDAR	N/A	N	Y	1922	1922	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3000 CEDAR	N/A	N	Y	2018	2018	Visual Inspection	U	P	G	GRR	u	N/R	N			N		
3001 CEDAR	N/A	N	Y	1947	1947	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3004 CEDAR	N/A	N	Y	1925	1925	Visual Inspection	U	P	G	GRR	u	N/R	N			N		
3005 CEDAR	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3008 CEDAR	N/A	N	Y	1933	1933	Visual Inspection	U	P	P	NL	u	N/R	N			N		
3009 CEDAR	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3012 CEDAR	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3013 CEDAR	N/A	N	Y	1975	1975	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3016 CEDAR	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Lead (L)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
3017 CEDAR	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3020 CEDAR	N/A	N	Y	1952	1952	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3100 CEDAR	N/A	N	Y	1983	1983	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3104 CEDAR	N/A	N	Y	1964	1964	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3108 CEDAR	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1004 CHAMPAIGN	N/A	N	Y	1939	1939	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1008 CHAMPAIGN	N/A	N	Y	1941	1941	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1009 CHAMPAIGN	N/A	N	Y	1953	1953	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1012 CHAMPAIGN	N/A	N	Y	1917	1917	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1016 CHAMPAIGN	N/A	N	Y	1886	1886	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1017 CHAMPAIGN	N/A	N	Y	1940	1940	Maintenance Records	U	P	P	NL	u	N/R	N			N		
1020 CHAMPAIGN	N/A	N	Y	1994	1994	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1021 CHAMPAIGN	N/A	N	Y	1954	1954	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1100 CHAMPAIGN	N/A	N	Y	1923	1923	Maintenance Records/CUST	U	C	P	NL	u	N/R	N			N		
1105 CHAMPAIGN	N/A	N	Y	1918	1918	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1108 CHAMPAIGN	N/A	N	Y	1961	1961	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1109 CHAMPAIGN	N/A	N	Y	1939	1939	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1112 CHAMPAIGN	N/A	N	Y	1939	1939	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1113 CHAMPAIGN	N/A	N	Y	2008	2008	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1116 CHAMPAIGN	N/A	N	Y	2016	2016	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1117 CHAMPAIGN	N/A	N	Y	1901	1901	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1120 CHAMPAIGN	N/A	N	Y	1939	1939	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1121 CHAMPAIGN	LC3T005	N	Y	1939	1939	Maintenance Records/CUST	U	C	G	GRR	u	N/R	N			N		
1201 CHAMPAIGN	N/A	N	Y	1903	1903	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1209 CHAMPAIGN	N/A	N	Y	1903	1903	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1213 CHAMPAIGN	N/A	N	Y	1903	1903	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1217 CHAMPAIGN	LC3T025	N	Y	1903	1903	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
1221 CHAMPAIGN	N/A	N	Y	1938	1938	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1300 CHAMPAIGN	N/A	N	Y	1938	1938	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1301 CHAMPAIGN	N/A	N	Y	1959	1959	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1304 CHAMPAIGN	N/A	N	Y	1946	1946	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1305 CHAMPAIGN	N/A	N	Y	1938	1938	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
1308 CHAMPAIGN	N/A	N	Y	1940	1940	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1309 CHAMPAIGN	N/A	N	Y	1948	1948	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1312 CHAMPAIGN	N/A	N	Y	1939	1939	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1313 CHAMPAIGN	N/A	N	Y	1986	1986	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1313 CHAMPAIGN 1/2	N/A	N	Y	1986	1986	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1316 CHAMPAIGN	N/A	N	Y	2002	2002	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1317 CHAMPAIGN	N/A	N	Y	1908	1908	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1321 CHAMPAIGN	N/A	N	Y	1972	1972	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1321 CHAMPAIGN 1/2	N/A	N	Y	1972	1972	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1400 CHAMPAIGN	N/A	N	Y	1953	1953	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1401 CHAMPAIGN	N/A	N	Y	1856	1856	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1404 CHAMPAIGN	N/A	N	Y	1940	1940	Viusal Inspection	U	C	G	GRR	u	N/R	N			N		
1405 CHAMPAIGN	N/A	N	Y	1946	1946	Viusal Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
1408 CHAMPAIGN	N/A	N	Y	1953	1953	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N		Leave blank if no Lead	N		
1409 CHAMPAIGN	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1412 CHAMPAIGN	N/A	N	Y	1911	1911	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1502 CHAMPAIGN	N/A	N	Y	1905	1905	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1504 CHAMPAIGN	N/A	N	Y	1896	1896	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
1508 CHAMPAIGN	N/A	N	Y	1890	1890	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
1509 CHAMPAIGN	N/A	N	Y	1995	1995	Maintenance Records/VISU	U	P	P	NL	u	N/R	N			N		
1512 CHAMPAIGN	N/A	N	Y	1972	1972	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1513 CHAMPAIGN	N/A	N	Y	1976	1976	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1516 CHAMPAIGN	N/A	N	Y	1900	1900	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1517 CHAMPAIGN	N/A	N	Y	1895	1895	Maintenance Records	U	P	C	NL	u	N/R	N			N		
1604 CHAMPAIGN 2	N/A	N	Y	1915	1915	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
1608 CHAMPAIGN	N/A	N	Y	1925	1925	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1620 CHAMPAIGN	N/A	N	Y	1944	1944	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1700 CHAMPAIGN	N/A	N	Y	1920	1920	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1712 CHAMPAIGN	N/A	N	Y	1914	1914	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1716 CHAMPAIGN	N/A	N	Y	1914	1914	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1805 CHAMPAIGN	N/A	N	Y	1928	1928	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1812 CHAMPAIGN	N/A	N	Y	1998	1998	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1908 CHAMPAIGN	LC3T042	N	Y	1937	1937	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
1916 CHAMPAIGN	N/A	N	Y	1939	1939	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N		
1917 CHAMPAIGN	N/A	N	Y	2006	2006	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2008 CHAMPAIGN	N/A	N	Y	2022	2022	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2112 CHAMPAIGN	N/A	N	Y	1929	1929	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2205 CHAMPAIGN	N/A	N	Y	1989	1989	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2209 CHAMPAIGN	N/A	N	Y	1912	1912	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2212 CHAMPAIGN	N/A	N	Y	1920	1920	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2213 CHAMPAIGN	N/A	N	Y	1931	1931	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2217 CHAMPAIGN	N/A	N	Y	1920	1920	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2221 CHAMPAIGN	N/A	N	Y	1955	1955	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
2301 CHAMPAIGN	N/A	N	Y	1918	1918	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N		
2308 CHAMPAIGN	N/A	N	Y	1946	1946	VISUAL INSPECTION	U	C	C/P	NL	u	N/R	N			N		
2309 CHAMPAIGN	N/A	N	Y	1935	1935	CUSTOMER SURVEY	U	G	C	GRR	u	N/R	N			N		
2312 CHAMPAIGN	N/A	N	Y	1991	1991	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2313 CHAMPAIGN	N/A	N	Y	1928	1928	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2316 CHAMPAIGN 1/2	N/A	N	Y	1991	1991	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2320 CHAMPAIGN	N/A	N	Y	1923	1923	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
2404 CHAMPAIGN	N/A	N	Y	1937	1937	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2408 CHAMPAIGN	N/A	N	Y	1932	1932	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2410 CHAMPAIGN	N/A	N	Y	1920	1920	Maintenance Records/VISU	U	P	P	NL	u	N/R	N			N		
2412 CHAMPAIGN	N/A	N	Y	1993	1993	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N		
2420 CHAMPAIGN	N/A	N	Y	1930	1930	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2504 CHAMPAIGN	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2505 CHAMPAIGN	N/A	N	Y	1951	1951	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2508 CHAMPAIGN	N/A	N	Y	1932	1932	Maintenance Records	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
2509 CHAMPAIGN	N/A	N	Y	1923	1923	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2512 CHAMPAIGN	N/A	N	Y	1940	1940	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2513 CHAMPAIGN	N/A	N	Y	1991	1991	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2516 CHAMPAIGN	N/A	N	Y	1947		Maintenance Records	U	C	P	NL	u	N/R	N			N		
2517 CHAMPAIGN	N/A	N	Y	1922	1922	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2520 CHAMPAIGN	N/A	N	Y	1923	1923	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
2521 CHAMPAIGN	N/A	N	Y	1977		Maintenance Records	U	C	G	GRR	u	N/R	N			N		
2600 CHAMPAIGN	N/A	N	Y	1921	1921	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2601 CHAMPAIGN	N/A	N	Y	1948	1948	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2608 CHAMPAIGN	N/A	N	Y	1927		Maintenance Records	U	G	P	GRR	u	N/R	N			N		
2611 CHAMPAIGN	N/A	N	Y	1995	1995	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2616 CHAMPAIGN	N/A	N	Y	1941	1941	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
2617 CHAMPAIGN	N/A	N	Y	1910		CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2620 CHAMPAIGN	N/A	N	Y	1939	1939	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2621 CHAMPAIGN	N/A	N	Y	1999	1999	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2700 CHAMPAIGN	N/A	N	Y	1913	1913	Maintenance Records	U	P	P	NL	u	N/R	N			N		
2704 CHAMPAIGN	N/A	N	Y	1950	1950	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2705 CHAMPAIGN	N/A	N	Y	1916	1916	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
2708 CHAMPAIGN	N/A	N	Y	1913	1913	Maintenance Records/VISU	U	G	P	GRR	u	N/R	N			N		
2709 CHAMPAIGN	N/A	N	Y	1914	1914	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2712 CHAMPAIGN	N/A	N	Y	1939	1939	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2713 CHAMPAIGN	N/A	N	Y	2001	2001	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2716 CHAMPAIGN	N/A	N	Y	1953	1953	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2720 CHAMPAIGN	N/A	N	Y	1935	1935	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2721 CHAMPAIGN	LC3T060	N	Y	1935	2016	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
2800 CHAMPAIGN	N/A	N	Y	1941	1941	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
2801 CHAMPAIGN	N/A	N	Y	1934	1934	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2804 CHAMPAIGN	N/A	N	Y	1901	1901	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2805 CHAMPAIGN	N/A	N	Y	1923	1923	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2808 CHAMPAIGN	N/A	N	Y	1945	1945	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
2809 CHAMPAIGN	N/A	N	Y	1994	1994	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2812 CHAMPAIGN	N/A	N	Y	1995	1995	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2813 CHAMPAIGN	N/A	N	Y	1923	1923	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
2816 CHAMPAIGN	N/A	N	Y	1995	1995	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2817 CHAMPAIGN	N/A	N	Y	1929	1929	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2820 CHAMPAIGN	N/A	N	Y	1924	1988	Maintenance Records/CUST	U	C	P	NL	u	N/R	N			N		
2821 CHAMPAIGN	N/A	N	Y	1923	1923	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
2901 CHAMPAIGN	N/A	N	Y	1924	1924	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
2905 CHAMPAIGN	N/A	N	Y	1921	1921	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2908 CHAMPAIGN	N/A	N	Y	1923	1923	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2909 CHAMPAIGN	N/A	N	Y	1924	1924	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N		
2913 CHAMPAIGN	N/A	N	Y	1929	1929	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2916 CHAMPAIGN	N/A	N	Y	1924	1924	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
2917 CHAMPAIGN	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2920 CHAMPAIGN	N/A	N	Y	1935	1935	Maintenance Records	U	G	C	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)			Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)			Plastic - PVC, HDPE, PEX (P)				Leave blank if no Lead				
2921 CHAMPAIGN	N/A	N	Y	1928	1928	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3000 CHAMPAIGN	N/A	N	Y	1940	1940	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3001 CHAMPAIGN	N/A	N	Y	1939	1939	Maintenance Records	U	C	P	NL	u	N/R	N			N		
3005 CHAMPAIGN	N/A	N	Y	1999	1999	Maintenance Records	U	C	P	NL	u	N/R	N			N		
3009 CHAMPAIGN	N/A	N	Y	1940	19340	Maintenance Records	U	C	P	NL	u	N/R	N			N		
3012 CHAMPAIGN	N/A	N	Y	1946	1946	Maintenance Records	U	C	P	NL	u	N/R	N			N		
3013 CHAMPAIGN	N/A	N	Y	1940	1940	Maintenance Records	U	P	G	GRR	u	N/R	N			N		
3016 CHAMPAIGN	LC3T006	N	Y	1926	1926	CUSTOMER SURVEY	U	G	G/P	GRR	u	N/R	N			N		
3017 CHAMPAIGN	N/A	N	Y	1940	1940	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
3020 CHAMPAIGN	N/A	N	Y	1927	1927	Maintenance Records	U	P	P	NL	u	N/R	N			N		
3021 CHAMPAIGN	N/A	N	Y	1948	1948	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
3100 CHAMPAIGN	N/A	N	Y	1954	1954	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
3101 CHAMPAIGN	N/A	N	Y	2008	2008	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
3104 CHAMPAIGN	N/A	N	Y	1952	1952	Maintenance Records	U	C	P	NL	u	N/R	N			N		
3105 CHAMPAIGN	N/A	N	Y	2015	2015	Maintenance Records/CUST	U	C	G	GRR	u	N/R	N			N		
3108 CHAMPAIGN	N/A	N	Y	1923	1923	Maintenance Records/CUST	U	G	G	GRR	u	N/R	N			N		
3109 CHAMPAIGN	N/A	N	Y	1987	1987	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
3112 CHAMPAIGN	N/A	N	Y	1927	1983	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
3113 CHAMPAIGN	N/A	N	Y	1987	1987	Maintenance Records	U	C	P	NL	u	N/R	N			N		
3117 CHAMPAIGN	N/A	N	Y	1986	1986	Maintenance Records	U	C	P	NL	u	N/R	N			N		
3120 CHAMPAIGN	N/A	N	Y	1991	1991	Maintenance Records	U	C	P	NL	u	N/R	N			N		
3121 CHAMPAIGN	N/A	N	Y	1989	1989	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3200 CHAMPAIGN	N/A	N	Y	1965	1965	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3201 CHAMPAIGN	N/A	N	Y	1928	1928	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
3204 CHAMPAIGN	N/A	N	Y	1962	1962	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3205 CHAMPAIGN	N/A	N	Y	1927	1927	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
3208 CHAMPAIGN	N/A	N	Y	1942	1942	CUSTOMER SURVEY	U	C	p	NL	u	N/R	N			N		
3209 CHAMPAIGN	N/A	N	Y	1925	1925	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
3212 CHAMPAIGN	N/A	N	Y	1927	1927	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3213 CHAMPAIGN	N/A	N	Y	1927	1927	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3216 CHAMPAIGN	N/A	N	Y	1946	1946	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3217 CHAMPAIGN	N/A	N	Y	1926	1926	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
3220 CHAMPAIGN	N/A	N	Y	1925	1925	Maintenance Records	U	C	P	NL	u	N/R	N			N		
3221 CHAMPAIGN	N/A	N	Y	1925	1925	Maintenance Records	U	P	P	NL	u	N/R	N			N		
3224 CHAMPAIGN	N/A	N	Y	1925	1925	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3225 CHAMPAIGN	N/A	N	Y	1916	1916	Maintenance Records	U	C	P	NL	u	N/R	N			N		
3228 CHAMPAIGN	N/A	N	Y	1991	1991	Maintenance Records	U	C	P	NL	u	N/R	N			N		
3229 CHAMPAIGN	N/A	N	Y	1938	1938	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3232 CHAMPAIGN	N/A	N	Y	1906	1906	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3233 CHAMPAIGN	N/A	N	Y	1925	1925	Maintenance Records	U	C	P	NL	u	N/R	N			N		
3300 CHAMPAIGN	N/A	N	Y	1922	1922	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3301 CHAMPAIGN	N/A	N	Y	1925	1925	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3304 CHAMPAIGN	N/A	N	Y	1940	1940	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3305 CHAMPAIGN	N/A	N	Y	2008	2008	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3308 CHAMPAIGN	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
3309 CHAMPAIGN	N/A	N	Y	1943	1943	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3312 CHAMPAIGN	N/A	N	Y	1924	1924	Visual Inspection	U	P	P	NL	u	N/R	N			N		
3313 CHAMPAIGN	N/A	N	Y	1927	1927	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		
3316 CHAMPAIGN	N/A	N	Y	1926	1926	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
3317 CHAMPAIGN	N/A	N	Y	1927	1927	Visual Inspection	U	P	P	NL	u	N/R	N			N		
3320 CHAMPAIGN	N/A	N	Y	1927	1927	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3321 CHAMPAIGN	N/A	N	Y	1926	1926	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3324 CHAMPAIGN	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3325 CHAMPAIGN	N/A	N	Y	1928	1928	Visual Inspection/CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
3328 CHAMPAIGN	N/A	N	Y	1906	1906	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3332 CHAMPAIGN	N/A	N	Y	1940	1940	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3333 CHAMPAIGN	N/A	N	Y	1900	1900	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3336 CHAMPAIGN	N/A	N	Y	1928	1928	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3337 CHAMPAIGN	N/A	N	Y	1927	1927	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3340 CHAMPAIGN	N/A	N	Y	1940	1940	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3341 CHAMPAIGN	N/A	N	Y	1939	1939	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3344 CHAMPAIGN	N/A	N	Y	1926	1926	Visual Inspection	U	P	G	GRR	u	N/R	N			N		
3347 CHAMPAIGN	N/A	N	Y	1929	1929	Maintenance Records/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
78 CHARLESTON	N/A	N	Y	1923	1923	Maintenance Records	U	C	C	NL	u	N/R	N			N		
101 CHARLESTON	N/A	N	Y	1945	1945	Visual Inspection	U	c	c	NL	u	N/R	N			N		
107 CHARLESTON	N/A	N	Y	1957	1957	Maintenance Records	U	C	P	NL	u	N/R	N			N		
112 CHARLESTON	N/A	N	Y	1923	1923	Visual Inspection	U	o	o	NL	u	N/R	N			N		
121 CHARLESTON	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
201 CHARLESTON	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N		
205 CHARLESTON	N/A	N	Y	1924	1924	Visual Inspection	U	C	C	NL	u	N/R	N			N		
221 CHARLESTON	N/A	N	Y	1956	1956	Maintenance Records	U	C	P	NL	u	N/R	N			N		
300 CHARLESTON	N/A	N	Y	1965	1965	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
301 CHARLESTON	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
312 CHARLESTON	N/A	N	Y	1999	1999	Maintenance Records	U	C	C	NL	u	N/R	N			N		
315 CHARLESTON	N/A	N	Y	1956	1956	Maintenance Records	U	C	P	NL	u	N/R	N			N		
320 CHARLESTON	N/A	N	Y	1999	1999	Maintenance Records	U	C	C	NL	u	N/R	N			N		
321 CHARLESTON	N/A	N	Y	1999	1999	Maintenance Records	U	C	C	NL	u	N/R	N			N		
400 CHARLESTON	N/A	N	Y	1999	1999	Maintenance Records	U	C	C	NL	u	N/R	N			N		
401 CHARLESTON	N/A	N	Y	1999	1999	Maintenance Records	U	P	P	NL	u	N/R	N			N		
409 CHARLESTON	N/A	N	Y	1924	1924	Visual Inspection	U	C	C	NL	u	N/R	N			N		
412 CHARLESTON	N/A	N	Y	1954	1956	Maintenance Records	U	G	C	GRR	u	N/R	N			N		
413 CHARLESTON	N/A	N	Y	1954	1956	Visual Inspection	U	c	c	NL	u	N/R	N			N		
420 CHARLESTON	N/A	N	Y	1983	1983	Maintenance Records	U	C	P	NL	u	N/R	N			N		
421 CHARLESTON	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
501 CHARLESTON	N/A	N	Y	1957	1957	Maintenance Records	U	C	C	NL	u	N/R	N			N		
504 CHARLESTON	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
512 CHARLESTON	N/A	N	Y	1942	1942	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
617 CHARLESTON	N/A	N	Y	2002	2002	Maintenance Records	U	C	P	NL	u	N/R	N			N		
908 CHARLESTON	N/A	N	Y	1900	1900	Visual Inspection	U	P	P	NL	u	N/R	N			N		
1012 CHARLESTON	N/A	N	Y	2009	2009	Visual Inspection	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
1112 CHARLESTON	N/A	N	Y	2007	2007	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1209 CHARLESTON	N/A	N	Y	1984	1984	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1613 CHARLESTON	N/A	N	Y	1928	1928	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2120 CHARLESTON	N/A	N	Y	1922	1922	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2121 CHARLESTON	N/A	N	Y	1922	1922	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2122 CHARLESTON	LC3T042	N	Y	1938	1938	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2200 CHARLESTON	N/A	N	Y	1912	1912	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2200 CHARLESTON 1/2	N/A	N	Y	1921	1921	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2202 CHARLESTON	N/A	N	Y	1923	1923	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2204 CHARLESTON	N/A	N	Y	1885	1885	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2212 CHARLESTON	N/A	N	Y	1907	1907	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2213 CHARLESTON	N/A	N	Y	1945	1945	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
2216 CHARLESTON	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2217 CHARLESTON	N/A	N	Y	1927	1927	CUSTOMER SURVEY	U	C	C/G	GRR	u	N/R	N			N		
2228 CHARLESTON	N/A	N	Y	1911	1911	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2300 CHARLESTON	N/A	N	Y	1938	1938	Visual Inspection/CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
2301 CHARLESTON	N/A	N	Y	1907	1907	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2304 CHARLESTON	N/A	N	Y	1950	1950	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2306 CHARLESTON	N/A	N	Y	1978	1978	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2308 CHARLESTON	N/A	N	Y	2010	2010	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2316 CHARLESTON	N/A	N	Y	1968	1968	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2317 CHARLESTON	N/A	N	Y	1900	1900	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
2318 CHARLESTON	N/A	N	Y	1949	1949	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2400 CHARLESTON	N/A	N	Y	1916	1916	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2404 CHARLESTON	N/A	N	Y	1916	1916	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2408 CHARLESTON	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2412 CHARLESTON	N/A	N	Y	1924	1924	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2414 CHARLESTON	N/A	N	Y	1923	1923	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2417 CHARLESTON	N/A	N	Y	1902	1902	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2421 CHARLESTON	N/A	N	Y	1998	1998	Visual Inspection	U	C	G	NL	u	N/R	N			N		
2500 CHARLESTON	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2501 CHARLESTON	N/A	N	Y	1939	1939	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2504 CHARLESTON	N/A	N	Y	1947	1947	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2505 CHARLESTON	N/A	N	Y	1913	1913	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2508 CHARLESTON	N/A	N	Y	1995	1995	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2512 CHARLESTON	N/A	N	Y	1949	1949	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2514 CHARLESTON	N/A	N	Y	1937	1937	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2516 CHARLESTON	N/A	N	Y	1925	1925	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2522 CHARLESTON	N/A	N	Y	1911	1911	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2600 CHARLESTON	N/A	N	Y	1944	1944	Maintenance Records	U	P	C	NL	u	N/R	N			N		
2604 CHARLESTON	N/A	N	Y	1942	1942	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2606 CHARLESTON	N/A	N	Y	1923	1923	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2608 CHARLESTON	N/A	N	Y	1995	1995	Maintenance Records	U	C	C	NL	u	N/R	N			N		
509 CHARLESTON TO 513	N/A	N	Y	1960	1960	Maintenance Records	U	C	C	NL	u	N/R	N			N		
74 CHERRY CT	N/A	N	Y	1973	1973	Visual Inspection	U	C	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
75 CHERRY CT	N/A	N	Y	1973	1973	Visual Inspection	U	C	P	NL	u	N/R	N			N		
76 CHERRY CT	N/A	N	Y	1973	1973	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
77 CHERRY CT	N/A	N	Y	1973	1973	Visual Inspection	U	C	P	NL	u	N/R	N			N		
79 CHERRY CT	N/A	N	Y	1973	1973	Maintenance Records	U	C	C	NL	u	N/R	N			N		
81 CHERRY CT	N/A	N	Y	1973	1973	Maintenance Records	U	C	C	NL	u	N/R	N			N		
82 CHERRY CT	N/A	N	Y	1973	1973	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
83 CHERRY CT	N/A	N	Y	1973	1973	Visual Inspection	U	C	P	NL	u	N/R	N			N		
84 CHERRY CT	N/A	N	Y	1973	1973	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
85 CHERRY CT	N/A	N	Y	1974	1974	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3300 CHESTNUT	N/A	N	Y	1954	1954	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3304 CHESTNUT	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3308 CHESTNUT	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3309 CHESTNUT	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3312 CHESTNUT	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3313 CHESTNUT	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3316 CHESTNUT	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3317 CHESTNUT	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3320 CHESTNUT	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3400 CHESTNUT	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3404 CHESTNUT	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3405 CHESTNUT	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3408 CHESTNUT	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
200 CIRCLE DR	N/A	N	Y	1961	1961	Visual Inspection	U	C	P	NL	u	N/R	N			N		
202 CIRCLE DR	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
203 CIRCLE DR	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N		
204 CIRCLE DR	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N		
205 CIRCLE DR	N/A	N	Y	1953	1953	Visual Inspection	U	C	C	NL	u	N/R	N			N		
206 CIRCLE DR	N/A	N	Y	1957	1957	Visual Inspection	U	C	C	NL	u	N/R	N			N		
207 CIRCLE DR	N/A	N	Y	1957	1957	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
208 CIRCLE DR	N/A	N	Y	1961	1963	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N		
209 CIRCLE DR	N/A	N	Y	1956	1956	Visual Inspection	U	C	C	NL	u	N/R	N			N		
210 CIRCLE DR	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N		
211 CIRCLE DR	N/A	N	Y	1981	1981	Visual Inspection	U	C	C	NL	u	N/R	N			N		
212 CIRCLE DR	N/A	N	Y	1960	1960	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
213 CIRCLE DR	N/A	N	Y	1960	1960	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
213 CIRCLE DR	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
215 CIRCLE DR	N/A	N	Y	1956	1956	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
217 CIRCLE DR	N/A	N	Y	1956	1956	Visual Inspection	U	C	C	NL	u	N/R	N			N		
219 CIRCLE DR	LC3T007	N	Y	1956	1956	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
221 CIRCLE DR	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N		
223 CIRCLE DR	N/A	N	Y	1956	1956	Visual Inspection	U	C	C	NL	u	N/R	N			N		
225 CIRCLE DR	N/A	N	Y	1957	1957	Visual Inspection	U	C	C	NL	u	N/R	N			N		
227 CIRCLE DR	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N		
229 CIRCLE DR	N/A	N	Y	1958	1958	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
231 CIRCLE DR	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
233 CIRCLE DR	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N						
235 CIRCLE DR	N/A	N	Y	1959	1959	Visual Inspection	U	C	C	NL	u	N/R	N			N						
237 CIRCLE DR	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2221 COMMERCIAL	LC3T043	N	Y	1920	1920	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2401 COMMERCIAL	N/A	N	Y	1949	1949	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2417 COMMERCIAL	N/A	N	Y	1915	1915	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2501 COMMERCIAL	N/A	N	Y	1906	1906	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2505 COMMERCIAL	N/A	N	Y	1995	1995	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2509 COMMERCIAL	N/A	N	Y	1907	1907	visual Inspection	U	P	P	NL	u	N/R	N			N						
2513 COMMERCIAL	N/A	N	Y	1995	1995	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2517 COMMERCIAL	N/A	N	Y	1995	1995	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2601 COMMERCIAL	N/A	N	Y	1995	1995	Maintenance Records	U	C	C	NL	u	N/R	N			N						
2603 COMMERCIAL	N/A	N	Y	1941	1941	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2605 COMMERCIAL	N/A	N	Y	1986	1986	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2607 COMMERCIAL	N/A	N	Y	1904	1904	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
2609 COMMERCIAL	N/A	N	Y	1953	1953	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2613 COMMERCIAL	N/A	N	Y	1900	1900	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2617 COMMERCIAL	N/A	N	Y	1956	1956	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2621 COMMERCIAL	N/A	N	Y	1951	1951	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
2701 COMMERCIAL	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2709 COMMERCIAL	N/A	N	Y	1896	1896	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2721 COMMERCIAL	N/A	N	Y	1964	1964	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2725 COMMERCIAL	N/A	N	Y	1948	1948	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2725 COMMERCIAL 1/2	N/A	N	Y	1962	1962	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2813 COMMERCIAL	N/A	N	Y	1947	1947	Maintenance Records	U	C	C	NL	u	N/R	N			N						
2815 COMMERCIAL	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2817 COMMERCIAL	N/A	N	Y	1943	1943	Maintenance Records	U	G	C	GRR	u	N/R	N			N						
2819 COMMERCIAL	N/A	N	Y	1958	1958	Maintenance Records	U	P	G	GRR	u	N/R	N			N						
2901 COMMERCIAL	N/A	N	Y	1950	1950	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
2905 COMMERCIAL	N/A	N	Y	1948	1948	Maintenance Records	U	C	P	NL	u	N/R	N			N						
2907 COMMERCIAL	N/A	N	Y	1943	1943	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2917 COMMERCIAL	N/A	N	Y	1943	1943	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N						
2921 COMMERCIAL	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
3005 COMMERCIAL	N/A	N	Y	1948	1948	Maintenance Records	U	C	C	NL	u	N/R	N			N						
3011 COMMERCIAL	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3013 COMMERCIAL	N/A	N	Y	1943	1943	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3016 COMMERCIAL	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
3101 COMMERCIAL	N/A	N	Y	1945	1945	Maintenance Records	U	C	P	NL	u	N/R	N			N						
3108 COMMERCIAL	N/A	N	Y	1956	1956	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
3109 COMMERCIAL	N/A	N	Y	1954	1954	Visual Inspection	U	P	G	GRR	u	N/R	N			N						
3113 COMMERCIAL	N/A	N	Y	1949	1949	Maintenance Records	U	C	C	NL	u	N/R	N			N						
7789 COUNTRY CL RD	N/A	N	Y	2014	2014	Maintenance Records	U	P	P	NL	u	N/R	N			N						
320 COUNTRY CLUB RD	N/A	N	Y	2010	2010	Maintenance Records	U	C	C	NL	u	N/R	N			N						
400 COUNTRY CLUB RD	N/A	N	Y	1963	1963	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
408 COUNTRY CLUB RD	N/A	N	Y	1949	1949	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)	Leave blank if no Lead						
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)													
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)													
500 COUNTRY CLUB RD	N/A	N	Y	1987	1987	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N						
600 COUNTRY CLUB RD	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N						
705 COUNTRY CLUB RD	N/A	N	Y	1995	1995	Maintenance Records	U	C	C	NL	u	N/R	N			N						
709 COUNTRY CLUB RD	N/A	N	Y	1950		Maintenance Records	U	c	P	NL	u	N/R	N			N						
801 COUNTRY CLUB RD	N/A	N	Y	1978	1978	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
901 COUNTRY CLUB RD	N/A	N	Y	1991	1991	Maintenance Records	U	C	P	NL	u	N/R	N			N						
905 COUNTRY CLUB RD	N/A	N	Y	1985		Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
920 COUNTRY CLUB RD	N/A	CHURCH	Y	2016	2016	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
1001 COUNTRY CLUB RD	N/A	N	Y	1998	1998	Maintenance Records/VISU	U	G	C	GRR	u	N/R	N			N						
1115 COUNTRY CLUB RD	N/A	N	Y	1998	1998	Maintenance Records	U	C	C	NL	u	N/R	N			N						
1 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2 COUNTRY GARDENS	N/A	N	Y	1970	1970	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
3 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N						
4 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N						
5 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N						
6 COUNTRY GARDENS	LC3T044	N	Y	1970	1970	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
7 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N						
8 COUNTRY GARDENS	N/A	N	Y	1970	1990	Visual Inspection	U	C	P	NL	u	N/R	N			N						
9 COUNTRY GARDENS	N/A	N	Y	1971	1971	Visual Inspection	U	C	C	NL	u	N/R	N			N						
10 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	C	NL	u	N/R	N			N						
11 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	C	NL	u	N/R	N			N						
12 COUNTRY GARDENS	N/A	N	Y	1970	1970	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
13 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N						
14 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
15 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N						
16 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N						
17 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	C	NL	u	N/R	N			N						
19 COUNTRY GARDENS	N/A	N	Y	1970	1970	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
20 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N						
22 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	C	NL	u	N/R	N			N						
23 COUNTRY GARDENS	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N						
24 COUNTRY GARDENS	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N						
25 COUNTRY GARDENS	LC3T008	N	Y	1970	1970	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
26 COUNTRY GARDENS	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N						
28 COUNTRY GARDENS	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N						
1 COUNTRY LN	N/A	N	Y	1974	1974	Maintenance Records	U	C	C	NL	u	N/R	N			N						
2 COUNTRY LN	N/A	N	Y	1969	1969	MAINTENANCE RECORDS/C	U	P	P	NL	u	N/R	N			N						
3 COUNTRY LN	N/A	N	Y	1969	1969	Maintenance Records	U	C	C	NL	u	N/R	N			N						
4 COUNTRY LN	N/A	N	Y	1969	1969	MAINTENANCE RECORDS/C	U	P	P	NL	u	N/R	N			N						
5 COUNTRY LN	N/A	N	Y	1973	1973	Maintenance Records	U	C	C	NL	u	N/R	N			N						
6 COUNTRY LN	N/A	N	Y	1969	1969	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N						
7 COUNTRY LN	N/A	N	Y	1971		Maintenance Records	U	C	C	NL	u	N/R	N			N						
8 COUNTRY LN	N/A	N	Y	1969	1969	Maintenance Records	U	C	P	NL	u	N/R	N			N						
9 COUNTRY LN	N/A	N	Y	1972	1972	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
10 COUNTRY LN	N/A	N	Y	1969	1969	Maintenance Records	U	C	C	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)								
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Galvanized (G)			
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Plastic - PVC, HDPE, PEX (P)			
							Cast/Ductile Iron or Transite (Q)	Lead (L)	Lead (L)						Cast/Ductile Iron or Transite (Q)			
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)									
							Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)									
							Unknown (U)								Leave blank if no Lead			
12 COUNTRY LN	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N		
13 COUNTRY LN	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N		
14 COUNTRY LN	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N		
15 COUNTRY LN	N/A	N	Y	1970		Maintenance Records	U	C	C	NL	u	N/R	N			N		
16 COUNTRY LN	N/A	N	Y	1969	1969	Maintenance Records	U	C	C	NL	u	N/R	N			N		
17 COUNTRY LN	N/A	N	Y	1972	1972	Maintenance Records	U	C	C	NL	u	N/R	N			N		
18 COUNTRY LN	N/A	N	Y	1970		Maintenance Records	U	C	C	NL	u	N/R	N			N		
19 COUNTRY LN	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N		
20 COUNTRY LN	N/A	N	Y	1969	1969	Maintenance Records	U	C	C	NL	u	N/R	N			N		
21 COUNTRY LN	N/A	N	Y	1969		Maintenance Records	U	C	C	NL	u	N/R	N			N		
22 COUNTRY LN	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N		
24 COUNTRY LN	N/A	N	Y	1975	1975	Maintenance Records	U	C	C	NL	u	N/R	N			N		
321 CRESCENT	N/A	N	Y	1970		MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N		
400 CRESCENT	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N		
401 CRESCENT	N/A	N	Y	1970		Maintenance Records	U	C	C	NL	u	N/R	N			N		
404 CRESCENT	N/A	N	Y	1971	1971	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N		
405 CRESCENT	N/A	N	Y	1971	1971	Maintenance Records	U	C	C	NL	u	N/R	N			N		
408 CRESCENT	N/A	N	Y	1972	1975	MAINTENANCE RECORDS/C	U	P	C	NL	u	N/R	N			N		
409 CRESCENT	N/A	N	Y	1971	1971	Maintenance Records	U	C	C	NL	u	N/R	N			N		
412 CRESCENT	N/A	N	Y	1971	1971	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N		
413 CRESCENT	N/A	N	Y	1972		Maintenance Records	U	C	C	NL	u	N/R	N			N		
416 CRESCENT	N/A	N	Y	1971	1971	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N		
417 CRESCENT	N/A	N	Y	1971	1971	Maintenance Records	U	C	C	NL	u	N/R	N			N		
421 CRESCENT	N/A	N	Y	1970		Maintenance Records	U	C	C	NL	u	N/R	N			N		
500 CRESCENT	N/A	N	Y	1972	1972	Maintenance Records	U	C	C	NL	u	N/R	N			N		
501 CRESCENT	N/A	N	Y	1972		CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
504 CRESCENT	N/A	N	Y	1973	1973	Maintenance Records	U	C	C	NL	u	N/R	N			N		
505 CRESCENT	N/A	N	Y	1975	1975	Maintenance Records/CUST	U	C	C	NL	u	N/R	N			N		
508 CRESCENT	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N		
509 CRESCENT	N/A	N	Y	1970		Maintenance Records	U	C	C	NL	u	N/R	N			N		
513 CRESCENT	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N		
404 CRESTMORE	N/A	N	Y	1958	1958	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
405 CRESTMORE	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
408 CRESTMORE	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
409 CRESTMORE	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
412 CRESTMORE	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
415 CRESTMORE	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
416 CRESTMORE	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
417 CRESTMORE	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
421 CRESTMORE	N/A	N	Y	1971	1971	Maintenance Records	U	C	C	NL	u	N/R	N			N		
425 CRESTMORE	N/A	N	Y	1964	1964	Maintenance Records	U	C	C	NL	u	N/R	N			N		
500 CRESTMORE	N/A	N	Y	1968	1968	Maintenance Records	U	C	C	NL	u	N/R	N			N		
501 CRESTMORE	N/A	N	Y	1968	1968	Maintenance Records	U	C	C	NL	u	N/R	N			N		
504 CRESTMORE	N/A	N	Y	1966	1966	Maintenance Records	U	C	C	NL	u	N/R	N			N		
505 CRESTMORE	N/A	N	Y	1966	1966	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
508 CRESTMORE	N/A	N	Y	1967	1967	Maintenance Records	U	C	C	NL	u	N/R	N			N						
509 CRESTMORE	N/A	N	Y	1966	1966	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N						
512 CRESTMORE	N/A	N	Y	1966	1966	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
513 CRESTMORE	N/A	N	Y	1967	1967	Maintenance Records	U	C	C	NL	u	N/R	N			N						
300 CRESTVIEW	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N						
301 CRESTVIEW	N/A	N	Y	1967	1967	Maintenance Records	U	C	C	NL	u	N/R	N			N						
304 CRESTVIEW	N/A	N	Y	1957	1957	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
305 CRESTVIEW	N/A	N	Y	1957	1957	Maintenance Records	U	C	C	NL	u	N/R	N			N						
308 CRESTVIEW	N/A	N	Y	1960	1960	Visual Inspection	U	C	C	NL	u	N/R	N			N						
309 CRESTVIEW	N/A	N	Y	1960	1960	Visual Inspection	U	C	C	NL	u	N/R	N			N						
312 CRESTVIEW	N/A	N	Y	1959	1959	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
313 CRESTVIEW	N/A	N	Y	1966	1966	Maintenance Records	U	C	C	NL	u	N/R	N			N						
316 CRESTVIEW	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
320 CRESTVIEW	N/A	N	Y	1968	1968	Maintenance Records	U	C	C	NL	u	N/R	N			N						
401 CRESTVIEW	N/A	N	Y	1967	1967	Maintenance Records	U	C	C	NL	u	N/R	N			N						
404 CRESTVIEW	N/A	N	Y	1968	1968	Maintenance Records	U	C	C	NL	u	N/R	N			N						
405 CRESTVIEW	N/A	N	Y	1961	1961	Visual Inspection	U	C	C	NL	u	N/R	N			N						
408 CRESTVIEW	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N						
409 CRESTVIEW	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N						
412 CRESTVIEW	N/A	N	Y	1958	1958	Visual Inspection	U	P	P	NL	u	N/R	N			N						
413 CRESTVIEW	N/A	N	Y	1962	1962	Visual Inspection	U	C	C	NL	u	N/R	N			N						
416 CRESTVIEW	N/A	N	Y	1959	1959	Visual Inspection	U	C	C	NL	u	N/R	N			N						
417 CRESTVIEW	N/A	N	Y	1964	1964	Maintenance Records	U	C	C	NL	u	N/R	N			N						
420 CRESTVIEW	N/A	N	Y	1965	1965	Visual Inspection	U	C	C	NL	u	N/R	N			N						
421 CRESTVIEW	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N						
424 CRESTVIEW	N/A	N	Y	1960	1960	Visual Inspection	U	C	C	NL	u	N/R	N			N						
500 CRESTVIEW	N/A	N	Y	1960	1960	Visual Inspection	U	C	C	NL	u	N/R	N			N						
501 CRESTVIEW	N/A	N	Y	1965	1965	Visual Inspection	U	C	P	NL	u	N/R	N			N						
504 CRESTVIEW	N/A	N	Y	1960	1960	Visual Inspection	U	C	P	NL	u	N/R	N			N						
505 CRESTVIEW	N/A	N	Y	1968	1968	Maintenance Records	U	C	C	NL	u	N/R	N			N						
508 CRESTVIEW	N/A	N	Y	1960	1960	Visual Inspection	U	C	P	NL	u	N/R	N			N						
512 CRESTVIEW	N/A	N	Y	1960	1960	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
600 CRESTVIEW	N/A	N	Y	1962	1962	Visual Inspection	U	C	C	NL	u	N/R	N			N						
604 CRESTVIEW	N/A	N	Y	1962	1962	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1412 CROSS CREEK	N/A	N	Y	2018	2018	Maintenance Records/CUST	U	P	P	NL	u	N/R	N			N						
1421 CROSS CREEK	N/A	N	Y	2018	2018	Maintenance Records	U	C	C	NL	u	N/R	N			N						
601 DAKOTA	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N						
608 DAKOTA	N/A	N	Y	1960	1960	Visual Inspection	U	P	G	GRR	u	N/R	N			N						
609 DAKOTA	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N						
613 DAKOTA	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N						
616 DAKOTA	N/A	N	Y	1958	1958	Visual Inspection	U	C	C/P	NL	u	N/R	N			N						
620 DAKOTA	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N						
621 DAKOTA	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N						
624 DAKOTA	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N						
625 DAKOTA	N/A	N	Y	1958	1958	Visual Inspection	U	C	G	GRR	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
700 DAKOTA	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N		
701 DAKOTA	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N		
704 DAKOTA	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N		
705 DAKOTA	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
708 DAKOTA	N/A	N	Y	1956	1956	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
709 DAKOTA	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N		
712 DAKOTA	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N		
713 DAKOTA	N/A	N	Y	1951	1951	Maintenance Records	U	C	C	NL	u	N/R	N			N		
716 DAKOTA	N/A	N	Y	1954	1954	Visual Inspection	U	C	C	NL	u	N/R	N			N		
720 DAKOTA	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
721 DAKOTA	N/A	N	Y	1948	1948	Maintenance Records	U	C	C	NL	u	N/R	N			N		
725 DAKOTA	N/A	N	Y	1948	1948	Maintenance Records	U	C	C	NL	u	N/R	N			N		
800 DAKOTA	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N		
804 DAKOTA	N/A	N	Y	1958	1958	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N		
805 DAKOTA	N/A	N	Y	1954	1954	CUSTOMER SURVEY	U	G	C	GRR	u	N/R	N			N		
808 DAKOTA	N/A	N	Y	1958	1958	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
809 DAKOTA	N/A	N	Y	1947	1947	Maintenance Records	U	C	C	NL	u	N/R	N			N		
813 DAKOTA	N/A	N	Y	1947	1947	Maintenance Records	U	C	C	NL	u	N/R	N			N		
817 DAKOTA	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N		
821 DAKOTA	N/A	N	Y	1947	1947	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
1201 DAKOTA	N/A	N	Y	2011	2011	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1209 DAKOTA	N/A	N	Y	2011	2011	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1217 DAKOTA	N/A	N	Y	2011	2011	Maintenance Records	U	P	P	NL	u	N/R	N			N		
1600 DAKOTA	N/A	N	Y	2011	2011	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
1812 DAKOTA	N/A	N	Y	1936	1936	CUSTOMER SURVEY	U	C	C/G/P	GRR	u	N/R	N			N		
1813 DAKOTA	N/A	N	Y	1941	1941	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1816 DAKOTA	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1817 DAKOTA	N/A	N	Y	1946	1946	Maintenance Records	U	P	C	NL	u	N/R	N			N		
1820 DAKOTA	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1821 DAKOTA	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1824 DAKOTA	N/A	N	Y	1979	1949	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1825 DAKOTA	N/A	N	Y	1932	1932	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1828 DAKOTA	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1829 DAKOTA	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2221 DAKOTA	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2301 DAKOTA	N/A	N	Y	1969	1969	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2309 DAKOTA	N/A	N	Y	1969	1969	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2313 DAKOTA	N/A	N	Y	1969	1969	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2317 DAKOTA	N/A	N	Y	1971	1971	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2321 DAKOTA	N/A	N	Y	1971	1971	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2405 DAKOTA	N/A	N	Y	1975	1975	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2409 DAKOTA	N/A	N	Y	1972	1972	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2413 DAKOTA	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2417 DAKOTA	N/A	N	Y	1923	1923	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2421 DAKOTA	N/A	N	Y	1972	1972	Visual Inspection	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
2501 DAKOTA	N/A	N	Y	1972	1972	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2505 DAKOTA	N/A	N	Y	1972	1972	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2509 DAKOTA	N/A	N	Y	1972	1972	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2513 DAKOTA	N/A	N	Y	1975	1975	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2517 DAKOTA	N/A	N	Y	1975	1975	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2521 DAKOTA	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N		
102 DETTRO DR	N/A	N	Y	1994	1994	Visual Inspection	U	C	C	NL	u	N/R	N			N		
40 DEWITT	N/A	N	Y	1994	1994	Visual Inspection	U	C	C	NL	u	N/R	N			N		
60 DEWITT	N/A	N	Y	1946	1946	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
68 DEWITT	N/A	N	Y	1995	1995	Visual Inspection	U	P	P	NL	u	N/R	N			N		
72 DEWITT	N/A	N	Y	1995	1995	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
75 DEWITT	N/A	N	Y	1994	1994	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
76 DEWITT	N/A	N	Y	1964	1964	Maintenance Records	U	C	C	NL	u	N/R	N			N		
80 DEWITT	N/A	N	Y	1949	1949	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
81 DEWITT	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
84 DEWITT	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N		
92 DEWITT	N/A	N	Y	1960	1960	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
98 DEWITT	N/A	N	Y	1979	1979	Maintenance Records	U	C	C	NL	u	N/R	N			N		
99 DEWITT	N/A	N	Y	1945	1945	Visual Inspection	U	G	C	GRR	u	N/R	N			N		
117 DEWITT	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
121 DEWITT	N/A	N	Y	1959	1959	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
204 DEWITT	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
221 DEWITT	N/A	N	Y	1961	1961	Visual Inspection	U	C	C	NL	u	N/R	N			N		
300 DEWITT	N/A	N	Y	1945	1945	Visual Inspection	U	C	P	NL	u	N/R	N			N		
301 DEWITT	N/A	N	Y	1946	1946	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
304 DEWITT	N/A	N	Y	1945	1945	Visual Inspection	U	C	P	NL	u	N/R	N			N		
307 DEWITT	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
308 DEWITT	N/A	N	Y	1992	1992	Maintenance Records	U	C	C	NL	u	N/R	N			N		
312 DEWITT	N/A	N	Y	1949	1949	Maintenance Records	U	C	C	NL	u	N/R	N			N		
313 DEWITT	N/A	N	Y	1992	1992	Maintenance Records	U	C	C	NL	u	N/R	N			N		
320 DEWITT	LC3T026	N	Y	1992	1992	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
400 DEWITT	N/A	N	Y	1992	1992	Maintenance Records	U	C	C	NL	u	N/R	N			N		
401 DEWITT	N/A	N	Y	1992	1992	Maintenance Records	U	C	C	NL	u	N/R	N			N		
405 DEWITT	N/A	N	Y	1947	1947	Maintenance Records	U	C	C	NL	u	N/R	N			N		
408 DEWITT	N/A	N	Y	1950	1950	Maintenance Records	U	C	C	NL	u	N/R	N			N		
409 DEWITT	LC3T009	N	Y	1992	1992	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
413 DEWITT	N/A	N	Y	1955	1955	Maintenance Records	U	C	C	NL	u	N/R	N			N		
417 DEWITT	N/A	N	Y	2014	2014	Maintenance Records	U	C	C	NL	u	N/R	N			N		
420 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
421 DEWITT	N/A	N	Y	1941	1941	Maintenance Records	U	C	C	NL	u	N/R	N			N		
512 DEWITT	N/A	N	Y	1928	1928	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
513 DEWITT	N/A	N	Y	1931	1931	Maintenance Records	U	C	C	NL	u	N/R	N			N		
514 DEWITT	N/A	N	Y	1991	1991	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
516 DEWITT	N/A	N	Y	1986	1986	Maintenance Records	U	C	C	NL	u	N/R	N			N		
517 DEWITT	N/A	N	Y	1930	1930	Maintenance Records	U	G	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
520 DEWITT	N/A	N	Y	1928	1928	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
521 DEWITT	N/A	N	Y	1933	1933	Maintenance Records	U	C	C	NL	u	N/R	N			N		
608 DEWITT	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
616 DEWITT	N/A	N	Y	1962	1962	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
617 DEWITT	N/A	N	Y	1947	1947	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
620 DEWITT	N/A	N	Y	1934	1934	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
621 DEWITT	N/A	N	Y	1947	1947	Visual Inspection	U	C	C	NL	u	N/R	N			N		
701 DEWITT	N/A	N	Y	1944	1944	Visual Inspection	U	P	P	NL	u	N/R	N			N		
704 DEWITT	N/A	N	Y	1950	1950	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
705 DEWITT	N/A	N	Y	1947	1947	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
706 DEWITT	N/A	N	Y	1946	1946	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
708 DEWITT	N/A	N	Y	1946	1946	Maintenance Records/CUST	U	P	P	NL	u	N/R	N			N		
709 DEWITT	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N		
712 DEWITT	N/A	N	Y	1940	1940	Maintenance Records	U	P	P	NL	u	N/R	N			N		
713 DEWITT	N/A	N	Y	1928	1928	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
716 DEWITT	N/A	N	Y	2006	2006	Visual Inspection	U	C	P	NL	u	N/R	N			N		
717 DEWITT	N/A	N	Y	1916	1916	Visual Inspection	U	C	C	NL	u	N/R	N			N		
720 DEWITT	N/A	N	Y	1951	1951	Maintenance Records	U	C	C	NL	u	N/R	N			N		
721 DEWITT	N/A	N	Y	1917	1917	Maintenance Records	U	C	C	NL	u	N/R	N			N		
800 DEWITT	N/A	N	Y	1929	1929	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
801 DEWITT	N/A	N	Y	1904	1904	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
804 DEWITT	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N		
805 DEWITT	N/A	N	Y	1940	1940	CUSTOMER SURVEY	U	C	G/P	GRR	u	N/R	N			N		
808 DEWITT	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N		
809 DEWITT	N/A	N	Y	2001	2001	Maintenance Records	U	C	C	NL	u	N/R	N			N		
812 DEWITT	N/A	N	Y	1930	1930	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
813 DEWITT	N/A	N	Y	1930	1930	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
817 DEWITT	N/A	N	Y	1923	1923	Maintenance Records	U	C	C	NL	u	N/R	N			N		
820 DEWITT	N/A	N	Y	1904	1904	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
821 DEWITT	N/A	N	Y	1944	1944	Maintenance Records/CUST	U	C	P	NL	u	N/R	N			N		
900 DEWITT	N/A	N	Y	1928	1928	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
901 DEWITT	N/A	N	Y	1933	1933	Maintenance Records	U	C	C	NL	u	N/R	N			N		
904 DEWITT	N/A	N	Y	1941	1941	Maintenance Records	U	C	C	NL	u	N/R	N			N		
905 DEWITT	N/A	N	Y	1933	1933	Maintenance Records	U	C	C	NL	u	N/R	N			N		
909 DEWITT	N/A	N	Y	1940	1940	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
912 DEWITT	N/A	N	Y	1925	1925	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
913 DEWITT	N/A	N	Y	1946	1946	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
916 DEWITT	N/A	N	Y	1944	1944	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1005 DEWITT	N/A	N	Y	1981	1981	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1020 DEWITT	N/A	N	Y	1934	1934	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
1021 DEWITT	N/A	N	Y	1927	1927	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1100 DEWITT	N/A	N	Y	1914	1914	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
1104 DEWITT	N/A	N	Y	1925	1925	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1105 DEWITT	N/A	N	Y	1944	1944	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1108 DEWITT	N/A	N	Y	1944	1944	Maintenance Records	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (Q)								
1112 DEWITT	N/A	N	Y	1933	1933	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
1113 DEWITT	N/A	N	Y	1938	1938	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
1116 DEWITT	N/A	N	Y	1931	1931	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
1120 DEWITT	N/A	N	Y	1928	1928	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1208 DEWITT	N/A	N	Y	1925	1925	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1208 DEWITT 1/2	N/A	N	Y	1925	1925	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1216 DEWITT	N/A	N	Y	1949	1949	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1217 DEWITT	N/A	N	Y	1924	1924	CUSTOMER SURVEY	U	C	C/G	GRR	u	N/R	N			N		
1220 DEWITT	N/A	N	Y	1937	1937	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1300 DEWITT	N/A	N	Y	1955	1955	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1301 DEWITT	N/A	N	Y	1948	1948	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
1304 DEWITT	N/A	N	Y	1937	1937	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
1305 DEWITT	N/A	N	Y	1937	1937	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
1308 DEWITT	N/A	N	Y	1948	1948	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1309 DEWITT	N/A	N	Y	1921	1921	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1313 DEWITT	N/A	N	Y	1921	1921	Maintenance Records	U	P	P	NL	u	N/R	N			N		
1321 DEWITT	N/A	N	Y	1955	1955	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1400 DEWITT	N/A	N	Y	1931	1931	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
1404 DEWITT	N/A	N	Y	1997	1997	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1408 DEWITT	N/A	N	Y	1997	1997	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1412 DEWITT	N/A	N	Y	1997	1997	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1416 DEWITT	N/A	N	Y	1997	1997	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1420 DEWITT	N/A	N	Y	1935	1935	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1701 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1705 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1713 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1716 DEWITT	N/A	N	Y	1928	1928	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
1717 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1720 DEWITT	N/A	N	Y	1923	1923	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
1721 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1801 DEWITT	N/A	N	Y	1946	1946	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1805 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1808 DEWITT	N/A	N	Y	1930	1930	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
1809 DEWITT	N/A	N	Y	1938	1938	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1812 DEWITT	N/A	N	Y	1917	1917	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
1900 DEWITT	N/A	N	Y	1911	1911	Visual Inspection	U	P	G	GRR	u	N/R	N			N		
1901 DEWITT	N/A	N	Y	1911	1911	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1904 DEWITT	N/A	N	Y	1944	1944	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
1905 DEWITT	N/A	N	Y	1955	1955	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
1908 DEWITT	N/A	N	Y	1928	1928	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
2000 DEWITT	N/A	N	Y	1959	1959	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2001 DEWITT	N/A	N	Y	1930	1930	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2004 DEWITT	N/A	N	Y	1950	1950	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2005 DEWITT	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2008 DEWITT	N/A	N	Y	1959	1959	Maintenance Records	U	cts	CTS	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
Leave blank if no Lead																		
2009 DEWITT	N/A	N	Y	1928	1928	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2105 DEWITT	N/A	N	Y	1911	1911	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2113 DEWITT 1/2	N/A	N	Y	1911	1911	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2200 DEWITT	N/A	N	Y	1992	1992	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2208 DEWITT	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2209 DEWITT	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2212 DEWITT	N/A	N	Y	1952	1952	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2216 DEWITT	N/A	N	Y	1924	1924	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2220 DEWITT	N/A	N	Y	1952	1952	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2301 DEWITT	N/A	N	Y	1986	1986	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2304 DEWITT	N/A	N	Y	1928	1928	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2305 DEWITT	N/A	N	Y	1953	1953	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2308 DEWITT	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2309 DEWITT	N/A	N	Y	1943	1943	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2312 DEWITT	N/A	N	Y	1946	1946	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
2313 DEWITT	N/A	N	Y	1943	1943	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2316 DEWITT	N/A	N	Y	1943	1943	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2317 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2321 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2400 DEWITT	N/A	N	Y	1935	1935	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2401 DEWITT	N/A	N	Y	1953	1953	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2404 DEWITT	N/A	N	Y	1978	1975	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2408 DEWITT	N/A	N	Y	1949	1949	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2409 DEWITT	N/A	N	Y	2017	2017	Maintenance Records	U	P	P	NL	u	N/R	N			N		
2416 DEWITT	N/A	N	Y	1931	1931	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2417 DEWITT	N/A	N	Y	1952	1952	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2420 DEWITT	N/A	N	Y	1925	1925	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
2421 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2500 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2501 DEWITT	N/A	N	Y	1937	1937	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2512 DEWITT	N/A	N	Y	1926	1926	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2516 DEWITT	N/A	N	Y	1926	1926	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2517 DEWITT	N/A	N	Y	1924	1924	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2521 DEWITT	N/A	N	Y	1945	1945	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2600 DEWITT	N/A	N	Y	1923	1923	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2604 DEWITT	N/A	N	Y	1950	1950	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2605 DEWITT	N/A	N	Y	1953	1953	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2608 DEWITT	N/A	N	Y	1923	1923	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2609 DEWITT	N/A	N	Y	1953	1953	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2612 DEWITT	N/A	N	Y	1946	1946	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2616 DEWITT	N/A	N	Y	1947	1947	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2617 DEWITT	N/A	N	Y	1955	1955	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2621 DEWITT	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2621 DEWITT 1/2	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2700 DEWITT	N/A	N	Y	1992	1992	Maintenance Records	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
2701 DEWITT	N/A	N	Y	1917	1917	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2704 DEWITT	N/A	N	Y	1927	1927	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2705 DEWITT	N/A	N	Y	1950	1950	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2708 DEWITT	N/A	N	Y	1937	1937	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2709 DEWITT	N/A	N	Y	1928	1928	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2712 DEWITT	N/A	N	Y	1952	1952	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2713 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2716 DEWITT	N/A	N	Y	1934	1934	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		
2720 DEWITT	N/A	N	Y	1992	1992	CUSTOMER SURVEY	U	G	G	GRR	u					N		
2721 DEWITT	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2800 DEWITT	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2801 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2804 DEWITT	N/A	N	Y	1954	1954	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
2805 DEWITT	N/A	N	Y	1928	1928	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2808 DEWITT	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2809 DEWITT	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2812 DEWITT	N/A	N	Y	1940	1940	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2813 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2816 DEWITT	N/A	N	Y	1923	1923	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2817 DEWITT	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2820 DEWITT	N/A	N	Y	2007	2007	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2821 DEWITT	N/A	N	Y	1940	1940	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2900 DEWITT	N/A	N	Y	1991	1991	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2901 DEWITT	N/A	N	Y	1929	1929	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2905 DEWITT	N/A	N	Y	1930	1930	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2908 DEWITT	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2909 DEWITT	N/A	N	Y	2017	2017	Visual Inspection	U	P	C	NL	u	N/R	N			N		
2912 DEWITT	N/A	N	Y	1925	1925	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2913 DEWITT	N/A	N	Y	1925	1925	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2916 DEWITT	N/A	N	Y	1980	1980	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2917 DEWITT	N/A	N	Y	1927	1927	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2920 DEWITT	N/A	N	Y	1927	1927	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2921 DEWITT	N/A	N	Y	1928	1928	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3000 DEWITT	N/A	N	Y	1951	1951	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3001 DEWITT	N/A	N	Y	1975	1975	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3005 DEWITT	N/A	N	Y	1928	1928	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
3009 DEWITT	N/A	N	Y	1940	1940	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3012 DEWITT	N/A	N	Y	1940	1940	CUSTOMER SURVEY	U	G/P	G	GRR	u	N/R	N			N		
3013 DEWITT	N/A	N	Y	1940	1940	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3017 DEWITT	N/A	N	Y	1924	1924	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3020 DEWITT	N/A	N	Y	1928	1928	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3021 DEWITT	N/A	N	Y	1924	1924	Maintenance Records/CUST	U	P	P/C	NL	u	N/R	N			N		
3100 DEWITT	N/A	N	Y	1921	1921	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3101 DEWITT	N/A	N	Y	1929	1929	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3104 DEWITT	N/A	N	Y	1966	1966	Visual Inspection	U	G	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)													Leave blank if no Lead			
3105 DEWITT	N/A	N	Y	1929	1929	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3108 DEWITT	N/A	N	Y	1928	1928	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
3109 DEWITT	N/A	N	Y	1955	1955	Visual Inspection	U	P	G	GRR	u	N/R	N			N		
3112 DEWITT	N/A	N	Y	1946	1946	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3116 DEWITT	N/A	N	Y	1992	1992	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3117 DEWITT	N/A	N	Y	1948	1948	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3120 DEWITT	N/A	N	Y	1944	1944	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3201 DEWITT	N/A	N	Y	1945	1945	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3205 DEWITT	N/A	N	Y	1945	1945	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3208 DEWITT	N/A	N	Y	1945	1945	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3209 DEWITT	N/A	N	Y	1945	1945	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3212 DEWITT	N/A	N	Y	1939	1939	Maintenance Records	U	P	P	NL	u	N/R	N			N		
3213 DEWITT	N/A	N	Y	1949	1949	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3216 DEWITT	N/A	N	Y	1946	1946	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3217 DEWITT	N/A	N	Y	1939	1939	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3221 DEWITT	N/A	N	Y	1930	1930	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3224 DEWITT	N/A	N	Y	1930	1930	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3225 DEWITT	N/A	N	Y	1930	1930	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3228 DEWITT	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3233 DEWITT	N/A	N	Y	1949	1949	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3405 DEWITT	N/A	N	Y	2002	2002	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3409 DEWITT	N/A	N	Y	1991	1991	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3417 DEWITT	N/A	N	Y	1992	1992	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3421 DEWITT	N/A	N	Y	1987	1987	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3621 DEWITT	N/A	N	Y	2023	2023	Maintenance Report	U	CTS	CTS	NL	u	N/R	N			N		
117 DEWITT 1/2	N/A	N	Y	1954	1954	Visual Inspection	U	C	C	NL	u	N/R	N			N		
312 DEWITT AVE EAST	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
909 DEWITT AVE EAST	N/A	N	Y	2010	2010	Maintenance Report	U	CTS	CTS	NL	u	N/R	N			N		
1516 DEWITT AVE EAST	N/A	N	Y	1998	1998	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
412 DEWITT THRU 414	N/A	N	Y	1998	1998	Maintenance Records	U	C	P	NL	u	N/R	N			N		
13 DORAL CT	N/A	N	Y	1978	1978	Visual Inspection	U	C	C	NL	u	N/R	N			N		
14 DORAL CT	N/A	N	Y	1978	1978	Visual Inspection	U	C	C	NL	u	N/R	N			N		
15 DORAL CT	N/A	N	Y	1978	1978	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
16 DORAL CT	N/A	N	Y	1979	1979	Visual Inspection	U	C	C	NL	u	N/R	N			N		
17 DORAL CT	N/A	N	Y	1978	1978	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2000 DOUGLAS	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2001 DOUGLAS	N/A	N	Y	1956	1956	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2004 DOUGLAS	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2008 DOUGLAS	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2012 DOUGLAS	N/A	N	Y	1955	1955	VISUAL INSPECTION/CUSTO	U	C	C	NL	u	N/R	N			N		
2016 DOUGLAS	N/A	N	Y	1956	1956	Visual Inspection/CUSTOM	U	C	P	NL	u	N/R	N			N		
2020 DOUGLAS	LC3T010	N	Y	1956	1956	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2021 DOUGLAS	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
14 DUCHESS CT	N/A	N	Y	2014	2014	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
15 DUCHESS CT	N/A	N	Y	1987	1987	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
16 DUCHESS CT	N/A	N	Y	1987	1987	Visual Inspection	U	C	P	NL	u	N/R	N			N		
18 DUCHESS CT	N/A	N	Y	1987	1987	Visual Inspection	U	C	C	NL	u	N/R	N			N		
19 DUCHESS CT	N/A	N	Y	1987	1987	Visual Inspection	U	C	P	NL	u	N/R	N			N		
5821 E CO RD 1000 N	N/A	N	Y	2010	2010	Visual Inspection	U	C	P	NL	u	N/R	N			N		
6657 E CO RD 1000 N	N/A	N	Y	1919	1919	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
7021 E CO RD 1000 N	N/A	N	Y	1923	1923	Visual Inspection	U	C	P	U	u	N/R	N			N		
6876 E CO RD 1200 N	N/A	N	Y	1919	1919	VISUAL INSPECTION	U	C	P	U	u	N/R	N			N		
6886 E CO RD 1200 N	N/A	N	Y	1910	1910	VISUAL INSPECTION	U	C	P	U	u	N/R	N			N		
6900 E CO RD 1200 N	N/A	N	Y	1923	1923	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
6918 E CO RD 1200 N	N/A	N	Y	1923	1923	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
6945 E CO RD 1200 N	N/A	N	Y	1920	1920	CUSTOMER SURVEY	U	C	P	U	u	N/R	N			N		
6961 E CO RD 1200 N	N/A	N	Y	1910	1910	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
7131 E CO RD 1200 N	N/A	N	Y	1910	1910	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
6860 E CO RD 1200N	N/A	N	Y	1976	1976	VISUAL INSPECTION/CUSTO	U	C	C	NL	u	N/R	N			N		
6927 E CO RD 1200N	N/A	N	Y	1983	1983	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
6936 E CO RD 1200N	N/A	N	Y	1976	1976	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
6954 E CO RD 1200N	N/A	N	Y	1923	1923	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
6970 E CO RD 1200N	N/A	N	Y	1976	1976	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
6789 E COUNTY RD 1000N	N/A	N	Y	1910	1910	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
3512 E COUNTY ROAD 900N	N/A	N	Y	1910	1910	Visual Inspection	U	C	C	U	u	N/R	N			N		
600 EDGAR	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
601 EDGAR	N/A	N	Y	2008	2008	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
604 EDGAR	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
605 EDGAR B	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
608 EDGAR	N/A	N	Y	1948	1948	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N		
609 EDGAR	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
613 EDGAR	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
616 EDGAR	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
617 EDGAR	N/A	N	Y	1938	1938	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
621 EDGAR	N/A	N	Y	1917	1917	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
700 EDGAR	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
704 EDGAR	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
708 EDGAR	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
709 EDGAR	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
712 EDGAR	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
713 EDGAR	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
716 EDGAR	N/A	N	Y	1932	1932	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
717 EDGAR	N/A	N	Y	1936	1936	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
720 EDGAR	N/A	N	Y	1914	1914	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
721 EDGAR	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
800 EDGAR	N/A	N	Y	1911	1911	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
801 EDGAR	N/A	N	Y	1922	1922	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
804 EDGAR	N/A	N	Y	1908	1908	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
805 EDGAR	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
808 EDGAR	N/A	N	Y	1911	1911	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)			
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)			
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)			
809 EDGAR	N/A	N	Y	1937	1937	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
811 EDGAR	N/A	N	Y	1914	1914	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
812 EDGAR	N/A	N	Y	1937	1937	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
816 EDGAR	N/A	N	Y	1912	1912	MAINTENANCE RECORDS	U	C	CTS	NL	u	N/R	N			N		
817 EDGAR	N/A	N	Y	1929	1929	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N		
820 EDGAR	N/A	N	Y	1964	1964	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
900 EDGAR	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
901 EDGAR	N/A	N	Y	1906	1906	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
904 EDGAR	LC3T011	N	Y	1913	1913	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
905 EDGAR	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
908 EDGAR	N/A	N	Y	1909	1909	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
909 EDGAR	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
912 EDGAR	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
913 EDGAR	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
916 EDGAR	N/A	N	Y	2024	2024	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
917 EDGAR	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
920 EDGAR	N/A	N	Y	1924	1924	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
921 EDGAR	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1000 EDGAR	N/A	N	Y	1915	1915	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1001 EDGAR	N/A	N	Y	1998	1998	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1005 EDGAR	N/A	N	Y	1945	1945	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1008 EDGAR	N/A	N	Y	1985	1985	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1009 EDGAR	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1012 EDGAR	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1013 EDGAR	LC3T012	N	Y	1913	1913	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
1016 EDGAR	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1017 EDGAR	N/A	N	Y	1924	1924	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1020 EDGAR	N/A	N	Y	1914	1914	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
1021 EDGAR	N/A	N	Y	1981	1981	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1100 EDGAR	N/A	N	Y	1934	1934	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1101 EDGAR	N/A	N	Y	1934	1934	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1104 EDGAR	N/A	N	Y	2008	2008	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1105 EDGAR	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1108 EDGAR	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1109 EDGAR	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1113 EDGAR	N/A	N	Y	1966	1966	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1116 EDGAR	N/A	N	Y	1917	1917	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1117 EDGAR	N/A	N	Y	1999	1999	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1121 EDGAR	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	C	G/P	GRR	u	N/R	N			N		
1200 EDGAR APT A	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1200 EDGAR APT B	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1205 EDGAR	N/A	N	Y	1913	1913	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1209 EDGAR	N/A	N	Y	1939	1939	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1210 EDGAR	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1212 EDGAR	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (Q)								
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Cast/Ductile Iron or Transite (Q)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)			
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)						Leave blank if no Lead			
							Unknown (U)											
1213 EDGAR	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1217 EDGAR	N/A	N	Y	1911	1911	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1218 EDGAR	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1220 EDGAR	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1221 EDGAR	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1300 EDGAR APT 1	N/A	N	Y	1907	1907	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1300 EDGAR APT 2	N/A	N	Y	1907	1907	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1304 EDGAR	N/A	N	Y	1991	1991	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1305 EDGAR	N/A	N	Y	1938	1938	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1308 EDGAR	N/A	N	Y	1935	1935	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1309 EDGAR	N/A	N	Y	1943	1943	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1312 EDGAR	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1313 EDGAR	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1316 EDGAR	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1317 EDGAR	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1320 EDGAR	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1401 EDGAR	N/A	N	Y	1991	1991	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
1404 EDGAR	N/A	N	Y	1990	1990	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1408 EDGAR	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1408 EDGAR APT 3	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1409 EDGAR	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1412 EDGAR	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1413 EDGAR	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1416 EDGAR	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1417 EDGAR	N/A	N	Y	1941	1941	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1421 EDGAR	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1500 EDGAR	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
1504 EDGAR	N/A	N	Y	1939	1939	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
1505 EDGAR	N/A	N	Y	1913	1913	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1508 EDGAR	N/A	N	Y	1931	1931	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
1509 EDGAR	N/A	N	Y	1908	1908	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1512 EDGAR	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1513 EDGAR	N/A	N	Y	1915	1915	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1516 EDGAR	LC3T045	N	Y	1939	1939	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
1517 EDGAR	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1520 EDGAR	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1521 EDGAR	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1605 EDGAR	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1609 EDGAR	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1612 EDGAR	N/A	N	Y	1948	1948	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1613 EDGAR	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1613 EDGAR 1/2	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1617 EDGAR	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1621 EDGAR	N/A	N	Y	2024	2004	MAINTENANCE RECORDS	U	CTS	CTS	NL	u	N/R	N			N		
1705 EDGAR	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
1709 EDGAR	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1712 EDGAR	N/A	N	Y	1907	1907	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
1716 EDGAR	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
605 A EDGAR	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1717 EDGEWATER	N/A	N	Y	2009	2009	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1721 EDGEWATER	N/A	N	Y	2002	2002	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1801 EDGEWATER	N/A	N	Y	2003	2003	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1804 EDGEWATER	N/A	N	Y	2002	2002	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1806 EDGEWATER	N/A	N	Y	2002	2002	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1808 EDGEWATER	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1810 EDGEWATER	N/A	N	Y	1997	1997	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3 EL RANCHO DR	N/A	N	Y	1958	1958	Visual Inspection	U	C	C	NL	u	N/R	N			N		
5 EL RANCHO DR	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N		
7 EL RANCHO DR	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N		
2 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
3 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N		
4 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N		
5 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS/C	U	P	C	NL	u	N/R	N			N		
6 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N		
7 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
8 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
9 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS/C	U	P	P	NL	u	N/R	N			N		
10 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N		
11 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
12 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
13 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
14 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
15 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N		
16 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N		
17 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS/C	U	P	C	NL	u	N/R	N			N		
18 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
19 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
20 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	P	NL	u	N/R	N			N		
21 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS/C	U	P	P	NL	u	N/R	N			N		
22 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
23 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
24 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	P	NL	u	N/R	N			N		
26 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N		
28 ELM RIDGE	N/A	N	Y	2013	2013	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		
29 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
30 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
31 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
32 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
33 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Plastic - PVC, HDPE, PEX (P)							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
34 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N						
35 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N						
36 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N						
37 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N						
38 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N						
39 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS/C	U	P	P	NL	u	N/R	N			N						
40 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N						
41 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N						
42 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS/C	U	P	C	NL	u	N/R	N			N						
43 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N						
44 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS/C	U	P	C	NL	u	N/R	N			N						
45 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N						
46 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N						
47 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N						
48 ELM RIDGE	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N						
49 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N						
50 ELM RIDGE	N/A	N	Y	2013	2013	MAINTENANCE RECORD/CL	U	P	G	GRR	u	N/R	N			N						
200 ESSEX	N/A	N	Y	1987	1987	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
207 ESSEX	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
208 ESSEX	N/A	N	Y	1988	1988	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N						
210 ESSEX	N/A	N	Y	1986	1986	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
211 ESSEX	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
214 ESSEX	N/A	N	Y	1989	1989	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
216 ESSEX	N/A	N	Y	1985	1985	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
217 ESSEX	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
304 ESSEX	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
305 ESSEX	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
308 ESSEX	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
309 ESSEX	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
312 ESSEX	N/A	N	Y	1968	1968	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
313 ESSEX	N/A	N	Y	1969	1969	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
316 ESSEX	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
317 ESSEX	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
400 ESSEX	N/A	N	Y	1967	1967	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
401 ESSEX	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
404 ESSEX	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
405 ESSEX	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
408 ESSEX	N/A	N	Y	1963	1963	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
409 ESSEX	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
412 ESSEX	N/A	N	Y	1964	1964	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
413 ESSEX	N/A	N	Y	1963	1963	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
416 ESSEX	N/A	N	Y	1963	1963	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
417 ESSEX	N/A	N	Y	1964	1964	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
420 ESSEX	N/A	N	Y	1965	1965	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N						
500 ESSEX	N/A	N	Y	1965	1965	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)			
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)			
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)			
501 ESSEX	N/A	N	Y	1963	1963	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N		
505 ESSEX	N/A	N	Y	1965	1965	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
516 ESSEX	N/A	N	Y	1965	1965	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
517 ESSEX	N/A	N	Y	1963	1963	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N		
1409 ESSEX	N/A	N	Y	1945	1945	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1612 ESSEX	N/A	N	Y	1938	1938	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1713 ESSEX	N/A	N	Y	1935	1935	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1809 ESSEX	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1812 ESSEX	N/A	N	Y	1975	1975	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1813 ESSEX	LC3T027	N	Y	1929	1929	Visual Inspection	U	P	G	GRR	u	N/R	N			N		
1824 ESSEX	N/A	N	Y	1947	1947	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1828 ESSEX	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2300 ESSEX	N/A	N	Y	1964	1964	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2301 ESSEX	N/A	N	Y	1906	1906	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2304 ESSEX	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2305 ESSEX	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2308 ESSEX	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2309 ESSEX	N/A	N	Y	1967	1967	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2312 ESSEX	N/A	N	Y	1969	1969	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2313 ESSEX	N/A	N	Y	1965	1965	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2316 ESSEX	N/A	N	Y	1967	1967	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2317 ESSEX	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2320 ESSEX	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2321 ESSEX	N/A	N	Y	1965	1965	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2404 ESSEX	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2405 ESSEX	N/A	N	Y	1965	1965	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2408 ESSEX	N/A	N	Y	1966	1966	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2409 ESSEX	N/A	N	Y	1965	1965	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N		
2412 ESSEX	N/A	N	Y	1966	1966	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2413 ESSEX	N/A	N	Y	1965	1965	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2416 ESSEX	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2417 ESSEX	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2420 ESSEX	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2421 ESSEX	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2501 ESSEX	N/A	N	Y	1965	1965	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2504 ESSEX	N/A	N	Y	1974	1974	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2505 ESSEX	N/A	N	Y	1965	1965	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2508 ESSEX	N/A	N	Y	1966	1966	CUSTOMER SURVEY	U	P	G	GRR	u	N/R	N			N		
2509 ESSEX	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2512 ESSEX	N/A	N	Y	1968	1968	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2513 ESSEX	N/A	N	Y	1965	1965	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2516 ESSEX	N/A	N	Y	1968	1968	Visual Inspection/CUSTOMER SURVEY	U	C	G/C	GRR	u	N/R	N			N		
2517 ESSEX	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2616 ESSEX	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2617 ESSEX	N/A	N	Y	1993	1993	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Leave blank if no Lead							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)													
							Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)													
2621 ESSEX	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2701 ESSEX	N/A	N	Y	1997	1997	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2705 ESSEX	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2709 ESSEX	N/A	N	Y	2000	200	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2713 ESSEX	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2717 ESSEX	N/A	N	Y	2002	2002	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2721 ESSEX	N/A	N	Y	2001	2001	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N						
2725 ESSEX	N/A	N	Y	2003	2003	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2801 ESSEX	N/A	N	Y	2001	2001	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
2901 ESSEX	N/A	N	Y	2016	2016	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
1904 EVERGREEN CT	N/A	N	Y	2012	2012	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N						
1906 EVERGREEN CT	N/A	N	Y	1995	1995	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1921 EVERGREEN CT	N/A	N	Y	2015	2015	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2020 EVERGREEN CT	N/A	N	Y	2014	2014	Visual Inspection	U	P	P	NL	u	N/R	N			N						
1905 EVERGREEN CT	N/A	N	Y	1995	1995	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1907 EVERGREEN CT	N/A	N	Y	1995	1995	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1908 EVERGREEN CT	N/A	N	Y	2010	2010	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1909 EVERGREEN CT	N/A	N	Y	1999	1999	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
1910 EVERGREEN CT	N/A	N	Y	2010	2010	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1911 EVERGREEN CT	N/A	N	Y	1999	1999	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1912 EVERGREEN CT	N/A	N	Y	1997	1997	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1913 EVERGREEN CT	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1915 EVERGREEN CT	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1916 EVERGREEN CT	N/A	N	Y	2016	2016	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1917 EVERGREEN CT	N/A	N	Y	2000	2000	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1920 EVERGREEN CT	N/A	N	Y	1995	1995	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1921 EVERGREEN CT	N/A	N	Y	2015	2015	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2000 EVERGREEN CT	N/A	N	Y	2000	2000	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2001 EVERGREEN CT	N/A	N	Y	1976	1976	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2004 EVERGREEN CT	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2005 EVERGREEN CT	N/A	N	Y	1975	1975	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2008 EVERGREEN CT	N/A	N	Y	2007	2007	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2009 EVERGREEN CT	N/A	N	Y	1995	1995	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2012 EVERGREEN CT	N/A	N	Y	2002	2002	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2013 EVERGREEN CT	N/A	N	Y	2017	2017	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2016 EVERGREEN CT	N/A	N	Y	1997	1997	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2017 EVERGREEN CT	N/A	N	Y	1998	1998	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2024 EVERGREEN CT	N/A	N	Y	2014	2014	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2025 EVERGREEN CT	N/A	N	Y	1996	1996	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2028 EVERGREEN CT	N/A	N	Y	2003	2003	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2029 EVERGREEN CT	N/A	N	Y	1997	1997	Visual Inspection	U	C	P	NL	u	N/R	N			N						
21 FAIRWAY LN	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
23 FAIRWAY LN	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
24 FAIRWAY LN	N/A	N	Y	2022	2022	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
25 FAIRWAY LN	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	p	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Plastic - PVC, HDPE, PEX (P)							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
26 FAIRWAY LN	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
27 FAIRWAY LN	N/A	N	Y	1975	1975	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
28 FAIRWAY LN	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
29 FAIRWAY LN	N/A	N	Y	1973	1973	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
30 FAIRWAY LN	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
31 FAIRWAY LN	N/A	N	Y	1976	1976	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
32 FAIRWAY LN	N/A	N	Y	1974	1974	MAINTENANCE RECORDS/C	U	C	G	GRR	u	N/R	N			N						
33 FAIRWAY LN	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
6177 FAIRWAY LN	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
6181 FAIRWAY LN	N/A	N	Y	1985	1985	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N						
1717 FEDERAL SQUARE	N/A	N	Y	1910	1910	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
5 FOX DR	N/A	N	Y	1998	1998	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N						
8 FOX DR	N/A	N	Y	1992	1992	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
11 FOX DR	N/A	N	Y	2012	2012	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
12 FOX DR	N/A	N	Y	2017	2017	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N						
1601 FROSTWOOD	N/A	N	Y	1972	1972	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
1602 FROSTWOOD	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1603 FROSTWOOD	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1604 FROSTWOOD	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1605 FROSTWOOD	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1606 FROSTWOOD	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1607 FROSTWOOD	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1608 FROSTWOOD	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1609 FROSTWOOD	N/A	N	Y	1970	1970	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
1610 FROSTWOOD	N/A	N	Y	1970	1970	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
1611 FROSTWOOD	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1612 FROSTWOOD	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1613 FROSTWOOD	N/A	N	Y	1971	1971	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N						
1614 FROSTWOOD	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1615 FROSTWOOD	N/A	N	Y	1970	1970	MAINTENANCE RECORDS/C	U	C	C/P	NL	u	N/R	N			N						
1616 FROSTWOOD	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1617 FROSTWOOD	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1618 FROSTWOOD	N/A	N	Y	1972	1972	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
1620 FROSTWOOD	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1622 FROSTWOOD	N/A	N	Y	1970	1970	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N						
1624 FROSTWOOD	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
900 GARFIELD	N/A	N	Y	2001	2001	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
2800 GARFIELD	N/A	N	Y	1959	1959	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
2801 GARFIELD	N/A	N	Y	1958	1958	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N						
2804 GARFIELD	LC3T028	N	Y	1960	1960	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2808 GARFIELD	LC3T046	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2812 GARFIELD	N/A	N	Y	1958	1958	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
2900 GARFIELD	N/A	N	Y	1956	1956	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
2901 GARFIELD	N/A	N	Y	1959	1959	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2904 GARFIELD	N/A	N	Y	2008	2008	Visual Inspection	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property		
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.		
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)				
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)				
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)				
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)				
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)				
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Plastic - PVC, HDPE, PEX (P)				
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead				
2920 GARFIELD	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N			
2921 GARFIELD	N/A	N	Y	1965	1965	Visual Inspection	U	C	P	NL	u	N/R	N			N			
3000 GARFIELD	N/A	N	Y	1960	1960	Visual Inspection	U	C	G	GRR	u	N/R	N			N			
3001 GARFIELD	N/A	N	Y	1965		CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N			
3004 GARFIELD	N/A	N	Y	1960	1960	Visual Inspection	U	C	G	GRR	u	N/R	N			N			
812 GRANT	N/A	N	Y	1956	1956	Visual Inspection	U	C	G	GRR	u	N/R	N			N			
813 GRANT	N/A	N	Y	1961		CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N			
816 GRANT	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N			
820 GRANT	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N			
821 GRANT	N/A	N	Y	1965	1965	Visual Inspection	U	C	C	NL	u	N/R	N			N			
900 GRANT	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	c	NL	u	N/R	N			N			
904 GRANT	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N			
905 GRANT	N/A	N	Y	1957	1957	Visual Inspection	U	C	PVC	NL	u	N/R	N			N			
908 GRANT	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N			
909 GRANT	N/A	N	Y	1962	1962	Visual Inspection	U	C	C	NL	u	N/R	N			N			
1800 GRANT	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N			
1801 GRANT	N/A	N	Y	1938	1938	Visual Inspection	U	C	G	GRR	u	N/R	N			N			
1804 GRANT	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N			
1805 GRANT	N/A	N	Y	1952	1952	Visual Inspection	U	C	C	NL	u	N/R	N			N			
1809 GRANT	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N			
1812 GRANT	N/A	N	Y	1937	1937	Visual Inspection	U	C	P	NL	u	N/R	N			N			
1813 GRANT	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N			
1816 GRANT	N/A	N	Y	1952	1952	Visual Inspection	U	C	G	GRR	u	N/R	N			N			
1817 GRANT	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N			
1820 GRANT	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N			
1821 GRANT	N/A	N	Y	1983	1983	Visual Inspection	U	C	P	NL	u	N/R	N			N			
1824 GRANT	N/A	N	Y	1984	1984	Visual Inspection	U	C	P	NL	u	N/R	N			N			
1825 GRANT	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N			
2300 GRANT	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N			
2301 GRANT	N/A	N	Y	1984	1984	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N			
2304 GRANT	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N			
2312 GRANT	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N			
2316 GRANT	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N			
2317 GRANT	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N			
2324 GRANT	N/A	N	Y	1990	1990	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N			
2325 GRANT	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N			
3320 GRANT	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N			
3321 GRANT	LC3T047	N	Y	1980	1980	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N			
3500 GRANT	N/A	N	Y	1978	1978	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N			
26 GREENBRIAR	N/A	N	Y	2005	2005	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N			
27 GREENBRIAR	N/A	N	Y	2006	2006	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N			
34 GREENBRIAR	N/A	N	Y	1997		MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N			
34 GREENBRIAR	N/A	N	Y	2005	2005	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N			
GREENBRIAR DR APT 5	N/A	N	Y	2005	2005	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N			
1 GREENBRIAR DR	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N			

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Plastic - PVC, HDPE, PEX (P)							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
3 GREENBRIAR DR	N/A	N	Y	1984	1984	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
4 GREENBRIAR DR	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
6 GREENBRIAR DR APT 2	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
8 GREENBRIAR DR APT A	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
8 GREENBRIAR DR APT B	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
9 GREENBRIAR DR	N/A	N	Y	1989	1989	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
11 GREENBRIAR DR	N/A	N	Y	1996	1996	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
13 GREENBRIAR DR	N/A	N	Y	1987	1987	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
15 GREENBRIAR DR	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
16 GREENBRIAR DR	N/A	N	Y	1989	1989	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
17 GREENBRIAR DR	N/A	N	Y	1984	1984	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N						
18 GREENBRIAR DR	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
20 GREENBRIAR DR	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
21 GREENBRIAR DR	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
22 GREENBRIAR DR	N/A	N	Y	1989	1989	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N						
23 GREENBRIAR DR	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
24 GREENBRIAR DR	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
28 GREENBRIAR DR	N/A	N	Y	1989	1989	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
29 GREENBRIAR DR	N/A	N	Y	1992	1992	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
30 GREENBRIAR DR	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
31 GREENBRIAR DR	N/A	N	Y	1990	1990	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
32 GREENBRIAR DR	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
33 GREENBRIAR DR	N/A	N	Y	1999	1999	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
36 GREENBRIAR DR	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
36 GREENBRIAR DR SPRNK	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
6 GREENBRIAR DR APT 1	N/A	N	Y	1995	1995	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
12 GREENBRIAR DR APT 1	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
12 GREENBRIAR DR APT 2 A	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
12 GREENBRIAR DR APT 3 A	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
12 GREENBRIAR DR APT 4	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
12 GREENBRIAR DR APT 5 A	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
12 GREENBRIAR DR APT 6 A	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1013 HARRISON	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N						
905 HAYES	N/A	N	Y	1965	1965	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
3100 HAYES	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
3120 HAYES	N/A	N	Y	1970	1970	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
3121 HAYES	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
3200 HAYES	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
3201 HAYES	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N						
3204 HAYES	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
3209 HAYES	N/A	N	Y	1977	1977	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N						
3212 HAYES	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
3215 HAYES	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
3216 HAYES	N/A	N	Y	1977	1977	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
3217 HAYES	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)																
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
3220 HAYES	N/A	N	Y	1978	1978	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
3221 HAYES	N/A	N	Y	1969	1969	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
204 HICKORY LN	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
208 HICKORY LN	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
209 HICKORY LN	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
212 HICKORY LN	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
213 HICKORY LN	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
216 HICKORY LN	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
217 HICKORY LN	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
220 HICKORY LN	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
224 HICKORY LN	N/A	N	Y	1957	1957	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
228 HICKORY LN	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
300 HICKORY LN	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
301 HICKORY LN	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
304 HICKORY LN	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
305 HICKORY LN	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
308 HICKORY LN	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
309 HICKORY LN	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
312 HICKORY LN	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
313 HICKORY LN	N/A	N	Y	1969	1969	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
316 HICKORY LN	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
317 HICKORY LN	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
320 HICKORY LN	N/A	N	Y	1972	1972	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
321 HICKORY LN	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
324 HICKORY LN	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
400 HICKORY LN	N/A	N	Y	1972	1972	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N		
401 HICKORY LN	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
404 HICKORY LN	N/A	N	Y	1998	1998	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
405 HICKORY LN	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
408 HICKORY LN	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
409 HICKORY LN	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
412 HICKORY LN	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
413 HICKORY LN	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
416 HICKORY LN	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
417 HICKORY LN	N/A	N	Y	1995	1995	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
420 HICKORY LN	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
421 HICKORY LN	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
500 HICKORY LN	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
501 HICKORY LN	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
504 HICKORY LN	N/A	N	Y	1993	1993	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
505 HICKORY LN	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
508 HICKORY LN	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
512 HICKORY LN	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
516 HICKORY LN	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
10129 HIGHWAY 45	N/A	N	Y	1976	1976	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
200 HILLCREST	N/A	N	Y	1976	1976	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
201 HILLCREST	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N						
204 HILLCREST	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
205 HILLCREST	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
208 HILLCREST	N/A	N	Y	1966	1966	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
209 HILLCREST	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
212 HILLCREST	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
216 HILLCREST	N/A	N	Y	1974	1974	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N						
220 HILLCREST	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
300 HILLCREST	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
304 HILLCREST	N/A	N	Y	1959	1959	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N						
308 HILLCREST	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
312 HILLCREST	N/A	N	Y	1971	1971	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
316 HILLCREST	N/A	N	Y	1972	1972	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N						
200 HOLIDAY ROAD	N/A	N	Y	2008	2008	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
120 ILLINOIS	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
121 ILLINOIS	N/A	N	Y	1965	1965	Maintenance Records/VISU	U	C	C	NL	u					N						
200 ILLINOIS	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
201 ILLINOIS	N/A	N	Y	1963	1963	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
203 ILLINOIS	N/A	N	Y	1959	1959	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
204 ILLINOIS	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
207 ILLINOIS	N/A	N	Y	1963	1963	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
208 ILLINOIS	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
211 ILLINOIS	N/A	N	Y	1963	1963	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N						
215 ILLINOIS	N/A	N	Y	1963	1963	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
219 ILLINOIS	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
300 ILLINOIS	N/A	N	Y	1957	1957	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
301 ILLINOIS	N/A	N	Y	1957	1957	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
303 ILLINOIS	N/A	N	Y	1959	1959	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
305 ILLINOIS	N/A	N	Y	1958	1958	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
309 ILLINOIS	N/A	N	Y	1958	1958	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
307 ILLINOIS	N/A	N	Y	1958	1958	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
310 ILLINOIS	N/A	N	Y	1959	1959	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
311 ILLINOIS	N/A	N	Y	1959	1959	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
314 ILLINOIS	N/A	N	Y	1962	1962	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
315 ILLINOIS	N/A	N	Y	1962	1962	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
318 ILLINOIS	N/A	N	Y	1963	1963	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
319 ILLINOIS	N/A	N	Y	1966	1966	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
320 ILLINOIS	N/A	N	Y	1966	1966	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
321 ILLINOIS	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
324 ILLINOIS	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
325 ILLINOIS	N/A	N	Y	1955	1955	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
326 ILLINOIS	N/A	N	Y	1962	1962	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
328 ILLINOIS	N/A	N	Y	1962	1962	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
329 ILLINOIS	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Cast/Ductile Iron or Transite (Q)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (Q)							
							Lead (L)	Lead (L)	Lead (L)													
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)													
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
404 ILLINOIS	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
405 ILLINOIS	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
408 ILLINOIS	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
409 ILLINOIS	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
412 ILLINOIS	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
413 ILLINOIS	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
416 ILLINOIS	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
417 ILLINOIS	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
420 ILLINOIS	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
421 ILLINOIS	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
424 ILLINOIS	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
425 ILLINOIS	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
428 ILLINOIS	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
429 ILLINOIS	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
433 ILLINOIS	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
437 ILLINOIS	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
500 ILLINOIS	N/A	N	Y	1951	1951	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N						
501 ILLINOIS	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
505 ILLINOIS	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
520 ILLINOIS	N/A	N	Y	1950	1950	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N						
521 ILLINOIS	N/A	N	Y	1950	1950	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N						
600 ILLINOIS	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
601 ILLINOIS	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
605 ILLINOIS	N/A	N	Y	1951	1951	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
608 ILLINOIS	N/A	N	Y	1950	1950	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
609 ILLINOIS	N/A	N	Y	1951	1951	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N						
612 ILLINOIS	N/A	N	Y	1951	1951	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
613 ILLINOIS	N/A	N	Y	1950	1950	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
616 ILLINOIS	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
617 ILLINOIS	N/A	N	Y	1951	1951	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
620 ILLINOIS	N/A	N	Y	1950	1950	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
621 ILLINOIS	N/A	N	Y	1950	1950	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
624 ILLINOIS	N/A	N	Y	1950	1950	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
625 ILLINOIS	N/A	N	Y	1950	1950	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N						
628 ILLINOIS	N/A	N	Y	1951	1951	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N						
629 ILLINOIS	N/A	N	Y	1951	1951	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
633 ILLINOIS	N/A	N	Y	1951	1951	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N						
637 ILLINOIS	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
400 KELLY	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
401 KELLY	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
404 KELLY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
407 KELLY	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
408 KELLY	N/A	N	Y	1952	1952	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
411 KELLY	N/A	N	Y	1953	1953	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
412 KELLY	N/A	N	Y	1953	1953	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (Q)							
							Cast/Ductile Iron or Transite (Q)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)						Plastic - PVC, HDPE, PEX (P)							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
415 KELLY	N/A	N	Y	1952	1952	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
416 KELLY	N/A	N	Y	1952	1952	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
418 KELLY	N/A	N	Y	1952	1952	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N						
419 KELLY	N/A	N	Y	1953	1953	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
420 KELLY	N/A	N	Y	1953	1953	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
421 KELLY	N/A	N	Y	1952	1952	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N						
1 KENTFIELD	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	c	c	NL	u	N/R	N			N						
2 KENTFIELD	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	c	c	NL	u	N/R	N			N						
3 KENTFIELD	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	c	c	NL	u	N/R	N			N						
4 KENTFIELD	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	c	c	NL	u	N/R	N			N						
5 KENTFIELD	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	c	c	NL	u	N/R	N			N						
6 KENTFIELD	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	c	c	NL	u	N/R	N			N						
5 LAFAYETTE	N/A	N	Y	1996	1996	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
15 LAFAYETTE	N/A	N	Y	2000	2000	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
21 LAFAYETTE	N/A	N	Y	2000	2000	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
65 LAFAYETTE	N/A	N	Y	1940	1940	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N						
69 LAFAYETTE	N/A	N	Y	1940	1940	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
73 LAFAYETTE	N/A	N	Y	1940	1940	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
77 LAFAYETTE	N/A	N	Y	1940	1940	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N						
101 LAFAYETTE	N/A	N	Y	1940	1940	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
111 LAFAYETTE	N/A	N	Y	1969	1969	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
115 LAFAYETTE	N/A	N	Y	1969	1969	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N						
201 LAFAYETTE	LC3T048	N	Y	1956	1956	VISUAL INSPECTION	U	G	C	GRR	u	N/R	N			N						
205 LAFAYETTE	N/A	N	Y	1958	1958	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
303 LAFAYETTE	N/A	N	Y	1958	1958	VISUAL INSPECTION	U	P	C	NL	u	N/R	N			N						
309 LAFAYETTE	N/A	N	Y	1958	1958	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
321 LAFAYETTE	N/A	N	Y	1950	1950	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
400 LAFAYETTE	N/A	N	Y	1969	1969	Maintenance Records	U	C	P	NL	u	N/R	N			N						
403 LAFAYETTE	N/A	N	Y	1950	1950	Maintenance Records	U	C	C	NL	u	N/R	N			N						
404 LAFAYETTE	N/A	N	Y	1950	1950	Maintenance Records	U	C	P	NL	u	N/R	N			N						
405 LAFAYETTE	LC3T029	N	Y	1950	1950	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N						
408 LAFAYETTE	N/A	N	Y	1951	1951	Maintenance Records	U	C	C	NL	u	N/R	N			N						
413 LAFAYETTE	N/A	N	Y	1929	1929	Maintenance Records	U	G	P	GRR	u	N/R	N			N						
420 LAFAYETTE	N/A	N	Y	1950	1950	Maintenance Records	U	C	C	NL	u	N/R	N			N						
500 LAFAYETTE	N/A	N	Y	1950	1950	Maintenance Records	U	C	C	NL	u	N/R	N			N						
504 LAFAYETTE	N/A	N	Y	1950	1950	Maintenance Records	U	C	C	NL	u	N/R	N			N						
509 LAFAYETTE #1	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
509 LAFAYETTE #2	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
509 LAFAYETTE #3	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
509 LAFAYETTE #4	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
509 LAFAYETTE #5	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
509 LAFAYETTE #6	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
509 LAFAYETTE #7	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
509 LAFAYETTE #8	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
509 LAFAYETTE #9	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Cast/Ductile Iron or Transite (O)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
512 LAFAYETTE	N/A	N	Y	1952	1952	Maintenance Records	U	C	C	NL	u	N/R	N			N						
516 LAFAYETTE	N/A	N	Y	1952	1952	VISUAL INSPECTION	U	G	C	GRR	u	N/R	N			N						
600 LAFAYETTE	N/A	N	Y	1982	1982	Maintenance Records	U	C	C	NL	u	N/R	N			N						
604 LAFAYETTE	N/A	N	Y	1915	1915	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
605 LAFAYETTE	N/A	N	Y	1915	1915	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
608 LAFAYETTE	N/A	N	Y	1941	1941	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
609 LAFAYETTE	N/A	N	Y	1941	1941	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
612 LAFAYETTE	N/A	N	Y	1909	1909	Maintenance Records	U	G	G	GRR	u	N/R	N			N						
613 LAFAYETTE	N/A	N	Y	1911	1911	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
616 LAFAYETTE	N/A	N	Y	1911	1911	Maintenance Records	U	G	G	GRR	u	N/R	N			N						
617 LAFAYETTE	N/A	N	Y	1964	1964	Maintenance Records	U	C	C	NL	u	N/R	N			N						
620 LAFAYETTE	N/A	N	Y	1950	1950	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
621 LAFAYETTE	N/A	N	Y	1953	1975	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
700 LAFAYETTE	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
701 LAFAYETTE	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
704 LAFAYETTE	N/A	N	Y	1938	1938	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
705 LAFAYETTE	N/A	N	Y	1912	1912	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
708 LAFAYETTE	N/A	N	Y	1914	1914	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
708 LAFAYETTE 1/2	N/A	N	Y	1914	1914	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
709 LAFAYETTE	N/A	N	Y	1912	1912	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
712 LAFAYETTE	N/A	N	Y	1914	1914	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
716 LAFAYETTE	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
717 LAFAYETTE	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
720 LAFAYETTE	N/A	N	Y	1972	1972	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
721 LAFAYETTE	N/A	N	Y	1939	1939	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
800 LAFAYETTE	N/A	N	Y	1939	1939	Maintenance Records/VISU	U	G	G	GRR	u	N/R	N			N						
801 LAFAYETTE	N/A	N	Y	1915	1915	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
804 LAFAYETTE	N/A	N	Y	1915	1915	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
805 LAFAYETTE	N/A	N	Y	1939	1939	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
808 LAFAYETTE	N/A	N	Y	1915	1915	Maintenance Records/VISU	U	G	P	GRR	u	N/R	N			N						
809 LAFAYETTE	N/A	N	Y	1991	1991	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
812 LAFAYETTE	N/A	N	Y	1945	1945	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
813 LAFAYETTE	N/A	N	Y	1952	1952	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
816 LAFAYETTE	N/A	N	Y	1916	1916	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N						
817 LAFAYETTE	N/A	N	Y	1926	1926	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
820 LAFAYETTE	N/A	N	Y	1942	1942	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
900 LAFAYETTE	N/A	N	Y	1951	1951	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
901 LAFAYETTE	N/A	N	Y	1913	1913	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
904 LAFAYETTE	N/A	N	Y	1951	1951	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
905 LAFAYETTE	N/A	N	Y	1927	1927	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
908 LAFAYETTE	N/A	N	Y	1951	1951	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
909 LAFAYETTE	N/A	N	Y	1910	1910	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
912 LAFAYETTE	N/A	N	Y	1937	1937	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
913 LAFAYETTE	N/A	N	Y	1937	1937	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
916 LAFAYETTE	N/A	N	Y	1937	1937	Maintenance Records/VISU	U	G	G	GRR	u	N/R	N			N						

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Plastic - PVC, HDPE, PEX (P)							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
917 LAFAYETTE	N/A	N	Y	1935	1935	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
920 LAFAYETTE	N/A	N	Y	1935	1935	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N						
921 LAFAYETTE	N/A	N	Y	1935	2010	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
1000 LAFAYETTE	N/A	N	Y	1989	1989	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1001 LAFAYETTE	N/A	N	Y	1989	1989	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1004 LAFAYETTE	N/A	N	Y	1946	1946	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1005 LAFAYETTE	N/A	N	Y	1923	1923	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1009 LAFAYETTE	N/A	N	Y	1911	1911	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
1010 LAFAYETTE	N/A	N	Y	1937	1937	Maintenance Records/VISU	U	G	P	GRR	u	N/R	N			N						
1012 LAFAYETTE	N/A	N	Y	1937	1937	Maintenance Records/VISU	U	G	G	GRR	u	N/R	N			N						
1013 LAFAYETTE	N/A	N	Y	1911	1911	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
1016 LAFAYETTE	N/A	N	Y	1910	1910	Maintenance Records/VISU	U	G	G	GRR	u	N/R	N			N						
1017 LAFAYETTE	N/A	N	Y	1937	1937	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1020 LAFAYETTE	N/A	N	Y	1928	1928	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1100 LAFAYETTE	N/A	N	Y	1986	1986	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1101 LAFAYETTE	N/A	N	Y	1999	1999	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1105 LAFAYETTE	N/A	N	Y	1999	1999	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1108 LAFAYETTE	N/A	N	Y	1965	1965	VISUAL INSPECTION	U	C	C	C	u	N/R	N			N						
1109 LAFAYETTE	N/A	N	Y	1930	1930	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
1112 LAFAYETTE	N/A	N	Y	1921	1921	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N						
1113 LAFAYETTE	N/A	N	Y	1913	1913	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1117 LAFAYETTE	N/A	N	Y	1938	1938	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
1120 LAFAYETTE	N/A	N	Y	1938	1938	Maintenance Records/VISU	U	G	G	GRR	u	N/R	N			N						
1121 LAFAYETTE	DAYCARE012A	N	Y	1917	1917	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N						
1201 LAFAYETTE A	N/A	N	Y	1938	1938	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
1203 LAFAYETTE	N/A	N	Y	1984	1984	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
1204 LAFAYETTE	N/A	N	Y	1947	1947	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1208 LAFAYETTE	N/A	N	Y	1898	1898	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
1211 LAFAYETTE	N/A	N	Y	1986	1986	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1212 LAFAYETTE	N/A	N	Y	2015	2015	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1212 LAFAYETTE 1/2	N/A	N	Y	2015	2015	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1213 LAFAYETTE	N/A	N	Y	1986	1986	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1214 LAFAYETTE	N/A	N	Y	1986	1986	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
1219 LAFAYETTE	N/A	N	Y	1999	1999	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1220 LAFAYETTE	N/A	N	Y	1999	1999	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N						
1221 LAFAYETTE	N/A	N	Y	1978	1978	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1300 LAFAYETTE	N/A	N	Y	1978	1978	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
1304 LAFAYETTE	N/A	N	Y	1906	1906	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
1306 LAFAYETTE	N/A	N	Y	1967	1967	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1309 LAFAYETTE	N/A	N	Y	1989	1989	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
1313 LAFAYETTE	N/A	N	Y	1898	1898	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
1317 LAFAYETTE	N/A	N	Y	1935	1935	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
1321 LAFAYETTE	N/A	N	Y	1899	1899	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1405 LAFAYETTE	N/A	N	Y	1904	1904	Maintenance Records/VISU	U	G	G	GRR	u	N/R	N			N						
1408 LAFAYETTE	N/A	N	Y	1895	1895	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Cast/Ductile Iron or Transite (O)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Plastic - PVC, HDPE, PEX (P)							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
1412 LAFAYETTE	N/A	N	Y	1966	1966	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1413 LAFAYETTE	N/A	N	Y	1964	1964	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1416 LAFAYETTE	N/A	N	Y	1924	1924	Maintenance Records/VISU	U	C	C/P	NL	u	N/R	N			N						
1417 LAFAYETTE	N/A	N	Y	1923	1923	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1420 LAFAYETTE	N/A	N	Y	1987	1987	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1501 LAFAYETTE	N/A	N	Y			VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N						
1509 LAFAYETTE	N/A	N	Y	1966	1966	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1513 LAFAYETTE	N/A	N	Y	1901	1901	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1516 LAFAYETTE	N/A	N	Y	1904	1904	Maintenance Records/VISU	U	G	G	GRR	u	N/R	N			N						
1521 LAFAYETTE	N/A	N	Y	1900	1900	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1600 LAFAYETTE	N/A	N	Y	1951	1951	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
1604 LAFAYETTE	N/A	N	Y	1995	1995	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1608 LAFAYETTE	N/A	N	Y	1898	1898	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1609 LAFAYETTE	N/A	N	Y	1895	1895	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1612 LAFAYETTE	N/A	N	Y	1977	1977	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1613 LAFAYETTE	N/A	N	Y	1901	1901	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1617 LAFAYETTE	N/A	N	Y	1998	1998	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1701 LAFAYETTE	N/A	N	Y	1993	1993	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1705 LAFAYETTE	N/A	N	Y	1948	1948	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1709 LAFAYETTE	N/A	N	Y	1938	1938	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1713 LAFAYETTE	N/A	N	Y	1912	1912	Maintenance Records/VISU	U	G	G	GRR	u	N/R	N			N						
1717 LAFAYETTE	N/A	N	Y	1944	1944	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
2112 LAFAYETTE	N/A	N	Y	1914	1914	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
2116 LAFAYETTE	N/A	N	Y	1913	1913	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N						
2120 LAFAYETTE	N/A	N	Y	2001	2001	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
2305 LAFAYETTE	N/A	N	Y	1995	1995	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
2401 LAFAYETTE	N/A	N	Y	1941	1941	VISUAL INSPECTION	U	G	C	GRR	u	N/R	N			N						
2405 LAFAYETTE	N/A	N	Y	1941	1941	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1421 LAFAYETTE APT 1	N/A	N	Y	1896	1896	Maintenance Records	U	C	C	NL	u	N/R	N			N						
1421 LAFAYETTE APT 2E	N/A	N	Y	1896	1896	Maintenance Records	U	C	C	NL	u	N/R	N			N						
1421 LAFAYETTE APT 3-W	N/A	N	Y	1896	1896	Maintenance Records	U	C	C	NL	u	N/R	N			N						
1 LAFAYETTE AVE	N/A	N	Y	1996	1996	Maintenance Records	U	C	C	NL	u	N/R	N			N						
118 LAFAYETTE AVE EAST	N/A	N	Y	2005	2005	Maintenance Records	U	C	P	NL	u	N/R	N			N						
120 LAFAYETTE AVE EAST	N/A	N	Y	2005	2005	Maintenance Records	U	C	P	NL	u	N/R	N			N						
400 LAFAYETTE AVE EAST	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
401 LAFAYETTE AVE EAST	N/A	N	Y	1971	1971	Maintenance Records	U	C	C	NL	u	N/R	N			N						
411 LAFAYETTE AVE EAST	N/A	N	Y	1974	1974	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
413 LAFAYETTE AVE EAST	N/A	N	Y	1972	1972	Maintenance Records	U	C	C	NL	u	N/R	N			N						
417 LAFAYETTE AVE EAST	N/A	N	Y	1971	1971	Maintenance Records	U	C	C	NL	u	N/R	N			N						
501 LAFAYETTE AVE EAST	N/A	N	Y	1969	1969	Maintenance Records	U	C	C	NL	u	N/R	N			N						
505 LAFAYETTE AVE EAST	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
509 LAFAYETTE AVE EAST	N/A	N	Y	1969	1969	Maintenance Records	U	C	C	NL	u	N/R	N			N						
513 LAFAYETTE AVE EAST	N/A	N	Y	1969	1969	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
1 LAFAYETTE MEADOWS	N/A	N	Y	1996	1996	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N						
2 LAFAYETTE MEADOWS	LC3T049	N	Y	1996	1996	MAINTENANCE RECORDS/C	U	C	G	GRR	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
3 LAFAYETTE MEADOWS	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
4 LAFAYETTE MEADOWS	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	C U	C	P	NL	u	N/R	N			N						
5 LAFAYETTE MEADOWS	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
6 LAFAYETTE MEADOWS	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
7 LAFAYETTE MEADOWS	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	C U	C	P	NL	u	N/R	N			N						
8 LAFAYETTE MEADOWS	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
9 LAFAYETTE MEADOWS	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
10 LAFAYETTE MEADOWS	N/A	N	Y	1995	1995	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
11 LAFAYETTE MEADOWS	N/A	N	Y	1998	1998	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
12 LAFAYETTE MEADOWS	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
13 LAFAYETTE MEADOWS	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
14 LAFAYETTE MEADOWS	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
16 LAFAYETTE MEADOWS	N/A	N	Y	2000	2000	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
17 LAFAYETTE MEADOWS	N/A	N	Y	2002	2002	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
18 LAFAYETTE MEADOWS	N/A	N	Y	1995	1995	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
19 LAFAYETTE MEADOWS	N/A	N	Y	2000	2000	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
20 LAFAYETTE MEADOWS	N/A	N	Y	2011	2011	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
21 LAFAYETTE MEADOWS	N/A	N	Y	2003	2003	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
22 LAFAYETTE MEADOWS	N/A	N	Y	2000	2000	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
23 LAFAYETTE MEADOWS	N/A	N	Y	1996	1996	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
24 LAFAYETTE MEADOWS	N/A	N	Y	2013	2013	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N						
25 LAFAYETTE MEADOWS	N/A	N	Y	1994	1994	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
26 LAFAYETTE MEADOWS APT	N/A	N	Y	1993	1993	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
26 LAFAYETTE MEADOWS APT	N/A	N	Y	1993	1993	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
27 LAFAYETTE MEADOWS APT	N/A	N	Y	1994	1994	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
27 LAFAYETTE MEADOWS APTA	N/A	N	Y	1994	1994	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
28 LAFAYETTE MEADOWS APT	N/A	N	Y	1994	1994	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
28 LAFAYETTE MEADOWS APT	N/A	N	Y	1994	1994	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N						
416 LAKE LAND	N/A	N	Y	1999	1999	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
524 LAKE LAND	N/A	N	Y	1999	1999	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
601 LAKE LAND	N/A	N	Y	1999	1999	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
620 LAKE LAND	N/A	N	Y	1999	1999	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
707 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
713 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
716 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
717 LAKE LAND	N/A	N	Y	1986	1986	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
719 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
721 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
725 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
800 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
804 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
900 LAKE LAND STE A	N/A	N	Y	2015	2015	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
908 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
916 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
920 LAKE LAND	N/A	N	Y	1986	1986	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
1000 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1001 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1009 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1108 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1200 LAKE LAND	N/A	N	Y	1986	2016	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
1204 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1208 LAKE LAND	N/A	N	Y	1986	1986	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
1212 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1213 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1216 LAKE LAND	N/A	N	Y	1986	1986	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
1217 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1221 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1301 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1305 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1309 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1518 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2820 LAKE LAND	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
716 LAKE LAND 1/2	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1300 LAKE LAND BLVD	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N						
1500 LAKE LAND BLVD #5	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2001 LAKER 10	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2001 LAKER 11	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2001 LAKER 12	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2001 LAKER APT 1	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2001 LAKER APT 2	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2001 LAKER APT 3	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2001 LAKER APT 4	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2001 LAKER APT 5	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2001 LAKER APT 6	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2001 LAKER APT 7	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2001 LAKER APT 8	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2001 LAKER APT 9	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2011 LAKER 10	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2011 LAKER 11	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2011 LAKER 12	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2011 LAKER APT 1	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2011 LAKER APT 2	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2011 LAKER APT 3	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2011 LAKER APT 4	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2011 LAKER APT 5	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2011 LAKER APT 6	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2011 LAKER APT 7	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2011 LAKER APT 8	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2011 LAKER APT 9	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2021 LAKER 10	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Leave blank if no Lead							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)													
2021 LAKER 11	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2021 LAKER 12	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2021 LAKER APT 1	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2021 LAKER APT 2	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2021 LAKER APT 3	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2021 LAKER APT 4	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2021 LAKER APT 5	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2021 LAKER APT 6	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2021 LAKER APT 7	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2021 LAKER APT 8	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2021 LAKER APT 9	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2101 LAKER 10	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2101 LAKER 11	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2101 LAKER 12	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2101 LAKER APT 1	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2101 LAKER APT 2	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2101 LAKER APT 3	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2101 LAKER APT 4	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2101 LAKER APT 5	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2101 LAKER APT 6	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2101 LAKER APT 7	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2101 LAKER APT 8	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2101 LAKER APT 9	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2111 LAKER 10	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2111 LAKER 11	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2111 LAKER 12	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2111 LAKER APT 1	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2111 LAKER APT 2	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2111 LAKER APT 3	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2111 LAKER APT 4	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2111 LAKER APT 5	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2111 LAKER APT 6	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2111 LAKER APT 7	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2111 LAKER APT 8	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2111 LAKER APT 9	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2121 LAKER 10	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2121 LAKER 11	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2121 LAKER 12	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2121 LAKER APT 1	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2121 LAKER APT 2	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2121 LAKER APT 3	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2121 LAKER APT 4	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2121 LAKER APT 5	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2121 LAKER APT 6	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2121 LAKER APT 7	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:								
Total Service Lines - Residential - 7021/Commercial - 991																				
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property			
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)										
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Galvanized (G)					
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Plastic - PVC, HDPE, PEX (P)					
							Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Leave blank if no Lead					
							Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)											
							Unknown (U)													
2121 LAKER APT 8	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N				
2121 LAKER APT 9	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N				
700 LINCOLN	N/A	N	Y	1953	1994	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N				
701 LINCOLN	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N				
704 LINCOLN	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N				
708 LINCOLN	N/A	N	Y	1943	1943	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N				
709 LINCOLN	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N				
712 LINCOLN	N/A	N	Y	1941	1990	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N				
713 LINCOLN	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N				
720 LINCOLN	N/A	N	Y	1943	1943	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N				
721 LINCOLN	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N				
725 LINCOLN	N/A	N	Y	1954	1954	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N				
729 LINCOLN	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N				
800 LINCOLN	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N				
801 LINCOLN	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N				
804 LINCOLN	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N				
805 LINCOLN	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N				
808 LINCOLN	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N				
812 LINCOLN	N/A	N	Y	2004	2004	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N				
813 LINCOLN	LC3T050	N	Y	1948	1948	CUSTOMER SURVEY	U	G	G	GRR	u	N/R	N			N				
816 LINCOLN	N/A	N	Y	1939	1939	Visual Inspection	U	C	P	NL	u	N/R	N			N				
304 LINDEN LN	N/A	N	Y	1986	1986	Visual Inspection	U	C	C	NL	u	N/R	N			N				
305 LINDEN LN	N/A	N	Y	1962	1962	Visual Inspection	U	C	C	NL	u	N/R	N			N				
308 LINDEN LN	N/A	N	Y	1961	1961	Visual Inspection	U	C	C	NL	u	N/R	N			N				
309 LINDEN LN	N/A	N	Y	1960	1960	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N				
312 LINDEN LN	N/A	N	Y	1966	1966	Visual Inspection	U	C	C	NL	u	N/R	N			N				
313 LINDEN LN	N/A	N	Y	1964	1964	Visual Inspection	U	C	P	NL	u	N/R	N			N				
316 LINDEN LN	N/A	N	Y	1964	1964	Visual Inspection	U	C	P	NL	u	N/R	N			N				
317 LINDEN LN	N/A	N	Y	1964	1964	Visual Inspection	U	C	C	NL	u	N/R	N			N				
320 LINDEN LN	N/A	N	Y	1963	1963	Visual Inspection	U	C	C	NL	u	N/R	N			N				
321 LINDEN LN	N/A	N	Y	1972	1972	Visual Inspection	U	C	C	NL	u	N/R	N			N				
324 LINDEN LN	N/A	N	Y	1968	1968	Visual Inspection	U	C	C	NL	u	N/R	N			N				
325 LINDEN LN	N/A	N	Y	1968	1968	Visual Inspection	U	C	C	NL	u	N/R	N			N				
328 LINDEN LN	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N				
332 LINDEN LN	N/A	N	Y	1973	1973	Visual Inspection	U	C	C	NL	u	N/R	N			N				
400 LINDEN LN	N/A	N	Y	1969	1969	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N				
401 LINDEN LN	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N				
405 LINDEN LN	N/A	N	Y	1972	1972	Visual Inspection	U	C	C	NL	u	N/R	N			N				
2 MANOR LN	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N				
3 MANOR LN	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N				
5 MANOR LN	N/A	N	Y	1981	1981	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N				
6 MANOR LN	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N				
7 MANOR LN	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N				
8 MANOR LN	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N				
9 MANOR LN	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N				

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Leave blank if no Lead							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)													
10 MANOR LN	N/A	N	Y	1972	1972	MAINTENANCE RECORDS/C	U	C	G	GRR	u	N/R	N			N						
11 MANOR LN	N/A	N	Y	1971	1971	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N						
12 MANOR LN	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
13 MANOR LN	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
14 MANOR LN	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
15 MANOR LN	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1301 MAPLE	N/A	N	Y	2011	2011	MAINTENANCE RECORDS/V	U	P	C	NL	u	N/R	N			N						
1305 MAPLE	N/A	N	Y	2011	2011	MAINTENANCE RECORDS/V	U	P	C	NL	u	N/R	N			N						
1309 MAPLE	N/A	N	Y	2011	2011	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N						
1316 MAPLE	N/A	N	Y	1952	1952	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N						
1812 MAPLE	N/A	N	Y	1923	1944	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1816 MAPLE	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1817 MAPLE	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1820 MAPLE	N/A	N	Y	1944	1944	Visual Inspection	U	G	G	GRR	u	N/R	N			N						
1821 MAPLE	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1824 MAPLE	N/A	N	Y	1902	1902	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1825 MAPLE	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1826 Maple	N/A	N	Y	1902	1902	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1828 MAPLE	N/A	N	Y	1944	1944	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N						
1829 MAPLE	N/A	N	Y	2007	2007	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2016 MAPLE	N/A	N	Y	1944	1944	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2020 MAPLE	N/A	N	Y	1944	1944	Visual Inspection	U	C	C	NL	u	N/R	N			N						
608 MARION	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
609 MARION	N/A	N	Y	1955	1955	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N						
612 MARION	N/A	N	Y	1987	1987	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N						
616 MARION	N/A	N	Y	1950	1950	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N						
620 MARION	N/A	N	Y	1926	1926	MAINTENANCE RECORDS/V	U	G	G	GRR	u	N/R	N			N						
621 MARION	N/A	N	Y	1949	1949	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
700 MARION	N/A	N	Y	1953	1953	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
701 MARION	N/A	N	Y	1897	1897	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N						
704 MARION	N/A	N	Y	1944	1944	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N						
705 MARION	N/A	N	Y	1940	1940	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N						
708 MARION	N/A	N	Y	1940	1940	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N						
712 MARION	N/A	N	Y	1943	1943	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
713 MARION	N/A	N	Y	1945	1945	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
717 MARION	N/A	N	Y	1940	1940	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N						
720 MARION	N/A	N	Y	1953	1953	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
721 MARION	N/A	N	Y	1939	1939	MAINTENANCE RECORDS/V	U	G	P	GRR	u	N/R	N			N						
800 MARION	N/A	N	Y	1917	1917	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N						
801 MARION	N/A	N	Y	1949	1949	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
804 MARION	N/A	N	Y	2015	2015	MAINTENANCE RECORDS/V	U	CTS	C	NL	u	N/R	N			N						
805 MARION	N/A	N	Y	1949	1949	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N						
808 MARION	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
809 MARION	N/A	N	Y	1939	1939	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N						
812 MARION	N/A	N	Y	1946	1946	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Plastic - PVC, HDPE, PEX (P)							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
813 MARION	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
817 MARION	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	N U	C	P	NL	u	N/R	N			N						
820 MARION	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	N U	C	P	NL	u	N/R	N			N						
1408 MARION	N/A	N	Y	1969	1969	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
1608 MARION	N/A	N	Y	1908	1908	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1612 MARION	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1613 MARION	N/A	N	Y	1928	1928	CUSTOMER SURVEY	U	G	P	NL	u	N/R	N			N						
1704 MARION	N/A	N	Y	1913	1913	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1708 MARION	N/A	N	Y	1912	1912	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1712 MARION	N/A	N	Y	1934	1934	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1804 MARION	N/A	N	Y	1946	1946	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
1816 MARION 1/2	N/A	N	Y	1946	1946	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1820 MARION	N/A	N	Y	1947	1947	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1908 MARION	N/A	N	Y	2000	2000	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2101 MARION	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2104 MARION	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2108 MARION	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2109 MARION	N/A	N	Y	1948	1948	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2117 MARION	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2120 MARION	N/A	N	Y	1912	1912	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2121 MARION	N/A	N	Y	1958	1958	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2200 MARION	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2204 MARION	N/A	N	Y	1947	1947	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N						
2205 MARION	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2212 MARION	LC3T013	N	Y	1945	1945	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N						
2213 MARION	N/A	N	Y	1994	1994	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2216 MARION	N/A	N	Y	1940	1940	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
2217 MARION	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2220 MARION	N/A	N	Y	1941	1941	Visual Inspection	U	G	G	GRR	u	N/R	N			N						
2300 MARION	N/A	N	Y	1928	1928	Visual Inspection	U	G	G	GRR	u	N/R	N			N						
2301 MARION	N/A	N	Y	1927	1927	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
2304 MARION	N/A	N	Y	1927	1927	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2305 MARION	N/A	N	Y	1927	1927	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2308 MARION	N/A	N	Y	1927	1927	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2309 MARION	N/A	N	Y	1927	1927	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
2312 MARION	N/A	N	Y	1927	1927	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2313 MARION	N/A	N	Y	1927	1927	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2316 MARION	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2317 MARION	N/A	N	Y	1927	1927	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2320 MARION	N/A	N	Y	1937	1937	Visual Inspection	U	P	G	GRR	u	N/R	N			N						
2321 MARION	N/A	N	Y	1927	1927	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2400 MARION	N/A	N	Y	1896	1896	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
2401 MARION	N/A	N	Y	1925	1925	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2404 MARION	N/A	N	Y	1937	1937	Visual Inspection/CUSTOMER SURVEY	U	G	C	GRR	u	N/R	N			N						
2405 MARION	N/A	N	Y	1921	1921	Visual Inspection	U	C	G	GRR	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Cast/Ductile Iron or Transite (Q)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (Q)							
							Lead (L)	Lead (L)	Lead (L)													
							Cast/Ductile Iron or Transite (Q)	Lead (L)	Lead (L)													
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)													
							Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)													
							Unknown (U)								Leave blank if no Lead							
2408 MARION	N/A	N	Y	1937	1937	Visual Inspection	U	G	G	GRR	u	N/R	N			N						
2409 MARION	N/A	N	Y	1926	1926	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2412 MARION	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2413 MARION	N/A	N	Y	1919	1919	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2416 MARION	N/A	N	Y	1983	1983	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2420 MARION	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2500 MARION	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2501 MARION	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2509 MARION	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2513 MARION	N/A	N	Y	1966	1966	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2517 MARION	N/A	N	Y	1949	1949	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2521 MARION	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2600 MARION	N/A	N	Y	1947	1947	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2601 MARION	N/A	N	Y	1936	1936	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2604 MARION	N/A	N	Y	1896	1896	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N						
2608 MARION	N/A	N	Y	1927	1927	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
2612 MARION	N/A	N	Y	1934	1934	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
2613 MARION	N/A	N	Y	1930	1930	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2616 MARION	N/A	N	Y	1949	1949	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2617 MARION	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2620 MARION	N/A	N	Y	1930	1930	Visual Inspection	U	P	G	GRR	u	N/R	N			N						
2801 MARION	N/A	N	Y	1967	1967	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2805 MARION	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2809 MARION	N/A	N	Y	1970	1970	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2817 MARION	N/A	N	Y	1928	1928	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N						
2821 MARION	N/A	N	Y	1987	1987	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
2900 MARION	N/A	N	Y	1945	1945	Visual Inspection	U	G	G	GRR	u	N/R	N			N						
2904 MARION	N/A	N	Y	1925	1925	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2905 MARION	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2908 MARION	N/A	N	Y	1945	1945	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2909 MARION	N/A	N	Y	1930	1930	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2912 MARION	LC3T014	N	Y	1945	1945	Visual Inspection/CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N						
2913 MARION	N/A	N	Y	1938	1938	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N						
2917 MARION	N/A	N	Y	1938	1938	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N						
2921 MARION	N/A	N	Y	1914	1914	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3000 MARION	LC3T061	N	Y	1906	1906	Visual Inspection	U	C	G/P/C	GRR	u	N/R	N			N						
3001 MARION	N/A	N	Y	1957	1957	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
3004 MARION	N/A	N	Y	1957	1957	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3008 MARION	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
3012 MARION	LC3T030	N	Y	1946	1946	Visual Inspection	U	G	G	GRR	u	N/R	N			N						
3016 MARION	N/A	N	Y	1965	1965	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
3020 MARION	N/A	N	Y	1850	1850	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
3100 MARION	N/A	N	Y	1944	1944	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
3104 MARION	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3105 MARION	N/A	N	Y	1946	1946	Visual Inspection	U	C	G	GRR	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
3108 MARION	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3109 MARION	N/A	N	Y	1958	1958	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3112 MARION	N/A	N	Y	1946	1946	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3113 MARION	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3116 MARION	LC3T057	N	Y	1946	1946	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
3117 MARION	N/A	N	Y	1821	1821	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3120 MARION	N/A	N	Y	1926	1926	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3121 MARION	N/A	N	Y	2016	2016	Visual Inspection	U	P	P	NL	u	N/R	N			N		
3201 MARION	N/A	N	Y	1939	1939	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3204 MARION	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3212 MARION	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3213 MARION	N/A	N	Y	1926	1926	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3216 MARION	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3217 MARION	N/A	N	Y	1942	1942	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3220 MARION	N/A	N	Y	1995	1995	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3224 MARION	N/A	N	Y	1994	1994	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3226 MARION	N/A	N	Y	1994	1994	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3228 MARION	N/A	N	Y	1921	1921	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3300 MARION	N/A	N	Y	1900	1900	CUSTOMER SURVEY	U	C	G/P	GRR	u	N/R	N			N		
3301 MARION	N/A	N	Y	1978	1978	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3304 MARION	N/A	N	Y	1949	1949	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3305 MARION	N/A	N	Y	1921	1921	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3308 MARION	N/A	N	Y	1949	1949	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3309 MARION	N/A	N	Y	1926	1926	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3312 MARION	N/A	N	Y	1932	1932	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3316 MARION	DAYCARE005A	N	Y	1989	1989	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3317 MARION	N/A	N	Y	1926	1926	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3320 MARION	N/A	N	Y	1912	1912	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3321 MARION	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3400 MARION	N/A	N	Y	1955	1955	Visual Inspection/CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
3401 MARION	N/A	N	Y	1926	1926	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3404 MARION	N/A	N	Y	1952	1952	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3408 MARION	N/A	N	Y	1953	1953	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3412 MARION	N/A	N	Y	1952	1952	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3416 MARION	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3420 MARION	N/A	N	Y	1952	1952	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3500 MARION	N/A	N	Y	1947	1947	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3501 MARION	N/A	N	Y	1946	1946	CUSTOMER SURVEY/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3504 MARION	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3505 MARION	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3508 MARION	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3509 MARION	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3512 MARION	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3513 MARION	N/A	N	Y	1975	1975	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3516 MARION	N/A	N	Y	1953	1953	Visual Inspection	U	G	P	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Plastic - PVC, HDPE, PEX (P)							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
3517 MARION	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3520 MARION	N/A	N	Y	1950	1950	Visual Inspection	U	G	G	GRR	u	N/R	N			N						
3521 MARION	N/A	N	Y	1963	1963	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
520 MARION APT 2A	N/A	N	Y	1976	1976	Visual Inspection	U	C	C	NL	u	N/R	N			N						
520 MARION APT A1	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
520 MARION APT B1	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
520 MARION APT B2	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
520 MARION APT C	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
601 MARSHALL	N/A	N	Y	1947	1947	Visual Inspection	U	C	C	NL	u	N/R	N			N						
605 MARSHALL	N/A	N	Y	1946	1946	Visual Inspection	U	C	C	NL	u	N/R	N			N						
608 MARSHALL	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N						
609 MARSHALL	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
612 MARSHALL	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N						
613 MARSHALL	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N						
613 MARSHALL 1/2	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N						
616 MARSHALL	N/A	N	Y	1949	1949	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
617 MARSHALL	N/A	N	Y	1943	1943	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
621 MARSHALL	LC3T051	N	Y	1947	1947	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
700 MARSHALL	N/A	N	Y	1943	1943	Visual Inspection	U	C	P	NL	u	N/R	N			N						
701 MARSHALL	N/A	N	Y	1931	1931	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
704 MARSHALL	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N						
705 MARSHALL	N/A	N	Y	1931	1931	Visual Inspection	U	C	P	NL	u	N/R	N			N						
708 MARSHALL	N/A	N	Y	1936	1936	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
709 MARSHALL	N/A	N	Y	1943	1943	Visual Inspection	U	C	C	NL	u	N/R	N			N						
712 MARSHALL	N/A	N	Y	1942	1942	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N						
713 MARSHALL	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N						
713 MARSHALL 1/2	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N						
716 MARSHALL	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
720 MARSHALL	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N						
800 MARSHALL	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
801 MARSHALL	N/A	N	Y	1921	1921	MAINTENANCE RECORDS	U	P	G	GRR	u	N/R	N			N						
804 MARSHALL	N/A	N	Y	1965	1965	Visual Inspection	U	C	C	NL	u	N/R	N			N						
805 MARSHALL	N/A	N	Y	1930	1930	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
808 MARSHALL	N/A	N	Y	1966	1966	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N						
812 MARSHALL	N/A	N	Y	1943	1943	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
813 MARSHALL	N/A	N	Y	1937	1937	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
817 MARSHALL	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N						
821 MARSHALL	N/A	N	Y	1928	1928	Visual Inspection	U	C	C	NL	u	N/R	N			N						
900 MARSHALL	N/A	N	Y	1939	1939	CUSTOMER SURVEY/VISUAL	U	P	P	NL	u	N/R	N			N						
901 MARSHALL	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
904 MARSHALL	N/A	N	Y	1937	1937	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N						
905 MARSHALL	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
908 MARSHALL	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N						
909 MARSHALL	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
912 MARSHALL	N/A	N	Y	2012	2012	CUSTOMER SURVEY	U	P	G/P	GRR	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
		Leave blank if no Lead																
913 MARSHALL	N/A	N	Y	1916	1916	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
916 MARSHALL	N/A	N	Y	1944	1944	Visual Inspection	U	C	C	NL	u	N/R	N			N		
917 MARSHALL	LC3T015	N	Y	1916	1916	MAINTENANCE RECORDS/C	U	P	G	GRR	u	N/R	N			N		
920 MARSHALL	N/A	N	Y	1915	1915	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
921 MARSHALL	N/A	N	Y	1914	1914	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
1004 MARSHALL	N/A	N	Y	1943	1943	MAINTENANCE RECORDS/V	U	P	P	NL	u	N/R	N			N		
1005 MARSHALL	N/A	N	Y	1909	1909	MAINTENANCE RECORDS/V	U	P	P	NL	u	N/R	N			N		
1008 MARSHALL	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1009 MARSHALL	N/A	N	Y	1922	1922	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1012 MARSHALL	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1016 MARSHALL	N/A	N	Y	1897	1897	MAINTENANCE RECORDS/V	U	P	P	NL	u	N/R	N			N		
1017 MARSHALL	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1020 MARSHALL	N/A	N	Y	1908	1908	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1023 MARSHALL	N/A	N	Y	1986	1986	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
1100 MARSHALL	N/A	N	Y	2025	2025	Visual Inspection	U	P	P	NL	U	N/R	N			N		
1101 MARSHALL	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1103 MARSHALL	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1104 MARSHALL	N/A	N	Y	1947	1947	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1105 MARSHALL	N/A	N	Y	1964	1964	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
1108 MARSHALL	N/A	N	Y	1964	1964	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
1109 MARSHALL	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1112 MARSHALL	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
1113 MARSHALL	N/A	N	Y	1916	1916	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
1116 MARSHALL	N/A	N	Y	1907	1907	MAINTENANCE RECORDS/V	U	P	C	NL	u	N/R	N			N		
1200 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	C	NL	u	N/R	N			N		
1204 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	C	NL	u	N/R	N			N		
1208 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1209 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1212 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1213 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1216 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	C	NL	u	N/R	N			N		
1217 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1220 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1221 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	G	GRR	u	N/R	N			N		
1300 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1301 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1308 MARSHALL	N/A	N	Y	2018	2018	CUSTOMER SURVEY	U	CTS POLY	C	NL	u	N/R	N			N		
1309 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1312 MARSHALL	N/A	N	Y	2018	2018	CUSTOMER SURVEY	U	CTS POLY	P	NL	u	N/R	N			N		
1313 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1317 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1320 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1321 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	CTS POLY	G	GRR	u	N/R	N			N		
1400 MARSHALL	N/A	N	Y	2018	2018	MAINTENANCE RECORDS/V	U	CTS POLY	C	NL	u	N/R	N			N		
1401 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
															Leave blank if no Lead			
1404 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	C	NL	u	N/R	N			N		
1405 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	C	NL	u	N/R	N			N		
1408 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	C	NL	u	N/R	N			N		
1409 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	C	NL	u	N/R	N			N		
1412 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	C	NL	u	N/R	N			N		
1413 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	C	NL	u	N/R	N			N		
1416 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	C	NL	u	N/R	N			N		
1417 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1420 MARSHALL	N/A	N	Y	2020	2020	CUSTOMER SURVEY	U	CTS POLY	C	NL	u	N/R	N			N		
1421 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	C	NL	u	N/R	N			N		
1500 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1501 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1502 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1505 MARSHALL	N/A	N	Y	2020	2020	CUSTOMER SURVEY	U	CTS POLY	G	GRR	u	N/R	N			N		
1509 MARSHALL	N/A	N	Y	2020	2020	CUSTOMER SURVEY	U	CTS POLY	P	NL	u	N/R	N			N		
1513 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	G	GRR	u	N/R	N			N		
1517 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1520 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1521 MARSHALL	N/A	N	Y	2020	2020	MAINTENANCE RECORDS	U	CTS POLY	P	NL	u	N/R	N			N		
1600 MARSHALL	N/A	N	Y	1974	1974	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1604 MARSHALL	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1605 MARSHALL	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1605 MARSHALL 1/2	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
1608 MARSHALL	N/A	N	Y	1920	1920	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1609 MARSHALL	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1612 MARSHALL	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
1613 MARSHALL	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1616 MARSHALL	N/A	N	Y	1944	1944	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1617 MARSHALL	N/A	N	Y	1944	1944	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1620 MARSHALL	N/A	N	Y	1920	1920	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1701 MARSHALL	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
1704 MARSHALL	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1708 MARSHALL	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1709 MARSHALL	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2101 MARSHALL	N/A	N	Y	1912	1912	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2105 MARSHALL	N/A	N	Y	1939	1939	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2109 MARSHALL	N/A	N	Y	2009	2009	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2113 MARSHALL	N/A	N	Y	1922	1922	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2117 MARSHALL	N/A	N	Y	1939	1939	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2201 MARSHALL	N/A	N	Y	1931	1931	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2208 MARSHALL	N/A	N	Y	1914	1914	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2212 MARSHALL	N/A	N	Y	2000	2000	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2216 MARSHALL	N/A	N	Y	1909	1909	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2220 MARSHALL	N/A	N	Y	1915	1915	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
2221 MARSHALL	N/A	N	Y	1922	1922	Visual Inspection	U	C	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Plastic - PVC, HDPE, PEX (P)							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
2301 MARSHALL	N/A	N	Y	1938	1938	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2304 MARSHALL	N/A	N	Y	1941	941	Visual Inspection	U	P	G	GRR	u	N/R	N			N						
2305 MARSHALL	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2309 MARSHALL	N/A	N	Y	1952		Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2312 MARSHALL	N/A	N	Y	1929	1929	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2313 MARSHALL	N/A	N	Y	1896	1896	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2316 MARSHALL	N/A	N	Y	1929		Visual Inspection	U	C	P	NL	u	N/R	N			N						
2317 MARSHALL	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2320 MARSHALL	N/A	N	Y	1997	1997	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2417 MARSHALL	N/A	N	Y	1943	1943	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
2500 MARSHALL	N/A	N	Y	1924	1924	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2501 MARSHALL	N/A	N	Y	2012	2012	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2504 MARSHALL	N/A	N	Y	1929	1929	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2505 MARSHALL	N/A	N	Y	1944	1944	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
2508 MARSHALL	N/A	N	Y	1913	1913	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2509 MARSHALL	N/A	N	Y	1917	1917	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2512 MARSHALL	N/A	N	Y	1946	1946	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2516 MARSHALL	N/A	N	Y	1949	1949	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N						
2517 MARSHALL	N/A	N	Y	1917	1917	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2520 MARSHALL	N/A	N	Y	1963	1963	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2521 MARSHALL	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2600 MARSHALL	N/A	N	Y	1986	1986	Visual Inspection	U	G	G	GRR	u	N/R	N			N						
2601 MARSHALL	N/A	N	Y	1942	1942	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2609 MARSHALL	N/A	N	Y	1922	1922	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2612 MARSHALL	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2613 MARSHALL	N/A	N	Y	2008	2008	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N						
2616 MARSHALL	N/A	N	Y	1935	1935	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
2617 MARSHALL	N/A	N	Y	1929	1929	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
2620 MARSHALL	N/A	N	Y	1914	1914	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2705 MARSHALL	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2708 MARSHALL	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2709 MARSHALL	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2712 MARSHALL	N/A	N	Y	1941	1941	Visual Inspection	U	P	G	GRR	u	N/R	N			N						
2716 MARSHALL	N/A	N	Y	1933	1933	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2720 MARSHALL	N/A	N	Y	1996	1996	Visual Inspection	U	G	G	GRR	u	N/R	N			N						
2801 MARSHALL	N/A	N	Y	1896	1896	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2805 MARSHALL	N/A	N	Y	1989	1989	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2808 MARSHALL	N/A	N	Y	1900	1900	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2809 MARSHALL	N/A	N	Y	1904	1904	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2813 MARSHALL	N/A	N	Y	1904	1904	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2816 MARSHALL	N/A	N	Y	1973	1973	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2817 MARSHALL	N/A	N	Y	2002	2002	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2821 MARSHALL	N/A	N	Y	1900	1900	Visual Inspection	U	P	P	NL	u	N/R	N			N						
3001 MARSHALL	N/A	N	Y	1891	1891	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
3009 MARSHALL	N/A	N	Y	1896	1896	Visual Inspection	U	P	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Plastic - PVC, HDPE, PEX (P)							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
3013 MARSHALL	N/A	N	Y	1906	1906	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3017 MARSHALL	N/A	N	Y	1925	1925	Visual Inspection	U	P	P	NL	u	N/R	N			N						
3021 MARSHALL	N/A	N	Y	1998	1998	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3100 MARSHALL	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3101 MARSHALL	N/A	N	Y	1988	1988	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
3104 MARSHALL	N/A	N	Y	1941	1941	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
3105 MARSHALL	N/A	N	Y	2002	2002	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3108 MARSHALL	N/A	N	Y	1906	1906	Visual Inspection/CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N						
3109 MARSHALL	N/A	N	Y	1929	1929	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
3113 MARSHALL	N/A	N	Y	1943	1943	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N						
3121 MARSHALL	N/A	N	Y	2016	2016	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3200 MARSHALL	N/A	N	Y	1974	1974	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3204 MARSHALL	N/A	N	Y	1936	1936	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
3208 MARSHALL	N/A	N	Y	2005	2005	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3212 MARSHALL	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3216 MARSHALL	N/A	N	Y	1926	1926	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3217 MARSHALL	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3220 MARSHALL	N/A	N	Y	1966	1966	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3221 MARSHALL	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3224 MARSHALL	N/A	N	Y	1944	1944	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3225 MARSHALL	N/A	N	Y	1971	1971	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3235 MARSHALL	N/A	N	Y	1900	1900	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3305 MARSHALL	N/A	N	Y	1924	1924	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3309 MARSHALL	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3313 MARSHALL	N/A	N	Y	1922	1922	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3317 MARSHALL	N/A	N	Y	1922	1922	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
3321 MARSHALL	N/A	N	Y	1943	1943	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
3401 MARSHALL	N/A	N	Y	2009	2009	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
3405 MARSHALL	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3409 MARSHALL	N/A	N	Y	1954	1954	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3501 MARSHALL	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3517 MARSHALL	N/A	N	Y	1987	1987	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3521 MARSHALL	N/A	N	Y	1900	1900	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3601 MARSHALL	N/A	N	Y	1998	1998	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3609 MARSHALL	N/A	N	Y	1900	1900	Visual Inspection	U	P	G	GRR	u	N/R	N			N						
3615 MARSHALL	N/A	N	Y	2006	2006	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3709 MARSHALL	N/A	N	Y	1977	1977	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
3713 MARSHALL	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3717 MARSHALL	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3721 MARSHALL	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2109 MARSHALL B	N/A	N	Y	1881	1881	Visual Inspection	U	G	C	GRR	u	N/R	N			N						
1112 MEADOW BROOK CT	N/A	N	Y	2022	2022	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
1113 MEADOW BROOK CT	N/A	N	Y	2022	2022	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1120 MEADOW BROOK CT	N/A	N	Y	2023	2023	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1201 MEADOW BROOK	N/A	N	Y	2014	2014	Visual Inspection	U	C	C	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
1117 MEADOW BROOK CT	N/A	N	Y	2019	2019	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1 MEADOW LN	N/A	N	Y	1975	1975	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
3 MEADOW LN	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
5 MEADOW LN	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
7 MEADOW LN	N/A	N	Y	1971	1971	Visual Inspection	U	C	P	NL	u	N/R	N			N						
9 MEADOW LN	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1100 MEADOWBROOK CT	N/A	N	Y	2020	2020	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
1116 MEADOWBROOK CT	N/A	N	Y	2019	2019	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1121 MEADOWBROOK CT	N/A	N	Y	2014	2014	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1100 MEADOWVIEW	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1104 MEADOWVIEW	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1105 MEADOWVIEW	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1108 MEADOWVIEW	N/A	N	Y	1998	1998	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1109 MEADOWVIEW	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1112 MEADOWVIEW	N/A	N	Y	1998	1998	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
1113 MEADOWVIEW	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1116 MEADOWVIEW	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1120 MEADOWVIEW	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1121 MEADOWVIEW	N/A	N	Y	1998	1998	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1 MEDINAH CT	N/A	N	Y	2005	2005	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N						
2 MEDINAH CT	N/A	N	Y	1998	1998	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
3 MEDINAH CT	N/A	N	Y	2002	2002	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
16 MEDINAH CT	N/A	N	Y	2005	2005	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
18 MEDINAH CT	N/A	N	Y	1997	1997	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
19 MEDINAH CT	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
100 MELODY LN	N/A	N	Y	1958	1958	Visual Inspection	U	C	C	NL	u	N/R	N			N						
108 MELODY LN	N/A	N	Y	1958	1958	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N						
109 MELODY LN	N/A	N	Y	1960	1960	Visual Inspection	U	C	C	NL	u	N/R	N			N						
200 MELODY LN	N/A	N	Y	1962	1962	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
204 MELODY LN	N/A	N	Y	1964	1964	Visual Inspection	U	C	C	NL	u	N/R	N			N						
205 MELODY LN	N/A	N	Y	1958	1958	Visual Inspection	U	C	C	NL	u	N/R	N			N						
209 MELODY LN	N/A	N	Y	1958	1958	Visual Inspection	U	C	C	NL	u	N/R	N			N						
300 MELODY LN	N/A	N	Y	1950	1950	Visual Inspection	U	C	C	NL	u	N/R	N			N						
301 MELODY LN	N/A	N	Y	1963	1963	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
304 MELODY LN	LC3T031	N	Y	1962	1962	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
305 MELODY LN	N/A	N	Y	1963	1963	Visual Inspection	U	C	P	NL	u	N/R	N			N						
308 MELODY LN	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N						
309 MELODY LN	LC3T016	N	Y	1964	1964	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
312 MELODY LN	N/A	N	Y	1967	1967	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
313 MELODY LN	N/A	N	Y	1964	1964	Visual Inspection	U	C	P	NL	u	N/R	N			N						
317 MELODY LN	N/A	N	Y	1965	1965	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
1 MITCHELL AVE	N/A	N	Y	1978	1978	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2 MITCHELL AVE	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3 MITCHELL AVE	N/A	N	Y	1975	1975	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
4 MITCHELL AVE	N/A	N	Y	1989	1989	Visual Inspection	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
5 MITCHELL AVE	N/A	N	Y	1978	1978	Visual Inspection	U	C	P	NL	u	N/R	N			N						
6 MITCHELL AVE	N/A	N	Y	1980	1980	Visual Inspection	U	C	C	NL	u	N/R	N			N						
7 MITCHELL AVE	N/A	N	Y	1970	1970	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N						
8 MITCHELL AVE	N/A	N	Y	1980	1980	Visual Inspection	U	C	P	NL	u	N/R	N			N						
41 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
47 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
50 MOULTRIE	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
64 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
70 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
72 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
74 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N						
77 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
92 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
94 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
98 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
105 MOULTRIE	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N						
121 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
201 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
208 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
213 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
217 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
301 MOULTRIE	N/A	N	Y	2008	2008	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
308 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
320 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
321 MOULTRIE	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
400 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
401 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
408 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
412 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
420 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
500 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
501 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
516 MOULTRIE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
520 MOULTRIE	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
605 MOULTRIE	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
612 MOULTRIE	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
620 MOULTRIE	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
700 MOULTRIE	N/A	N	Y	1929	1929	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
701 MOULTRIE	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
704 MOULTRIE	N/A	N	Y	1944	1944	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
705 MOULTRIE	N/A	N	Y	1954	1954	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
717 MOULTRIE	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
721 MOULTRIE	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
801 MOULTRIE	N/A	N	Y	1904	1904	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
804 MOULTRIE	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
808 MOULTRIE	N/A	N	Y	1944	1944	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
809 MOULTRIE	N/A	N	Y	1944	1944	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 MOULTRIE	N/A	N	Y	1944	1944	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
813 MOULTRIE	N/A	N	Y	1944	1944	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
816 MOULTRIE	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
820 MOULTRIE	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
821 MOULTRIE	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
900 MOULTRIE	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
901 MOULTRIE	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N						
904 MOULTRIE	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
905 MOULTRIE	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
908 MOULTRIE	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
909 MOULTRIE	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
912 MOULTRIE	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
913 MOULTRIE	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
917 MOULTRIE	N/A	N	Y	1922	1922	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N						
921 MOULTRIE	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1000 MOULTRIE	N/A	N	Y	1941	1941	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1001 MOULTRIE	N/A	N	Y	1945	1945	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1005 MOULTRIE	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1008 MOULTRIE	N/A	N	Y	2015	2015	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N						
1009 MOULTRIE	N/A	N	Y	1957	1957	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N						
1012 MOULTRIE	N/A	N	Y	1941	1941	VISUAL INSPECTION	U	G	C	GRR	u	N/R	N			N						
1013 MOULTRIE	N/A	N	Y	1918	1918	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
1016 MOULTRIE	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1017 MOULTRIE	N/A	N	Y	1911	1911	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1021 MOULTRIE	N/A	N	Y	2009	2009	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1100 MOULTRIE	N/A	N	Y	1931	1931	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1101 MOULTRIE	N/A	N	Y	1931	1931	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1104 MOULTRIE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1108 MOULTRIE	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1112 MOULTRIE	N/A	N	Y	1943	1943	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1113 MOULTRIE	N/A	N	Y	1916	1916	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1116 MOULTRIE	N/A	N	Y	1943	1943	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1201 MOULTRIE	N/A	N	Y	2016	2016	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1300 MOULTRIE	N/A	N	Y			VISUAL INSPECTION	U	P	G	GRR	u	N/R	N			N						
1304 MOULTRIE	N/A	N	Y	1964	1964	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1308 MOULTRIE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1309 MOULTRIE	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1312 MOULTRIE	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1313 MOULTRIE	N/A	N	Y	1966	1966	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1316 MOULTRIE	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N						
1317 MOULTRIE	N/A	N	Y	1966	1966	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N						
1320 MOULTRIE	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1321 MOULTRIE	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Galvanized (G)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Plastic - PVC, HDPE, PEX (P)							
							Cast/Ductile Iron or Transite (Q)	Lead (L)	Lead (L)						Cast/Ductile Iron or Transite (Q)	Leave blank if no Lead						
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)													
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)													
1401 MOULTRIE	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1404 MOULTRIE	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	C U	C	P	NL	u	N/R	N			N						
1408 MOULTRIE	N/A	N	Y	1929	1929	MAINTENANCE RECORDS	C U	C	P	NL	u	N/R	N			N						
1409 MOULTRIE	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	C U	C	C	NL	u	N/R	N			N						
1509 MOULTRIE	N/A	N	Y	1914	1914	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N						
1608 MOULTRIE	N/A	N	Y	1961	1961	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1609 MOULTRIE	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	C U	C	P	NL	u	N/R	N			N						
1610 MOULTRIE	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	C U	C	C	NL	u	N/R	N			N						
1612 MOULTRIE	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	C U	C	P	NL	u	N/R	N			N						
1613 MOULTRIE	N/A	N	Y	1941	1941	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
1616 MOULTRIE	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	C U	C	C	NL	u	N/R	N			N						
1617 MOULTRIE	N/A	N	Y	1896	1896	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1620 MOULTRIE 1/2	N/A	N	Y	1955	1955	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N						
1621 MOULTRIE	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	C U	C	C	NL	u	N/R	N			N						
1700 MOULTRIE	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	C U	C	P	NL	u	N/R	N			N						
1701 MOULTRIE	N/A	N	Y	1991	1991	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N						
1704 MOULTRIE	N/A	N	Y	1956	1956	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1708 MOULTRIE	N/A	N	Y	1946	1946	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N						
1709 MOULTRIE	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	C U	C	P	NL	u	N/R	N			N						
1712 MOULTRIE	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	C U	C	P	NL	u	N/R	N			N						
1713 MOULTRIE	N/A	N	Y	1939	1939	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1716 MOULTRIE	N/A	N	Y	1944	1944	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
1720 MOULTRIE	N/A	N	Y	1931	1931	MAINTENANCE RECORDS	C U	C	G	GRR	u	N/R	N			N						
1800 MOULTRIE	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	C U	C	P	NL	u	N/R	N			N						
1808 MOULTRIE	N/A	N	Y	1896	1896	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N						
1909 MOULTRIE	N/A	N	Y	1926	1926	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1913 MOULTRIE	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2008 MOULTRIE	N/A	N	Y	1937	1937	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N						
2011 MOULTRIE	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
2100 MOULTRIE	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
2104 MOULTRIE	N/A	N	Y	1988	1988	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N						
2108 MOULTRIE	N/A	N	Y	1931	1931	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2112 MOULTRIE	N/A	N	Y	1988	1988	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N						
2116 MOULTRIE	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2212 MOULTRIE	LC3T017	N	Y	1944	1944	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2220 MOULTRIE	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2300 MOULTRIE	N/A	N	Y	1996	1998	Visual Inspection/CUSTOMER	U	C	P	NL	u	N/R	N			N						
2304 MOULTRIE	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2308 MOULTRIE	N/A	N	Y	1974	1974	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
2309 MOULTRIE	N/A	N	Y	1974	1974	Visual Inspection/CUSTOMER	U	C	P	NL	u	N/R	N			N						
2312 MOULTRIE	N/A	N	Y	1910	1910	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2313 MOULTRIE	N/A	N	Y	1974	1974	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2316 MOULTRIE	N/A	N	Y	1917	1917	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
2320 MOULTRIE	N/A	N	Y	1911	1911	Visual Inspection	U	G	G	GRR	u	N/R	N			N						
2321 MOULTRIE	N/A	N	Y	1911	1911	Visual Inspection	U	G	P	GRR	u	N/R	N			N						

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Plastic - PVC, HDPE, PEX (P)							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
2401 MOULTRIE	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2404 MOULTRIE	N/A	N	Y	1925	1925	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2405 MOULTRIE	N/A	N	Y	1923	1923	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2408 MOULTRIE	N/A	N	Y	1931	1931	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2409 MOULTRIE	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2412 MOULTRIE	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2413 MOULTRIE	N/A	N	Y	1923	1923	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2416 MOULTRIE	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2417 MOULTRIE	N/A	N	Y	1923	1923	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2420 MOULTRIE	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2421 MOULTRIE	N/A	N	Y	1935	1935	Visual Inspection	U	G	G	GRR	u	N/R	N			N						
2500 MOULTRIE	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2501 MOULTRIE	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2504 MOULTRIE	N/A	N	Y	1924	1924	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2505 MOULTRIE	N/A	N	Y	1922	1922	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N						
2509 MOULTRIE	N/A	N	Y	1952	1952	Visual Inspection	U	P	C	NL	u	N/R	N			N						
2512 MOULTRIE	N/A	N	Y	1915	1915	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2513 MOULTRIE	N/A	N	Y	1925	1925	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2517 MOULTRIE	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
2520 MOULTRIE	N/A	N	Y	1953	1953	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2521 MOULTRIE	N/A	N	Y	1918	1918	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2600 MOULTRIE	N/A	N	Y	1922	1922	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
2601 MOULTRIE	N/A	N	Y	1941	1941	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
2605 MOULTRIE	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2608 MOULTRIE	N/A	N	Y	1935	1935	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
2609 MOULTRIE	N/A	N	Y	1945	1945	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
2612 MOULTRIE	N/A	N	Y	1913	1913	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2613 MOULTRIE	N/A	N	Y	1913	1913	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2616 MOULTRIE	N/A	N	Y	1977	1977	Visual Inspection/CUSTOMER	U	G	G	GRR	u	N/R	N			N						
2617 MOULTRIE	N/A	N	Y	1943	1943	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2620 MOULTRIE	N/A	N	Y	1913	1913	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2621 MOULTRIE	N/A	N	Y	1928	1928	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
2700 MOULTRIE	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2701 MOULTRIE	N/A	N	Y	1913	1913	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2704 MOULTRIE	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2705 MOULTRIE	N/A	N	Y	1924	1924	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2708 MOULTRIE	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2709 MOULTRIE	N/A	N	Y	1943	1943	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2712 MOULTRIE	N/A	N	Y	1947	1947	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2713 MOULTRIE	N/A	N	Y	1914	1914	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2716 MOULTRIE	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2717 MOULTRIE	N/A	N	Y	1941	1941	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
2720 MOULTRIE	N/A	N	Y	1928	1928	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N						
2721 MOULTRIE	N/A	N	Y	1924	1924	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2800 MOULTRIE	N/A	N	Y	1946	1946	Visual Inspection	U	C	C	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Leave blank if no Lead							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)													
2805 MOULTRIE	N/A	N	Y	1916	1916	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2808 MOULTRIE	N/A	N	Y	1929	2013	CUSTOMER SURVEY/VISUAL	U	G	C/P	GRR	u	N/R	N			N						
2809 MOULTRIE	N/A	N	Y	1896	1896	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
2812 MOULTRIE	N/A	N	Y	1950		Visual Inspection	U	C	P	NL	u	N/R	N			N						
2813 MOULTRIE	N/A	N	Y	1940	1940	Visual Inspection	U	P	G	GRR	u	N/R	N			N						
2817 MOULTRIE	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2821 MOULTRIE	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2900 MOULTRIE	N/A	N	Y	1947	1947	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2901 MOULTRIE	N/A	N	Y	1946	1946	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2904 MOULTRIE	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2905 MOULTRIE	N/A	N	Y	1925	1925	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2908 MOULTRIE	N/A	N	Y	1942	1942	Visual Inspection/CUSTOMER	U	C	P	NL	u	N/R	N			N						
2909 MOULTRIE	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2912 MOULTRIE	N/A	N	Y	1925	1925	Visual Inspection	U	P	G	GRR	u	N/R	N			N						
2913 MOULTRIE	N/A	N	Y	1946	1946	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2916 MOULTRIE	N/A	N	Y	1948	1948	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2917 MOULTRIE	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2920 MOULTRIE	N/A	N	Y	1929	1929	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2921 MOULTRIE	N/A	N	Y	1925	1925	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3000 MOULTRIE	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3004 MOULTRIE	N/A	N	Y	1939	1939	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3005 MOULTRIE	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3008 MOULTRIE	N/A	N	Y	1925	1925	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
3009 MOULTRIE	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3012 MOULTRIE	N/A	N	Y	1925	1925	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
3013 MOULTRIE	N/A	N	Y	1954	1954	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3016 MOULTRIE	N/A	N	Y	1925	1925	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3017 MOULTRIE	N/A	N	Y	1954	1954	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3020 MOULTRIE	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3021 MOULTRIE	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
3100 MOULTRIE	N/A	N	Y	1927	1927	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3101 MOULTRIE	N/A	N	Y	1928	1928	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3104 MOULTRIE	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3105 MOULTRIE	N/A	N	Y	1928	1928	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3108 MOULTRIE	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
3109 MOULTRIE	N/A	N	Y	1928	1928	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N						
3112 MOULTRIE	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
3116 MOULTRIE	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
3120 MOULTRIE	N/A	N	Y	1925	1925	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3121 MOULTRIE	N/A	N	Y	1925	1925	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
3200 MOULTRIE	N/A	N	Y	1954	1954	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3201 MOULTRIE	N/A	N	Y	1951	1951	Visual Inspection/CUSTOMER	U	C	P	NL	u	N/R	N			N						
3208 MOULTRIE	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3212 MOULTRIE	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3213 MOULTRIE	N/A	N	Y	1949	1949	Visual Inspection	U	C	C	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Plastic - PVC, HDPE, PEX (P)							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
3216 MOULTRIE	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3220 MOULTRIE	N/A	N	Y	1945	1945	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3221 MOULTRIE	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3224 MOULTRIE	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
3225 MOULTRIE	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3228 MOULTRIE	N/A	N	Y	1988	1988	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
3229 MOULTRIE	N/A	N	Y	1950	1950	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N						
3232 MOULTRIE	N/A	N	Y	1945	1945	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3233 MOULTRIE	N/A	N	Y	1939	1939	Visual Inspection/CUSTOMER	U	C	G	GRR	u	N/R	N			N						
3301 MOULTRIE	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3305 MOULTRIE	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3309 MOULTRIE	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3315 MOULTRIE	N/A	N	Y	1988	1988	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3319 MOULTRIE	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3323 MOULTRIE	N/A	N	Y	1942	1942	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3324 MOULTRIE	N/A	N	Y	1942	1942	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3327 MOULTRIE	N/A	N	Y	1942	1942	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3330 MOULTRIE	N/A	N	Y	1942	1942	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3331 MOULTRIE	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3334 MOULTRIE	N/A	N	Y	1942	1942	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3335 MOULTRIE	N/A	N	Y	1946	1946	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
3336 MOULTRIE	N/A	N	Y	1987	1987	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3336 MOULTRIE	N/A	N	Y	1987	1987	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
3339 MOULTRIE	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3345 MOULTRIE	N/A	N	Y	1960	1960	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
3400 MOULTRIE	N/A	N	Y	1985	1985	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N						
3406 MOULTRIE	N/A	N	Y	1985	1985	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3412 MOULTRIE	N/A	N	Y	1985	1985	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3418 MOULTRIE	N/A	N	Y	1987	1987	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3424 MOULTRIE	N/A	N	Y	1985	1985	Visual Inspection	U	C	P	NL	u	N/R	N			N						
508 MOULTRIE 1/2	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
1620 MOULTRIE DOWNSTAIRS	N/A	N	Y	1955	1955	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N						
1104 MOULTRIE REAR APT	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
108 N 10TH	N/A	N	Y	1996	1996	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N						
109 N 10TH	N/A	N	Y	1996	1996	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
113 N 10TH	N/A	N	Y	1996	1996	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
117 N 10TH	N/A	N	Y	1996	1996	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
121 N 10TH	N/A	N	Y	1996	1996	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
209 N 10TH	N/A	N	Y	1924	1924	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
212 N 10TH	N/A	N	Y	1978	1978	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
216 N 10TH	N/A	N	Y	1950	1950	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N						
809 N 10TH	N/A	N	Y	1927	1927	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
813 N 10TH	N/A	N	Y	1932	1998	VISUAL INSPECTION/CUSTOMER	U	C	C	NL	u	N/R	N			N						
816 N 10TH	N/A	N	Y	1942	1942	VISUAL INSPECTION/CUSTOMER	U	C	P	NL	u	N/R	N			N						
817 n 16TH	N/A	N	Y	1924	1924	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
820 N 10TH	N/A	N	Y	1964	1964	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
821 N 10TH	N/A	N	Y	1929	1929	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
825 N 10TH	N/A	N	Y	1950	1950	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
900 N 10TH	N/A	N	Y	1944		VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
902 N 10TH	N/A	N	Y	1921	1921	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N						
904 N 10TH	N/A	N	Y	1942	1942	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
905 N 10TH	N/A	N	Y	1958		VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
906 N 10TH	N/A	N	Y	2000	2000	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
909 N 10TH	N/A	N	Y	1925	1925	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
912 N 10TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
913 N 10TH	N/A	N	Y	1924	1924	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
916 N 16TH	N/A	N	Y	1952	1952	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
917 N 10TH	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
920 N 10TH	N/A	N	Y	1955	1955	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
921 N 10TH	N/A	N	Y	1929	1929	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
1000 N 10TH	N/A	N	Y	1937	1937	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N						
1005 N 10TH	N/A	N	Y	1929	1929	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1012 N 10TH	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1013 N 10TH	N/A	N	Y	1954	1954	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
1016 N 10TH	N/A	N	Y	1971	1971	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1017 N 10TH	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1020 N 10TH	N/A	N	Y	1946	1946	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N						
1021 N 10TH	N/A	N	Y	1955	1955	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1100 N 10TH	N/A	N	Y	1946	1946	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N						
1101 N 10TH	N/A	N	Y	1924	1924	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N						
1104 N 10TH	N/A	N	Y	1982	1982	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1108 N 10TH	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1112 N 10TH	N/A	N	Y	1906	1906	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1116 N 10TH	N/A	N	Y	1944	1944	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1117 N 10TH	N/A	N	Y	1951	1951	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N						
1120 N 10TH	N/A	N	Y	1993	1993	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1121 N 10TH	N/A	N	Y	1951	1951	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N						
1200 N 10TH	N/A	N	Y	1946	1946	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N						
1201 N 10TH	LC3T018	N	Y	1916	1916	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N						
1204 N 10TH	N/A	N	Y	2001	2001	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1205 N 10TH	N/A	N	Y	1948	1948	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1208 N 10TH	N/A	N	Y	1951	1951	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1209 N 10TH	N/A	N	Y	1896	1896	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1212 N 10TH	N/A	N	Y	1945	1945	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1216 N 10TH	N/A	N	Y	2000	2000	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1217 N 10TH	N/A	N	Y	1949	1949	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1220 N 10TH	N/A	N	Y	1953	1953	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1221 N 10TH	N/A	N	Y	1948	1948	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
1305 N 10TH	N/A	N	Y	1945	1945	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1308 N 10TH	N/A	N	Y	1986	1986	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)			
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)			
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)			
1309 N 10TH	N/A	N	Y	1993	1993	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1313 N 10TH	N/A	N	Y	2005	2005	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1316 N 10TH	N/A	N	Y	2002	2002	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1321 N 10TH	N/A	N	Y	2003	2003	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1401 N 10TH	N/A	N	Y	1956	1956	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1404 N 10TH	N/A	N	Y	1956	1956	VISUAL INSPECTION/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1408 N 10TH	N/A	N	Y	1956	1956	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
1409 N 10TH	N/A	N	Y	1944	1944	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1413 N 10TH	N/A	N	Y	1956	1956	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1416 N 10TH	N/A	N	Y	1964	1964	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1421 N 10TH	N/A	N	Y	1950	1950	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1501 N 10TH	N/A	N	Y	1991	1991	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1513 N 10TH	N/A	N	Y	1947	1947	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
108 N 11TH	N/A	N	Y	1995	1995	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
112 N 11TH	N/A	N	Y	1995	1995	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
116 N 11TH	N/A	N	Y	1995	1995	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
120 N 11TH	N/A	N	Y	1995	1995	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
209 N 11TH	N/A	N	Y	1910	1910	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
213 N 11TH	N/A	N	Y	1939	1939	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
413 N 11TH	N/A	N	Y	2002	2002	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
712 N 11TH	N/A	N	Y	1965	1965	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
800 N 11TH	N/A	N	Y	1997	1997	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
801 N 11TH	N/A	N	Y	1985	1985	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
804 N 11TH	N/A	N	Y	1905	1905	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
805 N 11TH	N/A	N	Y	1993	1993	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
808 N 11TH	LC3T052	N	Y	1935	1935	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
808 1/2 N 11TH	LC3T058	N	Y			VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
809 N 11TH	N/A	N	Y	1927	1927	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
812 N 11TH	LC3T059	N	Y	1996	1996	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
813 N 11TH	N/A	N	Y	2009	2009	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
816 N 11TH	N/A	N	Y	1962	1962	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
817 N 11TH	N/A	N	Y	1929	1929	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
820 N 11TH	N/A	N	Y	1924	1924	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
821 N 11TH	N/A	N	Y	1993	1993	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
900 N 11TH	N/A	N	Y	1952	1952	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
901 N 11TH	N/A	N	Y	1990	1990	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
905 N 11TH	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
908 N 11TH	N/A	N	Y	1928	1928	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
909 N 11TH	LC3T019	N	Y	1925	1925	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
912 N 11TH	N/A	N	Y	1944	1944	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
913 N 11TH	N/A	N	Y	1984	1984	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
916 N 11TH	N/A	N	Y	1960	1960	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
917 N 11TH	N/A	N	Y	1926	1926	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
920 N 11TH	N/A	N	Y	1999	1999	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		
921 N 11TH	N/A	N	Y	1940	1940	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
1000 N 11TH	N/A	N	Y	1940	1940	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
1001 N 11TH	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N						
1004 N 11TH	N/A	N	Y	1916	1916	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1008 N 11TH	N/A	N	Y	1913	1913	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1009 N 11TH	N/A	N	Y	1926	1926	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1012 N 11TH	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1013 N 11TH	N/A	N	Y	1924	1924	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1016 N 11TH	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1017 N 11TH	N/A	N	Y	1946	1946	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1020 N 11TH	N/A	N	Y	1992	1992	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N						
1021 N 11TH	N/A	N	Y	1967	1967	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1100 N 11TH	N/A	N	Y	1928	1928	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1112 N 11TH	N/A	N	Y	1955	1955	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1120 N 11TH	N/A	N	Y	1992	1992	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1200 N 11TH	N/A	N	Y	1956	1956	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1208 N 11TH	N/A	N	Y	1931	1931	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1212 N 11TH	N/A	N	Y	1931	1931	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N						
1217 N 11TH	N/A	N	Y	1955	1955	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1220 N 11TH	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1300 N 11TH	N/A	N	Y	1959	1959	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N						
1301 N 11TH	N/A	N	Y	1916	1916	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N						
1305 N 11TH	N/A	N	Y	2001	2001	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1308 N 11TH	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N						
1316 N 11TH	N/A	N	Y	1926	1926	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1320 N 11TH	N/A	N	Y	1953	1953	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1400 N 11TH	DAYCARE014A	N	Y	1964	1964	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
1404 N 11TH	N/A	N	Y	1964	1964	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
1420 N 11TH	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
1500 N 11TH	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N						
1504 N 11TH	N/A	N	Y	2012	2012	VISUAL INSPECTION	U	P	C	NL	u	N/R	N			N						
1520 N 11TH	N/A	N	Y	2012	2012	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N						
1305 N 11TH B	N/A	N	Y	1975	1975	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
208 N 12TH	N/A	N	Y	1920	1920	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
308 N 12TH	N/A	N	Y	1908	1908	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
310 N 12TH	N/A	N	Y	1908	1908	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
412 N 12TH	N/A	N	Y	1937	1937	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N						
420 N 12TH	N/A	N	Y	1937	1937	VISUAL INSPECTION	U	g	P	GRR	u	N/R	N			N						
513 N 12TH	N/A	N	Y	1920	1920	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
520 N 12TH	N/A	N	Y	1900	1900	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
709 N 12TH	N/A	N	Y	1856	1856	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
712 N 12TH	N/A	N	Y	1940	1940	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
713 N 12TH	N/A	N	Y	1940	1940	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N						
716 N 12TH	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
717 N 12TH	N/A	N	Y	1945	1945	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
720 N 12TH	N/A	N	Y	1974	1974	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)			
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)			
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)			
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)			
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Leave blank if no Lead			
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)									
721 N 12TH	N/A	N	Y	1946	1946	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
800 N 12TH	N/A	N	Y	1939	1939	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
801 N 12TH	N/A	N	Y	1917	1917	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
804 N 12TH	N/A	N	Y	1940	1940	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
805 N 12TH	N/A	N	Y	2012	2012	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
808 N 12TH	N/A	N	Y	1986	1986	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
809 N 12TH	N/A	N	Y	1922	1922	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
812 N 12TH	N/A	N	Y	1998	1998	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
813 N 12TH	N/A	N	Y	1945	1945	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
817 N 12TH	N/A	N	Y	1918	1918	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
820 N 12TH	N/A	N	Y	1963	1963	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
821 N 12TH	N/A	N	Y	1938	1938	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
900 N 12TH	N/A	N	Y	1952	1952	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
901 N 12TH	N/A	N	Y	1914	1914	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
904 N 12TH	N/A	N	Y	1956	1956	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
905 N 12TH	N/A	N	Y	1968	1968	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
908 N 12TH	N/A	N	Y	1992	1992	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
909 N 12TH	N/A	N	Y	1968	1968	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
912 N 12TH	N/A	N	Y	1992	1992	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
912 N 12TH 1/2	N/A	N	Y	1992	1992	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
916 N 12TH	N/A	N	Y	1992	1992	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
917 N 12TH	N/A	N	Y	1913	1913	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
920 N 12TH	N/A	N	Y	1992	1992	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
921 N 12TH	N/A	N	Y	1928	1928	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
1000 N 12TH	N/A	N	Y	1938	1938	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
1001 N 12TH	N/A	N	Y	1947	1947	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1004 N 12TH	N/A	N	Y	1975	1975	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
1005 N 12TH	N/A	N	Y	1919	1919	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
1008 N 12TH	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1009 N 12TH	N/A	N	Y	1996	1996	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
1012 N 12TH	N/A	N	Y	1938	1938	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
1013 N 12TH	N/A	N	Y	2001	2001	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1016 N 12TH	N/A	N	Y	1939	1939	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
1020 N 12TH	N/A	N	Y	1996	1996	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
509 N 13TH	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N		
712 N 13TH	N/A	N	Y			Visual Inspection	U	C	P	NL	u	N/R	N			N		
801 N 13TH	N/A	N	Y	1940	1940	CUSTOMER SURVEY	U	G	G	GRR	u	N/R	N			N		
804 N 13TH	N/A	N	Y	1939	1939	Visual Inspection	U	C	P	NL	u	N/R	N			N		
808 N 13TH	N/A	N	Y	1975	1975	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
812 N 13TH	N/A	N	Y	1975	1975	Visual Inspection	U	C	P	NL	u	N/R	N			N		
816 N 13TH	N/A	N	Y	1925	1925	Visual Inspection	U	C	P	NL	u	N/R	N			N		
817 N 13TH	N/A	N	Y	1983	1983	Visual Inspection	U	C	P	NL	u	N/R	N			N		
820 N 13TH	N/A	N	Y	1925	1925	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
821 N 13TH	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N		
900 N 13TH	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (Q)							
							Cast/Ductile Iron or Transite (Q)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)						Plastic - PVC, HDPE, PEX (P)							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
901 N 13TH	N/A	N	Y	1929	1929	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
904 N 13TH	N/A	N	Y	1999	1999	Visual Inspection	U	C	P	NL	u	N/R	N			N						
912 N 13TH	N/A	N	Y	1921	1921	Visual Inspection	U	C	P	NL	u	N/R	N			N						
913 N 13TH	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N						
916 N 13TH	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N						
917 N 13TH	N/A	N	Y	1975	1975	Visual Inspection	U	C	P	NL	u	N/R	N			N						
920 N 13TH	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N						
921 N 13TH	N/A	N	Y	1975	1975	Visual Inspection	U	G	C	GRR	u	N/R	N			N						
1000 N 13TH	N/A	N	Y	1975	1975	CUSTOMER SURVEY/VISUAL	U	C	C/P	NL	u	N/R	N			N						
1004 N 13TH	LC3T034	N	Y	1946	1946	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
1008 N 13TH	N/A	N	Y	1926	1926	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1012 N 13TH	N/A	N	Y	1924	1924	Visual Inspection	U	P	P	NL	u	N/R	N			N						
300 N 14TH	N/A	N	Y			Visual Inspection	U	C	G	GRR	u	N/R	N			N						
320 N 15TH	N/A	N	Y	1900	1900	Visual Inspection	U	C	P	NL	u	N/R	N			N						
412 N 15TH	N/A	N	Y	1985	1985	Visual Inspection	U	C	P	NL	u	N/R	N			N						
413 N 15TH	N/A	N	Y	1946	1946	Visual Inspection	U	G	C	NL	u	N/R	N			N						
605 N 15TH	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N						
709 N 15TH	N/A	N	Y	1994	1994	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1108 N 15TH	N/A	N	Y	1927	1927	Visual Inspection	U	C	C	NL	u	N/R	N			N						
301 N 16TH	N/A	N	Y	2002	2002	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N						
309 N 16TH	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N						
312 N 16TH	N/A	N	Y	1929	1929	Visual Inspection	U	C	P	NL	u	N/R	N			N						
317 N 16TH	N/A	N	Y	1891	1891	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
417 N 16TH	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N						
817 N 16TH	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N						
821 N 16TH	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N						
825 N 16TH	N/A	N	Y	1946	1946	Visual Inspection/CUSTOMER	U	C	P	NL	u	N/R	N			N						
900 N 16TH	N/A	N	Y	1998	1998	Visual Inspection	U	C	P	NL	u	N/R	N			N						
900 N 16TH 1/2	N/A	N	Y	1945	1945	Visual Inspection	U	C	P	NL	u	N/R	N			N						
901 N 16TH	N/A	N	Y	1945	1945	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N						
904 N 16TH	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N						
905 N 16TH	N/A	N	Y	1945	1945	Visual Inspection	U	G	G	GRR	u	N/R	N			N						
908 N 16TH	N/A	N	Y	1993	1993	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
916 N 16TH	N/A	N	Y	1947	1947	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
920 N 16TH	N/A	N	Y	1969	1969	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1000 N 16TH	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1004 N 16TH	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1006 N 16TH	N/A	N	Y	1988	1988	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1008 N 16TH	N/A	N	Y	1988	1988	Visual Inspection/CUSTOMER	U	C	C	NL	u	N/R	N			N						
1012 N 16TH	N/A	N	Y	1980	1980	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1016 N 16TH	N/A	N	Y	1946	1946	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1020 N 16TH	N/A	N	Y	1945	1945	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1100 N 16TH	N/A	N	Y	1945	1945	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N						
1104 N 16TH	N/A	N	Y	2002	2002	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1108 N 16TH	N/A	N	Y	200	2002	Visual Inspection	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)			
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)			
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)			
1117 N 16TH	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N		Leave blank if no Lead	N		
1200 N 16TH	N/A	N	Y	2002	2002	Visual Inspection	U	C	P	NL	u	N/R	N			N		
404 N 17TH	N/A	N	Y	1940	1940	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
408 N 17TH	N/A	N	Y	1940	1940	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
412 N 17TH	N/A	N	Y	1911	1911	Visual Inspection	U	C	P	NL	u	N/R	N			N		
420 N 17TH	N/A	N	Y	1935	1935	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
409 N 18TH	N/A	N	Y	1930	1930	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
412 N 18TH	N/A	N	Y	1938	1938	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
418 N 18TH	N/A	N	Y			CUSTOMER SURVEY/VISUAL	U	C	C	NL	u					N		
509 N 18TH	N/A	N	Y	1954	1954	CUSTOMER SURVEY/VISUAL	U	C	C/P	NL	u	N/R	N			N		
513 N 18TH	N/A	N	Y	1985	1985	Visual Inspection	U	C	P	NL	u	N/R	N			N		
517 N 18TH	N/A	N	Y	1992	1992	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
520 N 18TH	N/A	N	Y	1900	1900	Visual Inspection	U	C	P	NL	u	N/R	N			N		
521 N 18TH	LC3T035	N	Y	1923	1923	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
613 N 18TH	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
500 N 19TH	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
504 N 19TH	N/A	N	Y	1934	1934	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N		
508 N 19TH	N/A	N	Y	1933	2023	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
512 N 19TH	N/A	N	Y	1952	1952	Visual Inspection	U	C	C	NL	u	N/R	N			N		
609 N 19TH	N/A	N	Y	1900	1900	Visual Inspection	U	C	C	NL	u	N/R	N			N		
712 N 19TH	N/A	N	Y	1921	1921	Visual Inspection	U	C	P	NL	u	N/R	N			N		
713 N 19TH	N/A	N	Y	1911	1911	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
715 N 19TH	N/A	N	Y	1975	1975	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
716 N 19TH	N/A	N	Y	1922	1922	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
717 N 19TH	N/A	N	Y	1983	1983	Visual Inspection	U	C	P	NL	u	N/R	N			N		
720 N 19TH	N/A	N	Y	1991	1991	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
721 N 19TH	N/A	N	Y	1983	1983	Visual Inspection	U	C	P	NL	u	N/R	N			N		
725 N 19TH	N/A	N	Y	1916	1916	Visual Inspection	U	C	P	NL	u	N/R	N			N		
801 N 19TH	N/A	N	Y	1921	1921	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
805 N 19TH	LC3T020	N	Y	1921	1921	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
808 N 19TH	N/A	N	Y	1993	1993	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
809 N 19TH	N/A	N	Y	1919	1919	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
815 N 19TH	N/A	N	Y	1985	1985	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
820 N 19TH	N/A	N	Y	1951	1951	Visual Inspection	U	C	O	NL	u	N/R	N			N		
821 N 19TH	N/A	N	Y	2008	2008	Visual Inspection	U	C	C	NL	u	N/R	N			N		
901 N 19TH	N/A	N	Y	1917	1917	Visual Inspection	U	C	P	NL	u	N/R	N			N		
902 N 19TH	N/A	N	Y	1922	1922	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
904 N 19TH	N/A	N	Y	1954	1954	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
908 N 19TH	N/A	N	Y	1918	1918	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
916 N 19TH	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N		
917 N 19TH	N/A	N	Y	1993	1993	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
1009 N 19TH	N/A	N	Y	1904	1904	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1015 N 19TH	N/A	N	Y	1917	1917	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
1021 N 19TH	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1105 N 19TH	N/A	N	Y	1995	1995	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)			
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)			
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (Q)			
1107 N 19TH	N/A	N	Y	1960	1960	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
1112 N 19TH	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1304 N 19TH	N/A	N	Y	1993	1993	CUSTOMER SURVEY/VISUAL	U	G	C	GRR	u	N/R	N			N		
1310 N 19TH	N/A	N	Y	1941	1941	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1401 N 19TH	N/A	N	Y	1962	1962	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1402 N 19TH	N/A	N	Y	1900	1900	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1408 N 19TH	N/A	N	Y	1984	1984	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1410 N 19TH	N/A	N	Y	1983	1983	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1412 N 19TH	N/A	N	Y	1961	1961	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
1415 N 19TH	N/A	N	Y	1966	1966	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1417 N 19TH	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1419 N 19TH	N/A	N	Y	1957	1957	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
1420 N 19TH	N/A	N	Y	2011	2011	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1502 N 19TH	N/A	N	Y	1902	1902	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1503 N 19TH	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1512 N 19TH	N/A	N	Y	2016	2016	MAINTENANCE RECORDS/VISUAL	U	P	C	NL	u	N/R	N			N		
1612 N 19TH	N/A	N	Y	1952	1952	Visual Inspection	U	C	C/P	NL	u	N/R	N			N		
1616 N 19TH	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1410 N 19TH UNIT 3	N/A	N	Y	1983	1983	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1412 N 19TH UNIT 4	N/A	N	Y	1983	1983	Visual Inspection	U	C	C	NL	u	N/R	N			N		
205 N 1ST (100 PRAIRIE)	N/A	N	Y	1967	1967	CUSTOMER SURVEY/VISUAL	U	C	C/P	NL	u	N/R	N			N		
221 N 1ST	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N		
313 N 1ST	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N		
316 N 1ST	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N		
317 N 1ST	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
320 N 1ST	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N		
321 N 1ST	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N		
708 N 1ST	N/A	N	Y	1979	1979	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
716 N 1ST	N/A	N	Y	1979	1979	MAINTENANCE RECORDS/VISUAL	U	C	P	NL	u	N/R	N			N		
720 N 1ST	N/A	N	Y	1979	1979	MAINTENANCE RECORDS/VISUAL	U	C	P	NL	u	N/R	N			N		
724 N 1ST	N/A	N	Y	1979	1979	MAINTENANCE RECORDS/VISUAL	U	C	P	NL	u	N/R	N			N		
512 N 1ST DIVISION	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
704 N 1ST DIVISION	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
708 N 1ST DIVISION	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
710 N 1ST DIVISION	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
712 N 1ST DIVISION	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
713 N 1ST DIVISION	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
716 N 1ST DIVISION	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
717 N 1ST DIVISION	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
720 N 1ST DIVISION	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
721 N 1ST DIVISION	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
725 N 1ST DIVISION	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
729 N 1ST DIVISION	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
405 N 20TH	N/A	N	Y	1906	1906	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
408 N 20TH	N/A	N	Y	1961	1961	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (Q)							
409 N 20TH	N/A	N	Y	1916	1995	CUSTOMER SURVEY/VISUAL	U	P	P	NL	u	N/R	N		Leave blank if no Lead	N						
413 N 20TH	N/A	N	Y	1906	1906	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
505 N 20TH	N/A	N	Y	1947	1947	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
600 N 20TH	N/A	N	Y	1954	1954	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
620 N 20TH	N/A	N	Y	1930	1930	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N						
704 N 20TH	N/A	N	Y	1937	1937	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
712 N 20TH	N/A	N	Y	1916	1916	Visual Inspection	U	C	C	NL	u	N/R	N			N						
713 N 20TH	N/A	N	Y	1940	1940	MAINTENANCE RECORDS/C	U	P	C	NL	u	N/R	N			N						
716 N 20TH	N/A	N	Y	1921	1921	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
717 N 20TH	N/A	N	Y	1937	1937	Visual Inspection	U	C	C	NL	u	N/R	N			N						
720 N 20TH	N/A	N	Y	1989	1989	Visual Inspection	U	C	P	NL	u	N/R	N			N						
721 N 20TH	N/A	N	Y	1917	1917	Visual Inspection	U	C	C	NL	u	N/R	N			N						
724 N 20TH	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N						
729 N 20TH	N/A	N	Y	1916	1916	Visual Inspection	U	C	C	NL	u	N/R	N			N						
805 N 20TH	N/A	N	Y	1912	1912	Visual Inspection	U	C	P	NL	u	N/R	N			N						
809 N 20TH	N/A	N	Y	1992	1992	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
813 N 20TH	N/A	N	Y	1917	1917	Visual Inspection	U	C	P	NL	u	N/R	N			N						
817 N 20TH	N/A	N	Y	1950	1950	Visual Inspection	U	C	C	NL	u	N/R	N			N						
820 N 20TH	N/A	N	Y	1976	1976	Visual Inspection	U	C	P	NL	u	N/R	N			N						
821 N 20TH	N/A	N	Y	1917	1917	Visual Inspection	U	C	C	NL	u	N/R	N			N						
901 N 20TH	N/A	N	Y	1950	1950	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
905 N 20TH	N/A	N	Y	1954	1954	Visual Inspection	U	P	P	NL	u	N/R	N			N						
909 N 20TH	N/A	N	Y	1955	1955	Visual Inspection	U	P	P	NL	u	N/R	N			N						
913 N 20TH	N/A	N	Y	1955	2020	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N						
205 N 21ST	N/A	N	Y	1913	1913	Visual Inspection	U	C	C	NL	u	N/R	N			N						
209 N 21ST	N/A	N	Y	1915	1915	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N						
400 N 21ST	N/A	N	Y	1891	1891	Visual Inspection	U	C	C	NL	u	N/R	N			N						
408 N 21ST	N/A	N	Y	1999	1999	Visual Inspection	U	C	C	NL	u	N/R	N			N						
409 N 21ST	N/A	N	Y	1955	1955	Visual Inspection/CUSTOMER	U	G	P	GRR	u	N/R	N			N						
412 N 21ST	N/A	N	Y	1936	1936	Visual Inspection	U	C	C	NL	u	N/R	N			N						
413 N 21ST	N/A	N	Y	1956	1956	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N						
417 N 21ST	N/A	N	Y	1948	1948	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
421 N 21ST	N/A	N	Y	1930	1930	Visual Inspection	U	C	P	NL	u	N/R	N			N						
500 N 21ST	N/A	N	Y	1906	1906	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
501 N 21ST	N/A	N	Y	1947	1947	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
504 N 21ST	N/A	N	Y	1982	1982	Visual Inspection	U	C	P	NL	u	N/R	N			N						
505 N 21ST	N/A	N	Y	1989	1989	Visual Inspection	U	G	G	GRR	u	N/R	N			N						
508 N 21ST	N/A	N	Y	1982	1982	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
509 N 21ST	N/A	N	Y	1913	1913	Visual Inspection	U	C	C	NL	u	N/R	N			N						
512 N 21ST	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N						
513 N 21ST	N/A	N	Y	1966	1966	Visual Inspection	U	C	C	NL	u	N/R	N			N						
516 N 21ST	N/A	N	Y	1992	1992	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N						
520 N 21ST	N/A	N	Y	1886	1886	Visual Inspection	U	C	P	NL	u	N/R	N			N						
521 N 21ST	N/A	N	Y	1900	1900	Visual Inspection	U	C	P	NL	u	N/R	N			N						
604 N 21ST	N/A	N	Y	1953	1953	Visual Inspection	U	C	G	GRR	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)			
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Galvanized (G)			
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Plastic - PVC, HDPE, PEX (P)			
608 N 21ST	N/A	N	Y	1907	1907	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
612 N 21ST	N/A	N	Y	1959	1959	Visual Inspection	U	C	C	NL	u	N/R	N			N		
616 N 21ST	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
620 N 21ST	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
700 N 21ST	N/A	N	Y	1939	1939	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
701 N 21ST	N/A	N	Y	1939	1939	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
705 N 21ST	N/A	N	Y	1929	1929	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
709 N 21ST	N/A	N	Y	2020	2020	Visual Inspection	U	P	G	GRR	u	N/R	N			N		
712 N 21ST	N/A	N	Y	1994	1994	Visual Inspection	U	C	P	NL	u	N/R	N			N		
713 N 21ST	N/A	N	Y	2022	2022	Visual Inspection	U	P	P	NL	u	N/R	N			N		
716 N 21ST	N/A	N	Y	1993	1993	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
717 N 21ST	N/A	N	Y	2022	2022	Visual Inspection	U	P	G	GRR	u	N/R	N			N		
720 N 21ST	N/A	N	Y	1912	1912	Visual Inspection	U	C	P	NL	u	N/R	N			N		
728 N 21ST	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
800 N 21ST	N/A	N	Y	1927	1927	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
801 N 21ST	N/A	N	Y	1924	1924	Visual Inspection	U	C	P	NL	u	N/R	N			N		
804 N 21ST	N/A	N	Y	1945	1945	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
805 N 21ST	N/A	N	Y	2006	2006	Visual Inspection	U	C	P	NL	u	N/R	N			N		
809 N 21ST	N/A	N	Y	1993	1993	Visual Inspection	U	C	C	NL	u	N/R	N			N		
812 N 21ST	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
813 N 21ST	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N		
816 N 21ST	N/A	N	Y	1948	1948	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
817 N 21ST	N/A	N	Y	1969	1969	Visual Inspection	U	C	P	NL	u	N/R	N			N		
820 N 21ST	N/A	N	Y	1949	1949	Visual Inspection	U	C	P	NL	u	N/R	N			N		
900 N 21ST	N/A	N	Y	1951	1951	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
901 N 21ST	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N		
904 N 21ST	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N		
905 N 21ST	N/A	N	Y	1948	1948	CUSTOMER SURVEY/VISUAL	U	P	C/P	NL	u	N/R	N			N		
908 N 21ST	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
909 N 21ST	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N		
912 N 21ST	N/A	N	Y	1954	1954	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N		
921 N 21ST	N/A	N	Y	1941	1941	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
320 N 21ST RECTORY	N/A	CHURCH	Y	2000	2000	Visual Inspection	U	P	G	GRR	u	N/R	N			N		
104 N 22ND	N/A	N	Y	2014	2014	Visual Inspection	U	C	C	NL	u	N/R	N			N		
108 N 22ND	N/A	N	Y	2013	2013	Visual Inspection	U	C	C	NL	u	N/R	N			N		
200 N 22ND	N/A	N	Y	1896	1896	Visual Inspection	U	P	P	NL	u	N/R	N			N		
204 N 22ND	N/A	N	Y	2019	2019	Visual Inspection	U	C	P	NL	u	N/R	N			N		
208 N 22ND	N/A	N	Y	1896	1896	Visual Inspection	U	C	P	NL	u	N/R	N			N		
212 N 22ND	N/A	N	Y	1914	1914	Visual Inspection	U	C	P	NL	u	N/R	N			N		
216 N 22ND	N/A	N	Y	1908	1908	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
220 N 22ND	N/A	N	Y	1896	1896	Visual Inspection	U	C	P	NL	u	N/R	N			N		
300 N 22ND	N/A	N	Y	1974	1974	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
308 N 22ND	N/A	N	Y	1998	1998	Visual Inspection	U	C	P	NL	u	N/R	N			N		
309 N 22ND	N/A	N	Y	1890	1890	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
310 N 22ND	N/A	N	Y	1998	1998	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)			
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)			
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)			
312 N 22ND	N/A	N	Y	1998	1998	Visual Inspection	U	P	P	NL	u	N/R	N			N		
314 N 22ND	N/A	N	Y	1998	1998	Visual Inspection	U	P	P	NL	u	N/R	N			N		
317 N 22ND	N/A	N	Y	2009	2009	Visual Inspection	U	C	P	NL	u	N/R	N			N		
321 N 22ND	N/A	N	Y	2017	2017	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
321 N 22ND APT 2	N/A	N	Y	2017	2017	Visual Inspection	U	C	C	NL	u	N/R	N			N		
401 N 22ND	N/A	N	Y	1976	1976	Visual Inspection	U	C	P	NL	u	N/R	N			N		
404 N 22ND	N/A	N	Y	1924	1924	Visual Inspection	U	P	P	NL	u	N/R	N			N		
405 N 22ND	N/A	N	Y	1919	1919	Visual Inspection	U	C	C	NL	u	N/R	N			N		
408 N 22ND	N/A	N	Y	1913	1913	Visual Inspection	U	C	P	NL	u	N/R	N			N		
409 N 22ND	N/A	N	Y	2001	2001	Visual Inspection	U	C	P	NL	u	N/R	N			N		
412 N 22ND	N/A	N	Y	1971	1971	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
413 N 22ND	N/A	N	Y	2001	2001	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
417 N 22ND	N/A	N	Y	1976	1976	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
420 N 22ND	N/A	N	Y	1881	1881	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
421 N 22ND	N/A	N	Y	1989	1989	Visual Inspection	U	C	P	NL	u	N/R	N			N		
500 N 22ND	N/A	N	Y	1913	1913	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
501 N 22ND	N/A	N	Y	1924	1924	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
504 N 22ND	N/A	N	Y	1911	1911	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
505 N 22ND	N/A	N	Y	1935	1935	Visual Inspection	U	C	P	NL	u	N/R	N			N		
509 N 22ND	N/A	N	Y	1919	1919	Visual Inspection	U	C	C	NL	u	N/R	N			N		
512 N 22ND	N/A	N	Y	1905	1905	Visual Inspection	U	C	P	NL	u	N/R	N			N		
513 N 22ND	N/A	N	Y	1970	1970	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N		
516 N 22ND	N/A	N	Y	1993	1993	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
517 N 22ND	N/A	N	Y	2002	2002	Visual Inspection	U	P	P	NL	u	N/R	N			N		
520 N 22ND	N/A	N	Y	1934	1934	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
521 N 22ND	N/A	N	Y	1925	1925	CUSTOMER SURVEY/VISUAL	U	G	P	GRR	u	N/R	N			N		
601 N 22ND	N/A	N	Y	1924	1924	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
608 N 22ND	N/A	N	Y	1928	1928	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
609 N 22ND	N/A	N	Y	1924	1924	Visual Inspection	U	C	P	NL	u	N/R	N			N		
708 N 22ND	N/A	N	Y	1916	1916	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
711 N 22ND	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N		
712 N 22ND	N/A	N	Y	1927	1927	Visual Inspection	U	C	P	NL	u	N/R	N			N		
716 N 22ND	N/A	N	Y	2002	2002	Visual Inspection	U	C	C	NL	u	N/R	N			N		
720 N 22ND	N/A	N	Y	1916	1916	MAINTENANCE RECORDS/V	U	G	P	GRR	u	N/R	N			N		
803 N 22ND	N/A	N	Y	1945	1945	Visual Inspection	U	C	P	NL	u	N/R	N			N		
804 N 22ND	N/A	N	Y	1925	1925	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
805 N 22ND	N/A	N	Y	1926	1926	Visual Inspection	U	C	P	NL	u	N/R	N			N		
808 N 22ND	N/A	N	Y	1999	1999	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
812 N 22ND	N/A	N	Y	1948	1948	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
816 N 22ND	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N		
820 N 22ND	N/A	N	Y	1972	1972	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
821 N 22ND	N/A	N	Y	1921	1921	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
821 N 22ND 1/2	N/A	N	Y	1921	1921	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
900 N 22ND	N/A	N	Y	1945	1945	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
901 N 22ND	N/A	N	Y	1952	1952	Visual Inspection	U	C	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
903 N 22ND	N/A	N	Y	1952	1952	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N						
905 N 22ND	N/A	N	Y	1929	1929	Visual Inspection/CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N						
920 N 22ND	N/A	N	Y	1919	1919	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N						
615 N 22ND APT A	N/A	N	Y	1940	1940	Visual Inspection	U	C	C	NL	u	N/R	N			N						
717 N 22ND APT A	N/A	N	Y	2011	2011	Visual Inspection	U	C	P	NL	u	N/R	N			N						
721 N 22ND APT A	N/A	N	Y	1965	1965	Visual Inspection	U	C	P	NL	u	N/R	N			N						
615 N 22ND APT B	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N						
717 N 22ND APT B	N/A	N	Y	1965	1965	Visual Inspection	U	C	P	NL	u	N/R	N			N						
721 N 22ND APT B	N/A	N	Y	1965	1965	Visual Inspection	U	C	P	NL	u	N/R	N			N						
615 N 22ND APT C	N/A	N	Y	1940	1940	Visual Inspection	U	C	C	NL	u	N/R	N			N						
308 N 23RD	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N						
312 N 23RD	N/A	N	Y	1945	1945	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
317 N 23RD	N/A	N	Y	1940	1940	CUSTOMER SURVEY/VISUAL	U	C	C/G/P	GRR	u	N/R	N			N						
414 N 23RD	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
509 N 23RD	N/A	N	Y	1943	1943	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
516 N 23RD	N/A	N	Y	1933	1933	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
520 N 23RD	N/A	N	Y	1900	1900	CUSTOMER SURVEY/VISUAL	U	P	P	NL	u	N/R	N			N						
521 N 23RD	N/A	N	Y	1953	1953	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
608 N 23RD	N/A	N	Y	1910	1910	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
612 N 23RD	N/A	N	Y	1900	1900	Visual Inspection	U	C	P	NL	u	N/R	N			N						
620 N 23RD	N/A	N	Y	1960	1960	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
701 N 23RD	N/A	N	Y	1955	1955	CUSTOMER SURVEY/VISUAL	U	G	C	GRR	u	N/R	N			N						
713 N 23RD	N/A	N	Y	1968	1968	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
716 N 23RD	N/A	N	Y	1985	1985	Visual Inspection	U	C	P	NL	u	N/R	N			N						
720 N 23RD	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N						
721 N 23RD	N/A	N	Y	1977	1977	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
724 N 23RD	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N						
728 N 23RD	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N						
800 N 23RD	N/A	N	Y	1980	1980	Visual Inspection	U	C	P	NL	u	N/R	N			N						
804 N 23RD	N/A	N	Y	1973	1973	Visual Inspection	U	C	C	NL	u	N/R	N			N						
805 N 23RD	N/A	N	Y	2000	2000	Visual Inspection	U	C	P	NL	u	N/R	N			N						
808 N 23RD	N/A	N	Y	1973	1973	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N						
809 N 23RD	N/A	N	Y	1978	1978	Visual Inspection	U	C	P	NL	u	N/R	N			N						
813 N 23RD	N/A	N	Y	1976	1976	Visual Inspection	U	C	P	NL	u	N/R	N			N						
816 N 23RD	N/A	N	Y	1987	1987	Visual Inspection	U	C	C	NL	u	N/R	N			N						
112 N 24TH	N/A	N	Y	1881	1881	Visual Inspection	U	P	P	NL	u	N/R	N			N						
401 N 24TH	N/A	N	Y	2010	2010	Visual Inspection	U	C	C	NL	u	N/R	N			N						
405 N 24TH	N/A	N	Y	2010	2010	Visual Inspection	U	C	C	NL	u	N/R	N			N						
513 N 24TH	N/A	N	Y	1950	1950	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
609 N 24TH	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N						
708 N 24TH	N/A	N	Y	1940	1940	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
716 N 24TH	N/A	N	Y	1916	1916	Visual Inspection	U	C	P	NL	u	N/R	N			N						
717 N 24TH	N/A	N	Y	1950	1950	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
720 N 24TH	N/A	N	Y	1900	1900	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N						
721 N 24TH	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)			
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)			
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)			
213 N 25TH	N/A	N	Y	1989	1989	Visual Inspection	U	C	P	NL	u	N/R	N			N		
216 N 25TH	N/A	N	Y	1950	1950	Visual Inspection	U	C	C	NL	u	N/R	N			N		
421 N 25TH	N/A	N	Y	1970	1970	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
709 N 25TH	LC3T021	N	Y	1939	1939	Visual Inspection	U	G	C	GRR	u	N/R	N			N		
712 N 25TH	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
715 N 25TH	N/A	N	Y	1959	1959	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
720 N 25TH	N/A	N	Y	1964	1964	Visual Inspection	U	C	P	NL	u	N/R	N			N		
721 N 25TH	N/A	N	Y	1991	1991	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
105 N 26TH	N/A	N	Y	1941	1941	Visual Inspection	U	C	C	NL	u	N/R	N			N		
112 N 26TH	N/A	N	Y	1949	1949	Visual Inspection/CUSTOMER SURVEY	U	P	G	GRR	u	N/R	N			N		
212 N 26TH	N/A	N	Y	1947	1947	Visual Inspection	U	P	P	NL	u	N/R	N			N		
312 N 26TH	N/A	N	Y	1947	2019	Visual Inspection	U	C	P	NL	u	N/R	N			N		
313 N 26TH	N/A	N	Y	1948	1948	Visual Inspection	U	P	G	GRR	u	N/R	N			N		
609 N 26TH	N/A	N	Y	1939	1939	Visual Inspection	U	C	P	NL	u	N/R	N			N		
713 N 26TH	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N		
720 N 26TH	N/A	N	Y	1972	1972	Visual Inspection	U	C	C	NL	u	N/R	N			N		
721 N 26TH	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N		
805 N 26TH	N/A	N	Y	1974	1974	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
109 N 27TH	N/A	N	Y	1938	1938	Visual Inspection	U	C	P	NL	u	N/R	N			N		
313 N 27TH	N/A	N	Y	1962	1962	Visual Inspection	U	C	C	NL	u	N/R	N			N		
504 N 27TH	N/A	N	Y	1947	1947	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
512 N 27TH	N/A	N	Y	1949	1949	Visual Inspection	U	C	C	NL	u	N/R	N			N		
713 N 27TH	LC3T053	N	Y	1949	1949	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
716 N 27TH	N/A	N	Y	1957	1957	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
717 N 27TH	N/A	N	Y	1949	1949	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
720 N 27TH	N/A	N	Y	1957	1957	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
721 N 27TH	N/A	N	Y	1931	1931	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
800 N 27TH	N/A	N	Y	1974	1974	Visual Inspection	U	C	P	NL	u	N/R	N			N		
617 N 28TH	N/A	N	Y	1946	1946	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
715 N 28TH	N/A	N	Y	1994	1994	Visual Inspection	U	C	C	NL	u	N/R	N			N		
716 N 28TH	N/A	N	Y	1989	1989	Visual Inspection	U	C	P	NL	u	N/R	N			N		
721 N 28TH	N/A	N	Y	1978	1978	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
801 N 28TH	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
804 N 28TH	N/A	N	Y	1974	1974	MAINTENANCE RECORDS/Visual Inspection	U	C	P	NL	u	N/R	N			N		
805 N 28TH	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
808 N 28TH	N/A	N	Y	1925	1925	Visual Inspection	U	C	P	NL	u	N/R	N			N		
809 N 28TH	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
812 N 28TH	N/A	N	Y	2020	2020	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
813 N 28TH	N/A	N	Y	1956	1956	MAINTENANCE RECORDS/Visual Inspection	U	C	P	NL	u	N/R	N			N		
900 N 28TH	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N		
901 N 28TH	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
904 N 28TH	N/A	N	Y	1956	1956	MAINTENANCE RECORDS/Visual Inspection	U	C	P	NL	u	N/R	N			N		
905 N 28TH	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
908 N 28TH	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
909 N 28TH	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
912 N 28TH	N/A	N	Y	1964	1964	Visual Inspection	U	C	C	NL	u	N/R	N			N						
913 N 28TH	N/A	N	Y	1956	1956	Visual Inspection	U	C	C	NL	u	N/R	N			N						
916 N 28TH	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N						
917 N 28TH	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
921 N 28TH	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1000 N 28TH	N/A	N	Y	1956	1956	CUSTOMER SURVEY/VISUAL	U	C	P/C	NL	u	N/R	N			N						
1001 N 28TH	N/A	N	Y	1960	1960	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1004 N 28TH	N/A	N	Y	1958	1958	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
1005 N 28TH	N/A	N	Y	1958	1958	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
1009 N 28TH	N/A	N	Y	2007	2007	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1012 N 28TH	N/A	N	Y	1958	1958	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N						
1013 N 28TH	N/A	N	Y	1958	1958	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
1016 N 28TH	N/A	N	Y	1961	1961	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1017 N 28TH	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1020 N 28TH	N/A	N	Y	1964	1964	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
1021 N 28TH	N/A	N	Y	1959	1959	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1100 N 28TH	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1101 N 28TH	N/A	N	Y	1959	1959	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
1105 N 28TH	N/A	N	Y	1959	1959	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1200 N 28TH	N/A	N	Y	1964	1964	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
1204 N 28TH	N/A	N	Y	1964	1964	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1208 N 28TH	N/A	N	Y	1964	1964	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1212 N 28TH	N/A	N	Y	1964	1964	Visual Inspection	U	C	C	NL	u	N/R	N			N						
417 N 29TH	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N						
609 N 29TH	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N						
716 N 29TH	N/A	N	Y	1930	1930	Visual Inspection	U	C	P	NL	u	N/R	N			N						
720 N 29TH	N/A	N	Y	1930	1930	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
721 N 29TH	N/A	N	Y	1930	1930	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
800 N 29TH	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
804 N 29TH	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
808 N 29TH	N/A	N	Y	1958	1958	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
812 N 29TH	N/A	N	Y	1958	1958	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N						
900 N 29TH	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
901 N 29TH	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N						
904 N 29TH	N/A	N	Y	1957	1957	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N						
905 N 29TH	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N						
908 N 29TH	N/A	N	Y	1956	1956	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
909 N 29TH	N/A	N	Y	1955	1955	CUSTOMER SURVEY/VISUAL	U	C	C/G/P	GRR	u	N/R	N			N						
912 N 29TH	N/A	N	Y	1957	1957	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N						
913 N 29TH	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N						
916 N 29TH	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
917 N 29TH	N/A	N	Y	1963	1963	Visual Inspection	U	C	P	NL	u	N/R	N			N						
920 N 29TH	N/A	N	Y	1957	1957	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
921 N 29TH	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1000 N 29TH	N/A	N	Y	1957	1957	Visual Inspection	U	C	C	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
1001 N 29TH	N/A	N	Y	1957	1957	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
1004 N 29TH	N/A	N	Y	1960	1960	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1005 N 29TH	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1008 N 29TH	N/A	N	Y	2001	2001	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1009 N 29TH	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
1012 N 29TH	N/A	N	Y	2001	2001	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
1013 N 29TH	N/A	N	Y	1957	1957	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N						
1016 N 29TH	N/A	N	Y	1963	1963	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
1017 N 29TH	N/A	N	Y	2008	2008	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1020 N 29TH	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1021 N 29TH	N/A	N	Y	1958	1958	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
1100 N 29TH	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1101 N 29TH	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1104 N 29TH	N/A	N	Y	1958	1958	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
1105 N 29TH	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1108 N 29TH	N/A	N	Y	1957	1957	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N						
309 N 2ND	N/A	N	Y	1963	1963	Visual Inspection	U	C	P	NL	u	N/R	N			N						
312 N 2ND	N/A	N	Y	1963	1963	Visual Inspection	U	C	C	NL	u	N/R	N			N						
321 N 2ND	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N						
501 N 2ND	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N						
713 N 2ND	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N						
721 N 2ND	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
725 N 2ND	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N						
701 N 2ND DIVISION	N/A	N	Y	1979	1979	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
704 N 2ND DIVISION	N/A	N	Y	1947	1947	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
708 N 2MD DIVISION	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
712 N 2ND DIVISION	N/A	N	Y	1950	1950	Visual Inspection	U	C	C	NL	u	N/R	N			N						
713 N 2ND DIVISION	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N						
714 N 2ND DIVISION	N/A	N	Y	1900	1900	Visual Inspection	U	C	P	NL	u	N/R	N			N						
715 N 2ND DIVISION	N/A	N	Y	1930	1930	Visual Inspection	U	C	P	NL	u	N/R	N			N						
716 N 2ND DIVISION	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N						
717 N 2ND DIVISION	N/A	N	Y	1976	1976	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
718 N 2ND DIVISION	N/A	N	Y	1901	1901	Visual Inspection	U	C	P	NL	u	N/R	N			N						
720 N 2ND DIVISION	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
308 N 30TH	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N						
405 N 30TH	N/A	N	Y	1983	1983	Visual Inspection	U	C	P	NL	u	N/R	N			N						
409 N 30TH	N/A	N	Y	1943	1943	Visual Inspection	U	C	P	NL	u	N/R	N			N						
413 N 30TH	N/A	N	Y	1951	1951	Visual Inspection	U	C	C	NL	u	N/R	N			N						
417 N 30TH	N/A	N	Y	1969	1969	Visual Inspection	U	C	P	NL	u	N/R	N			N						
421 N 30TH	N/A	N	Y	1969	1969	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
509 N 30TH	N/A	N	Y	1969	1969	Visual Inspection	U	C	P	NL	u	N/R	N			N						
904 N 30TH	N/A	N	Y	1964	1964	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
905 N 30TH	N/A	N	Y	1961	1961	Visual Inspection	U	C	P	NL	u	N/R	N			N						
908 N 30TH	N/A	N	Y	1970	1970	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
909 N 30TH	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)			
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)			
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)			
912 N 30TH	N/A	N	Y	1967	1967	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
913 N 30TH	N/A	N	Y	1966	1966	Visual Inspection	U	C	P	NL	u	N/R	N			N		
916 N 30TH	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N		
917 N 30TH	N/A	N	Y	1961	1961	Visual Inspection	U	C	G	NL	u	N/R	N			N		
920 N 30TH	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N		
921 N 30TH	N/A	N	Y	1965	1965	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1000 N 30TH	N/A	N	Y	1967	1967	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1001 N 30TH	N/A	N	Y	1967	1967	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
1004 N 30TH	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1005 N 30TH	N/A	N	Y	1965	1965	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1008 N 30TH	N/A	N	Y	1965	1965	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1009 N 30TH	N/A	N	Y	1966	1966	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1012 N 30TH	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1013 N 30TH	N/A	N	Y	1965	1965	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1016 N 30TH	N/A	N	Y	1969	1969	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1017 N 30TH	N/A	N	Y	1961	1961	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1020 N 30TH	N/A	N	Y	1967	1967	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1100 N 30TH	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1101 N 30TH	N/A	N	Y	1964	1964	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1104 N 30TH	N/A	N	Y	1966	1966	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1105 N 30TH	N/A	N	Y	1965	1965	Visual Inspection	U	C	P	NL	u	N/R	N			N		
209 N 31ST	N/A	N	Y	1947	1947	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
412 N 31ST	N/A	N	Y	1944	1944	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
416 N 31ST	N/A	N	Y	1940	1940	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
712 N 31ST	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N		
713 N 31ST	N/A	N	Y	1963	1963	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
716 N 31ST	N/A	N	Y	1963	1963	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
720 N 31ST	N/A	N	Y	1978	1978	Visual Inspection	U	C	P	NL	u	N/R	N			N		
800 N 31ST	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N		
801 N 31ST	N/A	N	Y	1979	1979	Visual Inspection	U	C	C	NL	u	N/R	N			N		
804 N 31ST	N/A	N	Y	1978	1978	Visual Inspection	U	C	C	NL	u	N/R	N			N		
812 N 31ST	N/A	N	Y	1978	1978	Visual Inspection	U	C	C	NL	u	N/R	N			N		
813 N 31ST	N/A	N	Y	1983	1983	Visual Inspection	U	C	C	NL	u	N/R	N			N		
816 N 31ST	N/A	N	Y	1979	1979	Visual Inspection	U	C	C	NL	u	N/R	N			N		
817 N 31ST	N/A	N	Y	1978	1978	Visual Inspection	U	C	C	NL	u	N/R	N			N		
900 N 31ST	N/A	N	Y	1986	1986	Visual Inspection	U	C	C	NL	u	N/R	N			N		
901 N 31ST	N/A	N	Y	1978	1978	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
904 N 31ST	N/A	N	Y	1986	1986	Visual Inspection	U	C	P	NL	u	N/R	N			N		
907 N 31ST	N/A	N	Y	1983	1983	Visual Inspection	U	C	P	NL	u	N/R	N			N		
908 N 31ST	N/A	N	Y	1989	1989	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
909 N 31ST	N/A	N	Y	1986	1986	Visual Inspection	U	C	P	NL	u	N/R	N			N		
912 N 31ST	N/A	N	Y	1985	1985	Visual Inspection	U	C	P	NL	u	N/R	N			N		
913 N 31ST	N/A	N	Y	1987	1987	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1000 N 31ST	N/A	N	Y	1986	1986	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1001 N 31ST	N/A	N	Y	1986	1986	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Galvanized (G)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Plastic - PVC, HDPE, PEX (P)							
							Cast/Ductile Iron or Transite (Q)	Lead (L)	Lead (L)						Cast/Ductile Iron or Transite (Q)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)						Plastic - PVC, HDPE, PEX (P)							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
1004 N 31ST	N/A	N	Y	1986	1986	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1005 N 31ST	N/A	N	Y	1987	1987	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1008 N 31ST	N/A	N	Y	1987	1987	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
1009 N 31ST	N/A	N	Y	1990	1990	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1100 N 31ST	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1104 N 31ST	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1105 N 31ST	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1108 N 31ST	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1109 N 31ST	N/A	N	Y	1989	1989	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1110 N 31ST	N/A	N	Y	1990	1990	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
1112 N 31ST	N/A	N	Y	1987	1987	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1113 N 31ST	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1116 N 31ST	N/A	N	Y	1990	1990	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
508 N 32ND	N/A	N	Y	1947	1947	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
512 N 32ND	N/A	N	Y	1921	1921	Visual Inspection	U	C	P	NL	u	N/R	N			N						
513 N 32ND	N/A	N	Y	1943	1943	Visual Inspection	U	C	P	NL	u	N/R	N			N						
516 N 32ND	N/A	N	Y	1983	1983	Visual Inspection	U	C	P	NL	u	N/R	N			N						
517 N 32ND	N/A	N	Y	1943	1943	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
712 N 32ND	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N						
800 N 32ND	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
804 N 32ND	N/A	N	Y	1974	1974	Visual Inspection	U	C	P	NL	u	N/R	N			N						
808 N 32ND	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N						
809 N 32ND	N/A	N	Y	1968	1968	Visual Inspection	U	C	C	NL	u	N/R	N			N						
812 N 32ND	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
813 N 32ND	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N						
816 N 32ND	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N						
817 N 32ND	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N						
900 N 32ND	N/A	N	Y	1970	1970	Visual Inspection	U	C	C	NL	u	N/R	N			N						
901 N 32ND	N/A	N	Y	1969	1969	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
904 N 32ND	N/A	N	Y	1972	1972	Visual Inspection	U	C	C	NL	u	N/R	N			N						
905 N 32ND	N/A	N	Y	1969	1969	Visual Inspection	U	C	P	NL	u	N/R	N			N						
908 N 32ND	N/A	N	Y	1970	1970	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
909 N 32ND	N/A	N	Y	1971	1971	Visual Inspection	U	C	P	NL	u	N/R	N			N						
912 N 32ND	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N						
913 N 32ND	N/A	N	Y	1969	1969	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1000 N 32ND	N/A	N	Y	1970	1970	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
1001 N 32ND	N/A	N	Y	1970	1970	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
1004 N 32ND	N/A	N	Y	1973	1973	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
1005 N 32ND	N/A	N	Y	1971	1971	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1008 N 32ND	N/A	N	Y	1973	1973	Visual Inspection	U	C	C	NL	u	N/R	N			N						
1009 N 32ND	N/A	N	Y	1971	1971	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1104 N 32ND	N/A	N	Y	1971	1971	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1105 N 32ND	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1108 N 32ND	N/A	N	Y	1976	1976	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1109 N 32ND	N/A	N	Y	1970	1970	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
	1112 N 32ND	N/A	N	Y	1971	1971	Visual Inspection	U	C	C	NL	u	N/R	N		N						
	1113 N 32ND	N/A	N	Y	1969	1969	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	1116 N 32ND	N/A	N	Y	1971	1971	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	1117 N 32ND	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	420 N 33RD	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	509 N 33RD	N/A	N	Y	1941	1941	Visual Inspection	U	G	P	GRR	u	N/R	N		N						
	704 N 33RD	N/A	N	Y	1925	1925	Visual Inspection	U	C	G	GRR	u	N/R	N		N						
	812 N 33RD	N/A	N	Y	1959	1959	Visual Inspection	U	C	C	NL	u	N/R	N		N						
	817 N 33RD	LC3T022	N	Y	1942	1942	Visual Inspection	U	G/C	G	GRR	u	N/R	N		N						
	820 N 33RD	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	821 N 33RD	N/A	N	Y	1947	1947	Visual Inspection	U	G/C	G	GRR	u	N/R	N		N						
	822 N 33RD	N/A	N	Y	1963	1963	Visual Inspection	U	C	C	NL	u	N/R	N		N						
	824 N 33RD	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	826 N 33RD	N/A	N	Y	1963	1963	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	828 N 33RD	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N		N						
	901 N 33RD	N/A	N	Y	1986	1986	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	904 N 33RD	N/A	N	Y	1960	1960	Visual Inspection	U	C	C	NL	u	N/R	N		N						
	905 N 33RD	N/A	N	Y	2008	2008	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	906 N 33RD	N/A	N	Y	1958	1958	Visual Inspection	U	C	C	NL	u	N/R	N		N						
	908 N 33RD	N/A	N	Y	1994	1994	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N		N						
	909 N 33RD	N/A	N	Y	1989	1989	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N		N						
	910 N 33RD	N/A	N	Y	1960	1960	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N		N						
	912 N 33RD	N/A	N	Y	1958	1958	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N		N						
	914 N 33RD	N/A	N	Y	1961	1961	Visual Inspection	U	C	C	NL	u	N/R	N		N						
	916 N 33RD	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	917 N 33RD	N/A	N	Y	1897	1897	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	918 N 33RD	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	919 N 33RD	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	920 N 33RD	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	921 N 33RD	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	1013 N 33RD	N/A	N	Y	1958	1958	Visual Inspection	U	C	C	NL	u	N/R	N		N						
	1013 1/2 N 33RD	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	1020 N 33RD	N/A	N	Y	1999	1999	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	100 N 34TH	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N		N						
	102 N 34TH	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	104 N 34TH	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N		N						
	217 N 34TH	N/A	N	Y	1887	1887	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	317 N 34TH	N/A	N	Y	1991	1991	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N		N						
	321 N 34TH	N/A	N	Y	1992	1992	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N		N						
	405 N 34TH	N/A	N	Y	1991	1991	Visual Inspection	U	C	C	NL	u	N/R	N		N						
	413 N 34TH	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	508 N 34TH	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	804 N 34TH	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N		N						
	808 N 34TH	N/A	N	Y	1947	1947	Visual Inspection	U	C	C	NL	u	N/R	N		N						
	809 N 34TH	N/A	N	Y	1953	1953	Visual Inspection	U	C	C	NL	u	N/R	N		N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
812 N 34TH	N/A	N	Y	1947	1947	Visual Inspection	U	C	C	NL	u	N/R	N			N						
816 N 34TH	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N						
817 N 34TH	N/A	N	Y	1948	1948	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N						
821 N 34TH	N/A	N	Y	1991	1991	Visual Inspection	U	C	C	NL	u	N/R	N			N						
901 N 34TH	N/A	N	Y	1904	1904	Visual Inspection	U	C	C	NL	u	N/R	N			N						
905 N 34TH	N/A	N	Y	1987	1987	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
916 N 34TH	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N						
921 N 34TH	N/A	N	Y	1908	1908	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
204 N 35TH	N/A	N	Y	1938	1938	Visual Inspection	U	C	P	NL	u	N/R	N			N						
205 N 35TH	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N						
208 N 35TH	N/A	N	Y	1931	1931	Visual Inspection	U	C	P	NL	u	N/R	N			N						
209 N 35TH	N/A	N	Y	1936	1936	Visual Inspection	U	C	P	NL	u	N/R	N			N						
213 N 35TH	N/A	N	Y	1938	1938	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
216 N 35TH	N/A	N	Y	1936	1936	Visual Inspection	U	C	C	NL	u	N/R	N			N						
217 N 35TH	N/A	N	Y	1927	1927	Visual Inspection	U	C	P	NL	u	N/R	N			N						
221 N 35TH	N/A	N	Y	1937	1937	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
225 N 35TH	N/A	N	Y	1940	1940	Visual Inspection	U	C	C	NL	u	N/R	N			N						
229 N 35TH	N/A	N	Y	1939	1939	Visual Inspection	U	C	P	NL	u	N/R	N			N						
301 N 35TH	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
305 N 35TH	N/A	N	Y	1940	1940	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
309 N 35TH	N/A	N	Y	1940	1940	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
315 N 35TH	N/A	N	Y	1946	1946	Visual Inspection	U	C	C	NL	u	N/R	N			N						
316 N 35TH	N/A	N	Y	1991	1991	Visual Inspection	U	C	C	NL	u	N/R	N			N						
317 N 35TH	N/A	N	Y	1941	1941	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N						
320 N 35TH	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N						
321 N 35TH	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N						
404 N 35TH	N/A	N	Y	1990	1990	Visual Inspection	U	C	C	NL	u	N/R	N			N						
407 N 35TH	N/A	N	Y	1945	1945	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N						
411 N 35TH	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N						
412 N 35TH	N/A	N	Y	1989	1989	Visual Inspection	U	C	P	NL	u	N/R	N			N						
417 N 35TH	N/A	N	Y	1944	1944	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
117 N 43RD	N/A	N	Y	2014	2014	Visual Inspection	U	C	P	NL	u	N/R	N			N						
121 N 43RD	N/A	N	Y	2014	2014	Visual Inspection	U	C	C	NL	u	N/R	N			N						
620 N 43RD	N/A	N	Y	2014	2014	Visual Inspection	U	C	P	NL	u	N/R	N			N						
311 N 3RD	N/A	N	Y	1949	1949	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
317 N 3RD	N/A	N	Y	1953	1953	Visual Inspection	U	C	C	NL	u	N/R	N			N						
318 N 3RD	N/A	N	Y	2015	2015	Visual Inspection	U	C	P	NL	u	N/R	N			N						
508 N 3RD	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N						
509 N 3RD	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N						
717 N 3RD	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
117 N 43RD	N/A	N	Y	1985	1985	Visual Inspection	U	C	P	NL	u	N/R	N			N						
121 N 43RD	N/A	N	Y	2014	2014	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
620 N 43RD	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N						
712 N 4TH	N/A	N	Y	1944	1944	Visual Inspection	U	P	P	NL	u	N/R	N			N						
714 N 4TH	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
716 N 4TH	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N						
717 N 4TH	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N						
720 N 4TH	N/A	N	Y	1979	1979	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
721 N 4TH	N/A	N	Y	1979		Visual Inspection	U	C	P	NL	u	N/R	N			N						
621 N 5TH	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
720 N 5TH	N/A	N	Y	1979	1979	Visual Inspection	U	G	C	GRR	u	N/R	N			N						
121 N 6TH	N/A	N	Y	1911	1991	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
200 N 6TH	N/A	N	Y	1940	1940	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
204 N 6TH	N/A	N	Y	1963	1963	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
208 N 6TH	N/A	N	Y	1991	1991	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
212 N 6TH	N/A	N	Y	1940	2012	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
220 N 6TH	N/A	N	Y	1992		CUSTOMER SURVEY	U	C	C/G	GRR	u	N/R	N			N						
913 N 6TH	N/A	N	Y			CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
917 N 6TH	N/A	N	Y			Visual Inspection	U	G	P	GRR	u	N/R	N			N						
11295 N 700 E	N/A	N	Y	1970		VISUAL INSPECTION/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
108 N 7TH	LC3T032	N	Y	1923	1923	Visual Inspection	U	G	P	GRR	u	N/R	N			N						
805 N 7TH	N/A	N	Y	1948	1948	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 68	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 69	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 70	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 71	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 72	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 73	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 74	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 75	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 76	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 77	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 78	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 79	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 80	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 81	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 82	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 83	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 84	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 85	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 86	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 87	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 88	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 89	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 90	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 91	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 92	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 93	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 94	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						
812 N 7TH ST TRLR 95	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	c	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Leave blank if no Lead							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)													
608 N 8TH	LC3T033	N	Y	1923	1923	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N						
805 N 8TH	N/A	N	Y	2017	2017	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
812 N 8TH ST LOT 42	N/A	N	Y	1951	1980	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 35	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 36	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 37	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 38	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
812 N 8TH ST TRLR 39	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 40	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 41	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 43	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 44	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 45	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 46	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
812 N 8TH ST TRLR 47	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 48	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 49	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 50	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 51	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 52	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
812 N 8TH ST TRLR 53	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
812 N 8TH ST TRLR 54	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
812 N 8TH ST TRLR 55	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 56	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 57	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
812 N 8TH ST TRLR 58	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
812 N 8TH ST TRLR 59	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
812 N 8TH ST TRLR 60	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
812 N 8TH ST TRLR 61	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
812 N 8TH ST TRLR 62	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 63	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 64	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 65	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 66	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
812 N 8TH ST TRLR 67	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
812 N 9TH HOUSE	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST APT 1	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 10	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 12	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 15	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 17	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
812 N 9TH ST TRLR 18	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 19	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 2	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 20	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:											
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Cast/Ductile Iron or Transite (O)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Plastic - PVC, HDPE, PEX (P)													
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead							
812 N 9TH ST TRLR 21	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 22	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 23	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 24	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 25	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 26	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 27	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 28	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 31	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 32	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 33	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
812 N 9TH ST TRLR 8	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
8938 N CO ROAD 620E	N/A	N	Y	1978	1978	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
5626 N CO ROAD 650E	N/A	N	Y	2012	2012	CUSTOMER SURVEY	U	C	P/C	NL	u	N/R	N			N						
9990 N CO ROAD 700E	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
11339 N CO ROAD 700E	N/A	N	Y	1957	1957	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
11506 N CO ROAD 700E	N/A	N	Y	1969	1969	VISUAL INSPECTION/CUSTO	U	C	P	NL	u	N/R	N			N						
11534 N CO ROAD 700E	N/A	N	Y	2013	2013	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
11563 N CO ROAD 700E	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
11639 N CO ROAD 700E	N/A	N	Y	1965	1965	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
6445 N COUNTRY CLUB RD	N/A	N	Y	1969	1969	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
6517 N COUNTRY CLUB RD	N/A	N	Y	1900	1900	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
6559 N COUNTRY CLUB RD	N/A	N	Y	1892	1892	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
6601 N COUNTRY CLUB RD	N/A	N	Y	2001	2001	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
6645 N COUNTRY CLUB RD HS	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
6677 N COUNTRY CLUB RD	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
6709 N COUNTRY CLUB RD	N/A	N	Y	1988	1988	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
6759 N COUNTRY CLUB RD	N/A	N	Y	1978	1978	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N						
6807 N COUNTRY CLUB RD	N/A	N	Y	1985	1985	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
6855 N COUNTRY CLUB RD	N/A	N	Y	1976	1976	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N						
6879 N COUNTRY CLUB RD	N/A	N	Y	1957	1957	Maintenance records	U	C	C	NL	u	N/R	N			N						
6895 N COUNTRY CLUB RD	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
6915 N COUNTRY CLUB RD	N/A	N	Y	2004	2004	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
6935 N COUNTRY CLUB RD	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
6945 N COUNTRY CLUB RD	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
6111 N COUNTRY ROAD 650E	N/A	N	Y	1998	1998	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
121 N DIVISION	N/A	N	Y	1978	1978	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N						
209 N DIVISION	N/A	N	Y	1900	1900	Visual Inspection	U	C	P	NL	u	N/R	N			N						
218 N DIVISION	N/A	N	Y	2017	2017	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
220 N DIVISION	N/A	N	Y	2017	2017	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
312 N DIVISION	N/A	N	Y			Visual Inspection	U	C	P	NL	u	N/R	N			N						
313 N DIVISION	N/A	N	Y			Visual Inspection	U	C	P	NL	u	N/R	N			N						
317 N DIVISION	N/A	N	Y			Visual Inspection	U	C	P	NL	u	N/R	N			N						
201 N LOGAN	N/A	N	Y			CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
301 N LOGAN	N/A	N	Y			Visual Inspection	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)							
327 N LOGAN	N/A	N	Y			CUSTOMER SURVEY	U	C	P	NL	u	N/R	N		Leave blank if no Lead	N						
420 N LOGAN	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N						
507 N LOGAN	N/A	N	Y	1998	1998	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
713 N LOGAN	N/A	N	Y			MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
715 N LOGAN	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
717 N LOGAN	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
719 N LOGAN	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
721 N LOGAN	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
723 N LOGAN	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
732 N LOGAN	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
733 N LOGAN	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
4 NANTUCKET	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
12 NANTUCKET	N/A	N	Y	1994	1994	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
1 NOYES CT	N/A	N	Y	1939	1939	CUSTOMER SURVEY	U	C	C/G	GRR	u	N/R	N			N						
2 NOYES CT	N/A	N	Y	1931	1931	Visual Inspection	U	C	C	NL	u	N/R	N			N						
3 NOYES CT	LC3T036	N	Y	1941	1941	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
4 NOYES CT	LC3T023	N	Y	1937	1937	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
5 NOYES CT	N/A	N	Y	1938	1938	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
6 NOYES CT	N/A	N	Y	1927	1927	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
7 NOYES CT	N/A	N	Y	1950	1950	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
8 NOYES CT	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N						
9 NOYES CT	N/A	N	Y	1939	1939	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
10 NOYES CT	N/A	N	Y	1927	1927	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
11 NOYES CT	N/A	N	Y	1949	1949	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
12 NOYES CT	N/A	N	Y	1949	1949	Visual Inspection	U	C	P	NL	u	N/R	N			N						
13 NOYES CT	N/A	N	Y	1940	1940	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
1301 OAK	N/A	N	Y	1952	1952	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N						
1608 OAK	N/A	N	Y	1909	1909	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N						
1813 OAK	N/A	N	Y	1986	1986	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N						
1816 OAK	N/A	N	Y	1939	1939	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
1817 OAK	N/A	N	Y	1986	1986	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1821 OAK	N/A	N	Y	1986	1986	CUSTOMER SURVEY	U	C	C/G/P	GRR	u	N/R	N			N						
1825 OAK	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
1828 OAK	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N						
1829 OAK	N/A	N	Y	1986	1986	Visual Inspection	U	P	C	NL	u	N/R	N			N						
2700 OAK	N/A	N	Y	1959	1959	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
2701 OAK	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2704 OAK	N/A	N	Y	1959	1959	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
2705 OAK	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
2708 OAK	LC3T037	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2709 OAK	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2712 OAK	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2713 OAK	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2716 OAK	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2717 OAK	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:										
Total Service Lines - Residential - 7021/Commercial - 991																						
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property					
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.					
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)							
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)							
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)							
							Cast/Ductile Iron or Transite (Q)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (Q)							
2720 OAK	N/A	N	Y	1954	1954	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N						
2721 OAK	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2800 OAK	N/A	N	Y	1954	1954	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
2801 OAK	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2804 OAK	N/A	N	Y	1953	1953	Visual Inspection/CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N						
2805 OAK	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2808 OAK	N/A	N	Y	1953	1953	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2809 OAK	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2812 OAK	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N						
2813 OAK	N/A	N	Y	1953	1953	Visual Inspection	U	P	P	NL	u	N/R	N			N						
2817 OAK	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2820 OAK	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2821 OAK	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N						
2900 OAK	N/A	N	Y	1953	1953	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2901 OAK	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
2904 OAK	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2905 OAK	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2908 OAK	N/A	N	Y	1954	1954	Visual Inspection	U	C	C	NL	u	N/R	N			N						
2909 OAK	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2912 OAK	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2913 OAK	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2916 OAK	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N						
2917 OAK	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
2921 OAK	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
3000 OAK	N/A	N	Y	1952	1952	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N						
3001 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3004 OAK	N/A	N	Y	1952	1952	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N						
3005 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
3008 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3009 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	P	G	GRR	u	N/R	N			N						
3012 OAK	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N						
3013 OAK	N/A	N	Y	1952	1952	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N						
3016 OAK	N/A	N	Y	1952	1952	MAINTENANCE RECORDS/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
3017 OAK	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3020 OAK	N/A	N	Y	1952	1952	MAINTENANCE RECORDS/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N						
3021 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3100 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	G	GRR	u	N/R	N			N						
3101 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3104 OAK	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3105 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3108 OAK	N/A	N	Y	2009	2009	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3109 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3112 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N						
3113 OAK	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N						
3116 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N						

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
3117 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3120 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3121 OAK	N/A	N	Y	1952	1952	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
3124 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3200 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3201 OAK	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3204 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3205 OAK	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3208 OAK	N/A	N	Y	1953	1953	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3209 OAK	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3212 OAK	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3213 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3216 OAK	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3217 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3220 OAK	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3221 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3225 OAK	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3232 OAK	N/A	N	Y	1946	1946	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
3300 OAK	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3304 OAK	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3305 OAK	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3401 OAK	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3404 OAK	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3405 OAK	N/A	N	Y	2008	2008	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3408 OAK	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3409 OAK	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3412 OAK	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3501 OAK	N/A	N	Y	1968	1968	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3504 OAK	N/A	N	Y	1965	1965	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3512 OAK	N/A	N	Y	1966	1966	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3516 OAK	N/A	N	Y	1971	1971	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3517 OAK	N/A	N	Y	1966	1966	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3520 OAK	N/A	N	Y	1920	1920	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3600 OAK	LC3T038	N	Y	1965	1965	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3601 OAK	N/A	N	Y	1968	1968	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3604 OAK	N/A	N	Y	1969	1969	Visual Inspection	U	C	P	NL	u	N/R	N			N		
500 ODD FELLOW RD	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
508 ODD FELLOW RD	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
620 ODD FELLOW RD	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	P	C	UNL	u	N/R	N			N		
116 OKLAHOMA	N/A	N	Y	1970	1970	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
120 OKLAHOMA	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
121 OKLAHOMA	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
200 OKLAHOMA	N/A	N	Y	1970	1970	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
201 OKLAHOMA	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
204 OKLAHOMA	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
208 OKLAHOMA	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	P	P	UNL	u	N/R	N			N		
209 OKLAHOMA	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
212 OKLAHOMA	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
301 OKLAHOMA	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
304 OKLAHOMA	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
305 OKLAHOMA	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
308 OKLAHOMA	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
308 OKLAHOMA	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
309 OKLAHOMA	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
312 OKLAHOMA	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
313 OKLAHOMA	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
316 OKLAHOMA	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
401 OKLAHOMA	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
404 OKLAHOMA	N/A	N	Y	1957	1957	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
405 OKLAHOMA	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
408 OKLAHOMA	N/A	N	Y	1963	1963	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
409 OKLAHOMA	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
412 OKLAHOMA	N/A	N	Y	1962	1962	Visual Inspection	U	C	C	NL	u	N/R	N			N		
413 OKLAHOMA	N/A	N	Y	1962	1962	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
416 OKLAHOMA	N/A	N	Y	1961	1961	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
417 OKLAHOMA	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
420 OKLAHOMA	N/A	N	Y	1960	1960	CUSTOMER SURVEY	U	C	C	UNL	u	N/R	N			N		
421 OKLAHOMA	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
424 OKLAHOMA	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
428 OKLAHOMA	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
500 OKLAHOMA	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
504 OKLAHOMA	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
508 OKLAHOMA	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
516 OKLAHOMA	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
517 OKLAHOMA	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
520 OKLAHOMA	N/A	N	Y	1951	1951	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
521 OKLAHOMA	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
600 OKLAHOMA	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
601 OKLAHOMA	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
604 OKLAHOMA	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	P	G	GRR	u	N/R	N			N		
605 OKLAHOMA	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
608 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
609 OKLAHOMA	N/A	N	Y	1950	1950	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
612 OKLAHOMA	N/A	N	Y	1951	1951	MAINTENANCE RECORDS/N	U	C	G	GRR	u	N/R	N			N		
613 OKLAHOMA	N/A	N	Y	1954	1954	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
616 OKLAHOMA	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
617 OKLAHOMA	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
620 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
621 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
625 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
700 OKLAHOMA	N/A	N	Y	1949	1949	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
704 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
708 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
709 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
712 OKLAHOMA	N/A	N	Y	1949	1949	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
713 OKLAHOMA	N/A	N	Y	1949	949	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
716 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
720 OKLAHOMA	N/A	N	Y	1949	1949	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
724 OKLAHOMA	N/A	N	Y	1949	1949	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
800 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
801 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
804 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
805 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
808 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
809 OKLAHOMA	N/A	N	Y	2008	2008	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
812 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
816 OKLAHOMA	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
817 OKLAHOMA	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
820 OKLAHOMA	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
821 OKLAHOMA	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
900 OKLAHOMA	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
901 OKLAHOMA	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
904 OKLAHOMA	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
905 OKLAHOMA	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
908 OKLAHOMA	N/A	N	Y	1961	1961	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
909 OKLAHOMA	N/A	N	Y	1961	1961	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
912 OKLAHOMA	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
913 OKLAHOMA	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
916 OKLAHOMA	N/A	N	Y	1961	1961	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
917 OKLAHOMA	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
920 OKLAHOMA	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
921 OKLAHOMA	N/A	N	Y	1961	1961	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
925 OKLAHOMA	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
1000 OKLAHOMA	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1001 OKLAHOMA	N/A	N	Y	1962	1962	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1004 OKLAHOMA	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1005 OKLAHOMA	N/A	N	Y	1961	1961	CUSTOMER SURVEY	U	C	P	UNL	u	N/R	N			N		
1008 OKLAHOMA	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1009 OKLAHOMA	N/A	N	Y	1962	1962	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1012 OKLAHOMA	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1016 OKLAHOMA	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1020 OKLAHOMA	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1024 OKLAHOMA	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1100 OKLAHOMA	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1101 OKLAHOMA	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Galvanized (G)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Plastic - PVC, HDPE, PEX (P)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)													Leave blank if no Lead			
1104 OKLAHOMA	N/A	N	Y	1962	1962	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
1105 OKLAHOMA	N/A	N	Y	1964	1964	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
1108 OKLAHOMA	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
1109 OKLAHOMA	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1117 OKLAHOMA	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1512 OKLAHOMA	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1513 OKLAHOMA	N/A	N	Y	1998	1998	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1517 OKLAHOMA	N/A	N	Y	1998	1998	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1521 OKLAHOMA	N/A	N	Y	1998	1998	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1601 OKLAHOMA	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1605 OKLAHOMA	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
1609 OKLAHOMA	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1613 OKLAHOMA	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
4807 OLD STATE RD	N/A	N	Y	1966	1966	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
6160 OLD STATE RD	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
6172 OLD STATE RD	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
7440 OLD STATE RD	N/A	N	Y	1977	1977	Visual Inspection	U	C	C	NL	u	N/R	N			N		
7478 OLD STATE RD	N/A	N	Y	1977	1977	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
7498 OLD STATE RD	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
7528 OLD STATE RD	N/A	N	Y	1976	1976	Visual Inspection	U	P	C	NL	u	N/R	N			N		
7557 OLD STATE RD	N/A	N	Y	1981	1981	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
7568 OLD STATE RD	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
7605 OLD STATE RD	N/A	N	Y	1985	1985	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
7640 OLD STATE RD	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
7645 OLD STATE RD	N/A	N	Y	1972	1972	Visual Inspection	U	C	P	NL	u	N/R	N			N		
7886 OLD STATE RD	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
7914 OLD STATE RD	N/A	N	Y	1956	1956	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
7938 OLD STATE RD	N/A	N	Y	1956	1956	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
7978 OLD STATE RD	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
8002 OLD STATE RD	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
8030 OLD STATE RD	N/A	N	Y	1917	1917	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1604 OLIVE	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1605 OLIVE	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
1608 OLIVE	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1609 OLIVE	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1615 OLIVE	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1617 OLIVE	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1701 OLIVE	N/A	N	Y	1927	1927	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1705 OLIVE	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1709 OLIVE	N/A	N	Y	1926	1926	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1713 OLIVE	N/A	N	Y	1954	1954	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1717 OLIVE	N/A	N	Y	2009	2009	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1721 OLIVE	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1821 OLIVE	N/A	N	Y	1942	1942	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
101 OMAN CT	N/A	N	Y	2009	2009	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:				
Total Service Lines - Residential - 7021/Commercial - 991																	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)								
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)									
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)															
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead													
104 OMAN CT	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N	
105 OMAN CT	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N	
108 OMAN CT	N/A	N	Y	1997	1997	Visual Inspection	U	C	P	NL	u	N/R	N			N	
109 OMAN CT	N/A	N	Y	1997	1997	Visual Inspection	U	C	P	NL	u	N/R	N			N	
112 OMAN CT	N/A	N	Y	1997	1997	Visual Inspection	U	C	P	NL	u	N/R	N			N	
113 OMAN CT	N/A	N	Y	2000	2000	Visual Inspection	U	C	P	NL	u	N/R	N			N	
116 OMAN CT	N/A	N	Y	1999	1999	Visual Inspection	U	C	P	NL	u	N/R	N			N	
121 OMAN CT	N/A	N	Y	2000	2000	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
123 OMAN CT	N/A	N	Y	2000	2000	Visual Inspection	U	C	P	NL	u	N/R	N			N	
124 OMAN CT	N/A	N	Y	2000	2000	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
1000 PALM	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N	
312 PARK	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N	
316 PARK	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N	
320 PARK	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N	
400 PARK	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N	
404 PARK	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N	
408 PARK	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N	
412 PARK	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N	
416 PARK	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N	
420 PARK	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
424 PARK	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N	
400 PARKVIEW	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N	
401 PARKVIEW	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
409 PARKVIEW	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N	
412 PARKVIEW	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N	
413 PARKVIEW	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N	
416 PARKVIEW	N/A	N	Y	1955	1955	MAINTENANCE RECORDS/Visual Inspection	U	C	G	GRR	u	N/R	N			N	
417 PARKVIEW	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N	
420 PARKVIEW	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N	
421 PARKVIEW	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
424 PARKVIEW	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	
109 PEACH CT	N/A	N	Y	1999	1999	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
110 PEACH CT	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
100 PEAR CT	N/A	N	Y	1975	1975	Visual Inspection	U	C	P	NL	u	N/R	N			N	
101 PEAR CT	N/A	N	Y	1972	1972	Visual Inspection	U	C	P	NL	u	N/R	N			N	
102 PEAR CT	N/A	N	Y	1972	1972	Visual Inspection	U	C	P	NL	u	N/R	N			N	
103 PEAR CT	N/A	N	Y	1972	1972	Visual Inspection	U	C	P	NL	u	N/R	N			N	
104 PEAR CT	N/A	N	Y	1972	1972	Visual Inspection	U	C	P	NL	u	N/R	N			N	
105 PEAR CT	N/A	N	Y	1972	1972	Visual Inspection	U	C	P	NL	u	N/R	N			N	
106 PEAR CT	N/A	N	Y	1973	1973	Visual Inspection	U	C	P	NL	u	N/R	N			N	
107 PEAR CT	N/A	N	Y	1973	1973	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	
21 PIATT	N/A	N	Y	1990	1990	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
73 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
75 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
79 PIATT	N/A	N	Y	1999	1999	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)			
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)			
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)			
81 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
95 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
201 PIATT	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
209 PIATT	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		
213 PIATT	N/A	N	Y	2002	2002	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
217 PIATT	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
221 PIATT	N/A	N	Y	1979	1979	Visual Inspection	U	C	C	NL	u	N/R	N			N		
301 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
305 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
309 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
313 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
317 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
321 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
409 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
421 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
504 PIATT	N/A	N	Y			Visual Inspection	U	C	P	UNL	u	N/R	N			N		
520 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
521 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
600 PIATT	N/A	N	Y	1978	1978	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
612 PIATT	N/A	N	Y	1896	1896	Visual Inspection	U	C	P	UNL	u	N/R	N			N		
613 PIATT	N/A	N	Y	1900	1900	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
617 PIATT	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
621 PIATT	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	P	G	GRR	u	N/R	N			N		
700 PIATT	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
701 PIATT	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
705 PIATT	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
709 PIATT	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
713 PIATT	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
720 PIATT	N/A	N	Y	1929	1929	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
721 PIATT	N/A	N	Y	1938	1938	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
800 PIATT	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
801 PIATT	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
805 PIATT	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
808 PIATT	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
809 PIATT	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
816 PIATT	N/A	N	Y	2009	2009	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
817 PIATT	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
820 PIATT	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
900 PIATT	N/A	N	Y	1953	1953	Visual Inspection	U	C	C	NL	u	N/R	N			N		
901 PIATT	N/A	N	Y	1951	1951	Visual Inspection	U	C	C	NL	u	N/R	N			N		
905 PIATT	N/A	N	Y	1949	1949	Visual Inspection	U	C	C	NL	u	N/R	N			N		
909 PIATT	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N		
912 PIATT	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
913 PIATT	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N		
916 PIATT	N/A	N	Y	1963	1963	Visual Inspection	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
917 PIATT	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N		
920 PIATT	N/A	N	Y	1942	1942	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
921 PIATT	N/A	N	Y	1981	1981	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1000 PIATT	N/A	N	Y	1925	1925	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1008 PIATT	N/A	N	Y	1938	1938	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1009 PIATT	N/A	N	Y	1972	1972	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1013 PIATT	N/A	N	Y	1917	1917	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1021 PIATT	N/A	N	Y	1945	1945	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
1101 PIATT	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1105 PIATT	N/A	N	Y	1938	1938	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1109 PIATT	N/A	N	Y	1918	1918	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1209 PIATT	N/A	N	Y	1940	1940	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
1213 PIATT	N/A	N	Y	1941	1941	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
1217 PIATT	N/A	N	Y	1968	1968	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1219 PIATT	N/A	N	Y	1949	1949	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1220 PIATT	N/A	N	Y	1949	1949	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1221 PIATT	N/A	N	Y	1934	1934	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
1304 PIATT	N/A	N	Y	1963	1963	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1305 PIATT	N/A	N	Y	2009	2009	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1309 PIATT	N/A	N	Y	1936	1936	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1313 PIATT	N/A	N	Y	1942	1942	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1317 PIATT	N/A	N	Y	1929	1929	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1321 PIATT	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1401 PIATT	N/A	N	Y	1914	1914	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1409 PIATT	N/A	N	Y	1973	1973	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1413 PIATT	N/A	N	Y	2002	2002	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1417 PIATT	N/A	N	Y	1994	1994	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1421 PIATT	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1600 PIATT	N/A	N	Y	1923	1923	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1601 PIATT	N/A	N	Y	1994	1994	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1604 PIATT	N/A	N	Y	1945	1945	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
1609 PIATT	N/A	N	Y	1926	1926	CUSTOMER SURVEY	U	C	C/G	GRR	u	N/R	N			N		
1612 PIATT	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1613 PIATT	N/A	N	Y	1953	1953	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1617 PIATT	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1620 PIATT	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1621 PIATT	N/A	N	Y	1949	1949	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1700 PIATT	N/A	N	Y	1923	1923	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
1701 PIATT	N/A	N	Y	1924	1924	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1704 PIATT	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1705 PIATT	N/A	N	Y	1941	1941	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1708 PIATT	N/A	N	Y	1923	1923	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1712 PIATT	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1713 PIATT	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1720 PIATT	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
1721 PIATT	N/A	N	Y	1951	1951	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1800 PIATT	N/A	N	Y	1923	1923	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1801 PIATT	N/A	N	Y	1939	1939	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1804 PIATT	N/A	N	Y	1897	1897	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1805 PIATT	N/A	N	Y	1938	1938	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1808 PIATT	N/A	N	Y	1937	1937	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1809 PIATT	N/A	N	Y	1923	1923	Visual Inspection	U	P	P	NL	u	N/R	N			N		
1812 PIATT	N/A	N	Y	1928	1928	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1813 PIATT	N/A	N	Y	1923	1937	Visual Inspection	U	P	G	GRR	u	N/R	N			N		
1816 PIATT	N/A	N	Y	1937	1923	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1817 PIATT	N/A	N	Y	1923	1943	Visual Inspection	U	P	P	NL	u	N/R	N			N		
1820 PIATT	N/A	N	Y	1943	2000	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1824 PIATT	N/A	N	Y	2000	1975	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2500 PIATT	N/A	N	Y	1975	1916	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N		
3200 PIATT	N/A	N	Y	1916	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3201 PIATT	N/A	N	Y	1951	2001	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3209 PIATT	N/A	N	Y	2001	2001	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3213 PIATT	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3216 PIATT	N/A	N	Y	1991	1991	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3217 PIATT	N/A	N	Y	1957	1957	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
3220 PIATT	N/A	N	Y	1991	1956	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3221 PIATT	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3224 PIATT	N/A	N	Y	1956	1956	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3225 PIATT	N/A	N	Y	1956	1956	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
3228 PIATT	N/A	N	Y	1965	1936	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3232 PIATT	N/A	N	Y	1936	1947	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
3312 PIATT	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N		
121 PIATT AVE E	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
4 PIATT AVE EAST	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
105 PIATT AVE EAST	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
109 PIATT AVE EAST	N/A	N	Y	1979	1979	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
117 PIATT AVE EAST	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
201 PIATT AVE EAST	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
213 PIATT AVE EAST	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
708 PIATT AVE EAST	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
712 PIATT AVE EAST	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	C	p	NL	u	N/R	N			N		
2400 PINE	N/A	N	Y	1949	1949	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2404 PINE	N/A	N	Y	1902	1902	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2408 PINE	N/A	N	Y	2015	2015	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2410 PINE	N/A	N	Y	2019	2019	Visual Inspection/CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
2412 PINE	N/A	N	Y	1925	1925	Visual Inspection/CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
2420 PINE	N/A	N	Y	1897	1897	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2502 PINE	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2504 PINE	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2508 PINE	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)																
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
2516 PINE	N/A	N	Y	1924	1924	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2601 PINE	N/A	N	Y	1995	1995	Visual Inspection	U	P	P	NL	u	N/R	N			N		
2605 PINE	N/A	N	Y	1923	1923	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2608 PINE APT 1	N/A	N	Y	1980	1980	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2608 PINE APT 2	N/A	N	Y	1980	1980	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2608 PINE APT 3	N/A	N	Y	1980	1980	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2608 PINE APT 4	N/A	N	Y	1980	1980	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2608 PINE APT 5	N/A	N	Y	1980	1980	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2608 PINE APT 6	N/A	N	Y	1980	1980	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2609 PINE	N/A	N	Y	1931	1931	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2612 PINE	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2613 PINE	N/A	N	Y	1923	1923	Visual Inspection/CUSTOMER	U	C	G	GRR	u	N/R	N			N		
2616 PINE	N/A	N	Y	1998	1998	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2617 PINE	N/A	N	Y	1935	1935	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2620 PINE	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2621 PINE	N/A	N	Y	1908	1908	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
2700 PINE	N/A	N	Y	1914	1914	Visual Inspection	U	C	C/P	NL	u	N/R	N			N		
2701 PINE	N/A	N	Y	2001	2001	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2704 PINE	N/A	N	Y	1941	1941	Visual Inspection	U	G	C	GRR	u	N/R	N			N		
2705 PINE	N/A	N	Y	1924	1924	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2708 PINE	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2709 PINE	N/A	N	Y	1932	1932	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2712 PINE	N/A	N	Y	1926	1926	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2713 PINE	N/A	N	Y	1927	1927	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2717 PINE	N/A	N	Y	1939	1939	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2721 PINE	N/A	N	Y	1939	1939	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2800 PINE	N/A	N	Y	1958	1958	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2801 PINE	N/A	N	Y	1935	1935	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2804 PINE	N/A	N	Y	1910	1910	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2805 PINE	N/A	N	Y	1904	1904	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2808 PINE	N/A	N	Y	1989	1989	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2809 PINE	N/A	N	Y	1905	1905	Visual Inspection/CUSTOMER	U	G	P	GRR	u	N/R	N			N		
2812 PINE	N/A	N	Y	1935	1935	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2813 PINE	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2816 PINE	N/A	N	Y	1920	1920	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2817 PINE	N/A	N	Y	1904	1904	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2820 PINE	N/A	N	Y	1920	1920	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2821 PINE	N/A	N	Y	1938	1938	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2900 PINE	N/A	N	Y	1920	1920	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2901 PINE	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2904 PINE	N/A	N	Y	1920	1920	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2905 PINE	N/A	N	Y	1937	1937	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2908 PINE	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2909 PINE	N/A	N	Y	1919	1919	Visual Inspection/CUSTOMER	U	C	P	NL	u	N/R	N			N		
2912 PINE	N/A	N	Y	1936	1936	Visual Inspection	U	G	P	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)																
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
Leave blank if no Lead																		
2913 PINE	N/A	N	Y	1938	1938	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2916 PINE	N/A	N	Y	1939	1939	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2917 PINE	N/A	N	Y	1974	1974	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2920 PINE	N/A	N	Y	1923	1923	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2921 PINE	N/A	N	Y	1907	1907	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3001 PINE	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3004 PINE	N/A	N	Y	2004	2004	Visual Inspection/CUSTOM	U	C	P	NL	u	N/R	N			N		
3005 PINE	N/A	N	Y	1900	1900	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3008 PINE	N/A	N	Y	1941	1941	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
3009 PINE	N/A	N	Y	1926	1926	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3012 PINE	N/A	N	Y	1922	1922	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3013 PINE	N/A	N	Y	1919	1919	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3016 PINE	N/A	N	Y	1922	1922	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3017 PINE	N/A	N	Y	1911	1911	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3020 PINE	N/A	N	Y	1922	1922	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3021 PINE	N/A	N	Y	1956	1956	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
3100 PINE	N/A	N	Y	1921	1921	Visual Inspection/CUSTOM	U	G	C/G	GRR	u	N/R	N			N		
3101 PINE	N/A	N	Y	1911	1911	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3104 PINE	N/A	N	Y	1985	1985	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3105 PINE	N/A	N	Y	1923	1983	Visual Inspection/CUSTOM	U	C	P	NL	u	N/R	N			N		
3108 PINE	N/A	N	Y	1985	1985	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3109 PINE	N/A	N	Y	1927	1927	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3112 PINE	N/A	N	Y	1985	1985	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3113 PINE	N/A	N	Y	1985	1985	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3116 PINE	N/A	N	Y	1985	1985	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3117 PINE	N/A	N	Y	1985	1985	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3120 PINE	N/A	N	Y	1994	1994	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3121 PINE	N/A	N	Y	1925	1925	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1 PINEHURST	N/A	N	Y	1987	1987	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
2 PINEHURST	N/A	N	Y	1985	1985	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
3 PINEHURST	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N		
4 PINEHURST	N/A	N	Y	1991	1991	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
5 PINEHURST	N/A	N	Y	1984	1984	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
7 PINEHURST	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N		
87 PLUM CT	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
88 PLUM CT	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
89 PLUM CT	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
90 PLUM CT	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
91 PLUM CT	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
92 PLUM CT	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
93 PLUM CT	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
94 PLUM CT	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
95 PLUM CT	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
96 PLUM CT	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
98 PLUM CT	N/A	N	Y	1973	1973	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)		Plastic - PVC, HDPE, PEX (P)								
3412 POWELL LN	N/A	N	Y	2015	2015	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3417 POWELL LN	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3500 POWELL LN	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	C	C	G	GRR	u	N/R	N			N		
3501 POWELL LN	N/A	N	Y	1912	1912	MAINTENANCE RECORDS	C	C	P	NL	u	N/R	N			N		
17 PRAIRIE APT A	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	c	c	NL	u	N/R	N			N		
17 PRAIRIE APT B	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	c	c	NL	u	N/R	N			N		
17 PRAIRIE APT C	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	c	c	NL	u	N/R	N			N		
17 PRAIRIE APT D	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	c	p	NL	u	N/R	N			N		
21 PRAIRIE APT A	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	c	c	NL	u	N/R	N			N		
21 PRAIRIE APT B	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	c	c	NL	u	N/R	N			N		
21 PRAIRIE APT C	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	c	c	NL	u	N/R	N			N		
21 PRAIRIE APT D	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	c	p	NL	u	N/R	N			N		
21 PRAIRIE APT E	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	c	c	NL	u	N/R	N			N		
21 PRAIRIE APT F	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	c	p	NL	u	N/R	N			N		
25 PRAIRIE APT A	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	c	c	NL	u	N/R	N			N		
25 PRAIRIE APT B	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	c	c	NL	u	N/R	N			N		
25 PRAIRIE APT C	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	c	c	NL	u	N/R	N			N		
25 PRAIRIE APT D	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	c	c	NL	u	N/R	N			N		
64 PRAIRIE	N/A	N	Y	1942	1942	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
68 PRAIRIE	N/A	N	Y	1942	1942	MAINTENANCE RECORDS	U	c	p	NL	u	N/R	N			N		
116 PRAIRIE	N/A	N	Y	1969	1969	CUSTOMER SURVEY/VISUAL	U	C	C/P	NL	u	N/R	N			N		
600 PRAIRIE	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
604 PRAIRIE	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
608 PRAIRIE	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
610 PRAIRIE	N/A	N	Y	1920	1920	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
612 PRAIRIE	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
613 PRAIRIE	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
615 PRAIRIE	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	p	NL	u	N/R	N			N		
617 PRAIRIE	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
700 PRAIRIE	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
704 PRAIRIE	N/A	N	Y	1929	1929	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
708 PRAIRIE	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
709 PRAIRIE	N/A	N	Y	1945	1945	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
712 PRAIRIE	N/A	N	Y	1924	1924	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
713 PRAIRIE	N/A	N	Y	1915	1915	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
717 PRAIRIE	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
718 PRAIRIE	N/A	N	Y	1906	1906	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
720 PRAIRIE	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
800 PRAIRIE	N/A	N	Y	1920	1920	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
801 PRAIRIE	N/A	N	Y	1910	1910	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
805 PRAIRIE	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
808 PRAIRIE	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
809 PRAIRIE	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
812 PRAIRIE	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
813 PRAIRIE	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
820 PRAIRIE	N/A	N	Y	1936	1936	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
821 PRAIRIE	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
900 PRAIRIE	N/A	N	Y	1947	1995	MAINTENANCE RECORDS/C	U	C	P	NL	u	N/R	N			N		
901 PRAIRIE	N/A	N	Y	1942		MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
904 PRAIRIE	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
905 PRAIRIE	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
912 PRAIRIE	N/A	N	Y	1958		MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
913 PRAIRIE	N/A	N	Y	2005	2005	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
916 PRAIRIE	N/A	N	Y	1921	1921	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
917 PRAIRIE	N/A	N	Y	1938	1938	MAINTENANCE RECORDS/C	U	C	C/P	NL	u	N/R	N			N		
920 PRAIRIE	LC3T063	N	Y	1926	1926	MAINTENANCE RECORDS	U	C	P/G	GRR	u	N/R	N			N		
921 PRAIRIE	N/A	N	Y	1921	1921	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1000 PRAIRIE	N/A	N	Y	1972		MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1004 PRAIRIE	N/A	N	Y	1924	1924	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
1005 PRAIRIE	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1007 PRAIRIE	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1016 PRAIRIE	N/A	N	Y	1913	1913	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
1020 PRAIRIE	N/A	N	Y	1917	1917	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1100 PRAIRIE	N/A	N	Y	1917	1917	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1104 PRAIRIE	N/A	N	Y	1924	1924	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1112 PRAIRIE	N/A	N	Y	1989	1989	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1120 PRAIRIE	DAYCARE006A	N	Y	1924	1924	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1913 PRAIRIE	N/A	N	Y			Visual Inspection	U	C	C	NL	u	N/R	N			N		
2112 PRAIRIE	N/A	N	Y	1986	1986	MAINTENANCE RECORDS/N	U	G	P	GRR	u	N/R	N			N		
2205 PRAIRIE	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2209 PRAIRIE	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2213 PRAIRIE	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2216 PRAIRIE	N/A	N	Y	1914	1914	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2217 PRAIRIE	N/A	N	Y	1939	1939	MAINTENANCE RECORDS/N	U	C	C	NL	u	N/R	N			N		
2220 PRAIRIE	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2300 PRAIRIE	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2301 PRAIRIE	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2304 PRAIRIE	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
2305 PRAIRIE	N/A	N	Y	1908	1908	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2308 PRAIRIE	N/A	N	Y	1886	1886	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2309 PRAIRIE	N/A	N	Y	1992		MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2312 PRAIRIE	N/A	N	Y	1996	1996	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2313 PRAIRIE	N/A	N	Y	1937	1937	MAINTENANCE RECORDS/N	U	C	C	NL	u	N/R	N			N		
2316 PRAIRIE	N/A	N	Y	1912	1912	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
2317 PRAIRIE	N/A	N	Y	1916	1916	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2319 PRAIRIE	N/A	N	Y	1913	1913	MAINTENANCE RECORDS/N	U	C	P	NL	u	N/R	N			N		
2320 PRAIRIE	N/A	N	Y	1898	1898	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2321 PRAIRIE	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2401 PRAIRIE	LC3T054	N	Y	1959	1959	Visual Inspection	U	G	C	GRR	u	N/R	N			N		
2404 PRAIRIE	N/A	N	Y	1911	1911	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
2405 PRAIRIE	N/A	N	Y	1901	1901	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
2408 PRAIRIE	N/A	N	Y	1911	1911	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
2409 PRAIRIE	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2411 PRAIRIE	N/A	N	Y	1943	1943	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		
2412 PRAIRIE	N/A	N	Y	1900	1900	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
2413 PRAIRIE	N/A	N	Y	1943	1943	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2416 PRAIRIE	N/A	N	Y	1912	1912	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2417 PRAIRIE	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2419 PRAIRIE	N/A	N	Y			Visual Inspection	U	C	P	NL	u	N/R	N			N		
2420 PRAIRIE	N/A	N	Y	1915	1915	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2421 PRAIRIE	N/A	N	Y	1886	1886	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2500 PRAIRIE	N/A	N	Y	1890	1890	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
2501 PRAIRIE	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2504 PRAIRIE	N/A	N	Y	1908	1908	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2507 PRAIRIE	N/A	N	Y	1907	1907	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
2508 PRAIRIE	N/A	N	Y	1918	1918	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2509 PRAIRIE	N/A	N	Y	1900	1900	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
2512 PRAIRIE	N/A	N	Y	1936	1936	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2516 PRAIRIE	N/A	N	Y	2015	2015	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2517 PRAIRIE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2520 PRAIRIE	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2600 PRAIRIE	N/A	N	Y	1922	1922	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2600 PRAIRIE 1/2	N/A	N	Y	1922	1922	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2601 PRAIRIE	N/A	N	Y	1908	1908	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
2604 PRAIRIE	N/A	N	Y	1938	1938	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2605 PRAIRIE	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2608 PRAIRIE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2609 PRAIRIE	N/A	N	Y	1907	1907	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2612 PRAIRIE	N/A	N	Y	1937	1937	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2613 PRAIRIE	N/A	N	Y	1908	1908	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2613 PRAIRIE 1/2	N/A	N	Y	1908	1908	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2616 PRAIRIE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2617 PRAIRIE	N/A	N	Y	1911	1911	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2620 PRAIRIE	N/A	N	Y	1996	1996	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2621 PRAIRIE	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
2700 PRAIRIE	N/A	N	Y	1909	1909	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2704 PRAIRIE	N/A	N	Y	1912	1912	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2705 PRAIRIE	N/A	N	Y	1945	1945	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2708 PRAIRIE	N/A	N	Y	1901	1901	MAINTENANCE RECORDS	U	P	G	GRR	u	N/R	N			N		
2709 PRAIRIE	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2712 PRAIRIE	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2713 PRAIRIE	N/A	N	Y	1909	1909	CUSTOMER SURVEY	U	G	C	GRR	u	N/R	N			N		
2716 PRAIRIE	N/A	N	Y	1929	1929	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2720 PRAIRIE	N/A	N	Y	1897	1897	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2721 PRAIRIE	N/A	N	Y	1894	1894	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)			
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Leave blank if no Lead			
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)									
2800 PRAIRIE	N/A	N	Y	1911	1911	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
2804 PRAIRIE	N/A	N	Y	1945	1945	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2805 PRAIRIE	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2808 PRAIRIE	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2812 PRAIRIE	N/A	N	Y	1912	1912	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2813 PRAIRIE	N/A	N	Y	1926	1926	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2816 PRAIRIE	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2817 PRAIRIE	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2820 PRAIRIE	N/A	N	Y	1911	1911	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2821 PRAIRIE	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2900 PRAIRIE	N/A	N	Y	1924	1924	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2901 PRAIRIE	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2904 PRAIRIE	N/A	N	Y	1907	1907	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2905 PRAIRIE	N/A	N	Y	1916	1916	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2908 PRAIRIE	N/A	N	Y	1916	1916	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2909 PRAIRIE	N/A	N	Y	1914	1914	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2912 PRAIRIE	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2913 PRAIRIE	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2916 PRAIRIE	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2917 PRAIRIE	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2920 PRAIRIE	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2921 PRAIRIE	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3000 PRAIRIE	N/A	N	Y	1937	1937	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
3001 PRAIRIE	N/A	N	Y	1937	1937	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3004 PRAIRIE	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3005 PRAIRIE	N/A	N	Y	1935	1935	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3008 PRAIRIE	N/A	N	Y	1916	1916	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3009 PRAIRIE	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
3013 PRAIRIE	N/A	N	Y	1936	1936	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
3014 PRAIRIE	N/A	N	Y	1950	1950	CUSTOMER SURVEY	U	G	G	GRR	u	N/R	N			N		
3017 PRAIRIE	N/A	N	Y	1926	1926	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3020 PRAIRIE	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3021 PRAIRIE	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3100 PRAIRIE	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3101 PRAIRIE	N/A	N	Y	1926	1926	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3104 PRAIRIE	N/A	N	Y	1924	1924	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3105 PRAIRIE	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3108 PRAIRIE	N/A	N	Y	1912	1912	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3109 PRAIRIE	N/A	N	Y	1914	1914	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3112 PRAIRIE	N/A	N	Y	1926	1926	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3113 PRAIRIE	N/A	N	Y	1964	1964	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3116 PRAIRIE	N/A	N	Y	1926	1926	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
3117 PRAIRIE	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3120 PRAIRIE	N/A	N	Y	1907	1907	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3121 PRAIRIE	N/A	N	Y	1918	1918	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)																
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
3200 PRAIRIE	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3201 PRAIRIE	N/A	N	Y	1998	1998	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3204 PRAIRIE	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3205 PRAIRIE	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
3208 PRAIRIE	N/A	N	Y	1918	1918	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3209 PRAIRIE	N/A	N	Y	1936	1936	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3212 PRAIRIE	N/A	N	Y	1912	1912	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3213 PRAIRIE	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
3216 PRAIRIE	N/A	N	Y	1916	1916	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3217 PRAIRIE	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3220 PRAIRIE	N/A	N	Y	1910	1910	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3221 PRAIRIE	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3224 PRAIRIE	N/A	N	Y	1912	1912	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3225 PRAIRIE	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
3228 PRAIRIE	N/A	N	Y	1900	1900	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3229 PRAIRIE	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3232 PRAIRIE	N/A	N	Y	1918	1918	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3233 PRAIRIE	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
3300 PRAIRIE	N/A	N	Y	1926	1926	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3301 PRAIRIE	N/A	N	Y	1965	1965	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3304 PRAIRIE	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3308 PRAIRIE	N/A	N	Y	1949	1949	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3309 PRAIRIE	N/A	N	Y	1949	1949	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3312 PRAIRIE	N/A	N	Y	1916	1916	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3316 PRAIRIE	N/A	N	Y	1916	1916	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3317 PRAIRIE	N/A	N	Y	1983	1983	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3320 PRAIRIE	N/A	N	Y	1932	1932	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3321 PRAIRIE	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3324 PRAIRIE	N/A	N	Y	1916	1916	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3325 PRAIRIE	N/A	N	Y	1992	1992	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3328 PRAIRIE	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3332 PRAIRIE	N/A	N	Y	1942	1942	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3333 PRAIRIE	N/A	N	Y	2000	2000	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3336 PRAIRIE	N/A	N	Y	1906	1906	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3339 PRAIRIE	N/A	N	Y	2014	2014	Visual Inspection	U	P	P	NL	u	N/R	N			N		
3344 PRAIRIE	N/A	N	Y	1962	1962	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3345 PRAIRIE	N/A	N	Y	1938	1938	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3400 PRAIRIE	N/A	N	Y	1930	1930	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3401 PRAIRIE	N/A	N	Y	1954	1954	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3404 PRAIRIE	N/A	N	Y	1931	1931	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3405 PRAIRIE	N/A	N	Y	1937	1937	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3408 PRAIRIE	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3409 PRAIRIE	N/A	N	Y	1937	1937	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3412 PRAIRIE	N/A	N	Y	1938	1938	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3413 PRAIRIE	N/A	N	Y	1932	1932	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)							
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)							
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)							
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)							
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)		Cast/Ductile Iron or Transite (O)							
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Plastic - PVC, HDPE, PEX (P)					Leave blank if no Lead			
3416 PRAIRIE	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N	
3417 PRAIRIE	N/A	N	Y	1937	1937	Visual Inspection	U	C	P	NL	u	N/R	N			N	
3421 PRAIRIE	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N	
3500 PRAIRIE	N/A	N	Y	1936	1936	Visual Inspection	U	C	P	NL	u	N/R	N			N	
3501 PRAIRIE	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N	
2801 PRAIRIE APT 3	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
208 PRICE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
210 PRICE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
211 PRICE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
212 PRICE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
213 PRICE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
214 PRICE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
215 PRICE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
216 PRICE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
217 PRICE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
218 PRICE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
220 PRICE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
222 PRICE	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
300 PRICE	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N	
301 PRICE	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
304 PRICE	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
305 PRICE	N/A	N	Y	1996	1996	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	
308 PRICE	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
309 PRICE	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
312 PRICE	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
313 PRICE	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
316 PRICE	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
320 PRICE	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
321 PRICE	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
400 PRICE	N/A	N	Y	1974	1974	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	
401 PRICE	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
402 PRICE	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
404 PRICE	N/A	N	Y	1975	1975	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
405 PRICE	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
406 PRICE	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
408 PRICE	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
409 PRICE	N/A	N	Y	1975	1975	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
412 PRICE	N/A	N	Y	1975	1975	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
413 PRICE	N/A	N	Y	1975	1975	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
414 PRICE	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
416 PRICE	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
417 PRICE	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
418 PRICE	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
420 PRICE	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
422 PRICE	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
424 PRICE	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
426 PRICE	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
428 PRICE	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
430 PRICE	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
432 PRICE	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
434 PRICE	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
436 PRICE	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
440 PRICE	N/A	N	Y	1974	1974	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
448 PRICE	N/A	N	Y	1977	1977	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
500 PRICE	N/A	N	Y	1971	1971	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
501 PRICE	N/A	N	Y	1975	1975	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
520 PRICE	N/A	N	Y	1970	1970	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
521 PRICE	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
32 RICHMOND	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
67 RICHMOND	N/A	N	Y	1949	1968	Visual Inspection	U	C	C	NL	u	N/R	N			N		
70 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
71 RICHMOND	N/A	N	Y	1944	1999	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
74 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
75 RICHMOND	N/A	N	Y	1962	1962	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
76 RICHMOND	N/A	N	Y	1962	1962	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
77 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
78 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
79 RICHMOND	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
100 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
104 RICHMOND	N/A	N	Y	1992	1992	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
105 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
109 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
116 RICHMOND	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
117 RICHMOND	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
200 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
220 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
300 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
308 RICHMOND	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
312 RICHMOND	N/A	N	Y	1961	1961	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
316 RICHMOND	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
320 RICHMOND	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
408 RICHMOND	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
500 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
512 RICHMOND	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
520 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
600 RICHMOND	N/A	N	Y	2009	2009	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
601 RICHMOND	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
608 RICHMOND	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
609 RICHMOND	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
610 RICHMOND	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Galvanized (G)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Plastic - PVC, HDPE, PEX (P)								
							Cast/Ductile Iron or Transite (Q)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)			
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)						Cast/Ductile Iron or Transite (Q)			
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead			
612 RICHMOND	N/A	N	Y	1945	1945	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
616 RICHMOND	N/A	N	Y	1945	1945	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
617 RICHMOND	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
701 RICHMOND	N/A	N	Y	1982	1982	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
705 RICHMOND	N/A	N	Y	1886	1886	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
721 RICHMOND	N/A	N	Y	1916	1916	CUSTOMER SUIRVEY	U	C	P	NL	u	N/R	N			N		
801 RICHMOND	N/A	N	Y	1901	1901	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
809 RICHMOND	N/A	N	Y	1959	1959	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
901 RICHMOND	N/A	N	Y	2018	2018	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
905 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
913 RICHMOND	N/A	N	Y	1999	1999	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
917 RICHMOND	N/A	N	Y	1999	1999	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1021 RICHMOND	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1100 RICHMOND	N/A	N	Y	1962	1962	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1108 RICHMOND	N/A	N	Y	1946	1946	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1112 RICHMOND	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1116 RICHMOND	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1120 RICHMOND	N/A	N	Y	1978	1978	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1200 RICHMOND	N/A	N	Y	1945	1945	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1204 RICHMOND	N/A	N	Y	1963	1963	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1208 RICHMOND	N/A	N	Y	1992	1992	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1212 RICHMOND	N/A	N	Y	1906	1906	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1216 RICHMOND	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1216 RICHMOND 1/2	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1400 RICHMOND	N/A	N	Y	1906	1906	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1512 RICHMOND	N/A	N	Y	1983	1983	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1516 RICHMOND	N/A	N	Y	1956	1956	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1604 RICHMOND	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1616 RICHMOND	N/A	N	Y	1922	1922	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1801 RICHMOND	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
1804 RICHMOND	N/A	N	Y	2006	2006	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
1805 RICHMOND	N/A	N	Y	1902	1902	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1808 RICHMOND	N/A	N	Y	2006	2006	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1812 RICHMOND	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1816 RICHMOND	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
2112 RICHMOND	N/A	N	Y	1975	1975	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2201 RICHMOND	N/A	N	Y	1920	1920	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
2204 RICHMOND	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2205 RICHMOND	N/A	N	Y	1890	1890	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2208 RICHMOND	N/A	N	Y	1914	1914	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
2209 RICHMOND 1/2	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2209 RICHMOND APT 1	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
2212 RICHMOND	N/A	N	Y	1910	1910	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
2213 RICHMOND	N/A	N	Y	1913	1913	VISUAL INSPECTION/CUSTO	U	G	G	GRR	u	N/R	N			N		
2216 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
2221 RICHMOND	N/A	N	Y	1907	1907	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2221 RICHMOND 1/2	N/A	N	Y	1907	1907	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2304 RICHMOND	N/A	N	Y	1880	1880	VISUAL INSPECTION	U	P	C	NL	u	N/R	N			N		
2309 RICHMOND	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
2316 RICHMOND	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2317 RICHMOND	N/A	N	Y	1935	1935	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2320 RICHMOND	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2321 RICHMOND	N/A	N	Y	1934	1934	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2401 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2409 RICHMOND	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2413 RICHMOND	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2421 RICHMOND	N/A	N	Y	1935	1935	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
2501 RICHMOND	N/A	N	Y	1921	1921	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2504 RICHMOND	N/A	N	Y	1981	1981	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2505 RICHMOND	N/A	N	Y	1910	1910	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2508 RICHMOND	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2511 RICHMOND	N/A	N	Y	1950	1950	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2512 RICHMOND	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2513 RICHMOND	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2516 RICHMOND	N/A	N	Y	1947	1947	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
2517 RICHMOND	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2520 RICHMOND	N/A	N	Y	1991	1991	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2521 RICHMOND	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
2600 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
2601 RICHMOND	N/A	N	Y	1924	1924	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2604 RICHMOND	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2605 RICHMOND	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2608 RICHMOND	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2609 RICHMOND	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2612 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2613 RICHMOND	N/A	N	Y	1920	1920	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2616 RICHMOND	N/A	N	Y	1998	1998	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2617 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2621 RICHMOND	N/A	N	Y	1989	1989	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2700 RICHMOND	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2701 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2704 RICHMOND	N/A	N	Y	1992	1992	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2705 RICHMOND	N/A	N	Y	1920	1920	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
2709 RICHMOND	N/A	N	Y	1933	1933	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2712 RICHMOND	N/A	N	Y	1906	1906	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
2713 RICHMOND	N/A	N	Y	1926	1926	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
2716 RICHMOND	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2717 RICHMOND	N/A	N	Y	1984	1984	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2720 RICHMOND	N/A	N	Y	1903	1903	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
2721 RICHMOND	N/A	N	Y	1924	1924	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
2800 RICHMOND	N/A	N	Y	1933	1933	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2801 RICHMOND	N/A	N	Y	2005	2005	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2804 RICHMOND	N/A	N	Y	1928	1928	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		
2805 RICHMOND	N/A	N	Y	1931	1931	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2808 RICHMOND	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2809 RICHMOND	N/A	N	Y	1929	1929	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2812 RICHMOND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2813 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2817 RICHMOND	N/A	N	Y	1929	1929	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2820 RICHMOND	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2821 RICHMOND	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2900 RICHMOND	N/A	N	Y	1906	1906	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
2901 RICHMOND	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2904 RICHMOND	N/A	N	Y	1947	1947	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2905 RICHMOND	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2908 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2909 RICHMOND	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2913 RICHMOND	N/A	N	Y	1936	1936	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2917 RICHMOND	N/A	N	Y	1934	1934	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2920 RICHMOND	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2921 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3000 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3001 RICHMOND	N/A	N	Y	1934	1934	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3004 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3005 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3008 RICHMOND	N/A	N	Y	1992	1992	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
3009 RICHMOND	N/A	N	Y	1992	1992	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
3012 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3013 RICHMOND	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3016 RICHMOND	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3017 RICHMOND	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3020 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3021 RICHMOND	N/A	N	Y	1929	1929	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3100 RICHMOND	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3101 RICHMOND	N/A	N	Y	1987	1987	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3104 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3105 RICHMOND	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3108 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3109 RICHMOND	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3112 RICHMOND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3113 RICHMOND	N/A	N	Y	1922	1922	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3116 RICHMOND	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3120 RICHMOND	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3121 RICHMOND	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3200 RICHMOND	N/A	N	Y	1900	1900	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
3201 RICHMOND	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3204 RICHMOND	N/A	N	Y	1924	1924	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3205 RICHMOND	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3208 RICHMOND	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
3209 RICHMOND	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3212 RICHMOND	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3213 RICHMOND	N/A	N	Y	1938	1938	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3216 RICHMOND	N/A	N	Y	1938	1938	CUSTOMER SURVEY	U	G	G	GRR	u	N/R	N			N		
3217 RICHMOND	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3220 RICHMOND	N/A	N	Y	1943	1943	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3221 RICHMOND	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3224 RICHMOND	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3225 RICHMOND	N/A	N	Y	1920	1920	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3229 RICHMOND	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3232 RICHMOND	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3233 RICHMOND	N/A	N	Y	1920	1920	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3300 RICHMOND	N/A	N	Y	1910	1910	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3301 RICHMOND	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3304 RICHMOND	N/A	N	Y	1988	1988	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3305 RICHMOND	N/A	N	Y	1916	1916	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3308 RICHMOND	N/A	N	Y	1972	1972	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3309 RICHMOND	N/A	N	Y	1925	1925	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3312 RICHMOND	N/A	N	Y	1911	1911	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3313 RICHMOND	N/A	N	Y	1913	1913	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3316 RICHMOND	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3317 RICHMOND	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3320 RICHMOND	N/A	N	Y	1896	1896	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3321 RICHMOND	N/A	N	Y	1932	1932	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3324 RICHMOND	N/A	N	Y	1967	1967	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3325 RICHMOND	N/A	N	Y	1945	1945	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3328 RICHMOND	N/A	N	Y	1916	1916	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3329 RICHMOND	N/A	N	Y	1945	1945	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3332 RICHMOND	N/A	N	Y	1913	1913	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3333 RICHMOND	N/A	N	Y	1906	1906	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3336 RICHMOND	N/A	N	Y	1938	1938	Visual Inspection	U	G	C	GRR	u	N/R	N			N		
3340 RICHMOND	N/A	N	Y	1938	1938	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
3341 RICHMOND	N/A	N	Y	1964	1964	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3344 RICHMOND	N/A	N	Y	1937	1937	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3345 RICHMOND	N/A	N	Y	1947	1947	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
3400 RICHMOND	N/A	N	Y	1938	1938	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
3405 RICHMOND	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3408 RICHMOND	N/A	N	Y	1995	1995	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3409 RICHMOND	N/A	N	Y	1945	1945	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3413 RICHMOND	N/A	N	Y	1939	1939	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N		
3420 RICHMOND	N/A	N	Y	1950	1950	Visual Inspection	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
3421 RICHMOND	N/A	N	Y	1939	1939	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
28 RICHMOND AVE	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
WEST ROUTE 16	N/A	N	Y			Visual Inspection	U	C	P	NL	u	N/R	N			N		
711 RUDY	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
712 RUDY	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
713 RUDY	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
714 RUDY	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
715 RUDY	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
716 RUDY	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
717 RUDY	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
718 RUDY	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
719 RUDY	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
721 RUDY	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
723 RUDY	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
798 RUDY	N/A	N	Y	1990	1990	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
800 RUDY	N/A	N	Y	1990	1990	Visual Inspection	U	C	C	NL	u	N/R	N			N		
801 RUDY	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
802 RUDY	N/A	N	Y	1990	1990	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
803 RUDY	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
804 RUDY	N/A	N	Y	1990	1990	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
805 RUDY	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
806 RUDY	N/A	N	Y	1990	1990	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
807 RUDY	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
808 RUDY	N/A	N	Y	1990	1990	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
809 RUDY	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
810 RUDY	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
812 RUDY	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
814 RUDY	N/A	N	Y	1990	1990	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
816 RUDY	N/A	N	Y	1990	1990	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
900 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
901 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
904 RUDY	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
905 RUDY	N/A	N	Y	1956	1956	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
908 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
909 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
912 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
913 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
916 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
917 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
920 RUDY	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
921 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
925 RUDY	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
929 RUDY	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
933 RUDY	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
950 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
954 RUDY	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
958 RUDY	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
962 RUDY	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
966 RUDY	N/A	N	Y	1958	1958	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
970 RUDY	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1000 RUDY	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1001 RUDY	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1004 RUDY	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1005 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1008 RUDY	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1009 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1012 RUDY	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1013 RUDY	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1016 RUDY	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1020 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1050 RUDY	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1054 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1058 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1062 RUDY	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1066 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1070 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1100 RUDY	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1101 RUDY	N/A	N	Y	1959	1959	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
1104 RUDY	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1105 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1108 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1112 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1116 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1120 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1121 RUDY	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1200 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1201 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1206 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
1209 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1212 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1220 RUDY	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1221 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1300 RUDY	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1301 RUDY	N/A	N	Y	1957	1957	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1309 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1310 RUDY	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
1320 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1321 RUDY	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1400 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1401 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Galvanized (G)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Plastic - PVC, HDPE, PEX (P)								
							Cast/Ductile Iron or Transite (Q)	Lead (L)	Lead (L)						Cast/Ductile Iron or Transite (Q)			
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Plastic - PVC, HDPE, PEX (P)			
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead			
1407 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1412 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1413 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1418 RUDY	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1421 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1424 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1500 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1501 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1506 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1507 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1512 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1513 RUDY	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1518 RUDY	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1519 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1524 RUDY	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1525 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1530 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1531 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1600 RUDY	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1601 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1606 RUDY	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
1607 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1612 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1613 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1618 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1619 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1624 RUDY	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1625 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1630 RUDY	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1816 RUDY APT 1	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1816 RUDY APT 2	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1816 RUDY APT 3	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1816 RUDY APT 4	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1833 RUDY	N/A	N	Y	1969	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1820 RUDY APT 10	N/A	N	Y	1985	1985	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1820 RUDY APT 11	N/A	N	Y	1985	1985	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1816 RUDY APT 12	N/A	N	Y	1969	1969	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1816 RUDY APT 13	N/A	N	Y	1969	1969	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1816 RUDY APT 14	N/A	N	Y	1969	1969	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1820 RUDY APT 5	N/A	N	Y	1985	1985	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1820 RUDY APT 6	N/A	N	Y	1985	1985	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1820 RUDY APT 7	N/A	N	Y	1985	1985	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1820 RUDY APT 8	N/A	N	Y	1985	1985	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1820 RUDY APT 9	N/A	N	Y	1985	1985	Visual Inspection	U	C	C	NL	u	N/R	N			N		
109 S 11TH	N/A	N	Y	1915	1915	MAINTENANCE RECORDS/V	U	C	C	UNL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)									
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)															
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead													
400 S 11TH	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N	
404 S 11TH	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N	
408 S 11TH APT 3	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N	
313 S 12TH	N/A	N	Y	1916	1916	MAINTENANCE RECORDS	U	C	C	UNL	u	N/R	N			N	
409 S 12TH	N/A	N	Y	1988	1988	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	
413 S 12TH	N/A	N	Y	1988	1988	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	
416 S 12TH	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N	
420 S 12TH	N/A	N	Y	1937	1937	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N	
505 S 12TH	N/A	N	Y	1999	1999	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N	
512 S 12TH	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N	
520 S 12TH	N/A	N	Y	1945	1945	MAINTENANCE RECORDS	U	C	P	UNL	u	N/R	N			N	
1300 S 12TH	N/A	N	Y	1976	1976	CUSTOMER SURVEY	U	O	P	NL	u					N	
312 S 13TH	N/A	N	Y	1999	1999	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
412 S 13TH	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
414 S 13TH	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
512 S 13TH	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
900 S 13TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
904 S 13TH	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
905 S 13TH	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
908 S 13TH	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N	
909 S 13TH	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N	
912 S 13TH	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N	
913 S 13TH	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
916 S 13TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
917 S 13TH	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
920 S 13TH	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	P	G	GRR	u	N/R	N			N	
921 S 13TH	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N	
1000 S 13TH	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
1004 S 13TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
1008 S 13TH	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
1009 S 13TH	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N	
1012 S 13TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
1013 S 13TH	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
1016 S 13TH	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
1017 S 13TH	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
1020 S 13TH	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N	
312 S 14TH	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
317 S 14TH	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
401 S 14TH	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
405 S 14TH	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
415 S 14TH	N/A	N	Y	1876	1876	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
509 S 14TH	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
513 S 14TH	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
612 S 14TH	N/A	N	Y	1898	1898	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
613 S 14TH	N/A	N	Y	1887	1887	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N	

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)							
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)							
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)							
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)							
613 S 14TH 1/2	N/A	N	Y	1902	1902	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N		Leave blank if no Lead	N	
616 S 14TH	N/A	N	Y	1917	1917	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
617 S 14TH	N/A	N	Y	1876	1876	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
621 S 14TH	N/A	N	Y	1876	1876	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
625 S 14TH	N/A	N	Y	1876	1876	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
628 S 14TH	N/A	N	Y	1920	1920	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N	
629 S 14TH	N/A	N	Y	1876	1876	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
632 S 14TH	N/A	N	Y	1907	1907	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
701 S 14TH	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
705 S 14TH	N/A	N	Y	1912	1912	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
709 S 14TH	N/A	N	Y	1908	1908	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
713 S 14TH	N/A	N	Y	1908	1908	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
721 S 14TH	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
801 S 14TH	N/A	N	Y	1911	1911	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
805 S 14TH	N/A	N	Y	1981	1981	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
813 S 14TH	LC3T055	N	Y	1981	1981	CUSTOMER SURVEY	U	G	C/G/P	GRR	u	N/R	N			N	
817 S 14TH	N/A	N	Y	1981	1981	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
900 S 14TH	N/A	N	Y	1981	1981	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
901 S 14TH	N/A	N	Y	1981	1981	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N	
904 S 14TH	N/A	N	Y	1981	1981	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
905 S 14TH	N/A	N	Y	1981	1981	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
908 S 14TH	N/A	N	Y	1981	1981	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
909 S 14TH	N/A	N	Y	1981	1981	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
913 S 14TH	N/A	N	Y	1981	1981	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
914 S 14TH	N/A	N	Y	1981	1981	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
920 S 14TH	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
921 S 14TH	N/A	N	Y	1921	1921	CUSTOMER SURVEY	U	G	G	GRR	u	N/R	N			N	
1000 S 14TH	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N	
1004 S 14TH	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
1009 S 14TH	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
1013 S 14TH	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N	
1016 S 14TH	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N	
1017 S 14TH	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
1100 S 14TH	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N	
1101 S 14TH	N/A	N	Y	1922	1922	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
1105 S 14TH	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
1109 S 14TH	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
1112 S 14TH	N/A	N	Y	2002	2002	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
1113 S 14TH	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
1116 S 14TH	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
1117 S 14TH	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
1120 S 14TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
1121 S 14TH	N/A	N	Y	1905	1905	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
1200 S 14TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
1201 S 14TH	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)			Cast/Ductile Iron or Transite (O)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)			Leave blank if no Lead								
1204 S 14TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1205 S 14TH	N/A	N	Y	1935	1935	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1208 S 14TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1212 S 14TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1213 S 14TH	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1216 S 14TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1217 S 14TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1220 S 14TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1300 S 14TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1301 S 14TH	N/A	N	Y	1942	1942	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1304 S 14TH	N/A	N	Y	2008	2008	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1305 S 14TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1308 S 14TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1309 S 14TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1312 S 14TH	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1313 S 14TH	N/A	N	Y	1946	1946	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
1316 S 14TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1317 S 14TH	N/A	N	Y	1942	1942	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1320 S 14TH	N/A	N	Y	1946	1946	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
1400 S 14TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1401 S 14TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1404 S 14TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1405 S 14TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1408 S 14TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1409 S 14TH	N/A	N	Y	1947	1947	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N		
1412 S 14TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1413 S 14TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1416 S 14TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1417 S 14TH	N/A	N	Y	1947	1947	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
409 S 15TH	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
415 S 15TH	N/A	N	Y	1906	1906	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
417 S 15TH	N/A	N	Y	1966	1966	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N		
511 S 15TH	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
612 S 15TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
616 S 15TH	N/A	N	Y	1945	1945	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
620 S 15TH	N/A	N	Y	1945	1945	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
624 S 15TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
628 S 15TH	N/A	N	Y	1946	1946	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
632 S 15TH	N/A	N	Y	1944	1944	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
700 S 15TH	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
704 S 15TH	N/A	N	Y	1921	1921	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
705 S 15TH	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
708 S 15TH	N/A	N	Y	1955	1955	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
709 S 15TH	N/A	N	Y	1930	1930	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
712 S 15TH	N/A	N	Y	1948	1948	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (Q)								
713 S 15TH	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
716 S 15TH	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
717 S 15TH	N/A	N	Y	1962	1962	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
720 S 15TH	N/A	N	Y	1962	1962	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
721 S 15TH	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
800 S 15TH	N/A	N	Y	1924	1924	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
801 S 15TH	N/A	N	Y	1960	1960	CUSTOMER SURVEY	U	G	C/G/P	GRR	u	N/R	N			N		
804 S 15TH	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
805 S 15TH	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
808 S 15TH	N/A	N	Y	1917	1917	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
809 S 15TH	N/A	N	Y	1914	1914	Maintenance Report/VISUA	U	p	c	NL	u	N/R	N			N		
812 S 15TH	N/A	N	Y	1914	1914	Maintenance Report/VISUA	U	P	P	NL	u	N/R	N			N		
813 S 15TH	N/A	N	Y	1914	1914	Maintenance Report/VISUA	U	G	G	GRR	u	N/R	N			N		
816 S 15TH	N/A	N	Y	1914	1914	Maintenance Report/VISUA	U	G	P	GRR	u	N/R	N			N		
817 S 15TH	N/A	N	Y	1929	1929	Maintenance Report/VISUA	U	G	P	GRR	u	N/R	N			N		
900 S 15TH	N/A	N	Y	1933	1933	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
901 S 15TH	N/A	N	Y	1933	1933	CUSTOMER SURVEY/VISUA	U	C	P	NL	u	N/R	N			N		
908 S 15TH	N/A	N	Y	1956	1956	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
912 S 15TH	N/A	N	Y	1956	1956	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
917 S 15TH	N/A	N	Y	1955	1955	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
920 S 15TH	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	c	c	NL	u	N/R	N			N		
921 S 15TH	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	p	NL	u	N/R	N			N		
1000 S 15TH	N/A	N	Y	1994	1994	CUSTOMER SURVEY/VISUA	U	C	C	NL	u	N/R	N			N		
1001 S 15TH	N/A	N	Y	1925	1925	Maintenance Report/VISUA	U	G	P	GRR	u	N/R	N			N		
1004 S 15TH	N/A	N	Y	1996	1996	CUSTOMER SURVEY/VISUA	U	C	P	NL	u	N/R	N			N		
1005 S 15TH	N/A	N	Y	1925	1925	Maintenance Report/VISUA	U	G	P	GRR	u	N/R	N			N		
1008 S 15TH	N/A	N	Y	1927	1927	CUSTOMER SURVEY/VISUA	U	G	P	GRR	u	N/R	N			N		
1009 S 15TH	N/A	N	Y	1972	1972	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1012 S 15TH	N/A	N	Y	1937	1937	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1013 S 15TH	N/A	N	Y	1897	1897	CUSTOMER SURVEY/VISUA	U	C	C	NL	u	N/R	N			N		
1016 S 15TH	N/A	N	Y	1977	1977	CUSTOMER SURVEY/VISUA	U	C	P	NL	u	N/R	N			N		
1017 S 15TH	N/A	N	Y	1910	1910	Maintenance Report/VISUA	U	G	P	GRR	u	N/R	N			N		
1020 S 15TH	N/A	N	Y	2000	2000	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1100 S 15TH	N/A	N	Y	1922	1922	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
1101 S 15TH	N/A	N	Y	1928	1928	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1104 S 15TH	N/A	N	Y	1972	1972	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
1105 S 15TH	N/A	N	Y	1907	1907	CUSTOMER SURVEY/VISUA	U	G	P	GRR	u	N/R	N			N		
1108 S 15TH	N/A	N	Y	1994	1994	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1109 S 15TH	N/A	N	Y	1940	1940	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1112 S 15TH	N/A	N	Y	1926	1926	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1113 S 15TH	N/A	N	Y	1897	1897	CUSTOMER SURVEY/VISUA	U	c	p	NL	u	N/R	N			N		
1116 S 15TH	N/A	N	Y	1929	1929	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1117 S 15TH	N/A	N	Y	1997	1997	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1120 S 15TH	N/A	N	Y	1992	1992	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
1121 S 15TH	N/A	N	Y	1993	1993	Maintenance Report/VISUA	U	C	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
1200 S 15TH	N/A	N	Y	1924	1924	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1201 S 15TH	N/A	N	Y	1956	1956	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
1204 S 15TH	N/A	N	Y	1989	1989	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1205 S 15TH	N/A	N	Y	1940	1940	Maintenance Report/VISUA	U	G	G	GRR	u	N/R	N			N		
1208 S 15TH	N/A	N	Y	1988	1988	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1209 S 15TH	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
1212 S 15TH	N/A	N	Y	1926	1926	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
1213 S 15TH	N/A	N	Y	1926	1926	Maintenance Report/VISUA	U	G	P	GRR	u	N/R	N			N		
1216 S 15TH	N/A	N	Y	1986	1986	CUSTOMER SURVEY/VISUA	U	C	P	NL	u	N/R	N			N		
1217 S 15TH	N/A	N	Y	1935	1935	Maintenance Report/VISUA	U	G	G	GRR	u	N/R	N			N		
1300 S 15TH	N/A	N	Y	1992	1992	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1301 S 15TH	N/A	N	Y	1976	1976	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
1304 S 15TH	N/A	N	Y	1996	1996	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1305 S 15TH	DAYCARE001A	N	Y	1957	1957	Maintenance Report/VISUA	U	G	C	GRR	u	N/R	N			N		
1308 S 15TH	N/A	N	Y	1996	1996	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1309 S 15TH	N/A	N	Y	1976	1976	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1313 S 15TH	N/A	N	Y	1992	1992	Maintenance Report/VISUA	U	C	G	GRR	u	N/R	N			N		
1316 S 15TH	N/A	N	Y	1992	1992	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
1320 S 15TH	N/A	N	Y	1902	1902	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1400 S 15TH	N/A	N	Y	1992	1992	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
1401 S 15TH	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1404 S 15TH	N/A	N	Y	1940	1940	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1405 S 15TH	N/A	N	Y	1947	1947	CUSTOMER SURVEY/VISUA	U	C	C	NL	u	N/R	N			N		
1408 S 15TH	N/A	N	Y	1947	1947	Maintenance Report/VISUA	U	G	G	GRR	u	N/R	N			N		
1409 S 15TH	N/A	N	Y	1947	1947	CUSTOMER SURVEY/VISUA	U	C	G	GRR	u	N/R	N			N		
1412 S 15TH	N/A	N	Y	1947	1947	Maintenance Report/VISUA	U	G	P	GRR	u	N/R	N			N		
1413 S 15TH	N/A	N	Y	1947	1947	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1416 S 15TH	N/A	N	Y	1947	1947	Maintenance Report/VISUA	U	G	P	GRR	u	N/R	N			N		
1417 S 15TH	N/A	N	Y	1947	1947	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
421 S 16TH	N/A	N	Y	1940	1940	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
501 S 16TH	N/A	N	Y	1898	1898	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
508 S 16TH	N/A	N	Y	1907	1907	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
510 S 16TH	N/A	N	Y	1907	1907	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
516 S 16TH	N/A	N	Y	1897	1897	CUSTOMER SURVEY/VISUA	U	P	C	NL	u	N/R	N			N		
608 S 16TH	N/A	N	Y	1912	1912	Maintenance Report/VISUA	U	P	P	NL	u	N/R	N			N		
609 S 16TH	N/A	N	Y	1992	1992	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
611 S 16TH	N/A	N	Y	2000	2000	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
612 S 16TH	N/A	N	Y	1912	1912	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
613 S 16TH	N/A	N	Y	1995	1995	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
615 S 16TH	N/A	N	Y	1995	1995	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
616 S 16TH	N/A	N	Y	1913	1913	Maintenance Report/VISUA	U	P	P	NL	u	N/R	N			N		
617 S 16TH	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N		
700 S 16TH	N/A	N	Y	1991	1991	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
701 S 16TH	N/A	N	Y	1968	1968	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
703 S 16TH	N/A	N	Y	1912	1912	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (Q)								
705 S 16TH	N/A	N	Y	1982	1982	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
708 S 16TH	N/A	N	Y	1941	1941	Maintenance Report/VISUA	U	G	P	GRR	u	N/R	N			N		
711 S 16TH	N/A	N	Y	1913	1913	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
716 S 16TH	N/A	N	Y	1975	1975	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
717 S 16TH	N/A	N	Y	1954	1954	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
720 S 16TH	N/A	N	Y	1997	1997	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
721 S 16TH	N/A	N	Y	1927	1927	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
725 S 16TH	N/A	N	Y	1994	1994	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
800 S 16TH	N/A	N	Y	1986	1986	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
801 S 16TH	N/A	N	Y	1908	1908	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
804 S 16TH	N/A	N	Y	1991	1991	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
805 S 16TH	N/A	N	Y	1913	1913	Maintenance Report/VISUA	U	G	C	GRR	u	N/R	N			N		
808 S 16TH	N/A	N	Y	1980	1980	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
812 S 16TH	N/A	N	Y	1973	1973	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
821 S 16TH	N/A	N	Y	1992	1992	CUSTOMER SURVEY/VISUA	U	C	G	GRR	u	N/R	N			N		
900 S 16TH	N/A	N	Y	1997	1997	Maintenance Report	U	C	c	NL	u	N/R	N			N		
904 S 16TH	N/A	N	Y	1911	1911	Maintenance Report/VISUA	U	P	P	NL	u	N/R	N			N		
905 S 16TH	N/A	N	Y	2003	2003	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
908 S 16TH	N/A	N	Y	1950	1950	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
909 S 16TH	N/A	N	Y	2001	2001	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
909 S 16TH 1/2	N/A	N	Y	2001	2001	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
912 S 16TH	N/A	N	Y	1991	1991	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
913 S 16TH	N/A	N	Y	2001	2001	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
916 S 16TH	N/A	N	Y	1964	1964	CUSTOMER SURVEY/VISUA	U	C	P	NL	u	N/R	N			N		
917 S 16TH	N/A	N	Y	1965	1965	Maintenance Report	U	G	p	GRR	u	N/R	N			N		
920 S 16TH	N/A	N	Y	1989	1989	Maintenance Report	U	C	c	NL	u	N/R	N			N		
921 S 16TH	N/A	N	Y	1911	1911	CUSTOMER SURVEY/VISUA	U	P	P	NL	u	N/R	N			N		
1000 S 16TH	N/A	N	Y	1911	1911	Maintenance Report	U	c	c	NL	u	N/R	N			N		
1004 S 16TH	N/A	N	Y	1913	1913	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1005 S 16TH	N/A	N	Y	1905	1905	CUSTOMER SURVEY/VISUA	U	G	C/P	GRR	u	N/R	N			N		
1008 S 16TH	N/A	N	Y	1978	1978	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1009 S 16TH	N/A	N	Y	1912	1912	Maintenance Report/VISUA	U	C	G	GRR	u	N/R	N			N		
1012 S 16TH	N/A	N	Y	1904	1904	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1013 S 16TH	N/A	N	Y	1978	1978	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
1017 S 16TH	N/A	N	Y	1913	1913	Maintenance Report/VISUA	U	G	C	GRR	u	N/R	N			N		
1020 S 16TH	N/A	N	Y	1966	1966	CUSTOMER SURVEY/VISUA	U	C	C/P	NL	u	N/R	N			N		
1100 S 16TH	N/A	N	Y	1968	1968	CUSTOMER SURVEY/VISUA	U	C	P	NL	u	N/R	N			N		
1101 S 16TH	N/A	N	Y	1968	1968	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
1104 S 16TH	N/A	N	Y	1992	1992	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
1105 S 16TH	N/A	N	Y	1992	1992	Maintenance Report/VISUA	U	C	G	GRR	u	N/R	N			N		
1108 S 16TH	N/A	N	Y	1960	1960	Maintenance Report/VISUA	U	C	C	NL	u	N/R	N			N		
1109 S 16TH	N/A	N	Y	1919	1919	Maintenance Report/VISUA	U	G	P	GRR	u	N/R	N			N		
1112 S 16TH	N/A	N	Y	1913	1913	Maintenance Report/VISUA	U	P	p	NL	u	N/R	N			N		
1113 S 16TH	N/A	N	Y	1914	1914	Maintenance Report/Custoi	U	G	C	GRR	u	N/R	N			N		
1116 S 16TH	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
1117 S 16TH	N/A	N	Y	1986	1986	Maintenance Report/CUST	U	C	P	NL	u	N/R	N			N		
1120 S 16TH	N/A	N	Y	1939	1939	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
1121 S 16TH	N/A	N	Y	1919	1919	CUSTOMER SURVEY/VISUA	U	G	G	GRR	u	N/R	N			N		
1201 S 16TH	N/A	N	Y	2010		Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
1204 S 16TH	N/A	N	Y	1917	1917	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1208 S 16TH	N/A	N	Y	1916	1916	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
1209 S 16TH	N/A	N	Y	2009		Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
1215 S 16TH	N/A	N	Y	2011	2011	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
1216 S 16TH	N/A	N	Y	1927	1927	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
1219 S 16TH	N/A	N	Y	2012		Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1220 S 16TH	N/A	N	Y	1913	1913	Maintenance Records/VISU	U	P	G	GRR	u	N/R	N			N		
1308 S 16TH	N/A	N	Y	1925	1925	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
1309 S 16TH	N/A	N	Y	1991		Maintenance Report	U	C	P	NL	u	N/R	N			N		
1312 S 16TH	N/A	N	Y	1926	1926	Maintenance Report	U	C	P	NL	u	N/R	N			N		
1313 S 16TH	N/A	N	Y	1991	1991	Maintenance Records/VISU	U	G	G	GRR	u	N/R	N			N		
1316 S 16TH	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
1321 S 16TH	N/A	N	Y	1941	1941	Maintenance Records/VISU	U	G	G	GRR	u	N/R	N			N		
1401 S 16TH	N/A	N	Y	1939	1939	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N		
1404 S 16TH	N/A	N	Y	1947	1947	Maintenance Records/VISU	U	G	G	GRR	u	N/R	N			N		
1408 S 16TH	N/A	N	Y	1941	1941	Maintenance Report	U	G	G	GRR	u	N/R	N			N		
1416 S 16TH	N/A	N	Y	1946	1946	Maintenance Report	U	G	G	GRR	u	N/R	N			N		
913 S 16TH 1/2	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
417 S 17TH	N/A	N	Y	1913	1913	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
420 S 17TH	N/A	N	Y	1939	1939	Maintenance Report	U	C	P	NL	u	N/R	N			N		
501 S 17TH	N/A	N	Y	1976	1976	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
505 S 17TH	N/A	N	Y	1923	1923	Maintenance Report	U	G	P	GRR	u	N/R	N			N		
508 S 17TH	N/A	N	Y	1940	1940	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
521 S 17TH	N/A	N	Y	1995	1995	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
700 S 17TH	N/A	N	Y	1925	1925	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
701 S 17TH	N/A	N	Y	1892	1892	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
705 S 17TH	N/A	N	Y	1917	1917	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
709 S 17TH	N/A	N	Y	1913	1913	Maintenance Records/VISU	U	G	P	GRR	u	N/R	N			N		
800 S 17TH	N/A	N	Y	1911	1911	Maintenance Report/VISUA	U	C	P	NL	u	N/R	N			N		
804 S 17TH	N/A	N	Y	1962	1962	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
808 S 17TH	N/A	N	Y	1922	1922	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
809 S 17TH	N/A	N	Y	1976	1976	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
812 S 17TH	N/A	N	Y	1999	1999	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
813 S 17TH	N/A	N	Y	1916	1916	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
816 S 17TH	N/A	N	Y	1906	1906	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
817 S 17TH	N/A	N	Y	1912	1912	Maintenance Report	U	C	C	NL	u	N/R	N			N		
900 S 17TH	N/A	N	Y	1907	1907	Maintenance Records/VISU	U	G	P	GRR	u	N/R	N			N		
901 S 17TH	N/A	N	Y	1977	1977	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
904 S 17TH	N/A	N	Y	1972	1972	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
905 S 17th	N/A	N	Y	1970	1970	Visual Inspection	U	C	C	NL	u	N/R	N			N		
908 S 17TH	N/A	N	Y	1976	1976	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
909 S 17TH	N/A	N	Y	1970	1970	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
913 S 17TH	N/A	N	Y	1970	1970	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
916 S 17TH	N/A	N	Y	1990	1990	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
917 S 17TH	N/A	N	Y	1965	1965	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
920 S 17TH	N/A	N	Y	1887	1887	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
921 S 17TH	N/A	N	Y	1908	1908	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1000 S 17TH	N/A	N	Y	1897	1897	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1001 S 17TH	N/A	N	Y	1897	1897	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1004 S 17TH	N/A	N	Y	1896	1896	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
1007 S 17TH	N/A	N	Y	1897	1897	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1008 S 17TH	N/A	N	Y	1897	1897	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
1009 S 17TH	N/A	N	Y	1904	1904	CUSTOMER SURVEY/VISUAL	U	P	P	NL	u	N/R	N			N		
1012 S 17TH	N/A	N	Y	1918	1918	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1013 S 17TH	N/A	N	Y	1906	1906	Maintenance Records/VISUAL	U	C	C	NL	u	N/R	N			N		
1016 S 17TH	N/A	N	Y	1907	1907	Maintenance Records/VISUAL	U	C	C	NL	u	N/R	N			N		
1017 S 17TH	N/A	N	Y	1907	1907	Maintenance Records/VISUAL	U	G	C	GRR	u	N/R	N			N		
1020 S 17TH	N/A	N	Y	1900	1900	Maintenance Records/VISUAL	U	C	C	NL	u	N/R	N			N		
1021 S 17TH	N/A	N	Y	1882	1882	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1101 S 17TH	N/A	N	Y	1897	1897	Maintenance Records/VISUAL	U	C	G	GRR	u	N/R	N			N		
1104 S 17TH	N/A	N	Y	1952	1952	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1108 S 17TH	N/A	N	Y	1925	1925	Maintenance Records/VISUAL	U	C	G	GRR	u	N/R	N			N		
1109 S 17TH	N/A	N	Y	1891	1891	Maintenance Records/VISUAL	U	C	G	GRR	u	N/R	N			N		
1112 S 17TH	N/A	N	Y	1922	1922	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
1113 S 17TH	N/A	N	Y	1941	1941	Maintenance Records/VISUAL	U	C	C	NL	u	N/R	N			N		
1116 S 17TH	N/A	N	Y	1927	1927	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1117 S 17TH	N/A	N	Y	1970	1970	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N		
1120 S 17TH	N/A	N	Y	1923	1923	Maintenance Records/VISUAL	U	C	C	NL	u	N/R	N			N		
1121 S 17TH	N/A	N	Y	1907	1907	Maintenance Records/VISUAL	U	C	C	NL	u	N/R	N			N		
1200 S 17TH	N/A	N	Y	2008	2008	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
1201 S 17TH	N/A	N	Y	1970	1970	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
1205 S 17TH	N/A	N	Y	1970	1970	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1208 S 17TH	N/A	N	Y	2006	2006	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1209 S 17TH	N/A	N	Y	1940	1940	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1213 S 17TH	N/A	N	Y	1970	1970	CUSTOMER SURVEY/VISUAL	U	P	C	NL	u	N/R	N			N		
1216 S 17TH	N/A	N	Y	2008	2008	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1217 S 17TH	N/A	N	Y	2008	2008	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
1220 S 17TH	N/A	N	Y	2006	2006	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1221 S 17TH	N/A	N	Y	1970	1970	Maintenance Report	U	G	P	GRR	u	N/R	N			N		
1300 S 17TH	N/A	N	Y	1970	1970	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N		
1301 S 17TH	N/A	N	Y	1954	1954	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1304 S 17TH	N/A	N	Y	1990	1990	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1305 S 17TH	N/A	N	Y	1923	1923	Maintenance Records/VISUAL	U	C	C	NL	u	N/R	N			N		
1308 S 17TH	N/A	N	Y	1970	1970	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
1309 S 17TH	N/A	N	Y	1925	1925	Maintenance Records/VISUAL	U	G	C	GRR	u	N/R	N			N		
1312 S 17TH	N/A	N	Y	1970	1970	Maintenance Records/VISUAL	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
1313 S 17TH	N/A	N	Y	1927	1927	Maintenance Records/VISUAL	U	G	C	GRR	u	N/R	N			N		
1316 S 17TH	N/A	N	Y	1925	1925	Maintenance Records/VISUAL	U	G	C	GRR	u	N/R	N			N		
1317 S 17TH	N/A	N	Y	1928	1928	CUSTOMER SURVEY/VISUAL	U	G	G	GRR	u	N/R	N			N		
1320 S 17TH	N/A	N	Y	1928	1928	Maintenance Records/VISUAL	U	G	P	GRR	u	N/R	N			N		
1321 S 17TH	N/A	N	Y	1927	1927	Maintenance Records/VISUAL	U	G	P	GRR	u	N/R	N			N		
1408 S 17TH	N/A	N	Y	1941	1941	Maintenance Records/VISUAL	U	P	G	GRR	u	N/R	N			N		
1409 S 17TH	N/A	N	Y	1928	1928	Maintenance Records/VISUAL	U	C	C	NL	u	N/R	N			N		
801 S 19TH	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N		
804 S 19TH	N/A	N	Y	1938	1938	Visual Inspection	U	C	P	NL	u	N/R	N			N		
912 S 19TH	N/A	N	Y	1937	1937	Visual Inspection	U	C	P	NL	u	N/R	N			N		
913 S 19TH	N/A	N	Y	1968	1968	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1021 S 19TH	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2206 S 19TH	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2210 S 19TH	N/A	N	Y	1963	1963	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2300 S 19TH	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2310 S 19TH	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2314 S 19TH	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2400 S 19TH	N/A	N	Y	1962	1962	Maintenance Records/VISUAL	U	C	C	NL	u	N/R	N			N		
2406 S 19TH	N/A	N	Y	1953	1953	Maintenance Records/VISUAL	U	C	P	NL	u	N/R	N			N		
2410 S 19TH	N/A	N	Y	1954	1954	Visual Inspection	U	c	c	NL	u	N/R	N			N		
2420 S 19TH	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
309 S 21ST 1&2	N/A	N	Y	1984	1984	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
407 S 21ST	N/A	N	Y	1978	1978	Visual Inspection	U	C	P	NL	u	N/R	N			N		
420 S 21ST	N/A	N	Y	1940	1940	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
612 S 21ST	N/A	N	Y	1934	1934	Visual Inspection	U	C	P	NL	u	N/R	N			N		
613 S 21ST	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N		
616 S 21ST	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N		
621 S 21ST	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N		
624 S 21ST	N/A	N	Y	1896	1896	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
628 S 21ST	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N		
630 S 21ST	N/A	N	Y	1948	2023	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
634 S 21ST	N/A	N	Y	1944	1944	Visual Inspection	U	C	P	NL	u	N/R	N			N		
636 S 21ST	N/A	N	Y	1935	1935	Visual Inspection	U	C	P	NL	u	N/R	N			N		
716 S 21ST	N/A	N	Y	1935	1935	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
309 S 21ST UNIT 3	N/A	N	Y	1984	1984	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
309 S 21ST UNIT 5	N/A	N	Y	1984	1984	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
309 S 21ST UNIT 6	N/A	N	Y	1984	1984	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
317 S 22ND	N/A	N	Y	1992	1992	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N		
321 S 22ND	N/A	N	Y	1976	1976	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
709 S 22ND	N/A	N	Y	1953	1953	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
712 S 22ND	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N		
713 S 22ND	N/A	N	Y	2010	2010	Visual Inspection	U	C	P	NL	u	N/R	N			N		
717 S 22ND	N/A	N	Y	2011	2011	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
720 S 22ND	N/A	N	Y	1973	1973	Visual Inspection	U	C	P	NL	u	N/R	N			N		
709 S 23RD	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Lead (L)	Lead (L)								
Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)																
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
713 S 23RD	N/A	N	Y	1954	1954	Maintenance Records/VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
716 S 23RD	N/A	N	Y	1986	1986	Visual Inspection	U	C	P	NL	u	N/R	N			N		
721 S 23RD	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N		
809 S 23RD	N/A	N	Y	1959	1959	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
813 S 23RD	N/A	N	Y	1960	1960	Visual Inspection	U	C	P	NL	u	N/R	N			N		
816 S 23RD	N/A	N	Y	1998	1998	CUSTOMER SURVEY/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
817 S 23RD	N/A	N	Y	1961	1961	Visual Inspection	U	P	P	NL	u	N/R	N			N		
820 S 23RD	N/A	N	Y	1960	1960	CUSTOMER SURVEY/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
821 S 23RD	N/A	N	Y	1961	1961	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
825 S 23RD	N/A	N	Y	1960	1960	Visual Inspection	U	C	P	NL	u	N/R	N			N		
900 S 23RD	N/A	N	Y	2000	2000	Visual Inspection	U	C	P	NL	u	N/R	N			N		
901 S 23RD	N/A	N	Y	1963	1963	CUSTOMER SURVEY/VISUAL INSPECTION	U	C	C/P	NL	u	N/R	N			N		
904 S 23RD	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
905 S 23RD	N/A	N	Y	1961	1961	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
908 S 23RD	N/A	N	Y	1961	1961	Visual Inspection	U	C	C	NL	u	N/R	N			N		
909 S 23RD	N/A	N	Y	1960	1960	Visual Inspection	U	C	P	NL	u	N/R	N			N		
912 S 23RD	N/A	N	Y	1961	1961	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
913 S 23RD	N/A	N	Y	1960	1960	Visual Inspection	U	C	P	NL	u	N/R	N			N		
916 S 23RD	N/A	N	Y	1960	1960	Visual Inspection	U	C	P	NL	u	N/R	N			N		
917 S 23RD	N/A	N	Y	1960	1960	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1000 S 23RD	N/A	N	Y	1959	1959	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1001 S 23RD	N/A	N	Y	1960	1960	CUSTOMER SURVEY/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1004 S 23RD	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1005 S 23RD	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1008 S 23RD	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1009 S 23RD	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1012 S 23RD	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1013 S 23RD	N/A	N	Y	1959	1982	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1016 S 23RD	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1020 S 23RD	N/A	N	Y	1963	1963	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1021 S 23RD	N/A	N	Y	1962	1962	CUSTOMER SURVEY/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1104 S 23RD	N/A	N	Y	1965	1965	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1105 S 23RD	N/A	N	Y	1964	1964	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1108 S 23RD	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1112 S 23RD	N/A	N	Y	1998	1998	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1200 S 23RD	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1204 S 23RD	N/A	N	Y	1964	1964	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
113 S 24TH	N/A	N	Y	1982	1982	Visual Inspection	U	C	P	NL	u	N/R	N			N		
113 S 24TH	N/A	N	Y	1918	1918	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
713 S 24TH	N/A	N	Y	1916	1916	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
716 S 24TH	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N		
720 S 24TH	N/A	N	Y	2006	2006	Visual Inspection	U	C	P	NL	u	N/R	N			N		
721 S 24TH	N/A	N	Y	1976	1976	Visual Inspection	U	C	C	NL	u	N/R	N			N		
724 S 24TH	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N		
725 S 24TH	N/A	N	Y	1959	1959	Visual Inspection	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
729 S 24TH	N/A	N	Y	1960	1960	Visual Inspection	U	C	P	NL	u	N/R	N			N		
733 S 24TH	N/A	N	Y	1959	1959	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
113 S 25TH	N/A	N	Y	1911	1911	Visual Inspection	U	C	C	NL	u	N/R	N			N		
117 S 25TH	N/A	N	Y	1986	1986	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
121 S 25TH	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N		
501 S 25TH	N/A	N	Y	1950	1950	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
509 S 25TH	N/A	N	Y	1891	1891	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
708 S 25TH	N/A	N	Y	1984	1984	CUSTOMER SURVEY/VISUAL	U	C	C/P	NL	u	N/R	N			N		
712 S 25TH	N/A	N	Y	1916	1916	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
713 S 25TH	N/A	N	Y	1944	1944	Visual Inspection	U	P	P	NL	u	N/R	N			N		
716 S 25TH	N/A	N	Y	1949	1949	Maintenance Records/VISU	U	C	G	GRR	u	N/R	N			N		
720 S 25TH	N/A	N	Y	1950	1950	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
721 S 25TH	N/A	N	Y	1976	1976	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1125 S 25TH	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N		
109 S 26TH	N/A	N	Y	1973	1973	Visual Inspection	U	C	P	NL	u	N/R	N			N		
112 S 26TH	N/A	N	Y	1978	1978	Visual Inspection	U	C	P	NL	u	N/R	N			N		
114 S 26TH	N/A	N	Y	1978	1978	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
115 S 26TH	N/A	N	Y	1973	1973	Visual Inspection	U	C	P	NL	u	N/R	N			N		
117 S 26TH	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
120 S 26TH	N/A	N	Y	1895	1895	Visual Inspection	U	G	C	GRR	u	N/R	N			N		
200 S 26TH	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
500 S 26TH	N/A	N	Y	1943	1943	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
504 S 26TH	N/A	N	Y	1990	1990	Visual Inspection	U	C	P	NL	u	N/R	N			N		
513 S 26TH	N/A	N	Y	1954	1954	Visual Inspection	U	C	C	NL	u	N/R	N			N		
620 S 26TH	N/A	N	Y	1958	1958	Visual Inspection	U	C	C	NL	u	N/R	N			N		
721 S 26TH	N/A	N	Y	1977	1977	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
500 S 27TH	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
504 S 27TH	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
608 S 27TH	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
617 S 27TH	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N		
621 S 27TH	N/A	N	Y	1961	1961	Visual Inspection	U	C	C	NL	u	N/R	N			N		
712 S 27TH	N/A	N	Y	1977	1977	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
720 S 27TH	N/A	N	Y	1977	1977	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
1017 S 27TH	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1021 S 27TH	N/A	N	Y	1999	1999	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1101 S 27TH	N/A	N	Y	1999	1999	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1111 S 27TH	N/A	N	Y	2000	2000	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1120 S 27TH	N/A	N	Y	1993	1993	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
1124 S 27TH	N/A	N	Y	1993	1993	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
1125 S 27TH	N/A	N	Y	1995	1995	Visual Inspection	U	C	C	NL	u	N/R	N			N		
500 S 28TH	N/A	N	Y	2001	2001	Visual Inspection	U	C	P	NL	u	N/R	N			N		
508 S 28TH	N/A	N	Y	2001	2001	Visual Inspection	U	C	P	NL	u	N/R	N			N		
612 S 28TH	N/A	N	Y	1959	1959	Visual Inspection	U	C	C	NL	u	N/R	N			N		
717 S 28TH	N/A	N	Y	1951	1951	CUSTOMER SURVEY/VISUAL	U	G	P	GRR	u	N/R	N			N		
721 S 28TH	N/A	N	Y	1951	1951	Visual Inspection	U	P	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
205 S 29TH	N/A	N	Y	1975	1975	Visual Inspection	U	C	P	NL	u	N/R	N			N		
500 S 29TH	N/A	N	Y	1975	1975	Visual Inspection	U	C	P	NL	u	N/R	N			N		
504 S 29TH	N/A	N	Y	1995	1995	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
709 S 29TH	N/A	N	Y	1975	1975	Visual Inspection	U	C	P	NL	u	N/R	N			N		
713 S 29TH	N/A	N	Y	1930	1930	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
716 S 29TH	N/A	N	Y	1930	1930	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
717 S 29TH	N/A	N	Y	1940	1940	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
720 S 29TH	N/A	N	Y	1930	1930	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
721 S 29TH	N/A	N	Y	1930	1930	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
1304 S 2ND	N/A	N	Y	1970	1970	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
1305 S 2ND	N/A	N	Y	1970	1970	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1308 S 2ND	N/A	N	Y	1970	1970	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1309 S 2ND	N/A	N	Y	1970	1970	Maintenance Records	U	C	c	NL	u	N/R	N			N		
1312 S 2ND	N/A	N	Y	1970	1970	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1313 S 2ND	N/A	N	Y	1970	1970	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1316 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1317 S 2ND	N/A	N	Y	1971	1971	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N		
1320 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1321 S 2ND	N/A	N	Y	1969	1969	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1400 S 2ND	N/A	N	Y	1969	1969	Maintenance Records	U	C	c	NL	u	N/R	N			N		
1401 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1404 S 2ND	N/A	N	Y	1969	1969	Maintenance Records	U	C	c	NL	u	N/R	N			N		
1405 S 2ND	N/A	N	Y	1969	1969	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
1408 S 2ND	N/A	N	Y	1969	1969	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1409 S 2ND	N/A	N	Y	1970	1970	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1412 S 2ND	N/A	N	Y	1969	1969	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1413 S 2ND	N/A	N	Y	1970	1970	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1416 S 2ND	N/A	N	Y	1969	1969	CUSTOMER SURVEY	U	c	c	NL	u	N/R	N			N		
1417 S 2ND	N/A	N	Y	1969	1969	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1420 S 2ND	N/A	N	Y	1969	1969	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1421 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1500 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1501 S 2ND	N/A	N	Y	1971	1971	Maintenance Records	U	C	c	NL	u	N/R	N			N		
1504 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1505 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1508 S 2ND	N/A	N	Y	1971	1971	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N		
1509 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1512 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N		
1513 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1516 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1520 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1521 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1600 S 2ND	N/A	N	Y	1971	1971	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1601 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1604 S 2ND	N/A	N	Y	1971	1971	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)				Leave blank if no Lead												
1605 S 2ND	N/A	N	Y	1971	1971	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1608 S 2ND	N/A	N	Y	1971	1971	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
216 S 30TH	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N		
220 S 30TH	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N		
309 S 30TH	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N		
616 S 30TH	N/A	N	Y	2006	2006	Visual Inspection	U	C	P	NL	u	N/R	N			N		
620 S 30TH	N/A	N	Y	2006	2006	Visual Inspection	U	C	P	NL	u	N/R	N			N		
707 S 30TH	N/A	N	Y	1957	1957	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
712 S 30TH	N/A	N	Y	1954	1954	Maintenance Records	U	C	P	NL	u	N/R	N			N		
713 S 30TH	N/A	N	Y	1957	1957	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
716 S 30TH	N/A	N	Y	1954	1954	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
717 S 30TH	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N		
720 S 30TH	N/A	N	Y	1954	1954	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
721 S 30TH	N/A	N	Y	1957	1957	MAINTENANCE RECORDS/v	U	C	C	NL	u	N/R	N			N		
112 S 31ST	N/A	N	Y	1957	1957	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
321 S 31ST	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N		
500 S 31ST	N/A	N	Y	1979	1979	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
501 S 31ST	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N		
505 S 31ST	N/A	N	Y	1979	1979	MAINTENANCE RECORDS/v	U	C	P	NL	u	N/R	N			N		
508 S 31ST	N/A	N	Y	1979	1979	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
509 S 31ST	N/A	N	Y	1979	1979	Visual Inspection	U	P	P	NL	u	N/R	N			N		
700 S 31ST	N/A	N	Y	2008	2008	Visual Inspection	U	C	P	NL	u	N/R	N			N		
701 S 31ST	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
706 S 31ST	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
712 S 31ST	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
713 S 31ST	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
716 S 31ST	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
717 S 31ST	N/A	N	Y	1957	1957	MAINTENANCE RECORDS/v	U	C	P	NL	u	N/R	N			N		
720 S 31ST	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N		
721 S 31ST	N/A	N	Y	1959	1959	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
208 S 32ND	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N		
212 S 32ND	LC37056	N	Y	1935	1935	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
220 S 32ND	N/A	N	Y	1952	1952	Visual Inspection	U	P	P	NL	u	N/R	N			N		
216 S 32ND	N/A	N	Y	1935	1935	Visual Inspection	U	C	P	NL	u	N/R	N			N		
502 S 32ND	N/A	N	Y	1961	1961	Visual Inspection	U	C	P	NL	u	N/R	N			N		
617 S 32ND	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
621 S 32ND	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
712 S 32ND	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
713 S 32ND	N/A	N	Y	1943	1943	Visual Inspection	U	C	P	NL	u	N/R	N			N		
716 S 32ND	N/A	N	Y	1952	1952	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
717 S 32ND	N/A	N	Y	1938	1938	Visual Inspection	U	P	P	NL	u	N/R	N			N		
720 S 32ND	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
721 S 32ND	N/A	N	Y	1953	1953	Visual Inspection	U	C	C	NL	u	N/R	N			N		
700 S 33RD	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N		
704 S 33RD	N/A	N	Y	1964	1964	Visual Inspection/CUSTOMER	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
708 S 33RD	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N		
712 S 33RD	N/A	N	Y	1967	1967	Visual Inspection	U	C	C	NL	u	N/R	N			N		
713 S 33RD	N/A	N	Y	1978	1978	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
716 S 33RD	N/A	N	Y	1971	1971	Visual Inspection	U	C	C	NL	u	N/R	N			N		
721 S 33RD	N/A	N	Y	2003	2003	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
723 S 33RD	N/A	N	Y	1976	1976	Visual Inspection	U	C	P	NL	u	N/R	N			N		
724 S 33RD	N/A	N	Y	1946	1946	CUSTOMER SURVEY	U	G	C	GRR	u	N/R	N			N		
725 S 33RD	N/A	N	Y	1978	1978	Visual Inspection	U	C	C	NL	u	N/R	N			N		
728 S 33RD	N/A	N	Y	1992	1992	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
800 S 33RD	N/A	N	Y	1992	1992	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
801 S 33RD	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
804 S 33RD	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
805 S 33RD	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
808 S 33RD	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
812 S 33RD	N/A	N	Y	1946	1946	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
817 S 33RD	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
900 S 33RD	N/A	N	Y	1950	1950	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
901 S 33RD	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
904 S 33RD	N/A	N	Y	1988	1988	Visual Inspection	U	C	C	NL	u	N/R	N			N		
905 S 33RD	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N		
908 S 33RD	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N		
909 S 33RD	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N		
913 S 33RD	N/A	N	Y	1957	1957	Visual Inspection	U	C	C	NL	u	N/R	N			N		
110 S 34TH	N/A	N	Y	2015	2015	Visual Inspection	U	P	P	NL	u	N/R	N			N		
112 S 34TH	N/A	N	Y	2015	2015	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
120 S 34TH	N/A	N	Y	2015	2015	Visual Inspection	U	P	C	NL	u	N/R	N			N		
121 S 34TH	N/A	N	Y	1908	1908	Visual Inspection	U	C	P	NL	u	N/R	N			N		
125 S 34TH	N/A	N	Y	2016	2016	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
200 S 34TH	N/A	N	Y	2015	2015	Visual Inspection	U	P	C	NL	u	N/R	N			N		
201 S 34TH	N/A	N	Y	2016	2016	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
206 S 34TH	N/A	N	Y	2015	2015	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
208 S 34TH	N/A	N	Y	2015	2015	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		
221 S 34TH	N/A	N	Y	1964	1964	Visual Inspection	U	C	C	NL	u	N/R	N			N		
712 S 34TH	N/A	N	Y	1952	1952	Visual Inspection	U	C	C	NL	u	N/R	N			N		
900 S 34TH	N/A	N	Y	1957	1957	MAINTENANCE RECORDS/Visual Inspection	U	C	P	NL	u	N/R	N			N		
904 S 34TH	N/A	N	Y	1956	1956	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
908 S 34TH	N/A	N	Y	1957	2013	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
909 S 34TH	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
912 S 34TH	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
913 S 34TH	N/A	N	Y	1960	1960	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
600 S 35TH	N/A	N	Y	2024	2024	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
604 S 35TH	N/A	N	Y	1953	1953	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
608 S 35TH	N/A	N	Y	2024	2024	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
609 S 35TH	N/A	N	Y	1961	1961	Visual Inspection	U	C	C	NL	u	N/R	N			N		
713 S 35TH	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
717 S 35TH	N/A	N	Y	1948	1948	Visual Inspection	U	P	P	NL	u	N/R	N		Leave blank if no Lead	N		
721 S 35TH	N/A	N	Y	1951	1951	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
905 S 35TH	N/A	N	Y	1967	1967	Visual Inspection	U	C	C	NL	u	N/R	N			N		
909 S 35TH	N/A	N	Y	1967	1967	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
913 S 35TH	N/A	N	Y	1967	1967	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
916 S 35TH	N/A	N	Y	1968	1968	Visual Inspection	U	C	C	NL	u	N/R	N			N		
917 S 35TH	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N		
920 S 35TH	N/A	N	Y	1967	1967	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
701 S 36TH	N/A	N	Y	1987	1987	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
705 S 36TH	N/A	N	Y	1987	1987	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
709 S 36TH	N/A	N	Y	1987	1987	Visual Inspection	U	C	C	NL	u	N/R	N			N		
713 S 36TH	N/A	N	Y	1987	1987	Visual Inspection	U	C	P	NL	u	N/R	N			N		
717 S 36TH	N/A	N	Y	1986	1986	Visual Inspection	U	C	P	NL	u	N/R	N			N		
721 S 36TH	N/A	N	Y	1987	1989	Visual Inspection/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
900 S 36TH	N/A	N	Y	1968	1968	Maintenance Records	U	C	C	NL	u	N/R	N			N		
904 S 36TH	N/A	N	Y	1969	1969	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
905 S 36TH	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N		
908 S 36TH	N/A	N	Y	1968	1968	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
909 S 36TH	N/A	N	Y	1965	1965	Visual Inspection	U	C	C	NL	u	N/R	N			N		
912 S 36TH	N/A	N	Y	1968	1968	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
913 S 36TH	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
916 S 36TH	N/A	N	Y	1968	1968	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
917 S 36TH	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1121 S 3RD	N/A	N	Y	1971	1971	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1200 S 3RD	N/A	N	Y	1978	1978	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1201 S 3RD	N/A	N	Y	1971	1971	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1220 S 3RD	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1221 S 3RD	N/A	N	Y	1959	1959	Maintenance Records	U	P	P	NL	u	N/R	N			N		
1300 S 3RD	N/A	N	Y	1957	1957	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1301 S 3RD	N/A	N	Y	1955	1955	Maintenance Records/CUSTOMER SURVEY	U	C	C	NL	U	N/R	N			N		
1304 S 3RD	N/A	N	Y	1955	1955	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1305 S 3RD	N/A	N	Y	1965	1965	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1308 S 3RD	N/A	N	Y	1955	1955	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1309 S 3RD	N/A	N	Y	1955	1955	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1312 S 3RD	N/A	N	Y	1970	1970	MAINTENANCE RECORDS/Visual Inspection	U	C	C	NL	u	N/R	N			N		
1316 S 3RD	N/A	N	Y	1955	1955	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1320 S 3RD	N/A	N	Y	1955	1955	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1400 S 3RD	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1404 S 3RD	N/A	N	Y	1955	1955	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
1405 S 3RD	N/A	N	Y	1969	1969	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1408 S 3RD	N/A	N	Y	1955	1955	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1409 S 3RD	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1412 S 3RD	N/A	N	Y	1955	1955	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1413 S 3RD	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1416 S 3RD	N/A	N	Y	1955	1955	Maintenance Records	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)			
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Leave blank if no Lead			
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)									
1417 S 3RD	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1420 S 3RD	N/A	N	Y	1959	1959	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1421 S 3RD	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1500 S 3RD	N/A	N	Y	1959		Maintenance Records	U	C	C	NL	u	N/R	N			N		
1501 S 3RD	N/A	N	Y	1956	1956	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1504 S 3RD	N/A	N	Y	1957	1957	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1505 S 3RD	N/A	N	Y	1956		MAINTENANCE RECORDS/	U	C	C	NL	u	N/R	N			N		
1507 S 3RD	N/A	N	Y	1956	1956	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1508 S 3RD	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1509 S 3RD	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1511 S 3RD	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1512 S 3RD	N/A	N	Y	1962	1962	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1513 S 3RD	N/A	N	Y	1962		CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1515 S 3RD	N/A	N	Y	1960	1960	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1516 S 3RD	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1519 S 3RD	N/A	N	Y	1959	1959	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1520 S 3RD	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1521 S 3RD	N/A	N	Y	1957	1957	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1600 S 3RD	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1604 S 3RD	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1608 S 3RD	N/A	N	Y	1969	1969	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1609 S 3RD	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1612 S 3RD	N/A	N	Y	1959	1959	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1613 S 3RD	N/A	N	Y	2018	2018	Maintenance Records	U	P	C	NL	u	N/R	N			N		
1616 S 3RD	N/A	N	Y	1958	1958	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1300 S 4TH	LC3T062	N	Y	1974	1974	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1302 S 4TH	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1303 S 4TH	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1304 S 4TH	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1305 S 4TH	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1306 S 4TH	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1307 S 4TH	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1308 S 4TH	N/A	N	Y	1953	1953	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1310 S 4TH	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1312 S 4TH	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1314 S 4TH	N/A	N	Y	1955	1955	Maintenance Records	U	C	p	NL	u	N/R	N			N		
1316 S 4TH	N/A	N	Y	1955	1955	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1318 S 4TH	N/A	N	Y	1955	1955	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1319 S 4TH	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	c	p	NL	u	N/R	N			N		
1320 S 4TH	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1321 S 4TH	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1400 S 4TH	N/A	N	Y	1952		Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1401 S 4TH	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1414 S 4TH	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1300 S 5TH	N/A	N	Y	1954	1954	Maintenance Records	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:				
Total Service Lines - Residential - 7021/Commercial - 991																	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)									
		Plastic - PVC, HDPE, PEX (P)					Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)									
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)															
1301 S 5TH	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N	
1302 S 5TH	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N	
1307 S 5TH	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
1309 S 5TH	N/A	N	Y	1953	1953	Maintenance Records	U	G	G	GRR	u	N/R	N			N	
1311 S 5TH	N/A	N	Y	1953	1953	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1313 S 5TH	N/A	N	Y	1953	1953	Maintenance Records	U	G	G	GRR	u	N/R	N			N	
1314 S 5TH	N/A	N	Y	1952	1952	Maintenance Records	U	C	G	GRR	u	N/R	N			N	
1317 S 5TH	N/A	N	Y	1952	1952	Maintenance Records	U	C	P	NL	u	N/R	N			N	
1320 S 5TH	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
701 S 5TH PL	N/A	N	Y	1969	1969	Maintenance Records	U	C	C	NL	u	N/R	N			N	
705 S 5TH PL	N/A	N	Y	1968	1968	Maintenance Records	U	C	G	GRR	u	N/R	N			N	
709 S 5TH PL	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
801 S 5TH PL	N/A	N	Y	1966	1966	Maintenance Records	U	C	C	NL	u	N/R	N			N	
805 S 5TH PL	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N	
809 S 5TH PL	N/A	N	Y	1969	1969	Maintenance Records	U	C	C	NL	u	N/R	N			N	
813 S 5TH PL	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
316 S 6TH	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
400 S 6TH	N/A	N	Y	1922	1922	Maintenance Records	U	G	C	GRR	u	N/R	N			N	
412 S 6TH	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
416 S 6TH	N/A	N	Y	1977	1977	Maintenance Records	U	C	C	NL	u	N/R	N			N	
424 S 6TH	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
500 S 6TH	N/A	N	Y	1943	1943	Maintenance Records	U	C	P	NL	u	N/R	N			N	
504 S 6TH	N/A	N	Y	1978	1978	Maintenance Records	U	P	P	NL	u	N/R	N			N	
508 S 6TH	N/A	N	Y	1939	1939	Maintenance Records	U	G	C	GRR	u	N/R	N			N	
512 S 6TH	N/A	N	Y	1943	1943	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N	
516 S 6TH	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
520 S 6TH	N/A	N	Y	1975	1975	Maintenance Records	U	C	C	NL	u	N/R	N			N	
524 S 6TH	N/A	N	Y	1947	1947	Maintenance Records	U	C	C	NL	u	N/R	N			N	
528 S 6TH	N/A	N	Y	1969	1969	Maintenance Records	U	C	P	NL	u	N/R	N			N	
600 S 6TH	N/A	N	Y	2005	2005	Maintenance Records	U	C	P	NL	u	N/R	N			N	
609 S 6TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
617 S 6TH	N/A	N	Y	2011	2011	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N	
621 S 6TH	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N	
700 S 6TH	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
704 S 6TH	N/A	N	Y	1966	1966	Maintenance Records	U	C	C	NL	u	N/R	N			N	
708 S 6TH	N/A	N	Y	1967	1967	Maintenance Records	U	C	C	NL	u	N/R	N			N	
712 S 6TH	N/A	N	Y	1967	1967	Maintenance Records	U	C	C	NL	u	N/R	N			N	
804 S 6TH	N/A	N	Y	1969	1969	Maintenance Records	U	C	C	NL	u	N/R	N			N	
808 S 6TH	N/A	N	Y	1965	1965	Maintenance Records	U	C	C	NL	u	N/R	N			N	
812 S 6TH	N/A	N	Y	1966	1966	Maintenance Records	U	C	P	NL	u	N/R	N			N	
912 S 6TH	N/A	N	Y	1964	1964	Maintenance Records	U	C	C	NL	u	N/R	N			N	
916 S 6TH	N/A	N	Y	1966	1966	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N	
917 S 6TH	N/A	N	Y	1964	1964	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
920 S 6TH	N/A	N	Y	1966	1966	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
921 S 6TH	N/A	N	Y	1961	1961	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
1000 S 6TH	N/A	N	Y	1961	1961	Maintenance Records/CUST	U	C	C	NL	u	N/R	N			N		
1004 S 6TH	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1012 S 6TH	N/A	N	Y	1958	1958	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1020 S 6TH	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
1100 S 6TH	N/A	N	Y	1971	1971	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1120 S 6TH	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1200 S 6TH	N/A	N	Y	1964	1964	Maintenance Records/CUST	U	C	P	NL	u	N/R	N			N		
1204 S 6TH	N/A	N	Y	1965	1965	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1304 S 6TH	N/A	N	Y	1950	1950	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1308 S 6TH	N/A	N	Y	1950	1950	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1312 S 6TH	N/A	N	Y	1950	1950	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1313 S 6TH	N/A	N	Y	1948	1948	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1316 S 6TH	N/A	N	Y	1950	1950	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1317 S 6TH	N/A	N	Y	1951	1951	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1320 S 6TH	N/A	N	Y	1948	1948	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1321 S 6TH	N/A	N	Y	1951	1951	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1324 S 6TH	N/A	N	Y	1950	1950	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1325 S 6TH	N/A	N	Y	1951	1951	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1328 S 6TH	N/A	N	Y	1951	1951	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1404 S 6TH	N/A	N	Y	1951	1951	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1405 S 6TH	N/A	N	Y	1951	1951	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
624 S 6TH APT A1	N/A	N	Y	1977	1977	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
624 S 6TH APT A2	N/A	N	Y	1977	1977	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
624 S 6TH APT B1	N/A	N	Y	1977	1977	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
624 S 6TH APT B2	N/A	N	Y	1977	1977	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
624 S 6TH APT C	N/A	N	Y	1977	1977	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
624 S 6TH APT D	N/A	N	Y	1977	1977	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
624 S 6TH APT E1	N/A	N	Y	1977	1977	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
624 S 6TH APT E2	N/A	N	Y	1977	1977	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
616 S 6TH APT L1	N/A	N	Y	1977	1977	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
616 S 6TH APT L2	N/A	N	Y	1977	1977	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
616 S 6TH APT M2	N/A	N	Y	1977	1977	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
616 S 6TH APT M3	N/A	N	Y	1977	1977	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
213 S 7TH 1/2	N/A	N	Y	1994	1994	Maintenance Records	U	C	P	NL	u	N/R	N			N		
416 S 7TH	N/A	N	Y	1992	1992	Maintenance Records	U	C	C	NL	u	N/R	N			N		
420 S 7TH	N/A	N	Y	1992	1992	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
613 S 7TH	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
213 S 8TH	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
508 S 8TH	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
512 S 8TH	N/A	N	Y	1988	1988	Maintenance Records	U	C	P	NL	u	N/R	N			N		
514 S 8TH	N/A	N	Y	1988	1988	Maintenance Records	U	C	P	NL	u	N/R	N			N		
516 S 8TH	N/A	N	Y	1988	1988	Maintenance Records	U	C	P	NL	u	N/R	N			N		
518 S 8TH	N/A	N	Y	1988	1988	Maintenance Records	U	C	P	NL	u	N/R	N			N		
520 S 8TH	N/A	N	Y	1988	1988	Maintenance Records	U	C	P	NL	u	N/R	N			N		
600 S 8TH APT 1	N/A	N	Y	1934	1934	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
604 S 8TH	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
608 S 8TH	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
610 S 8TH	N/A	N	Y	1934	1934	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
612 S 8TH	N/A	N	Y	1934	1934	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
109 S 9TH	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
309 S 9TH	N/A	N	Y	1943	1943	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
512 S 9TH	N/A	N	Y	1940	1940	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
613 S 9TH	N/A	N	Y	2013	2013	Maintenance Records	U	G	C	GRR	u	N/R	N			N		
617 S 9TH	N/A	N	Y	2013	2013	Maintenance Records	U	C	C	NL	u	N/R	N			N		
621 S 9TH	LC3T064	N	Y	1931	1931	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
629 S 9TH	N/A	N	Y	1967	1967	Maintenance Records	U	C	C	NL	u	N/R	N			N		
800 S 9TH	N/A	N	Y	1948	1948	Maintenance Records	U	C	P	NL	u	N/R	N			N		
804 S 9TH	N/A	N	Y	1948	1948	Maintenance Records	U	C	P	NL	u	N/R	N			N		
808 S 9TH	N/A	N	Y	1948	1948	Maintenance Records	U	C	P	NL	u	N/R	N			N		
812 S 9TH	N/A	N	Y	1948	1948	Maintenance Records	U	C	C	NL	u	N/R	N			N		
816 S 9TH	N/A	N	Y	1948	1948	Maintenance Records	U	C	P	NL	u	N/R	N			N		
820 S 9TH	N/A	N	Y	1966	1966	Maintenance Records	U	C	P	NL	u	N/R	N			N		
824 S 9TH	N/A	N	Y	2008	2008	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1012 S 9TH	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1209 S 9TH	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1217 S 9TH	N/A	N	Y	1949	1949	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1220 S 9TH	N/A	N	Y	1965	1965	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1221 S 9TH	N/A	N	Y	1947	1947	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1225 S 9TH	N/A	N	Y	1963	1963	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1305 S 9TH	N/A	N	Y	1960	1960	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1309 S 9TH	N/A	N	Y	1960	1960	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1416 S 9TH	N/A	N	Y	1971	1971	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1420 S 9TH	N/A	N	Y	1971	1971	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1500 S 9TH	N/A	N	Y	1971	1971	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N		
1504 S 9TH	N/A	N	Y	1971	1971	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1508 S 9TH	N/A	N	Y	1971	1971	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1512 S 9TH	N/A	N	Y	1971	1971	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1516 S 9TH	N/A	N	Y	1971	1971	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1520 S 9TH	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1524 S 9TH	N/A	N	Y	1968	1968	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1600 S 9TH	N/A	N	Y	1965	1965	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1604 S 9TH	N/A	N	Y	1965	1965	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1608 S 9TH	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1620 S 9TH	N/A	N	Y	1992	1992	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1920 S 9TH	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1201 S 9TH VETERANS FIELD	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2 S COUNTRY CLUB RD	N/A	N	Y	1976	1976	Maintenance Records	U	C	C	NL	u	N/R	N			N		
4 S COUNTRY CLUB RD	N/A	N	Y	2004	2004	CUSTOMER SURVEY	U	C	p	NL	u	N/R	N			N		
6 S COUNTRY CLUB RD	N/A	N	Y	2005	2005	Maintenance Records	U	C	p	NL	u	N/R	N			N		
8 S COUNTRY CLUB RD	N/A	N	Y	2004	2004	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)			Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead				
9 S COUNTRY CLUB RD	N/A	N	Y	2010	2010	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
10 S COUNTRY CLUB RD	N/A	N	Y	2005	2005	Maintenance Records	U	C	P	NL	u	N/R	N			N		
11 S COUNTRY CLUB RD	N/A	N	Y	2005	2005	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
12 S COUNTRY CLUB RD	N/A	N	Y	2005	2005	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
13 S COUNTRY CLUB RD	N/A	N	Y	2005	2005	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
14 S COUNTRY CLUB RD	N/A	N	Y	2005	2005	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
15 S COUNTRY CLUB RD	N/A	N	Y	2006		Maintenance Records	U	C	P	NL	u	N/R	N			N		
18 S COUNTRY CLUB RD	N/A	N	Y	1981	1981	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
19 S COUNTRY CLUB RD	N/A	N	Y	1981	1981	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
20 S COUNTRY CLUB RD	N/A	N	Y	1981		Maintenance Records	U	C	C	NL	u	N/R	N			N		
21 S COUNTRY CLUB RD	N/A	N	Y	1985	1985	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
22 S COUNTRY CLUB RD	N/A	N	Y	1983	1983	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
23 S COUNTRY CLUB RD	N/A	N	Y	1985	1985	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
24 S COUNTRY CLUB RD	N/A	N	Y	1985	1985	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
25 S COUNTRY CLUB RD	N/A	N	Y	1983		Maintenance Records	U	C	C	NL	u	N/R	N			N		
26 S COUNTRY CLUB RD	N/A	N	Y	1988	1988	Maintenance Records	U	C	P	NL	u	N/R	N			N		
27 S COUNTRY CLUB RD	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
28 S COUNTRY CLUB RD	N/A	N	Y	1985	1985	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
28 S COUNTRY CLUB RD SPRI	N/A	N	Y	1985	1985	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
30 S COUNTRY CLUB RD	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
32 S COUNTRY CLUB RD	N/A	N	Y	1988	1988	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
7A S COUNTRY CLUB RD	N/A	N	Y	1983	1983	Maintenance Records	U	C	P	NL	u	N/R	N			N		
7B S COUNTRY CLUB RD	N/A	N	Y	1983	1983	Maintenance Records	U	C	P	NL	u	N/R	N			N		
65 SHELBY	N/A	N	Y	2005	2005	Maintenance Records	U	C	C	NL	u	N/R	N			N		
120 SHELBY	N/A	N	Y	1979	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
220 SHELBY	N/A	N	Y	1979	1979	Maintenance Records	U	C	C	NL	u	N/R	N			N		
300 SHELBY	N/A	N	Y	1979	1979	Maintenance Records	U	C	P	NL	u	N/R	N			N		
302 SHELBY	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
308 SHELBY 1/2	N/A	N	Y	1979	1979	Maintenance Records	U	C	P	NL	u	N/R	N			N		
316 SHELBY 1/2	N/A	N	Y	1979	1979	Maintenance Records	U	C	P	NL	u	N/R	N			N		
320 SHELBY	N/A	N	Y	1979	1979	Maintenance Records	U	C	C	NL	u	N/R	N			N		
608 SHELBY	N/A	N	Y	1975	1975	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
620 SHELBY	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
700 SHELBY	N/A	N	Y	1979	1979	Maintenance Records	U	C	C	NL	u	N/R	N			N		
808 SHELBY	N/A	N	Y	1955	1955	Maintenance Records	U	C	P	NL	u	N/R	N			N		
816 SHELBY	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
816 SHELBY 1/2	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
920 SHELBY	N/A	N	Y	1979	1979	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1000 SHELBY	N/A	N	Y	1941	1941	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1004 SHELBY	N/A	N	Y	1996	1996	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1008 SHELBY	N/A	N	Y	1961	1961	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1009 SHELBY	N/A	N	Y	1972	1972	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1012 SHELBY	N/A	N	Y	1955	1955	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1013 SHELBY	N/A	N	Y	1939	1939	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1016 SHELBY	N/A	N	Y	1926	1926	Maintenance Records	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)									
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)									
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead			
1017 SHELBY	N/A	N	Y			Visual Inspection	U	C	P	NL	u	N/R	N			N		
1020 SHELBY	N/A	N	Y		1968	1968 CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1021 SHELBY 1	N/A	N	Y		1914	1914 Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1100 SHELBY	N/A	N	Y		2006	2006 Maintenance Records	U	C	C	NL	u	N/R	N			N		
1101 SHELBY	N/A	N	Y		1952	1952 Maintenance Records	U	C	C	NL	u	N/R	N			N		
1104 SHELBY	N/A	N	Y		1968	1968 Maintenance Records	U	C	P	NL	u	N/R	N			N		
1105 SHELBY	N/A	N	Y		1992	1992 Maintenance Records	U	C	P	NL	u	N/R	N			N		
1108 SHELBY	N/A	N	Y		1954	1954 Maintenance Records	U	G	P	GRR	u	N/R	N			N		
1112 SHELBY	N/A	N	Y		1992	1992 CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1116 SHELBY	N/A	N	Y		1928	1928 Maintenance Records	U	G	C	GRR	u	N/R	N			N		
1200 SHELBY	N/A	N	Y		2017	2017 Maintenance Records	U	C	C	NL	u	N/R	N			N		
1202 SHELBY	N/A	N	Y		2017	2017 MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1206 SHELBY	N/A	N	Y		2017	2017 MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1208 SHELBY	N/A	N	Y		2013	2013 MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1212 SHELBY	N/A	N	Y		2013	2013 MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1214 SHELBY	N/A	N	Y		2013	2013 Maintenance Records	U	P	C	NL	u	N/R	N			N		
1218 SHELBY	N/A	N	Y		2013	2013 Maintenance Records	U	P	C	NL	u	N/R	N			N		
1220 SHELBY	N/A	N	Y		2013	2013 Maintenance Records	U	P	C	NL	u	N/R	N			N		
1300 SHELBY	N/A	N	Y		1914	1914 Maintenance Records	U	G	P	GRR	u	N/R	N			N		
1301 SHELBY	N/A	N	Y		1886	1886 CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
1304 SHELBY	N/A	N	Y		1962	1962 Maintenance Records	U	C	P	NL	u	N/R	N			N		
1305 SHELBY	N/A	N	Y		1965	1965 Maintenance Records	U	G	C	GRR	u	N/R	N			N		
1308 SHELBY	N/A	N	Y		1942	1942 Maintenance Records	U	G	P	GRR	u	N/R	N			N		
1309 SHELBY	N/A	N	Y		1994	1994 Maintenance Records	U	C	P	NL	u	N/R	N			N		
1313 SHELBY	N/A	N	Y		1949	1949 Maintenance Records	U	G	P	GRR	u	N/R	N			N		
1316 SHELBY	N/A	N	Y		1917	1917 Maintenance Records	U	C	P	NL	u	N/R	N			N		
1317 SHELBY	N/A	N	Y		1976	1976 CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1320 SHELBY	N/A	N	N		1937	1937 Visual Inspection	U	G	P	GRR	u	N/R	N			N		
1321 SHELBY	N/A	N	N		2001	2001 Visual Inspection	U	C	P	NL	u	N/R	N			N		
1408 SHELBY	N/A	N	Y		1923	1923 Maintenance Records	U	G	G	GRR	u	N/R	N			N		
1409 SHELBY	N/A	N	Y		1941	1941 Maintenance Records	U	G	C	GRR	u	N/R	N			N		
1413 SHELBY	N/A	N	Y		1994	1994 CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
1417 SHELBY	N/A	N	Y		1914	1914 CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1500 SHELBY	N/A	N	Y		1914	1914 MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1504 SHELBY	N/A	N	Y		1980	1980 Maintenance Records	U	C	C	NL	u	N/R	N			N		
1508 SHELBY	N/A	N	Y		1912	1912 Maintenance Records	U	C	C	NL	u	N/R	N			N		
1509 SHELBY	N/A	N	Y		1995	1995 Maintenance Records	U	C	P	NL	u	N/R	N			N		
1513 SHELBY	N/A	N	Y		1978	1978 Maintenance Records	U	C	P	NL	u	N/R	N			N		
1601 SHELBY	N/A	N	Y		1952	1952 Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1613 SHELBY	N/A	N	Y		1947	1947 CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1616 SHELBY	N/A	N	Y		1944	1944 Maintenance Records	U	C	P	NL	u	N/R	N			N		
1620 SHELBY	N/A	N	Y		1974	1974 Maintenance Records	U	C	P	NL	u	N/R	N			N		
1621 SHELBY	N/A	N	Y		1954	1954 MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1700 SHELBY	N/A	N	Y		1998	1998 Maintenance Records	U	G	P	GRR	u	N/R	N			N		
1700 SHELBY 1/2	N/A	N	Y		1998	1998 CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
1704 SHELBY	N/A	N	Y	1978	1978	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1708 SHELBY	N/A	N	Y	1925	1925	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1709 SHELBY	N/A	N	Y	1950	1950	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1712 SHELBY	N/A	N	Y	1921	1921	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
1713 SHELBY	N/A	N	Y	1950	1950	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1716 SHELBY	N/A	N	Y	1976	1976	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1717 SHELBY	N/A	N	Y	1962	1962	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
1720 SHELBY	N/A	N	Y	1924	1924	Maintenance Records	U	G	C	GRR	u	N/R	N			N		
1721 SHELBY	N/A	N	Y	1987	1987	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1800 SHELBY	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1805 SHELBY	N/A	N	Y	1923	1923	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N		
1809 SHELBY	N/A	N	Y	1928	1928	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
1813 SHELBY	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1904 SHELBY	LC3T039	N	Y	1949	1949	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
1905 SHELBY	N/A	N	Y	1949	1949	VISUAL INSPECTION/CUSTO	U	C	C	NL	u	N/R	N			N		
1908 SHELBY	N/A	N	Y	1976	1976	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
1909 SHELBY	N/A	N	Y	1928	1928	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		
1912 SHELBY	N/A	N	Y	1922	1922	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1913 SHELBY	N/A	N	Y	1922	1922	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2004 SHELBY	N/A	N	Y	1982	1982	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2012 SHELBY	N/A	N	Y	1941	1941	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2212 SHELBY	N/A	N	Y	1923	1923	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
2217 SHELBY	N/A	N	Y	1954	1954	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2220 SHELBY	N/A	N	Y	1987	1987	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2221 SHELBY	N/A	N	Y	1960	1960	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2300 SHELBY	N/A	N	Y	1939	1939	VISUAL INSPECTION	U	G	C	GRR	u	N/R	N			N		
2304 SHELBY	N/A	N	Y	1909	1909	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2305 SHELBY	N/A	N	Y	1938	1938	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
2312 SHELBY	N/A	N	Y	1925	1925	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
2313 SHELBY	N/A	N	Y	1953	1953	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
2316 SHELBY	N/A	N	Y	1999	1999	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2317 SHELBY	N/A	N	Y	1936	1936	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2320 SHELBY	N/A	N	Y	1991	1991	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
2321 SHELBY	N/A	N	Y	1991	1991	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2400 SHELBY	N/A	N	Y	1929	1929	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
2401 SHELBY	N/A	N	Y	1929	1929	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2404 SHELBY	N/A	N	Y	1925	1925	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
2405 SHELBY	N/A	N	Y	1984	1984	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2408 SHELBY	N/A	N	Y	1934	1934	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
2409 SHELBY	N/A	N	Y	1984	1984	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2412 SHELBY	N/A	N	Y	1928	1928	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
2413 SHELBY	N/A	N	Y	1977	1977	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2416 SHELBY	N/A	N	Y	1928	1928	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
2417 SHELBY	N/A	N	Y	1928	1928	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
2420 SHELBY	N/A	N	Y	1941	1941	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
2421 SHELBY	N/A	N	Y	1984	1984	VISUAL INSPECTION	U	C	P	NL	u	N/R	N		Leave blank if no Lead	N		
2500 SHELBY	N/A	N	Y	1935	1935	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
2504 SHELBY	N/A	N	Y	1927	1927	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2505 SHELBY	N/A	N	Y	1965	1965	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2508 SHELBY	N/A	N	Y	1929	1929	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
2509 SHELBY	N/A	N	Y	1981	1981	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2512 SHELBY	N/A	N	Y	1975	1975	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2513 SHELBY	N/A	N	Y	2024	1924	MAINTENANCE RECORDS/V	U	P	P	NL	u	N/R	N			N		
2516 SHELBY	N/A	N	Y	1994	1994	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2517 SHELBY	N/A	N	Y	1994	1994	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2521 SHELBY	N/A	N	Y	1978	1978	VISUAL INSPECTION/CUSTO	U	C	P	NL	u	N/R	N			N		
2600 SHELBY	N/A	N	Y	1982	1982	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
2601 SHELBY	N/A	N	Y	1982	1982	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2604 SHELBY	N/A	N	Y	1938	1938	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2605 SHELBY	N/A	N	Y	1941	1941	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2608 SHELBY	N/A	N	Y	1934	1934	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2609 SHELBY	N/A	N	Y	2001	2001	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2612 SHELBY	N/A	N	Y	1952	1952	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2613 SHELBY	N/A	N	Y	1941	1941	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
2616 SHELBY	N/A	N	Y	1929	1929	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
2617 SHELBY	N/A	N	Y	1952	1952	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2621 SHELBY	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2701 SHELBY	N/A	N	Y	1930	1930	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2704 SHELBY	N/A	N	Y	1973	1973	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2705 SHELBY	N/A	N	Y	1952	1952	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2708 SHELBY	N/A	N	Y	1952	1952	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2709 SHELBY	N/A	N	Y	1952	1952	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2712 SHELBY	N/A	N	Y	1952	1952	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2713 SHELBY	N/A	N	Y	1947	1947	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2716 SHELBY	N/A	N	Y	1947	1947	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2717 SHELBY	N/A	N	Y	1951	1951	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2720 SHELBY	N/A	N	Y	1948	1948	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2721 SHELBY	N/A	N	Y	1951	1951	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
2800 SHELBY	N/A	N	Y	1939	1939	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2801 SHELBY	N/A	N	Y	2007	2007	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2804 SHELBY	N/A	N	Y	1946	1946	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2805 SHELBY	N/A	N	Y	1963	1963	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2808 SHELBY	N/A	N	Y	1989	1989	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2809 SHELBY	N/A	N	Y	1927	1927	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
2813 SHELBY	N/A	N	Y	1927	1927	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2817 SHELBY	N/A	N	Y	1977	1977	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2820 SHELBY	N/A	N	Y	1982	1982	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2821 SHELBY	LC3T065	N	Y	1982	1982	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
2900 SHELBY	N/A	N	Y	1946	1946	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2901 SHELBY	N/A	N	Y	1998	1998	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)		Cast/Ductile Iron or Transite (O)								
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Plastic - PVC, HDPE, PEX (P)		Plastic - PVC, HDPE, PEX (P)														
2905 SHELBY	N/A	N	Y	1946	1946	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2908 SHELBY	N/A	N	Y	1947	1947	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2912 SHELBY	N/A	N	Y	1958	1958	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2916 SHELBY	N/A	N	Y	1947	1947	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2917 SHELBY	N/A	N	Y	1969	1969	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3000 SHELBY	N/A	N	Y	1969	1969	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3004 SHELBY	N/A	N	Y	1947	1947	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
3008 SHELBY	N/A	N	Y	1957	1957	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
3012 SHELBY	N/A	N	Y	1954	1954	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
3016 SHELBY	N/A	N	Y	1975	1975	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3020 SHELBY	N/A	N	Y	1925	1925	MAINTENANCE RECORDS/V	U	P	G	GRR	u	N/R	N			N		
3021 SHELBY	N/A	N	Y	1925	1925	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
3100 SHELBY	N/A	N	Y	1925	1925	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
3101 SHELBY	N/A	N	Y	2009	2009	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3104 SHELBY	N/A	N	Y	1970	1970	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3105 SHELBY	N/A	N	Y	1971	1971	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3108 SHELBY	N/A	N	Y	1983	1983	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
3109 SHELBY	N/A	N	Y	1934	1934	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
3112 SHELBY	N/A	N	Y	1943	1943	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3113 SHELBY	N/A	N	Y	1926	1926	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
3116 SHELBY	N/A	N	Y	1943	1943	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3117 SHELBY	N/A	N	Y	1947	1947	VISUAL INSPECTION	U	G	C	GRR	u	N/R	N			N		
3120 SHELBY	N/A	N	Y	1939	1939	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3121 SHELBY	N/A	N	Y	1939	1939	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3200 SHELBY	N/A	N	Y	1988	1988	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3201 SHELBY	N/A	N	Y	1928	1928	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
3204 SHELBY	N/A	N	Y	1988	1988	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3205 SHELBY	N/A	N	Y	1927	1927	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3208 SHELBY	N/A	N	Y	1977	1977	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
3209 SHELBY	N/A	N	Y	1928	1928	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
3212 SHELBY	N/A	N	Y	1925	1925	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
3213 SHELBY	N/A	N	Y	1995	1995	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3216 SHELBY	N/A	N	Y	1946	1946	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
3217 SHELBY	N/A	N	Y	1947	1947	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
3220 SHELBY	N/A	N	Y	1947	1947	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3221 SHELBY	N/A	N	Y	1947	1947	Customer Survey	U	C	P	NL	u	N/R	N			N		
3224 SHELBY	N/A	N	Y	2019	2019	MAINTENANCE RECORDS/V	U	P	C	NL	u	N/R	N			N		
3225 SHELBY	N/A	N	Y	1947	1947	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3228 SHELBY	N/A	N	Y	1928	1928	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N		
3229 SHELBY	N/A	N	Y	1928	1928	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3232 SHELBY	N/A	N	Y	1926	1926	VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
3300 SHELBY	N/A	N	Y	1946	1946	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
3301 SHELBY	N/A	N	Y	1937	1937	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
3305 SHELBY	N/A	N	Y	1938	1938	MAINTENANCE RECORDS/V	U	G	P	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
3308 SHELBY	N/A	N	Y	1945	1945	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N		Leave blank if no Lead	N		
3309 SHELBY	N/A	N	Y	1984	1984	Maintenance Records	U	C	P	NL	u	N/R	N			N		
3312 SHELBY	N/A	N	Y	1943	1943	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3313 SHELBY	N/A	N	Y	1984	1984	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3316 SHELBY	N/A	N	Y	1973	1973	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3317 SHELBY	N/A	N	Y	1938	1938	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3320 SHELBY	N/A	N	Y	1938	1938	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3324 SHELBY	N/A	N	Y	1930	1930	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3325 SHELBY	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3328 SHELBY	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3329 SHELBY	N/A	N	Y	1984	1984	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3331 SHELBY	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3332 SHELBY	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3333 SHELBY	N/A	N	Y	1962	1962	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3336 SHELBY	N/A	N	Y	1946	1946	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3340 SHELBY	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3341 SHELBY	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3345 SHELBY	N/A	N	Y	1946	1946	Visual Inspection	U	P	P	NL	u	N/R	N			N		
1810 SHELBY & 1812	N/A	N	Y	1928	1928	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
1909 SHELBY APT A	N/A	N	Y	1976	1976	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1021 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1100 SOUTH LAWN	N/A	N	Y	1949	1949	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1101 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1104 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1108 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1109 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1112 SOUTH LAWN	N/A	N	Y	1992	2011	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1116 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1117 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1120 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1124 SOUTH LAWN	N/A	N	Y	1982	1982	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1128 SOUTH LAWN	N/A	N	Y	1992	1992	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1129 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1132 SOUTH LAWN	N/A	N	Y	1949	1949	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1133 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1201 SOUTH LAWN	N/A	N	Y	1949	1949	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
1204 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1205 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1208 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1209 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1216 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1217 SOUTH LAWN	N/A	N	Y	1948	1948	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1220 SOUTH LAWN	N/A	N	Y	1948	1948	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1300 SOUTH LAWN	N/A	N	Y	1948	1948	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
1301 SOUTH LAWN	N/A	N	Y	1948	1948	Maintenance Records	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
1304 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1305 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1308 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1309 SOUTH LAWN	N/A	N	Y	1996	1996	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1312 SOUTH LAWN	N/A	N	Y	1948	1948	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1313 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1316 SOUTH LAWN	N/A	N	Y	1949	1949	Maintenance Records/CUST	U	C	C	NL	u	N/R	N			N		
1320 SOUTH LAWN	N/A	N	Y	1949	1949	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1321 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1400 SOUTH LAWN	N/A	N	Y	1949	1949	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1401 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1404 SOUTH LAWN	N/A	N	Y	1949	1949	Maintenance Records/CUST	U	C	P	NL	u	N/R	N			N		
1405 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1408 SOUTH LAWN	N/A	N	Y	1949	1949	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1409 SOUTH LAWN	N/A	N	Y	1949	1949	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1412 SOUTH LAWN	N/A	N	Y	1992	1992	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1413 SOUTH LAWN	N/A	N	Y	1949	1949	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1416 SOUTH LAWN	N/A	N	Y	1949	1949	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
1417 SOUTH LAWN	N/A	N	Y	1949	1949	Maintenance Records/CUST	U	C	P	NL	u	N/R	N			N		
6 ST ANDREWS	N/A	N	Y	2002	2002	Maintenance Records/CUST	U	C	P	NL	u	N/R	N			N		
1 ST ANDREWS PL	N/A	N	Y	1984	1984	Maintenance Records/CUST	U	C	P	NL	u	N/R	N			N		
2 ST ANDREWS PL	N/A	N	Y	1983	1983	Maintenance Records	U	C	P	NL	u	N/R	N			N		
3 ST ANDREWS PL	N/A	N	Y	1983	1983	Maintenance Records	U	C	C	NL	u	N/R	N			N		
4 ST ANDREWS PL	N/A	N	Y	1984	1984	Maintenance Records	U	C	C	NL	u	N/R	N			N		
5 ST ANDREWS PL	N/A	N	Y	1984	1984	Maintenance Records	U	C	P	NL	u	N/R	N			N		
8 ST ANDREWS PL	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
9 ST ANDREWS PL	N/A	N	Y	1984	1984	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
10 ST ANDREWS PL	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
11 ST ANDREWS PL	N/A	N	Y	1993	1993	Maintenance Records	U	C	C	NL	u	N/R	N			N		
12 ST ANDREWS PL	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
18 ST ANDREWS PL	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
19 ST ANDREWS PL	N/A	N	Y	1984	1984	Maintenance Records	U	C	C	NL	u	N/R	N			N		
20 ST ANDREWS PL	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
21 ST ANDREWS PL	N/A	N	Y	1991	1991	Maintenance Records/CUST	U	C	C	NL	u	N/R	N			N		
22 ST ANDREWS PL	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
23 ST ANDREWS PL	N/A	N	Y	1979	1979	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
24 ST ANDREWS PL	N/A	N	Y	1979	1979	Maintenance Records	U	C	C	NL	u	N/R	N			N		
25 ST ANDREWS PL	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
11 ST ANDREWS PL SPRIN	N/A	N	Y	1993	1993	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
9 STACEY LN	N/A	N	Y	1979	1979	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
10 STACEY LN	N/A	N	Y	1976	1976	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
11 STACEY LN	N/A	N	Y	1972	1972	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
12 STACEY LN	N/A	N	Y	1991	1991	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
15 STACEY LN	N/A	N	Y	1976	1976	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
16 STACEY LN	N/A	N	Y	1979	1979	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
17 STACEY LN	N/A	N	Y	1970	1970	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
13 STACY LN	N/A	N	Y	1990	1990	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
300 STANLEY	N/A	N	Y	1963	1963	Maintenance Records	U	C	C	NL	u	N/R	N			N		
301 STANLEY	N/A	N	Y	1956	1956	Maintenance Records	U	C	C	NL	u	N/R	N			N		
308 STANLEY	N/A	N	Y	1955	1955	Maintenance Records	U	C	C	NL	u	N/R	N			N		
309 STANLEY	N/A	N	Y	1955	1955	Maintenance Records	U	C	C	NL	u	N/R	N			N		
315 STANLEY	N/A	N	Y	1955	1955	Maintenance Records	U	C	C	NL	u	N/R	N			N		
316 STANLEY	N/A	N	Y	1955	1955	Maintenance Records	U	C	C	NL	u	N/R	N			N		
320 STANLEY	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
400 STANLEY	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
403 STANLEY	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
404 STANLEY	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
407 STANLEY	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
408 STANLEY	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
411 STANLEY	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
412 STANLEY	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
415 STANLEY	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
416 STANLEY	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
417 STANLEY	N/A	N	Y	1957	1957	Maintenance Records	U	C	C	NL	u	N/R	N			N		
420 STANLEY	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
421 STANLEY	N/A	N	Y	1990	1990	Maintenance Records	U	C	C	NL	u	N/R	N			N		
424 STANLEY	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
900 STINSON	N/A	N	Y	1980	1980	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
901 STINSON	N/A	N	Y	1967	1967	Maintenance Records	U	C	P	NL	u	N/R	N			N		
904 STINSON	N/A	N	Y	1967	1967	Maintenance Records	U	C	C	NL	u	N/R	N			N		
905 STINSON	N/A	N	Y	1967	1967	Maintenance Records	U	C	C	NL	u	N/R	N			N		
908 STINSON	N/A	N	Y	1968	1968	Maintenance Records	U	C	P	NL	u	N/R	N			N		
909 STINSON	N/A	N	Y	1968	1968	Maintenance Records	U	C	P	NL	u	N/R	N			N		
912 STINSON	N/A	N	Y	1970	1970	Maintenance Records	U	C	P	NL	u	N/R	N			N		
913 STINSON	N/A	N	Y	1967	1967	Maintenance Records	U	C	P	NL	u	N/R	N			N		
916 STINSON	N/A	N	Y	1968	1968	Maintenance Records	U	C	P	NL	u	N/R	N			N		
917 STINSON	N/A	N	Y	1968	1968	Maintenance Records	U	C	P	NL	u	N/R	N			N		
920 STINSON	N/A	N	Y	1967	1967	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1000 STINSON	N/A	N	Y	1970	1970	Maintenance Records/CUST	U	C	C	NL	u	N/R	N			N		
1001 STINSON	N/A	N	Y	1967	1967	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1005 STINSON	N/A	N	Y	1967	1967	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1008 STINSON	N/A	N	Y	1970	1970	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1009 STINSON	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1012 STINSON	N/A	N	Y	1968	1968	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1013 STINSON	N/A	N	Y	1968	1968	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1016 STINSON	N/A	N	Y	1968	1968	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1017 STINSON	N/A	N	Y	1968	1968	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1020 STINSON	N/A	N	Y	1968	1968	Maintenance Records/CUST	U	C	C	NL	u	N/R	N			N		
1100 STINSON	N/A	N	Y	1968	1968	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1101 STINSON	N/A	N	Y	1970	1970	Maintenance Records	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
1105 STINSON	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1108 STINSON	N/A	N	Y	1968	1968	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1109 STINSON	N/A	N	Y	1969	1969	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1112 STINSON	N/A	N	Y	1968	1968	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1113 STINSON	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1116 STINSON	N/A	N	Y	1969	1969	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1117 STINSON	N/A	N	Y	1969	1969	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1200 STINSON	N/A	N	Y	1973	1973	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
1201 STINSON	N/A	N	Y	1973	1973	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N		
1210 STINSON	N/A	N	Y	1976	1976	CUSTOMER SURVEY/VISUAL	U	C	C/P	NL	u	N/R	N			N		
1211 STINSON	N/A	N	Y	1975	1975	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1220 STINSON	N/A	N	Y	1975	1975	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1221 STINSON	N/A	N	Y	1976	1976	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1300 STINSON	N/A	N	Y	1975	1975	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1301 STINSON	N/A	N	Y	1974	1974	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1310 STINSON	N/A	N	Y	1975	1975	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1311 STINSON	N/A	N	Y	1976	1976	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1320 STINSON	N/A	N	Y	1976	1976	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1321 STINSON	N/A	N	Y	1976	1976	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1400 STINSON	N/A	N	Y	1977	1977	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1401 STINSON	N/A	N	Y	1978	1978	Maintenance Records/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1410 STINSON	N/A	N	Y	1978	1978	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1411 STINSON	N/A	N	Y	1978	1978	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1415 STINSON	N/A	N	Y	1978	1978	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1416 STINSON	N/A	N	Y	1978	1978	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1424 STINSON	N/A	N	Y	1978	1978	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1425 STINSON	N/A	N	Y	1987	1987	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1500 STINSON	N/A	N	Y	1978	1978	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1501 STINSON	N/A	N	Y	1978	1978	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1505 STINSON	N/A	N	Y	1978	1978	Maintenance Records/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1508 STINSON	N/A	N	Y	2000	2000	Maintenance Records/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1509 STINSON	N/A	N	Y	2000	2000	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1516 STINSON	N/A	N	Y	1978	1978	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1524 STINSON	N/A	N	Y	1978	1978	Maintenance Records/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1525 STINSON	N/A	N	Y	1986	1986	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1600 STINSON	N/A	N	Y	1979	1979	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1601 STINSON	N/A	N	Y	1987	1987	Maintenance Records/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1608 STINSON	N/A	N	Y	1980	1980	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1609 STINSON	N/A	N	Y	1980	1980	Maintenance Records/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1616 STINSON	N/A	N	Y	1986	1986	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1621 STINSON	N/A	N	Y	1986	1986	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1623 STINSON	N/A	N	Y	1988	1988	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1624 STINSON	N/A	N	Y	1983	1983	Maintenance Records	U	C	P	NL	u	N/R	N			N		
5 TINSBURY LN	N/A	N	Y	1997	1997	Maintenance Records	U	C	P	NL	u	N/R	N			N		
6 TINSBURY LN	N/A	N	Y	2010	2010	Maintenance Records	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:				
Total Service Lines - Residential - 7021/Commercial - 991																	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)									
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)															
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)															
7 TINSBURY LN	N/A	N	Y	2010	2010	Maintenance Records	U	C	P	NL	u	N/R	N			N	
8 TINSBURY LN	N/A	N	Y	1995	1995	Maintenance Records/CUST	U	C	C/G	GRR	u	N/R	N			N	
9 TINSBURY LN	N/A	N	Y	1997	1997	Maintenance Records	U	C	C	NL	u	N/R	N			N	
10 TINSBURY LN	N/A	N	Y	1997	1997	Maintenance Records	U	C	P	NL	u	N/R	N			N	
11 TINSBURY LN	N/A	N	Y	2001	2001	Maintenance Records	U	C	P	NL	u	N/R	N			N	
26 TINSBURY LN	N/A	N	Y	1997	1997	Maintenance Records/CUST	U	C	C	NL	u	N/R	N			N	
28 TINSBURY LN	N/A	N	Y	1996	1996	Maintenance Records	U	C	C	NL	u	N/R	N			N	
1100 UNIQUE CT	N/A	N	Y	2005	2005	Visual Inspection	U	C	P	NL	u	N/R	N			N	
1104 UNIQUE CT	N/A	N	Y	2003	2003	Visual Inspection	U	C	P	NL	u	N/R	N			N	
1105 UNIQUE CT	N/A	N	Y	2003	2003	Visual Inspection	U	C	P	NL	u	N/R	N			N	
1108 UNIQUE CT	N/A	N	Y	2006	2006	Maintenance Records/CUST	U	P	C	NL	u	N/R	N			N	
1109 UNIQUE CT	N/A	N	Y	2006	2006	Visual Inspection	U	C	P	NL	u	N/R	N			N	
1112 UNIQUE CT	N/A	N	Y	2001	2001	Visual Inspection	U	C	P	NL	u	N/R	N			N	
1113 UNIQUE CT	N/A	N	Y	2001	2001	Visual Inspection	U	C	P	NL	u	N/R	N			N	
1120 UNIQUE CT	N/A	N	Y	2001	2001	Visual Inspection	U	C	P	NL	u	N/R	N			N	
1121 UNIQUE CT	N/A	N	Y	2001	2001	Visual Inspection	U	C	P	NL	u	N/R	N			N	
4733 US HIGHWAY 45	N/A	N	Y	1893	1893	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
4935 US HIGHWAY 45	N/A	N	Y	1907	1907	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N	
1705 US HWY 45	N/A	N	Y	1945	1945	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	
1721 US HWY 45	N/A	N	Y	1960	1960	Visual Inspection	U	C	C	NL	u	N/R	N			N	
5340 US HWY 45	N/A	N	Y	1917	1917	Visual Inspection	U	C	P	NL	u	N/R	N			N	
10139 US HWY 45	N/A	N	Y	1917	1917	Visual Inspection	U	C	P	NL	u	N/R	N			N	
10141 US HWY 45	N/A	N	Y	2007	2007	Visual Inspection	U	C	P	NL	u	N/R	N			N	
10147 US HWY 45	N/A	N	Y	1963	1963	Visual Inspection	U	C	P	NL	u	N/R	N			N	
10155 US HWY 45	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N	
10167 US HWY 45	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N	
11297 US HWY 45	N/A	N	Y	1976	1976	Visual Inspection	U	C	P	NL	u	N/R	N			N	
712 VANLANINGHAM	N/A	N	Y	2005	2005	Visual Inspection	U	C	P	NL	u	N/R	N			N	
713 VANLANINGHAM	N/A	N	Y	1912	1912	Visual Inspection	U	C	P	NL	u	N/R	N			N	
800 VANLANINGHAM	N/A	N	Y	1931	1931	Visual Inspection	U	C	P	NL	u	N/R	N			N	
805 VANLANINGHAM	N/A	N	Y	1999	1999	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	
808 VANLANINGHAM	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N	
809 VANLANINGHAM	N/A	N	Y	1996	1996	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
812 VANLANINGHAM	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N	
813 VANLANINGHAM	N/A	N	Y	1996	1996	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
816 VANLANINGHAM	N/A	N	Y	1995	1995	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	
817 VANLANINGHAM	N/A	N	Y	1997	1997	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
820 VANLANINGHAM	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N	
821 VANLANINGHAM	N/A	N	Y	1996	1996	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
900 VANLANINGHAM	N/A	N	Y	1995	1995	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N	
901 VANLANINGHAM	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N	
904 VANLANINGHAM	N/A	N	Y	1997	1997	Visual Inspection	U	C	P	NL	u	N/R	N			N	
905 VANLANINGHAM	N/A	N	Y	1997	1997	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N	
908 VANLANINGHAM	N/A	N	Y	2001	2001	Visual Inspection	U	C	P	NL	u	N/R	N			N	
909 VANLANINGHAM	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N	

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Galvanized (G)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)													Leave blank if no Lead			
913 VANLANINGHAM	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N		
916 VANLANINGHAM	N/A	N	Y	1995	1995	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
7584 W COUNTRY CLUB RD	N/A	N	Y	2004	2004	Maintenance Records	U	C	P	NL	u	N/R	N			N		
7604 W COUNTRY CLUB RD	N/A	N	Y	2004	2004	Maintenance Records	U	C	P	NL	u	N/R	N			N		
7624 W COUNTRY CLUB RD	N/A	N	Y	2004	2004	Maintenance Records	U	C	P	NL	u	N/R	N			N		
7644 W COUNTRY CLUB RD	N/A	N	Y	2004	2004	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
7664 W COUNTRY CLUB RD	N/A	N	Y	2004	2004	Maintenance Records	U	C	P	NL	u	N/R	N			N		
7665 W COUNTRY CLUB RD	N/A	N	Y	2004	2004	Maintenance Records	U	C	P	NL	u	N/R	N			N		
7670 W COUNTRY CLUB RD	N/A	N	Y	2004	2004	Maintenance Records	U	C	P	NL	u	N/R	N			N		
7685 W COUNTRY CLUB RD	N/A	N	Y	2004	2004	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
7686 W COUNTRY CLUB RD	N/A	N	Y	2004	2004	Maintenance Records	U	C	C	NL	u	N/R	N			N		
7705 W COUNTRY CLUB RD	N/A	N	Y	2012	2012	Maintenance Records	U	C	P	NL	u	N/R	N			N		
7710 W COUNTRY CLUB RD	N/A	N	Y	2012	2012	Maintenance Records	U	C	P	NL	u	N/R	N			N		
7735 W COUNTRY CLUB RD	N/A	N	Y	2012	2012	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
7736 W COUNTRY CLUB RD	N/A	N	Y	1904	1904	Maintenance Records	U	C	P	NL	u	N/R	N			N		
7745 W COUNTRY CLUB RD	N/A	N	Y	2012	2012	Maintenance Records	U	C	P	NL	u	N/R	N			N		
4 WABASH	N/A	N	Y	1995	1995	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
8 WABASH	N/A	N	Y	1995	1995	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
12 WABASH	N/A	N	Y	1953	1953	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
20 WABASH	N/A	N	Y	1937	1937	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
50 WABASH	N/A	N	Y	1974	1974	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
51 WABASH	N/A	N	Y	1957	1957	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
58 WABASH	N/A	N	Y	1974	1974	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
63 WABASH	N/A	N	Y	1934	1934	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
64 WABASH	N/A	N	Y	1936	1936	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
67 WABASH	N/A	N	Y	1934	1934	VISUAL INSPECTION	U	G	C	GRR	u	N/R	N			N		
68 WABASH	N/A	N	Y	1937	1937	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
74 WABASH	N/A	N	Y	1947	1947	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
78 WABASH	N/A	N	Y	1919	1919	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
79 WABASH	N/A	N	Y	1957	1957	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N		
100 WABASH	N/A	N	Y	1954	1954	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
101 WABASH	N/A	N	Y	1914	1914	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
112 WABASH	N/A	N	Y	1924	1924	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
116 WABASH	N/A	N	Y	1957	1957	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
117 WABASH	N/A	N	Y	1991	1991	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
120 WABASH	N/A	N	Y	1923	1923	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
200 WABASH	N/A	N	Y	1921	1921	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
201 WABASH	N/A	N	Y	1911	1911	Visual Inspection	U	G	C	GRR	u	N/R	N			N		
208 WABASH	N/A	N	Y	1965	1965	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
211 WABASH	N/A	N	Y	1939	1939	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
212 WABASH	N/A	N	Y	1917	1917	Visual Inspection	U	C	C	NL	u	N/R	N			N		
216 WABASH	N/A	N	Y	1974	1974	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
220 WABASH	N/A	N	Y	1974	1974	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
221 WABASH	N/A	N	Y	1929	1929	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
300 WABASH	N/A	N	Y	1964	1964	Visual Inspection	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
301 WABASH	N/A	N	Y	1950	1950	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
308 WABASH	N/A	N	Y	1929	1929	Visual Inspection	U	P	P	NL	u	N/R	N			N		
309 WABASH	N/A	N	Y	1934	1934	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
312 WABASH	N/A	N	Y	1962	1962	Visual Inspection	U	C	C	NL	u	N/R	N			N		
316 WABASH	N/A	N	Y	1961	1961	Visual Inspection	U	C	C	NL	u	N/R	N			N		
320 WABASH	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
321 WABASH	N/A	N	Y	1951	1951	Visual Inspection	U	C	C	NL	u	N/R	N			N		
400 WABASH	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N		
401 WABASH	N/A	N	Y	1937	1937	Visual Inspection	U	C	P	NL	u	N/R	N			N		
404 WABASH	N/A	N	Y	1928	1928	Visual Inspection	U	C	C	NL	u	N/R	N			N		
408 WABASH	N/A	N	Y	1938	1938	Visual Inspection	U	C	G/C	GRR	u	N/R	N			N		
409 WABASH	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N		
412 WABASH	N/A	N	Y	1929	1929	Visual Inspection	U	C	P	NL	u	N/R	N			N		
413 WABASH	N/A	N	Y	1929	1929	Visual Inspection	U	C	P	NL	u	N/R	N			N		
420 WABASH	N/A	N	Y	1922	1922	Visual Inspection	U	C	P	NL	u	N/R	N			N		
421 WABASH	N/A	N	Y	1981	1981	Visual Inspection	U	C	P	NL	u	N/R	N			N		
500 WABASH	N/A	N	Y	1965	1965	Visual Inspection	U	C	C	NL	u	N/R	N			N		
501 WABASH	N/A	N	Y	1953	1953	Visual Inspection	U	C	C/G	GRR	u	N/R	N			N		
504 WABASH	N/A	N	Y	1966	1966	Visual Inspection	U	C	P	NL	u	N/R	N			N		
505 WABASH	N/A	N	Y	1964	1964	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
513 WABASH	N/A	N	Y	1960	1960	Visual Inspection	U	C	C	NL	u	N/R	N			N		
517 WABASH	N/A	N	Y	2008	2008	Visual Inspection	U	C	P	NL	u	N/R	N			N		
521 WABASH	N/A	N	Y	1951	1951	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
600 WABASH	N/A	N	Y	1923	1923	Visual Inspection	U	G	C	GRR	u	N/R	N			N		
601 WABASH	N/A	N	Y	1965	1965	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
604 WABASH	N/A	N	Y	1912	1912	Visual Inspection	U	P	P	NL	u	N/R	N			N		
605 WABASH	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N		
608 WABASH	N/A	N	Y	1980	1980	Visual Inspection	U	C	C	NL	u	N/R	N			N		
609 WABASH	N/A	N	Y	1924	1924	CUSTOMER SURVEY	U	G	G	GRR	u	N/R	N			N		
612 WABASH	N/A	N	Y	1992	1992	Visual Inspection	U	C	C	NL	u	N/R	N			N		
613 WABASH	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
616 WABASH	N/A	N	Y	1911	1911	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
617 WABASH	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N		
620 WABASH	N/A	N	Y	1949	1949	Visual Inspection	U	C	P	NL	u	N/R	N			N		
621 WABASH	N/A	N	Y	1911	1911	Visual Inspection	U	C	P	NL	u	N/R	N			N		
700 WABASH	N/A	N	Y	1973	1973	Visual Inspection	U	C	P	NL	u	N/R	N			N		
704 WABASH	N/A	N	Y	1946	1946	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
708 WABASH	N/A	N	Y	1941	1941	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
709 WABASH	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N		
712 WABASH	N/A	N	Y	1925	1925	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
716 WABASH	N/A	N	Y	1986	1986	Maintenance Records/CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
717 WABASH	N/A	N	Y	1948	1948	Visual Inspection	U	C	C	NL	u	N/R	N			N		
720 WABASH	N/A	N	Y	1914	1914	Visual Inspection	U	C	P	NL	u	N/R	N			N		
800 WABASH	N/A	N	Y	1965	1965	Visual Inspection	U	G	C	GRR	u	N/R	N			N		
800 WABASH 1/2	N/A	N	Y	1965	1965	Visual Inspection	U	G	C	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
801 WABASH	N/A	N	Y	1913	1913	Visual Inspection	U	G	p	GRR	u	N/R	N			N		
802 WABASH	N/A	N	Y	1965	1965	Visual Inspection	U	G	C	GRR	u	N/R	N			N		
804 WABASH	N/A	N	Y	1907	1907	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
805 WABASH	N/A	N	Y	1975	1975	Visual Inspection	U	C	C	NL	u	N/R	N			N		
808 WABASH	N/A	N	Y	1903	1903	Visual Inspection	U	G	p	GRR	u	N/R	N			N		
809 WABASH	N/A	N	Y	1991	1991	Visual Inspection	U	C	C	NL	u	N/R	N			N		
812 WABASH	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
813 WABASH	N/A	N	Y	1991	1991	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
816 WABASH	N/A	N	Y	1921	1921	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
817 WABASH	N/A	N	Y	1976	1976	Visual Inspection	U	C	P	NL	u	N/R	N			N		
820 WABASH	N/A	N	Y	1925	1925	Visual Inspection	U	P	P	NL	u	N/R	N			N		
821 WABASH	N/A	N	Y	1930	1930	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
900 WABASH	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N		
904 WABASH	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	G	G	GRR	u	N/R	N			N		
905 WABASH	N/A	N	Y	1976	1976	Visual Inspection	U	C	P	NL	u	N/R	N			N		
908 WABASH	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N		
909 WABASH	N/A	N	Y	1916	1916	Visual Inspection	U	C	P	NL	u	N/R	N			N		
915 WABASH	N/A	N	Y	1916	1916	Visual Inspection	U	C	P	NL	u	N/R	N			N		
917 WABASH	N/A	N	Y	1991	1991	Visual Inspection	U	C	P	NL	u	N/R	N			N		
920 WABASH	N/A	N	Y	1994	1994	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
921 WABASH	N/A	N	Y	1916	1916	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1000 WABASH	N/A	N	Y	1992	1992	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1001 WABASH	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1004 WABASH	N/A	N	Y	1916	1916	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1005 WABASH	N/A	N	Y	1937	1937	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1008 WABASH	N/A	N	Y	1937	1937	Visual Inspection	U	G	C	GRR	u	N/R	N			N		
1009 WABASH	N/A	N	Y	1937	1937	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1013 WABASH	N/A	N	Y	1876	1876	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1016 WABASH	N/A	N	Y	1910	1910	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1017 WABASH	N/A	N	Y	1886	1886	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1020 WABASH	N/A	N	Y	1903	1903	Visual Inspection	U	G	G	GRR	U	N/R	N			N		
1021 WABASH	N/A	N	Y	1909	1909	Visual Inspection	U	P	G	GRR	u	N/R	N			N		
1100 WABASH	N/A	N	Y	1906	1906	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
1101 WABASH	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1106 WABASH	N/A	N	Y	1906	1906	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1107 WABASH	N/A	N	Y	1886	1886	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1108 WABASH	N/A	N	Y	1994	1994	Visual Inspection	U	G	C	GRR	u	N/R	N			N		
1113 WABASH	N/A	N	Y	1900	1900	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
1117 WABASH	N/A	N	Y	1896	1896	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1118 WABASH	N/A	N	Y	1899	1899	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
1120 WABASH	N/A	N	Y	1992	1992	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1121 WABASH	N/A	N	Y	1964	1964	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1201 WABASH	N/A	N	Y	1891	1891	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1209 WABASH	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1217 WABASH	N/A	N	Y	1926	1926	Visual Inspection	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
		Plastic - PVC, HDPE, PEX (P)					Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)										
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
1220 WABASH	N/A	N	Y	1896	1896	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1221 WABASH	N/A	N	Y	1996	1996	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1301 WABASH	N/A	N	Y	1912	1912	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1312 WABASH	N/A	N	Y	1985	1985	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1314 WABASH	N/A	N	Y	1994	1994	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1316 WABASH	N/A	N	Y	1994	1994	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1317 WABASH	N/A	N	Y	1900	1900	Visual Inspection	U	P	C	NL	u	N/R	N			N		
1321 WABASH	N/A	N	Y	1903	1903	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1404 WABASH	N/A	N	Y	1965	1965	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1405 WABASH	N/A	N	Y	1906	1906	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1408 WABASH	N/A	N	Y	1914	1914	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1515 WABASH	N/A	N	Y	1987	1987	Visual Inspection	U	C	G/P	GRR	u	N/R	N			N		
1617 WABASH APT 2	N/A	N	Y	2014	2014	Visual Inspection	U	P	C	NL	u	N/R	N			N		
1617 WABASH APT 3	N/A	N	Y	2014	2014	Visual Inspection	U	P	C	NL	u	N/R	N			N		
1617 WABASH APT 4	N/A	N	Y	2014	2014	Visual Inspection	U	P	C	NL	u	N/R	N			N		
1704 WALNUT	N/A	N	Y	1980	1980	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1804 WALNUT	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1812 WALNUT	N/A	N	Y	1924	1924	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1813 WALNUT	N/A	N	Y	1939	1939	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
1816 WALNUT	N/A	N	Y	1939	1939	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1817 WALNUT	N/A	N	Y	1939	1939	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
1820 WALNUT	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1821 WALNUT	N/A	N	Y	1956	1956	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
1824 WALNUT	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
1828 WALNUT	N/A	N	Y	1940	1940	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
1829 WALNUT	N/A	N	Y	1940	1940	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2104 WALNUT	N/A	N	Y	1899	1899	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2300 WALNUT	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2301 WALNUT	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2304 WALNUT	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2305 WALNUT	N/A	N	Y	1961	1961	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2308 WALNUT	N/A	N	Y	1960	1960	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2309 WALNUT	N/A	N	Y	1960	1960	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
2313 WALNUT	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2317 WALNUT	N/A	N	Y	1961	1961	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2321 WALNUT	N/A	N	Y	1960	1960	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
2701 WALNUT	N/A	N	Y	1952	1952	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2705 WALNUT	N/A	N	Y	1951	1951	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2709 WALNUT	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2713 WALNUT	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2717 WALNUT	N/A	N	Y	1952	1952	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2721 WALNUT	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2800 WALNUT	N/A	N	Y	1951	1951	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2801 WALNUT	N/A	N	Y	1951	1951	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2804 WALNUT	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
2805 WALNUT	N/A	N	Y	1951	1951	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2808 WALNUT	N/A	N	Y	1952	1952	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2809 WALNUT	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2812 WALNUT	N/A	N	Y	1952	1952	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2813 WALNUT	N/A	N	Y	1951	1951	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2816 WALNUT	N/A	N	Y	1950	1950	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
2817 WALNUT	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2820 WALNUT	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2821 WALNUT	N/A	N	Y	1957	1957	CUSTOMER SURVEY	U	G	C	GRR	u	N/R	N			N		
2824 WALNUT	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2825 WALNUT	N/A	N	Y	1950	1950	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2829 WALNUT	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2900 WALNUT	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2904 WALNUT	N/A	N	Y	1951	1951	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2905 WALNUT	N/A	N	Y	1951	1951	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2908 WALNUT	N/A	N	Y	1950	1950	CUSTOMER SURVEY	U	C	C/G/P	GRR	u	N/R	N			N		
2909 WALNUT	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2912 WALNUT	N/A	N	Y	1951	1951	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2913 WALNUT	N/A	N	Y	1950	1950	Visual Inspection	U	P	P	NL	u	N/R	N			N		
2916 WALNUT	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2917 WALNUT	N/A	N	Y	2023	2023	CUSTOMER SURVEY	U	C	C/G/P	GRR	u	N/R	N			N		
2920 WALNUT	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2921 WALNUT	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3000 WALNUT	N/A	N	Y	1946	1946	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
3001 WALNUT	N/A	N	Y	1951	1951	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3004 WALNUT	N/A	N	Y	1949	1949	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3005 WALNUT	N/A	N	Y	1947	1947	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3008 WALNUT	N/A	N	Y	1949	1949	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3009 WALNUT	N/A	N	Y	1949	1949	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3012 WALNUT	N/A	N	Y	1991	1991	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3013 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3016 WALNUT	N/A	N	Y	1950	1950	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
3017 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3020 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3021 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3024 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3025 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3100 WALNUT	N/A	N	Y	1946	1946	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
3101 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3104 WALNUT	N/A	N	Y	1992	1992	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3105 WALNUT	N/A	N	Y	1978	1978	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3108 WALNUT	N/A	N	Y	1947	1947	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3109 WALNUT	N/A	N	Y	1950	1950	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3112 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3113 WALNUT	N/A	N	Y	1992	1992	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
3116 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3117 WALNUT	N/A	N	Y	1949	1949	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3120 WALNUT	N/A	N	Y	1992	1992	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3121 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3124 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3125 WALNUT	N/A	N	Y	1950	1950	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3200 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3201 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3204 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3205 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3208 WALNUT	N/A	N	Y	1947	1947	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3209 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3212 WALNUT	LC3T040	N	Y	1992	1992	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3213 WALNUT	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3216 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3217 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3220 WALNUT	N/A	N	Y	1950	1950	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3221 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3224 WALNUT	N/A	N	Y	1992	1992	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3416 WALNUT	N/A	N	Y	1980	1980	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3512 WALNUT	N/A	N	Y	2016	2016	CUSTOMER SURVEY	U	C	C/G/P	GRR	u	N/R	N			N		
3516 WALNUT	N/A	N	Y	2016	2016	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3520 WALNUT	N/A	N	Y	1978	1978	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1701 WALNUT APT 1	N/A	N	Y	2000	2000	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1701 WALNUT APT 2	N/A	N	Y	2000	2000	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1701 WALNUT APT 3	N/A	N	Y	2000	2000	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1701 WALNUT APT 4	N/A	N	Y	2000	2000	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1701 WALNUT APT 5	N/A	N	Y	2000	2000	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1701 WALNUT APT 6	N/A	N	Y	2000	2000	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1701 WALNUT APT 7	N/A	N	Y	2000	2000	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1701 WALNUT APT 8	N/A	N	Y	2000	2000	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1108 WASHINGTON	N/A	N	Y	1916	1916	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1216 WASHINGTON	N/A	N	Y	2007	2007	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2101 WASHINGTON	N/A	N	Y	1970	1970	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2300 WASHINGTON	N/A	N	Y	1977	2005	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2304 WASHINGTON	N/A	N	Y	1979	1979	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2308 WASHINGTON	N/A	N	Y	1984	1984	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2313 WASHINGTON	N/A	N	Y	1978	1978	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2319 WASHINGTON	N/A	N	Y	1978	1978	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2325 WASHINGTON	N/A	N	Y	1979	1979	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2913 WASHINGTON	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2917 WASHINGTON	N/A	N	Y	1963	1963	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2920 WASHINGTON	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3000 WASHINGTON	N/A	N	Y	1962	1962	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3001 WASHINGTON	N/A	N	Y	1964	1964	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
10 WEDGEWOOD CT	N/A	N	Y	1973	1973	Maintenance Records	U	C	C	NL	u	N/R	N			N		
11 WEDGEWOOD CT	N/A	N	Y	1972	1972	Maintenance Records	U	C	C	NL	u	N/R	N			N		
12 WEDGEWOOD CT	N/A	N	Y	1972	1972	Maintenance Records	U	C	P	NL	u	N/R	N			N		
14 WEDGEWOOD CT	N/A	N	Y	1973	1973	Maintenance Records	U	C	C	NL	u	N/R	N			N		
15 WEDGEWOOD CT	N/A	N	Y	1975	1975	Maintenance Records	U	C	C	NL	u	N/R	N			N		
2200 WESTERN	N/A	N	Y	1934	1934	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2204 WESTERN	N/A	N	Y	1999	1999	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2206 WESTERN	N/A	N	Y	1998	1998	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2214 WESTERN	N/A	N	Y	1921	1921	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2217 WESTERN	N/A	N	Y	1986	1986	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2220 WESTERN	N/A	CHURCH	Y	2007	2007	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2221 WESTERN	N/A	N	Y	1891	1891	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2300 WESTERN	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2301 WESTERN	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2305 WESTERN	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2308 WESTERN	N/A	N	Y	1876	1876	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2309 WESTERN	N/A	N	Y	1998	1998	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2312 WESTERN	N/A	N	Y	1912	1912	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
2313 WESTERN	N/A	N	Y	1911	1911	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2316 WESTERN	N/A	N	Y	1996	1996	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2317 WESTERN	N/A	N	Y	1991	1991	Visual Inspection	U	P	G	GRR	u	N/R	N			N		
2321 WESTERN	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2400 WESTERN	N/A	N	Y	1897	1897	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		
2401 WESTERN	N/A	N	Y	1976	1976	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
2404 WESTERN	N/A	N	Y	1912	1912	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2405 WESTERN	N/A	N	Y	1940	1940	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2408 WESTERN	N/A	N	Y	1900	1900	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2409 WESTERN	N/A	N	Y	1901	1901	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
2414 WESTERN	N/A	N	Y	1916	1916	Visual Inspectoin	U	C	C	NL	u	N/R	N			N		
2416 WESTERN	N/A	N	Y	1894	1894	Visual Inspectoin	U	C	P	NL	u	N/R	N			N		
2420 WESTERN	N/A	N	Y	1919	1919	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2421 WESTERN	N/A	N	Y	1938	1938	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2500 WESTERN	N/A	N	Y	1941	1941	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2501 WESTERN	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2504 WESTERN	N/A	N	Y	1931	1931	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2509 WESTERN	N/A	N	Y	1926	1926	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2512 WESTERN	N/A	N	Y	1978	1978	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2513 WESTERN	N/A	N	Y	1960	1960	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2520 WESTERN	N/A	N	Y	1978	1978	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2521 WESTERN	N/A	N	Y	1906	1906	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2600 WESTERN	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2601 WESTERN	N/A	N	Y	1977	1977	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2609 WESTERN	N/A	N	Y	1902	1902	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2612 WESTERN	N/A	N	Y	1943	1943	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2613 WESTERN	N/A	N	Y	1928	1928	Visual Inspection	U	C	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
2616 WESTERN	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2617 WESTERN	N/A	N	Y	1930	1930	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2620 WESTERN	N/A	N	Y	1993	1993	Visual Inspectoin	U	C	P	NL	u	N/R	N			N		
2621 WESTERN	N/A	N	Y	1928	1928	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2701 WESTERN	N/A	N	Y	1884	1884	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2708 WESTERN	N/A	N	Y	1930	1930	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2715 WESTERN	N/A	N	Y	1987	1987	Visual Inspection	U	c	P	NL	u	N/R	N			N		
2716 WESTERN	N/A	N	Y	1987	1987	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2717 WESTERN	N/A	N	Y	1904	1904	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
2720 WESTERN	N/A	N	Y	1906	1906	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2721 WESTERN	N/A	N	Y	1896	1896	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2800 WESTERN	N/A	N	Y	1891	1891	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N		
2800 WESTERN 1/2	N/A	N	Y	1891	1891	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N		
2801 WESTERN	N/A	N	Y	1888	1888	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2804 WESTERN	N/A	N	Y	1929	1929	Visual Inspection	U	P	G	GRR	u	N/R	N			N		
2805 WESTERN	N/A	N	Y	1922	1922	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
2808 WESTERN	N/A	N	Y	1921	1921	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
2809 WESTERN	N/A	N	Y	1881	1881	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2812 WESTERN	N/A	N	Y	1897	1897	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2813 WESTERN	N/A	N	Y	1911	1911	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2816 WESTERN	N/A	N	Y	1923	1923	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2817 WESTERN	N/A	N	Y	1928	1928	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2820 WESTERN	N/A	N	Y	1924	1924	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2821 WESTERN	N/A	N	Y	1896	1896	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2900 WESTERN	N/A	N	Y	1916	1916	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2901 WESTERN	N/A	N	Y	1916	1916	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
2904 WESTERN	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2905 WESTERN	N/A	N	Y	1896	1896	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2908 WESTERN	N/A	N	Y	1940	1940	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2909 WESTERN	N/A	N	Y	1930	1930	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
2912 WESTERN	N/A	N	Y	1903	1903	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2913 WESTERN	N/A	N	Y	1916	1916	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
2916 WESTERN	N/A	N	Y	1903	1903	Maintenance Records/CUST	U	C	P	NL	u	N/R	N			N		
2917 WESTERN	N/A	N	Y	1995	1995	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
2920 WESTERN	N/A	N	Y	1987	1987	CUSTOMER SURVEY	U	C	C/G	GRR	u	N/R	N			N		
2921 WESTERN	N/A	N	Y	1913	1913	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3000 WESTERN APT 1	N/A	N	Y	1887	1887	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
3008 WESTERN	N/A	N	Y	1956	1956	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3009 WESTERN	N/A	N	Y	1914	1914	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3015 WESTERN	N/A	N	Y	2018	2018	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3020 WESTERN	N/A	N	Y	1950	1950	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3021 WESTERN	N/A	N	Y	1975	1975	Visual Inspectoin	U	C	C	NL	u	N/R	N			N		
3100 WESTERN	N/A	N	Y	1941	1941	Visual Inspectoin	U	g-c	g-c	GRR	u	N/R	N			N		
3101 WESTERN	N/A	N	Y	1955	1955	Visual Inspectoin	U	C	P	NL	u	N/R	N			N		
3105 WESTERN	N/A	N	Y	1926	1926	Visual Inspectoin	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
3113 WESTERN	N/A	N	Y	1927	1927	Visual Inspectoin	U	G	P	GRR	u	N/R	N			N		
3116 WESTERN	N/A	N	Y	1953	1953	Visual Inspectoin	U	C	G	GRR	u	N/R	N			N		
3117 WESTERN	N/A	N	Y	1925	1925	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
3120 WESTERN	N/A	N	Y	1905	1905	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3121 WESTERN	N/A	N	Y	1979	1979	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3200 WESTERN	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
3205 WESTERN	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3208 WESTERN	N/A	N	Y	1929	1929	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3216 WESTERN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
3217 WESTERN	N/A	N	Y	1954	1954	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3220 WESTERN	N/A	N	Y	1908	1908	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
3229 WESTERN	N/A	N	Y	1948	1948	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3230 WESTERN	N/A	N	Y	1977	1977	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
3300 WESTERN	N/A	N	Y	1990	1990	Maintenance Records	U	C	C	NL	u	N/R	N			N		
3304 WESTERN	N/A	N	Y	1926	1926	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
3308 WESTERN	N/A	N	Y	1941	1941	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
3312 WESTERN	N/A	N	Y	1941	1941	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
3316 WESTERN	N/A	N	Y	1986	1986	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3320 WESTERN	N/A	N	Y	1923	1923	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3321 WESTERN	N/A	N	Y	1907	1907	Visual Inspection	U	P	P	NL	u	N/R	N			N		
3324 WESTERN	N/A	N	Y	1916	1916	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3328 WESTERN	N/A	N	Y	1896	1896	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3334 WESTERN	N/A	N	Y	1954	1954	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3401 WESTERN	N/A	N	Y	1906	1906	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3404 WESTERN	N/A	N	Y	1907	1907	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3408 WESTERN	N/A	N	Y	1914	1914	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3412 WESTERN	N/A	N	Y	1950	1950	Visual Inspection	U	G	P	GRR	u	N/R	N			N		
3413 WESTERN	N/A	N	Y	1935	1935	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3416 WESTERN	N/A	N	Y	1927	2009	Maintenance Records/CUST	U	G	P	GRR	u	N/R	N			N		
3417 WESTERN	N/A	N	Y	2009	2009	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3420 WESTERN	N/A	N	Y	1995	1995	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3421 WESTERN	N/A	N	Y	1914	1914	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3429 WESTERN	N/A	N	Y	1950	1950	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3432 WESTERN	N/A	N	Y	1907	1907	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3433 WESTERN	N/A	N	Y	1964	1964	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
3444 WESTERN	N/A	N	Y	1952	1952	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3445 WESTERN	N/A	N	Y	1929	1929	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3448 WESTERN	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3449 WESTERN	N/A	N	Y	1948	1948	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3453 WESTERN	N/A	N	Y	1915	1915	Visual Inspection	U	G	G	GRR	u	N/R	N			N		
3457 WESTERN	N/A	N	Y	1960	1960	CUSTOMER SURVEY/VISUAL	U	P	P	NL	u	N/R	N			N		
3500 WESTERN	N/A	N	Y	1950	1950	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3516 WESTERN	N/A	N	Y	1993	1993	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3517 WESTERN	N/A	N	Y	1987	1987	Maintenance Records/CUST	U	C	P	NL	u	N/R	N			N		
3520 WESTERN	N/A	N	Y	1897	1897	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:						
Total Service Lines - Residential - 7021/Commercial - 991																			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property		
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.		
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)		Plastic - PVC, HDPE, PEX (P)									
3521 WESTERN	N/A	N	Y	1980	1980	Visual Inspection	U	C	P	NL	u	N/R	N		Leave blank if no Lead	N			
3600 WESTERN	N/A	N	Y	1924	1924	Visual Inspection	U	C	P	NL	u	N/R	N			N			
3601 WESTERN	N/A	N	Y	1977	1977	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N			
3604 WESTERN	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N			
3605 WESTERN	N/A	N	Y	1922	1922	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N			
3608 WESTERN	N/A	N	Y	1957	1957	Visual Inspection	U	C	C	NL	u	N/R	N			N			
3609 WESTERN	N/A	N	Y	1998	1998	Visual Inspection	U	C	C	NL	u	N/R	N			N			
3612 WESTERN	N/A	N	Y	1988	1988	CUSTOMER SURVEY	U	C	G/P	GRR	u	N/R	N			N			
3613 WESTERN	N/A	N	Y	1942	1942	Maintenance Records	U	C	C	NL	u	N/R	N			N			
3616 WESTERN	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N			
3617 WESTERN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N			
3701 WESTERN	N/A	N	Y	1965	1965	Visual Inspection	U	c	c	NL	u	N/R	N			N			
3705 WESTERN	N/A	N	Y	1967	1967	CUSTOMER SURVEY	U	c	C	NL	u	N/R	N			N			
3709 WESTERN	N/A	N	Y	1970	1970	Visual Inspection	U	c	c	NL	u	N/R	N			N			
3801 WESTERN	N/A	N	Y	1970	1970	Visual Inspection	U	c	P	NL	u	N/R	N			N			
3804 WESTERN	N/A	N	Y	1970	1970	Visual Inspection	U	C	G	GRR	u	N/R	N			N			
3805 WESTERN	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N			
3808 WESTERN	N/A	N	Y	1970	1970	Visual Inspection	U	c	P	NL	u	N/R	N			N			
3809 WESTERN	N/A	N	Y	1970	1970	Visual Inspection	U	c	P	NL	u	N/R	N			N			
3812 WESTERN	N/A	N	Y	1970	1970	Visual Inspection	U	c	P	NL	u	N/R	N			N			
3813 WESTERN	N/A	N	Y	1970	1970	Maintenance Records	U	C	C	NL	u	N/R	N			N			
3816 WESTERN	N/A	N	Y	1970	1970	Visual Inspection	U	c	P	NL	u	N/R	N			N			
3900 WESTERN	N/A	N	Y	1975	1975	Visual Inspection	U	c	c	NL	u	N/R	N			N			
3901 WESTERN	N/A	N	Y	1970	1970	Visual Inspection	U	c	P	NL	u	N/R	N			N			
3905 WESTERN	N/A	N	Y	1969	1969	Visual Inspection	U	c	P	NL	u	N/R	N			N			
3908 WESTERN	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	c	C	NL	u	N/R	N			N			
3912 WESTERN	N/A	N	Y	2016	2016	Visual Inspection	U	c	c	NL	u	N/R	N			N			
3913 WESTERN	N/A	N	Y	1917	1917	Visual Inspection	U	c	P	NL	u	N/R	N			N			
3916 WESTERN	N/A	N	Y	1970	1970	Visual Inspection	U	c	c	NL	u	N/R	N			N			
3920 WESTERN	N/A	N	Y	1970	1970	Visual Inspection	U	c	P	NL	u	N/R	N			N			
4000 WESTERN	N/A	N	Y	1941	1941	Visual Inspection	U	c	c	NL	u	N/R	N			N			
4001 WESTERN	N/A	N	Y	1967	1967	Visual Inspection	U	c	P	NL	u	N/R	N			N			
4104 WESTERN	N/A	N	Y	1963	1963	CUSTOMER SURVEY	U	c	g	GRR	u	N/R	N			N			
4300 WESTERN	N/A	N	Y	1989	1989	Visual Inspection	U	c	P	NL	u	N/R	N			N			
4304 WESTERN	N/A	N	Y	1988	1988	Visual Inspection	U	c	P	NL	u	N/R	N			N			
4308 WESTERN	N/A	N	Y	1958	1958	Visual Inspection	U	c	c	NL	u	N/R	N			N			
4312 WESTERN	N/A	N	Y	1967	1967	Visual Inspection	U	c	P	NL	u	N/R	N			N			
4316 WESTERN	N/A	N	Y	1993	1993	Visual Inspection	U	c	c	NL	u	N/R	N			N			
4320 WESTERN	N/A	N	Y	1960	1960	Visual Inspection	U	c	P	NL	u	N/R	N			N			
4324 WESTERN	N/A	N	Y	1990	1990	Visual Inspection	U	c	P	NL	u	N/R	N			N			
4400 WESTERN	N/A	N	Y	1988	1988	Visual Inspection	U	c	c	NL	u	N/R	N			N			
4404 WESTERN	N/A	N	Y	1989	1989	Visual Inspection	U	c	c	NL	u	N/R	N			N			
4408 WESTERN	N/A	N	Y	1990	1990	Visual Inspection	U	c	c	NL	u	N/R	N			N			
4412 WESTERN	N/A	N	Y	1991	1991	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N			
4416 WESTERN	N/A	N	Y	1991	1991	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N			

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
4420 WESTERN	N/A	N	Y	1992	1992	Visual Inspection	U	C	C	NL	u	N/R	N			N		
1 WESTERN AVE HTS	N/A	N	Y	1977	1977	Visual Inspection	U	C	C	NL	u	N/R	N			N		
2 WESTERN AVE HTS	N/A	N	Y	1952	1952	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3 WESTERN AVE HTS	N/A	N	Y	1971	1971	Visual Inspection	U	C	C	NL	u	N/R	N			N		
4 WESTERN AVE HTS	N/A	N	Y	1970	1970	Visual Inspection	U	C	C	NL	u	N/R	N			N		
5 WESTERN AVE HTS	N/A	N	Y	1965	1965	Visual Inspection	U	C	P	NL	u	N/R	N			N		
6 WESTERN AVE HTS	N/A	N	Y	1967	1967	Visual Inspection	U	C	P	NL	u	N/R	N			N		
7 WESTERN AVE HTS	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N		
8 WESTERN AVE HTS	N/A	N	Y	1967	1967	Visual Inspection	U	C	C	NL	u	N/R	N			N		
9 WESTERN AVE HTS	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N		
10 WESTERN AVE HTS	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
11 WESTERN AVE HTS	N/A	N	Y	1956	1956	Visual Inspection	U	C	C	NL	u	N/R	N			N		
12 WESTERN AVE HTS	N/A	N	Y	2015	2015	Visual Inspection	U	C	P	NL	u	N/R	N			N		
13 WESTERN AVE HTS	N/A	N	Y	1967	1967	Visual Inspection	U	C	C	NL	u	N/R	N			N		
14 WESTERN AVE HTS	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
15 WESTERN AVE HTS	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
16 WESTERN AVE HTS	N/A	N	Y	1983	1983	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2213 WESTERN THRU 2215	N/A	N	Y	1913	1913	Visual Inspection	U	C	P	NL	u	N/R	N			N		
1602 WESTGATE	N/A	N	Y	1977	1977	Maintenance Record	U	P	P	NL	u	N/R	N			N		
1603 WESTGATE	N/A	N	Y	1976	1976	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1604 WESTGATE	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1605 WESTGATE	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1606 WESTGATE	N/A	N	Y	1987	1987	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1607 WESTGATE	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1608 WESTGATE	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1609 WESTGATE	N/A	N	Y	1987	1987	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1611 WESTGATE	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1612 WESTGATE	N/A	N	Y	1987	1987	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1613 WESTGATE	N/A	N	Y	1987	1987	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1615 WESTGATE	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1616 WESTGATE	N/A	N	Y	1998	1998	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1617 WESTGATE	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1620 WESTGATE	N/A	N	Y	1987	1987	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1621 WESTGATE	N/A	N	Y	1976	1976	Maintenance Record	U	C	C	NL	u	N/R	N			N		
1623 WESTGATE	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
100 WESTVIEW	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N		
101 WESTVIEW	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
102 WESTVIEW	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
103 WESTVIEW	N/A	N	Y	1953	1953	Visual Inspection	U	C	P	NL	u	N/R	N			N		
104 WESTVIEW	N/A	N	Y	1954	1954	Visual Inspection	U	C	C	NL	u	N/R	N			N		
105 WESTVIEW	N/A	N	Y	1992	1992	Visual Inspection	U	C	P	NL	u	N/R	N			N		
106 WESTVIEW	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N		
107 WESTVIEW	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N		
108 WESTVIEW	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N		
109 WESTVIEW	N/A	N	Y	1955	1955	Visual Inspection	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Lead (L)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
110 WESTVIEW	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
111 WESTVIEW	N/A	N	Y	1954	1954	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
112 WESTVIEW	N/A	N	Y	1956	1956	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
113 WESTVIEW	N/A	N	Y	1955	1955	Visual Inspection/customer	U	C	G	GRR	u	N/R	N			N		
114 WESTVIEW	N/A	N	Y	1966	1966	Visual Inspection	U	C	P	NL	u	N/R	N			N		
115 WESTVIEW	N/A	N	Y	1955	1955	Visual Inspection/customer	U	C	G	GRR	u	N/R	N			N		
116 WESTVIEW	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
118 WESTVIEW	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
120 WESTVIEW	N/A	N	Y	1954	1954	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
121 WESTVIEW	N/A	N	Y	1963	1963	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
122 WESTVIEW	N/A	N	Y	1965	1965	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
123 WESTVIEW	N/A	N	Y	1978	1978	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
124 WESTVIEW	N/A	N	Y	1957	1957	Visual Inspection	U	C	C	NL	u	N/R	N			N		
125 WESTVIEW	N/A	N	Y	1957	1957	Visual Inspection	U	C	P	NL	u	N/R	N			N		
127 WESTVIEW	N/A	N	Y	1960	1960	Visual Inspection	U	C	P	NL	u	N/R	N			N		
128 WESTVIEW	N/A	N	Y	1966	1966	Visual Inspection	U	C	P	NL	u	N/R	N			N		
129 WESTVIEW	N/A	N	Y	1960	1960	Visual Inspection	U	C	P	NL	u	N/R	N			N		
130 WESTVIEW	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
131 WESTVIEW	N/A	N	Y	1959	1959	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
132 WESTVIEW	N/A	N	Y	1960	1960	Visual Inspection	U	C	P	NL	u	N/R	N			N		
134 WESTVIEW	N/A	N	Y	1959	1959	Visual Inspection	U	C	P	NL	u	N/R	N			N		
136 WESTVIEW	N/A	N	Y	1963	1963	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
140 WESTVIEW	N/A	N	Y	1961	1961	Visual Inspection	U	C	C	NL	u	N/R	N			N		
142 WESTVIEW	N/A	N	Y	1965	1965	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
144 WESTVIEW	N/A	N	Y	1969	1969	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1 WESTWOOD	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N		
2 WESTWOOD	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3 WESTWOOD	N/A	N	Y	1954	1954	Visual Inspection	U	C	P	NL	u	N/R	N			N		
4 WESTWOOD	N/A	N	Y	1988	1988	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
5 WESTWOOD	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N		
6 WESTWOOD	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N		
7 WESTWOOD	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N		
8 WESTWOOD	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N		
9 WESTWOOD	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		
10 WESTWOOD	N/A	N	Y	1947	1947	Visual Inspection	U	C	P	NL	u	N/R	N			N		
11 WESTWOOD	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N		
12 WESTWOOD	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N		
13 WESTWOOD	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N		
14 WESTWOOD	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N		
15 WESTWOOD	N/A	N	Y	1942	1942	Visual Inspection	U	C	P	NL	u	N/R	N			N		
16 WESTWOOD	N/A	N	Y	1942	1942	Visual Inspection	U	C	P	NL	u	N/R	N			N		
17 WESTWOOD	N/A	N	Y	1941	1941	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
18 WESTWOOD	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N		
19 WESTWOOD	N/A	N	Y	1941	1941	Visual Inspection	U	C	P	NL	u	N/R	N			N		
20 WESTWOOD	N/A	N	Y	1946	1946	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)			
		Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)					Galvanized (G)			
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)					Plastic - PVC, HDPE, PEX (P)			
							Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)					Cast/Ductile Iron or Transite (O)			
22 WESTWOOD	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N		
23 WESTWOOD	N/A	N	Y	1988	1988	Visual Inspection	U	C	C	NL	u	N/R	N			N		
24 WESTWOOD	N/A	N	Y	1988	1988	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
25 WESTWOOD	N/A	N	Y	1988	1988	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
26 WESTWOOD	N/A	N	Y	1988	1988	MAINTENANCE RECORDS/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
27 WESTWOOD	N/A	N	Y	1988	1988	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
29 WESTWOOD	N/A	N	Y	1988	1988	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
30 WESTWOOD	N/A	N	Y	2018	2018	Visual Inspection	U	C	C	NL	u	N/R	N			N		
31 WESTWOOD	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N		
32 WESTWOOD	N/A	N	Y	1988	1988	CUSTOMER SURVEY/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
33 WESTWOOD	N/A	N	Y	1988	1988	Visual Inspection	U	C	P	NL	u	N/R	N			N		
9 WILLIAMS CT	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
10 WILLIAMS CT	N/A	N	Y	1948	1948	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
11 WILLIAMS CT	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
12 WILLIAMS CT	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
13 WILLIAMS CT	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
14 WILLIAMS CT	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
15 WILLIAMS CT	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
16 WILLIAMS CT	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
17 WILLIAMS CT	N/A	N	Y	1948	2000	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
3401 WILLOW DR	N/A	N	Y	1958	1958	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3404 WILLOW DR	N/A	N	Y	1955	1955	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3408 WILLOW DR	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3409 WILLOW DR	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3412 WILLOW DR	N/A	N	Y	1957	1957	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3413 WILLOW DR	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3416 WILLOW DR	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3417 WILLOW DR	N/A	N	Y	1956	1956	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3420 WILLOW DR	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3421 WILLOW DR	N/A	N	Y	1955	1955	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3424 WILLOW DR	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	P	G	GRR	u	N/R	N			N		
3425 WILLOW DR	N/A	N	Y	1962	1962	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3428 WILLOW DR	N/A	N	Y	1985	1985	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3429 WILLOW DR	N/A	N	Y	1958	1958	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3432 WILLOW DR	N/A	N	Y	1985	2018	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3433 WILLOW DR	N/A	N	Y	1970	1970	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3436 WILLOW DR	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
3500 WILLOW DR	N/A	N	Y	1969	1969	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3501 WILLOW DR	N/A	N	Y	1969	1969	Visual Inspection	U	C	P	NL	u	N/R	N			N		
3504 WILLOW DR	N/A	N	Y	1965	1965	Visual Inspection	U	C	G	GRR	u	N/R	N			N		
3505 WILLOW DR	N/A	N	Y	1966	1966	Visual Inspection/CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3508 WILLOW DR	N/A	N	Y	1969	1969	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3509 WILLOW DR	N/A	N	Y	1968	1968	Visual Inspection	U	C	C	NL	u	N/R	N			N		
3512 WILLOW DR	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3513 WILLOW DR	N/A	N	Y	1968	1968	Visual Inspection	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
4 WILTON	N/A	N	Y	1945	1945	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
99 WOODGATE	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
120 WOODGATE	N/A	N	Y	1987	1987	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
121 WOODGATE	N/A	N	Y	1984	1984	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
200 WOODGATE	N/A	N	Y	1987	1987	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
201 WOODGATE	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
301 WOODGATE	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
309 WOODGATE	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
1702 WOODGATE	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
91 WOODLAWN	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
94 WOODLAWN	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
95 WOODLAWN	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
99 WOODLAWN	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
100 WOODLAWN	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
105 WOODLAWN	N/A	N	Y	1953	1985	MAINTENANCE RECORDS/C	U	C	C	NL	u	N/R	N			N		
109 WOODLAWN	N/A	N	Y	1953	1953	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
113 WOODLAWN	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
117 WOODLAWN	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
121 WOODLAWN	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
122 WOODLAWN	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
125 WOODLAWN	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
126 WOODLAWN	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
129 WOODLAWN	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
130 WOODLAWN	N/A	N	Y	1957	1957	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
134 WOODLAWN	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
138 WOODLAWN	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
201 WOODLAWN	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
202 WOODLAWN	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
205 WOODLAWN	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
209 WOODLAWN	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
210 WOODLAWN	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
213 WOODLAWN	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
217 WOODLAWN	N/A	N	Y	1954	1954	MAINTENANCE RECORDS/N	U	C	C	NL	u	N/R	N			N		
218 WOODLAWN	N/A	N	Y	1955	1955	MAINTENANCE RECORDS/N	U	C	C	NL	u	N/R	N			N		
221 WOODLAWN	N/A	N	Y	1955	1955	MAINTENANCE RECORDS/N	U	C	C	NL	u	N/R	N			N		
222 WOODLAWN	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
225 WOODLAWN	N/A	N	Y	1954	1954	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
226 WOODLAWN	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
233 WOODLAWN	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
234 WOODLAWN	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
237 WOODLAWN	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
301 WOODLAWN	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
302 WOODLAWN	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
306 WOODLAWN	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
309 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
310 WOODLAWN	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
313 WOODLAWN	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
314 WOODLAWN	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
317 WOODLAWN	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
318 WOODLAWN	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
321 WOODLAWN	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
325 WOODLAWN	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
329 WOODLAWN	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
400 WOODLAWN	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
401 WOODLAWN	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
405 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
408 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
409 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
412 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
413 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
416 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
417 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
420 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
424 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
425 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
428 WOODLAWN	N/A	N	Y	2002	2002	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
432 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
433 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
437 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
500 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
504 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
505 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
508 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
509 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
517 WOODLAWN	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
520 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
521 WOODLAWN	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
525 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
529 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
600 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
601 WOODLAWN	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
604 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
605 WOODLAWN	N/A	N	Y	1950	1950	CUSTOMER SURVEY	U	C	C/P	NL	u	N/R	N			N		
608 WOODLAWN	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
609 WOODLAWN	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
612 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
613 WOODLAWN	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
616 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
617 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
621 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Galvanized (G)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)			Leave blank if no Lead													
624 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
625 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
628 WOODLAWN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
629 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
632 WOODLAWN	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
633 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
636 WOODLAWN	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
637 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
640 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
641 WOODLAWN	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
644 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
645 WOODLAWN	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
648 WOODLAWN	N/A	N	Y	2016	2016	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
649 WOODLAWN	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
653 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
657 WOODLAWN	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
1512 LAKELAND 1516	N/A	N	Y	1980	1980	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
19TH & MARION MTCE	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
19TH & MARSHALL	N/A	N	Y			VISUAL INSPECTION	U	O	O	NL	u	N/R	N			N		
208 DEWITT AVE EAST	N/A	N	Y	1945	1945	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
N.RT 45 -ALTON	N/A	N	Y			MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
412 AIRPORT RD	N/A	N	Y	1964	1964	MAINTENANCE RECORDS	U	O	C	NL	u	N/R	N			N		
432 AIRPORT RD	N/A	N	Y	1964	1964	MAINTENANCE RECORDS	U	O	C	NL	u	N/R	N			N		
400 AIRPORT ROAD	N/A	N	Y	1964	1964	MAINTENANCE RECORDS	U	O	C	NL	u	N/R	N			N		
480 AIRPORT ROAD EA	N/A	N	Y	1964	1964	MAINTENANCE RECORDS	U	O	C	NL	u	N/R	N			N		
432 AIRPORT ROAD TE	N/A	N	Y	1964	1964	MAINTENANCE RECORDS	U	O	C	NL	u	N/R	N			N		
BASEBALL DIAMOND	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
RT 4 BOX 148	N/A	N	Y			VISUAL INSPECTION	U	o	o	NL	u	N/R	N			N		
RT 4 BOX 148 SEWER	N/A	N	Y			VISUAL INSPECTION	U	p	p	NL	u	N/R	N			N		
RR 2 BOX 23	N/A	N	Y			VISUAL INSPECTION	U	c	c	NL	u	N/R	N			N		
RR 2 BOX 23(B)	N/A	N	Y			VISUAL INSPECTION	U	c	c	NL	u	N/R	N			N		
20 BROADWAY	N/A	N	Y	1990	1990	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
80 BROADWAY	N/A	N	Y	1994	1994	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
88 BROADWAY	N/A	N	Y	1956	1956	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
90 BROADWAY	N/A	N	Y	1998	1998	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
100 BROADWAY FIRE LINE	N/A	N	Y	1971	1971	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
100 BROADWAY - CHURCH/SCHOOL	SCH008A	Y	Y	2011	2011	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
101 BROADWAY	N/A	N	Y	1997	1997	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
500 BROADWAY - PARK	N/A	Y	Y			Maintenance records	U	c	c	NL	u	N/R	N			N		
600 BROADWAY	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
601 BROADWAY - DENTIST	N/A	Y	Y	1990	1990	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
608 BROADWAY	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
613 BROADWAY	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
616 BROADWAY - DAY CARE	DAYCARE013A	Y	Y	1970	1970	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
700 BROADWAY	N/A	N	Y	2006	2006	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
700 BROADWAY SPRIN	N/A	N	Y	2006	2006	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
705 BROADWAY	N/A	N	Y	1900	1900	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
708 BROADWAY	N/A	N	Y	2006	2006	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
712 BROADWAY	N/A	N	Y	1923	1923	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
720 BROADWAY	N/A	N	Y	1972	1972	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
721 BROADWAY	N/A	N	Y	1950	1950	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
801 BROADWAY	N/A	N	Y	2000	2000	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
804 BROADWAY	N/A	N	Y	2004	2004	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
809 BROADWAY	N/A	N	Y	2004	2004	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
815 BROADWAY	N/A	N	Y	1980	1980	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
816 BROADWAY	N/A	N	Y	1900	1900	MAINTENANCE RECORDS/V	U	P	C	NL	u	N/R	N			N		
820 BROADWAY	N/A	N	Y	1973	1973	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
904 BROADWAY	N/A	N	Y	1886	1886	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
920 BROADWAY	N/A	N	Y	1995	1995	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
921 BROADWAY	N/A	N	Y	1975	1975	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1000 BROADWAY	N/A	N	Y	1975	1975	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
1009 BROADWAY	N/A	N	Y	1903	1903	MAINTENANCE RECORDS/V	U	G	C	GRR	u	N/R	N			N		
1012 BROADWAY	N/A	N	Y	1926	1926	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1016 BROADWAY	N/A	N	Y	1904	1904	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1017 BROADWAY - DENTIST	N/A	Y	Y	1977	1977	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1020 BROADWAY	N/A	N	Y	1965	1965	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1100 BROADWAY	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	G	C/P	GRR	u	N/R	N			N		
1101 BROADWAY	N/A	N	Y	1977	1977	CUSTOMER SURVEY	U	G	C	GRR	u	N/R	N			N		
1109 BROADWAY	N/A	N	Y	1905	1905	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1116 BROADWAY	N/A	N	Y	1908	1908	MAINTENANCE RECORDS/V	U	G	G	GRR	u	N/R	N			N		
1117 BROADWAY	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1212 BROADWAY	N/A	N	Y	1948	1948	VISUAL INSPECTION	U	P	C	NL	u	N/R	N			N		
1221 BROADWAY	N/A	N	Y	1906	1906	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1300 BROADWAY	N/A	N	Y	1905	1905	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1312 BROADWAY	N/A	N	Y	2007	2007	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1320 BROADWAY	N/A	N	Y	2019	2019	MAINTENANCE RECORDS/V	U	CTS	C	NL	u	N/R	N			N		
1402 BROADWAY	N/A	N	Y	2024	2024	MAINTENANCE RECORDS	U	P	P	NL	u	Aug-24	N	Aug-24	p	N		
1410 BROADWAY	N/A	N	Y	2024	2024	MAINTENANCE RECORDS	U	P	P	NL	u	Aug-24	N	Aug-24	p	N		
1412 BROADWAY	N/A	N	Y	2024	2024	MAINTENANCE RECORDS	U	P	P	NL	u	Aug-24	N	Aug-24	p	N		
1414 BROADWAY	N/A	N	Y	2024	2024	MAINTENANCE RECORDS	U	P	P	NL	u	Aug-24	N	Aug-24	p	N		
1500 BROADWAY	N/A	N	Y	2024	1987	MAINTENANCE RECORDS	U	P	P	NL	u	Aug-24	Y	Aug-24	p	N		
1501 BROADWAY	N/A	N	Y	2024	1996	MAINTENANCE RECORDS	U	P	P	NL	u	Aug-24	Y	Aug-24	p	N		
1504 BROADWAY	N/A	N	Y	2024	1996	MAINTENANCE RECORDS	U	P	P	NL	u	Aug-24	y	Aug-24	p	N		
1510 BROADWAY	N/A	N	Y	2024	1996	MAINTENANCE RECORDS	U	P	P	NL	u	Aug-24	y	Aug-24	p	N		
1516 BROADWAY	N/A	N	Y	2024	1988	MAINTENANCE RECORDS	U	P	P	NL	u	Aug-24	y	Aug-24	p	N		
1520 BROADWAY	N/A	N	Y	2024	1988	MAINTENANCE RECORDS	U	P	P	NL	u	Aug-24	y	Aug-24	p	N		
1520 BROADWAY 1/2	N/A	N	Y	2024	1988	MAINTENANCE RECORDS	U	P	P	NL	u	Aug-24	y	Aug-24	p	N		
1528 BROADWAY	N/A	N	Y	2024	2008	MAINTENANCE RECORDS	U	P	P	NL	u	Aug-24	y	Aug-24	p	N		
1600 BROADWAY	N/A	N	Y	2021	2021	MAINTENANCE RECORDS	U	P	P	NL	u	2021	y	2021	P	N		
1601 BROADWAY	N/A	N	Y	2021	2021	MAINTENANCE RECORDS	U	P	P	NL	u	2021	Y	2021	P	N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)																
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
1604 BROADWAY	N/A	N	Y	2021	2021	MAINTENANCE RECORDS	U	P	P	NL	u	2021	Y	2021	P	N		
1606 BROADWAY	N/A	N	Y	2021	2021	MAINTENANCE RECORDS/C	U	P	C	NL	u	2021	Y	2021	P	N		
1607 BROADWAY 1	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1607 BROADWAY 2	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1607 BROADWAY 3	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1608 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1609 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1610 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1611 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1612 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1614 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1618 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1620 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1622 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1624 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1626 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1628 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1630 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1632 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1701 BROADWAY	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021	Y	2021	P	N		
1718 BROADWAY	N/A	N	Y	2021	2021	CUSTOMER SURVEY	U	P	C	NL	u	2021	Y	2021	P	N		
1803 BROADWAY	N/A	N	Y	2019	2019	Maintenance Records	U	P	P	NL	u	2019	Y	2019	P	N		
1804 BROADWAY	N/A	N	Y	2019	2019	Maintenance Records	U	P	P	NL	u	2019	Y	2019	P	N		
1808 BROADWAY	N/A	N	Y	2019	2019	Maintenance Records	U	P	P	NL	u	2019	Y	2019	P	N		
1813 BROADWAY	N/A	N	Y	2019	2019	MAINTENANCE RECORDS/C	U	P	C	NL	u	2019	Y	2019	P	N		
1815 BROADWAY	N/A	N	Y	2019	2019	Maintenance Records	U	P	P	NL	u	2019	Y	2019	P	N		
1816 BROADWAY	N/A	N	Y	2019	2019	Maintenance Records	U	P	P	NL	u	2019	Y	2019	P	N		
1818 BROADWAY	N/A	N	Y	2019	2019	Maintenance Records	U	P	P	NL	u	2019	Y	2019	P	N		
1820 BROADWAY	N/A	N	Y	2019	2019	Maintenance Records	U	P	P	NL	u	2019	Y	2019	P	N		
1822 BROADWAY	N/A	N	Y	2019	2019	Maintenance Records	U	P	P	NL	u	2019	Y	2019	P	N		
1824 BROADWAY	N/A	N	Y	2019	2019	Maintenance Records	U	P	P	NL	u	2019	Y	2019	P	N		
1826 BROADWAY	N/A	N	Y	2019	2019	Maintenance Records	U	P	P	NL	u	2019	Y	2019	P	N		
1830 BROADWAY	N/A	N	Y	2019	2019	Maintenance Records	U	P	P	NL	u	2019	Y	2019	P	N		
1901 BROADWAY A	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1901 BROADWAY B	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1901 BROADWAY C	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1901 BROADWAY D	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1901 BROADWAY E	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2017 BROADWAY	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2100 BROADWAY	N/A	N	Y	1990	1990	MAINTENANCE RECORDS/A	U	C	P	NL	u	N/R	N			N		
2412 BROADWAY	N/A	N	Y	1996	1996	MAINTENANCE RECORDS/A	U	C	P	NL	u	N/R	N			N		
2500 BROADWAY	N/A	N	Y	2023	2023	MAINTENANCE RECORDS/A	U	C	C	NL	u	N/R	N			N		
511 BROADWAY APT 202	N/A	N	Y	1973	1973	MAINTENANCE RECORDS/A	U	C	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E GLIKS	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
700 BROADWAY AVE E CLAIRES	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N		Leave blank if no Lead	N		
700 BROADWAY AVE E JOANN	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E MARSHALL	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RUE 21	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E BATH BODY	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E JOURNAL	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E COMMUNITY BLOOD	N/A	Y	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E FOUNTAIN	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E SHOE	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E MAURICES	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
1000 BROADWAY AVE E SPRINKLER	N/A	N	Y	1964	1964	Maintenance Records	U	O	C	NL	u	N/R	N			N		
1000 BROADWAY AVE E	N/A	N	Y	1964	1964	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E CC KETTLECORN	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E BE RO LUONG	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E ALAMO	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E DUNHAMS	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E CHRISTOPHER B	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y	1970	1970	Maintenance Records	U	O	C	NL	u	N/R	N			N		
700 BROADWAY AVE E RURAL KING	N/A	N	Y															

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)			
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead			
1117 BROADWAY AVE E	N/A	N	Y	2016	2016	maintenance Records	U	C	C	NL	u	N/R	N			N		
1121 BROADWAY AVE E	N/A	N	Y	1999	1999	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1121 BROADWAY AVE E	N/A	N	Y	1999	1999	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1209 BROADWAY AVE E	N/A	N	Y	2000	2000	maintenance Records	U	C	C	NL	u	N/R	N			N		
1209 BROADWAY AVE E	N/A	N	Y	2000	2000	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1320 BROADWAY AVE E	N/A	N	Y	1988	1988	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1400 BROADWAY AVE E	N/A	N	Y	1996	1996	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1408 BROADWAY AVE E	N/A	N	Y	2000	2000	Maintenance Records	U	O	O	NL	u	N/R	N			N		
1416 BROADWAY AVE E	N/A	N	Y	1995	1995	maintenance Records	U	G	P	GRR	u	N/R	N			N		
500 BROADWAY PET PA	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1611 BROADWAY THRU	N/A	N	Y	2021	2021	Maintenance Records	U	P	P	NL	u	2021 Y		2021		N		
500 BROADWAY-PETERS	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1920 BROOKSTONE LN - ASS. LIVING	N/A	Y	Y	2001	2001	maintenance Records	U	p	p	NL	u	N/R	N			N		
1920 BROOKSTONE LN - ASS. LIVING	N/A	Y	Y	2001	2001	maintenance Records	U	p	p	NL	u	N/R	N			N		
320 BUXTON DR	N/A	N	Y	2003	2003	maintenance Records	U	c	C	NL	u	N/R	N			N		
2504 BUXTON DR	N/A	N	Y	1999	1999	MAINTENANCE RECORDS/V	U	G	G	GRR	u	N/R	N			N		
4884 CARTER LANE	N/A	N	Y	1954	1954	Maintenance Records	U	C	C	NL	u	N/R	N			N		
4840 CARTER LN A	N/A	N	Y	1950	1950	maintenance Records	U	G	P	GRR	u	N/R	N			N		
4840 CARTER LN B	N/A	N	Y	1950	1950	Maintenance Records	U	P	G	GRR	u	N/R	N			N		
4840 CARTER LN C	N/A	N	Y	1950	1950	Maintenance Records	U	G	G	GRR	u	N/R	N			N		
2901 CEDAR	N/A	N	Y	1951	1951	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
3101 CEDAR	N/A	N	Y	1967	1967	Maintenance Records/VISU	U	C	C	NL	u	N/R	N			N		
1101 CHAMPAIGN	N/A	N	Y	1905	1905	Maintenance Records/VISU	U	G	P	GRR	u	N/R	N			N		
1409 CHAMPAIGN	N/A	N	Y	1946	1946	Maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
1413 CHAMPAIGN	N/A	N	Y	1960	1960	Maintenance Records/VISU	U	P	C	NL	u	N/R	N			N		
1416 CHAMPAIGN	N/A	N	Y	1920	1920	Maintenance Records/VISU	U	G	P	GRR	u	N/R	N			N		
1417 CHAMPAIGN	N/A	N	Y	1904	1904	Maintenance Records/VISU	U	G	P	GRR	u	N/R	N			N		
1420 CHAMPAIGN	N/A	N	Y	1990	1990	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1600 CHAMPAIGN	N/A	N	Y	1887	1887	maintenance Records/VISU	U	C	P	NL	u	N/R	N			N		
1604 CHAMPAIGN	N/A	N	Y	1915	1915	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1701 CHAMPAIGN	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1720 CHAMPAIGN	N/A	N	Y	1970	1970	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1816 CHAMPAIGN	N/A	N	Y	1915	1915	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
1900 CHAMPAIGN	N/A	N	Y	1953	1953	maintenance Records	U	C	C	NL	u	N/R	N			N		
1901 CHAMPAIGN	N/A	N	Y	1929	1929	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2101 CHAMPAIGN	N/A	N	Y	1999	1999	MAINTENANCE RECORDS/V	U	G	G	GRR	u	N/R	N			N		
2220 CHAMPAIGN	N/A	N	Y	1942	1942	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
2305 CHAMPAIGN	N/A	N	Y	1923	1923	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
2308 CHAMPAIGN	N/A	N	Y	1930	1930	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
2321 CHAMPAIGN	N/A	N	Y	1923	1923	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2500 CHAMPAIGN	N/A	N	Y	1921	1921	maintenance Records	U	C	P	NL	u	N/R	N			N		
2405 CHAMPAIGN-HAWT	SCH005A	Y	Y	2007	2007	MAINTENANCE RECORDS/V	U	G	G	GRR	u	N/R	N			N		
10 CHARLESTON - CHURCH	N/A	Y	Y	2007	2007	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
200 CHARLESTON - CHURCH/SCHOOL	N/A	Y	Y	2007	2007	MAINTENANCE RECORDS/V	U	G	G	GRR	u	N/R	N			N		
521 CHARLESTON	N/A	N	Y	1950	1950	MAINTENANCE RECORDS/V	U	G	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
600 CHARLESTON	N/A	N	y	1979	1979	MAINTENANCE RECORDS/VISUAL INSPECTION	U	C	C	NL	u	N/R	N		Leave blank if no Lead	N		
600 CHARLESTON	N/A	N	y	1979	1979	MAINTENANCE RECORDS/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
601 CHARLESTON	N/A	N	Y	1981	1981	CUSTOMER SURVEY	U	G	C	GRR	u	N/R	N			N		
612 CHARLESTON	N/A	N	Y	1969	1969	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
616 CHARLESTON	N/A	N	y	1931	1979	Maintenance Records	U	C	P	NL	u	N/R	N			N		
620 CHARLESTON	N/A	N	Y	2013	1973	Maintenance Records	U	C	P	NL	u	N/R	N			N		
620 CHARLESTON B	N/A	N	Y	2013	2013	Maintenance Records	U	C	P	NL	u	N/R	N			N		
621 CHARLESTON	N/A	N	Y	1979	1979	Maintenance Records	U	C	P	NL	u	N/R	N			N		
701 CHARLESTON	N/A	N	Y	2016	2016	Maintenance Records	U	C	P	NL	u	N/R	N			N		
701 CHARLESTON SPRING	N/A	N	Y	2016	2016	Maintenance Records	U	C	C	NL	u	N/R	N			N		
708 CHARLESTON	N/A	N	Y	1985	1985	maintenance Records	U	C	C	NL	u	N/R	N			N		
712 CHARLESTON	N/A	N	Y	1982	1982	Maintenance Records	U	C	P	NL	u	N/R	N			N		
721 CHARLESTON	N/A	N	Y	1970	1970	Maintenance Records	U	G	C	GRR	u	N/R	N			N		
801 CHARLESTON	N/A	N	y	1991	1991	maintenance Records	U	C	C	NL	u	N/R	N			N		
812 CHARLESTON	N/A	N	Y	2020	2020	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
815 CHARLESTON	N/A	N	y	1988	1988	Maintenance Records	U	C	C	NL	u	N/R	N			N		
821 CHARLESTON	N/A	N	Y	1950	1950	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
900 CHARLESTON	N/A	N	Y	1923	1923	Maintenance Records	U	C	C	NL	u	N/R	N			N		
901 CHARLESTON	N/A	N	Y	1971	1971	Maintenance Records	U	C	C	NL	u	N/R	N			N		
913 CHARLESTON	N/A	N	Y	1913	1913	Maintenance Records	U	C	C	NL	u	N/R	N			N		
921 CHARLESTON	N/A	N	Y	1974	1974	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1001 CHARLESTON	N/A	N	Y	1985	1985	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1004 CHARLESTON	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1016 CHARLESTON	N/A	N	y	1892	1892	MAINTENANCE RECORDS/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1111 CHARLESTON	N/A	N	Y	1996	1996	CUSTOMER SURVEY/VISUAL INSPECTION	U	G	C	GRR	u	N/R	N			N		
1200 CHARLESTON	N/A	N	Y	1962	1962	CUSTOMER SURVEY/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1208 CHARLESTON	N/A	N	y	1975	1975	MAINTENANCE RECORDS/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1220 CHARLESTON	N/A	N	Y	1953	1953	CUSTOMER SURVEY/VISUAL INSPECTION	U	P	C	NL	u	N/R	N			N		
1300 CHARLESTON	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1301 CHARLESTON	N/A	N	Y	1953	1953	MAINTENANCE RECORDS/VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1302 CHARLESTON	N/A	N	Y			CUSTOMER SURVEY/VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1304 CHARLESTON	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1316 CHARLESTON	N/A	N	y	2009	2009	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
1316 CHARLESTON SPRING	N/A	N	y	2009	2009	maintenance Records	U	C	G	GRR	u	N/R	N			N		
1321 CHARLESTON AVE	N/A	N	Y	2008	2008	CUSTOMER SURVEY/VISUAL INSPECTION	U	C	C/P	NL	u	N/R	N			N		
1400 CHARLESTON	N/A	N	y	1973	1973	MAINTENANCE RECORDS/VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
1401 CHARLESTON	N/A	N	Y	1903	1903	Maintenance Records	U	G	P	GRR	u	N/R	N			N		
1407 CHARLESTON	N/A	N	y	1966	1966	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1421 CHARLESTON	N/A	N	Y	1929	1929	CUSTOMER SURVEY	U	G	C/P	GRR	u	N/R	N			N		
1500 CHARLESTON	N/A	N	Y	1928	1928	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1501 CHARLESTON	N/A	N	y	1995	1995	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1515 CHARLESTON	N/A	N	Y	1984	1984	CUSTOMER SURVEY/VISUAL INSPECTION	U	C	C/P	NL	u	N/R	N			N		
1520 CHARLESTON	N/A	N	Y	1972	1972	CUSTOMER SURVEY/VISUAL INSPECTION	U	C	C/P	NL	u	N/R	N			N		
1600 CHARLESTON - CHURCH	N/A	Y	y	1994	1994	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1601 CHARLESTON	N/A	N	y	2007	2007	Maintenance Records	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)		Plastic - PVC, HDPE, PEX (P)								
1612 CHARLESTON APT	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1612 CHARLESTON APT	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1612 CHARLESTON LAU	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1620 CHARLESTON 1/2	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1701 CHARLESTON ADM	N/A	Y	Y	2013	2013	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1717 CHARLESTON	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1810 CHARLESTON	N/A	N	Y	1936	1936	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1821 CHARLESTON	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1913 CHARLESTON	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
2020 CHARLESTON	N/A	N	Y	1926	1926	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2305 CHARLESTON	N/A	N	Y	1901	1901	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2313 CHARLESTON	N/A	N	Y	1896	1896	Maintenance Records	U	C	G	GRR	u	N/R	N			N		
2320 CHARLESTON	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2521 CHARLESTON	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2612 CHARLESTON	N/A	N	Y	1975	1975	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		
1013 CHARLESTON AV	N/A	N	Y	2007	2007	maintenance Records	U	C	P	NL	u	N/R	N			N		
10 CHARLESTON AVE	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
204 CHARLESTON AVE	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
917 CHARLESTON AVE	N/A	N	Y	2012	2012	maintenance Records	U	C	C	NL	u	N/R	N			N		
1001 CHARLESTON AVE	N/A	N	Y	1998	1998	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1005 CHARLESTON AVE	N/A	N	Y	1998	1998	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1007 CHARLESTON AVE	N/A	N	Y	1998	1998	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1009 CHARLESTON AVE	N/A	N	Y	1998	1998	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1011 CHARLESTON AVE	N/A	N	Y	1998	1998	Maintenance Records	U	C	P	NL	u	N/R	N			N		
1015 CHARLESTON AVE	N/A	N	Y	1998	1998	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1017 CHARLESTON AVE	N/A	N	Y	1998	1998	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1019 CHARLESTON AVE	N/A	N	Y	1998	1998	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1021 CHARLESTON AVE	N/A	N	Y	1998	1998	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1023 CHARLESTON AVE	N/A	N	Y	1998	1998	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1101 CHARLESTON AVE	N/A	N	Y	1998	1998	Maintenance Records	U	O	C	NL	u	N/R	N			N		
1201 CHARLESTON AVE	N/A	N	Y			CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1219 CHARLESTON THR	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
6674 CO RD 1000N	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
101 COLES CENTRE PA - SPECIAL CARE	N/A	Y	Y	2009	2009	CUSTOMER SURVEY	U	G	C/P	GRR	u	N/R	N			N		
101 COLES CENTRE PA	N/A	N	Y	2009	2009	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
201 COLES CENTRE PA	N/A	N	Y	2009	2009	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
201 COLES CENTRE PA	N/A	N	Y	2009	2009	VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
300 COLES CENTRE PA - SBL	N/A	Y	Y	2010	2010	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
100 COLES CENTRE PK	N/A	N	Y	2009	2009	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
100 COLES CENTRE PK	N/A	N	Y	2009	2009	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
100 COLES CENTRE PK	N/A	N	Y	2009	2009	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
2121 COMMERCIAL	N/A	N	Y	2009	2009	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2213 COMMERCIAL	N/A	N	Y	1914	1914	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2217 COMMERCIAL	N/A	N	Y	1915	1915	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2320 COMMERCIAL	N/A	N	Y	1915	1915	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
2417 COMMERCIAL	N/A	N	Y	1995	1995	Maintenance Records	U	C	P	NL	u	N/R	N			N		
2709 COMMERCIAL	N/A	N	Y	1896	1896	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		
201 COUNTRY CLUB RD - CHURCH	N/A	Y	Y	2007	2007	Maintenance Records	U	C	C	NL	u	N/R	N			N		
205 COUNTRY CLUB RD - CHURCH	N/A	Y	Y	2001	2001	Maintenance Records	U	C	C	NL	u	N/R	N			N		
920 COUNTRY CLUB RD - ASS. LIVING	N/A	Y	Y	2016	2016	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1001 COUNTRY CLUB R	N/A	N	Y	1998	1998	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
7426 W COUNTRY CLUB RD - CHURCH	N/A	Y	Y	1994	1994	MAINTENANCE/VISUAL INS	U	P	G	GRR	u	N/R	N			N		
6565 E COUNTY RD 1000N	N/A	N	Y			MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
6877 E CO RD 1200 N	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2405 DAKOTA AVE	N/A	N	Y	1975	1975	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N		
2500 DAKOTA-SPORTS	N/A	N	Y			VISUAL INSPECTION	U	G	G	GRR	u	N/R	N			N		
136 DETTRO DR	N/A	N	Y	2008	2008	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
140 DETTRO DR	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
144 DETTRO	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	p	NL	u	N/R	N			N		
101 DETTRO DR	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
103 DETTRO DR	N/A	N	Y	2007	1994	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
104 DETTRO DR	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	p	NL	u	N/R	N			N		
105 DETTRO DR	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
108 DETTRO DR	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	p	NL	u	N/R	N			N		
112 DETTRO DR	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	p	NL	u	N/R	N			N		
116 DETTRO DR	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	p	NL	u	N/R	N			N		
118 DETTRO DR	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	p	NL	u	N/R	N			N		
120 DETTRO DR	N/A	N	Y	2016	2016	MAINTENANCE RECORDS	U	c	p	NL	u	N/R	N			N		
122 DETTRO DR	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	p	NL	u	N/R	N			N		
124 DETTRO DR	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	p	NL	u	N/R	N			N		
132 DETTRO DR	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	c	NL	u	N/R	N			N		
134 DETTRO DR	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	p	NL	u	N/R	N			N		
136 DETTRO DR	N/A	N	Y	2007	2007	CUSTOMER SURVEY/VISUAL	U	C	p	NL	u	N/R	N			N		
138 DETTRO DR	N/A	N	Y	2007	2007	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N		
142 DETTRO DR	N/A	N	Y	2012	2012	MAINTENANCE RECORDS	U	C	p	NL	u	N/R	N			N		
146 DETTRO DR	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	p	p	NL	u	N/R	N			N		
200 DETTRO DR - SBL	N/A	Y	Y	2017	2017	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
43 DEWITT	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
61 DEWITT	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
79 DEWITT	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
93 DEWITT	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
200 DEWITT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
208 DEWITT	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
500 DEWITT	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
508 DEWITT	N/A	N	Y	2008	2008	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
600 DEWITT	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
601 DEWITT	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
920 DEWITT	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1000 DEWITT	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1001 DEWITT	N/A	N	Y	1923	1923	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)		Cast/Ductile Iron or Transite (O)								
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)													
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
1312 DEWITT	N/A	N	Y	1959	1959	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1320 DEWITT	N/A	Y	Y	1946	1946	MAINTENANCE RECORDS	U	C	C	NL	U	N/R	N			N		
1401 DEWITT	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1708 DEWITT	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1800 DEWITT	N/A	N	Y	1946	1946	Maintenance Records	U	C	C	NL	u	N/R	N			N		
1820 DEWITT	N/A	N	Y	1911	1911	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1821 DEWITT	N/A	N	Y	1933	1933	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2120 DEWITT - CHURCH	N/A	Y	Y	1946	1946	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2520 DEWITT	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
2720 DEWITT	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
2904 DEWITT	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3012 DEWITT	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3121 DEWITT	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3300 DEWITT	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
3301 DEWITT	N/A	N	Y	1981	1981	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3320 DEWITT	N/A	N	Y	2011	2011	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
3321 DEWITT	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3400 DEWITT	N/A	N	Y	2008	2008	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3521 DEWITT	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3521 DEWITT - CHURCH	N/A	Y	Y	2007	2007	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3801 DEWITT	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
3801 DEWITT	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
3801 DEWITT SEWER	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	O	O	NL	u	N/R	N			N		
3921 DEWITT	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	O	C	NL	u	N/R	N			N		
4005 DEWITT	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	O	C	NL	u	N/R	N			N		
4121 DEWITT	N/A	N	Y	2010	2010	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
4216 DEWITT	N/A	N	Y	1998	1999	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
4217 DEWITT	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
4100 DEWITT AVE	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
104 DEWITT AVE EAST	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
315 DEWITT AVE EAST	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
317 DEWITT AVE EAST	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
400 DEWITT AVE EAST	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
401 DEWITT AVE EAST	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
401 DEWITT AVE EAST	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
513 DEWITT AVE EAST	N/A	N	Y	1931	1931	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
705 DEWITT AVE EAST	N/A	N	Y	1947	1947	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
721 DEWITT AVE EAST	N/A	N	Y	1917	1917	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
900 DEWITT AVE EAST - DENTIST	N/A	Y	Y	1928	1928	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
921 DEWITT AVE EAST	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1413 DEWITT AVE EAST	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1509 DEWITT AVE EAST	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1509 DEWITT AVE EAST	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
9008 DEWITT AVE EAST	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
900C DEWITT AVE EAST	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
DOLE RD	N/A	N	Y			VISUAL INSPECTION	U	O	O	NL	u	N/R	N			N		
DOLE RD	N/A	N	Y			VISUAL INSPECTION	U	O	O	NL	u	N/R	N			N		
4557 E CO RD 450 N	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
10490 E RT 16	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
501-510 EAST RUDY	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
601-610 EAST RUDY	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
701-710 EAST RUDY	N/A	N	Y	1990	1990	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
701 EDGAR HOUSE	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1112 EDGAR	N/A	N	Y	1913	1913	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1301 EDGAR	N/A	N	Y	2009	2009	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1405 EDGAR	N/A	N	Y	1991	1991	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
1501 EDGAR	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1713 EDGAR	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1312 FORT WORTH WAY	N/A	N	Y	2003	2003	CUSTOMER SURVEY/VISUAL	U	C	C/P	NL	u	N/R	N			N		
1220 FORTWORTH WAY	N/A	N	Y	2003	2003	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1301 FORTWORTH WAY	N/A	N	Y	2002	2002	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1606 FROSTWOOD	N/A	N	Y	1973	1973	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
1400 GRANT	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
900 HAYES	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1001 HEALTH CENTER - SBL	N/A	Y	Y	1989	1989	MAINTENANCE RECORDS	U	P	G	GRR	u	N/R	N			N		
1000 HEALTH CENTER - SBL	N/A	Y	Y	1968	1968	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
1004 HEALTH CENTER - SBL	N/A	Y	Y	2010	2010	MAINTENANCE RECORDS	U	P	C	NL	U	N/R	N			N		
1005 HEALTH CENTER - SBL	N/A	Y	Y	2010	2010	MAINTENANCE RECORDS	U	P	C	NL	U	N/R	N			N		
117 HOLIDAY RD - DENTIST	N/A	Y	Y	2008	2008	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
200 HOLIDAY RD	N/A	N	Y	2008	2008	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2500 HURST DR	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
2500 HURST DR	N/A	N	Y	2013	2013	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
2509 HURST DR	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	O	O	NL	u	N/R	N			N		
3501 JUSTRITE DR	N/A	N	Y	2006	2006	CUSTOMER SURVEY	U	O	P	NL	u	N/R	N			N		
201 LAFAYETTE EAST - NURSING HOME	N/A	Y	Y	2007	2007	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
201 LAFAYETTE EAST - NURSING HOME	N/A	Y	Y	2007	2007	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
1104 LAFAYETTE	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1200 LAFAYETTE	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
1216 LAFAYETTE	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1301 LAFAYETTE	N/A	N	Y	1910	1910	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1305 LAFAYETTE	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1308 LAFAYETTE 1/2	N/A	N	Y	1900	1900	CUSTOMER SURVEY/VISUAL	U	C	C/G	GRR	u	N/R	N			N		
1312 LAFAYETTE	N/A	N	Y	1915	1915	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
1316 LAFAYETTE	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
1320 LAFAYETTE	N/A	N	Y	1935	1935	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1421 LAFAYETTE	N/A	N	Y	1896	1896	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1500 LAFAYETTE	N/A	N	Y	1979	1979	CUSTOMER SURVEY/VISUAL	U	G	C/P	GRR	u	N/R	N			N		
1501 LAFAYETTE	N/A	N	Y	1895	1895	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
1509 LAFAYETTE	N/A	N	Y	1891	1891	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
1512 LAFAYETTE	N/A	N	Y	1937	1937	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1517 LAFAYETTE	N/A	N	Y	1904	1904	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1520 LAFAYETTE	N/A	N	Y	1916	1916	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
1601 LAFAYETTE	N/A	N	Y	1911	1911	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1608 LAFAYETTE	N/A	N	Y	1898	1898	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1616 LAFAYETTE	N/A	N	Y	1900	1900	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1620 LAFAYETTE	N/A	N	Y	1967	1967	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1621 LAFAYETTE	N/A	N	Y	1927	1927	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1721 LAFAYETTE	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2001 LAFAYETTE	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2113 LAFAYETTE	N/A	N	Y	1920	1920	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N		
2201 LAFAYETTE	N/A	N	Y	1975	1975	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
2205 LAFAYETTE	N/A	N	Y	1944	1944	VISUAL INSPECTION	U	G	P	GRR	u	N/R	N			N		
1409 LAFAYETTE & 14	N/A	N	Y	1886	1886	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
200 LAFAYETTE AVE E - CHURCH	N/A	Y	Y	2007	2007	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
201 LAFAYETTE AVE E	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N			N		
301 LAFAYETTE AVE E - ELDERLY	N/A	Y	Y	1982	1982	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
409 LAFAYETTE AVE E	N/A	N	Y	2010	2010	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
209 LAKE LAND	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
217 LAKE LAND	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
301 LAKE LAND	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
317 LAKE LAND	N/A	N	Y	2015	2015	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
320 LAKE LAND	N/A	N	Y	2014	2014	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
401 LAKE LAND	N/A	N	Y	1986	1986	CUSTOMER SURVEY/VISUAL	U	C	C/G	GRR	u	N/R	N			N		
401 1/2 LAKE LAND	N/A	N	Y	1986	1986	CUSTOMER SURVEY/VISUAL	U	C	C/G	GRR	u	N/R	N			N		
405 LAKE LAND	N/A	N	Y	1984	1984	CUSTOMER SURVEY/VISUAL	U	C	C/G	GRR	u	N/R	N			N		
408 LAKE LAND	N/A	N	Y	1892	1892	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
500 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
501 LAKE LAND D - VA CLINIC	N/A	Y	Y	2009	2009	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
501 LAKE LAND STE A	N/A	N	Y	2009	2009	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
511 LAKE LAND	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
512 LAKE LAND	N/A	N	Y	1999	1999	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
520 LAKE LAND	N/A	N	Y	1999	1999	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
604 LAKE LAND	N/A	N	Y	2007	2007	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
712 LAKE LAND	N/A	N	Y	1986	1986	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N		
801 LAKE LAND	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
808 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
809 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
900 LAKE LAND STE B	N/A	N	Y	2015	2015	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
921 LAKE LAND	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1020 LAKE LAND	N/A	N	Y	1986	1986	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
1100 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1116 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1117 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1304 LAKE LAND	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category		Total Service lines:		8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:					
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
1320 LAKE LAND	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1321 LAKE LAND	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1401 LAKE LAND	N/A	N	Y	1937	1937	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1421 LAKE LAND	N/A	N	Y	1956	1956	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1501 LAKE LAND	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1510 LAKE LAND	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1524 LAKE LAND	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1601 LAKE LAND	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1601 LAKE LAND BLVD	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1616 LAKE LAND	N/A	N	Y	1984	1984	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1617 LAKE LAND ADUL	SCH006A	Y	Y	2007	2007	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1617 LAKE LAND ADUL	SCH006A	Y	Y	2007	2007	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1717 LAKE LAND	N/A	N	Y	1970	1970	VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
1800 LAKE LAND	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1900 LAKE LAND	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1901 LAKE LAND	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1917 LAKE LAND	N/A	N	Y	2000	2000	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2000 LAKE LAND	N/A	N	Y	1963	1963	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2001 LAKE LAND	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2005 LAKE LAND	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2009 LAKE LAND	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2109 LAKE LAND	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2116 LAKE LAND	N/A	N	Y	1965	1965	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2117 LAKE LAND	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2201 LAKE LAND	N/A	N	Y	1989	1989	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2212 LAKE LAND	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2401 LAKE LAND	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2403 LAKE LAND	N/A	N	Y	1975	1975	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2404 LAKE LAND	N/A	N	Y	1977	1977	VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2405 LAKE LAND	N/A	N	Y	1996	1996	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2416 LAKE LAND	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2417 LAKE LAND	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2621 LAKE LAND	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2908 LAKE LAND	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
2916 LAKE LAND BLVD	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
3020 LAKE LAND	N/A	N	Y	2009	2009	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
3601 LAKE LAND	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
4200 LAKE LAND	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	O	NL	u	N/R	N			N		
4213 LAKE LAND	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1104-1106 LAKE LAND	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1700 LAKE LAND A	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1120 LAKE LAND BLVD	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1120 LAKE LAND BLVD	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1420 LAKE LAND BLVD	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1500 LAKE LAND BLVD	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)			Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Plastic - PVC, HDPE, PEX (P)							Leave blank if no Lead				
1500 LAKE LAND BLVD	N/A	N	Y	1988	1988	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1518 LAKE LAND BLVD	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1601 LAKE LAND BLVD	N/A	N	Y	1968	1968	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2404 LAKE LAND BLVD	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
4212 LAKE LAND BLVD	N/A	N	Y	1990	1990	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
5001 LAKE LAND BLVD - LLC	N/A	Y	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
4920 LAKE LAND COUR	N/A	N	Y	2002	2002	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1016 LAKE LAND THRU	N/A	N	Y			VISUAL INSPECTION	U	C	G	GRR	u	N/R	N			N		
2201 LAKER	N/A	N	Y	2008	2008	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
LAKER LAUNDRY	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
LERNA RD	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
200 LERNA RD S - CARLE	N/A	Y	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
300 LERNA RD SOUTH	N/A	N	Y	2006	2006	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
320 LERNA RD SOUTH	N/A	N	Y	2008	2008	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
220 LOGAN	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
220 LOGAN	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
LOGAN AND DEWITT 8	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1903 MAPLE	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1924 MAPLE	N/A	N	Y	1937	1937	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1937 MAPLE	N/A	N	Y	1960	1960	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1512 MARION	N/A	N	Y	1955	1955	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N		
1709 MARION	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1721 MARION	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1800 MARION	N/A	N	Y	1962	1962	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2720 MARION	N/A	N	Y	1946	1946	MAINTENANCE RECORDS/V	U	P	P	NL	u	N/R	N			N		
3409 MARION	N/A	N	Y	1951	1951	MAINTENANCE RECORDS/V	U	G	P	GRR	u	N/R	N			N		
3413 MARION AVE	N/A	N	Y	1960	1960	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
609 MARION-TRAILOR	N/A	N	Y	1955	1955	MAINTENANCE RECORDS/V	U	G	C	GRR	u	N/R	N			N		
1508 MARSHALL	N/A	N	Y	1902	1902	MAINTENANCE RECORDS/V	U	P	P	NL	u	N/R	N			N		
1820 MARSHALL	N/A	N	Y	1947	1947	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
1821 MARSHALL	N/A	N	Y	1969	1969	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1901 MARSHALL	N/A	N	Y	2006	2006	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2012 MARSHALL	N/A	N	Y	1951	1951	MAINTENANCE RECORDS/V	U	G	G	GRR	u	N/R	N			N		
2120 MARSHALL	N/A	N	Y	1941	1941	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2121 MARSHALL	N/A	N	Y	1931	1931	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2122 MARSHALL	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2205 MARSHALL	N/A	N	Y	1908	1908	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2401 MARSHALL	N/A	N	Y	1994	1994	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2520 MARSHALL	N/A	N	Y	1963	1963	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
2700 MARSHALL	N/A	N	Y	1940	1940	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2701 MARSHALL	N/A	N	Y	1914	1914	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N		
2713 MARSHALL	N/A	N	Y	1941	1941	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2800 MARSHALL	N/A	N	Y	1948	1948	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
2812 MARSHALL	N/A	N	Y	1984	1984	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
2816 MARSHALL	N/A	N	Y	1973	1973	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead														
2916 MARSHALL	N/A	N	Y	2006	2006	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N		Leave blank if no Lead	N		
2920 MARSHALL	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
3120 MARSHALL	N/A	N	Y	1917	1917	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
3232 MARSHALL	N/A	N	Y	1965	1965	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
3233 MARSHALL	N/A	N	Y	1962	1962	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
3300 MARSHALL	N/A	N	Y	2013	2013	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
3304 MARSHALL	N/A	N	Y	2014	2014	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
3316 MARSHALL	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
3320 MARSHALL	N/A	N	Y	1980	1980	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
3408 MARSHALL	N/A	N	Y	1980	1980	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
3412 MARSHALL	N/A	N	Y	1999	1999	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
3420 MARSHALL	N/A	N	Y	1980	1980	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
3601 1/2 MARSHALL - DAY CARE	DAYCARE004A	Y	Y	1998	1998	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
3801 MARSHALL	N/A	N	Y	1998	1998	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
3300 1/2 MARSHALL	N/A	N	Y	1999	1999	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
600 MARSHALL (E MTR	N/A	N	Y	1969	1969	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
600 MARSHALL (W MET	N/A	N	Y	1969	1969	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2800 MARSHALL-REAR	N/A	N	Y	1948	1948	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
205 MCFALL	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
100 MILLER ROAD	N/A	N	Y	2015	2015	CUSTOMER SURVEY	U	C	G	GRR	u	N/R	N			N		
313 MOULTRIE	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
600 MOULTRIE	N/A	N	Y	1994	1994	CUSTOMER SURVEY	U	C	C/G	GRR	u	N/R	N			N		
1020 MOULTRIE	N/A	N	Y	1897	1897	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
1205 MOULTRIE	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1208 MOULTRIE	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
1301 MOULTRIE	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1400 MOULTRIE	N/A	N	Y	1927	1927	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
1405 MOULTRIE	N/A	N	Y	1900	1900	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1412 MOULTRIE	N/A	N	Y	1987	1987	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1416 MOULTRIE	N/A	N	Y	1934	1934	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
1420 MOULTRIE	N/A	N	Y	1994	1994	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1517 MOULTRIE	N/A	N	Y	1914	1914	MAINTENANCE RECORDS	U	c	c	NL	u	N/R	N			N		
2820 MOULTRIE - DAY CARE	DAYCARE008A	Y	Y	1996	1996	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2820 MOULTRIE B - DAY CARE	N/A	Y	Y	1996	1996	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
3322 MOULTRIE - DAY CARE	DAYCARE003A	Y	Y	1984	1984	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
206 McFALL	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
213 N 10TH	N/A	N	Y	1900	1900	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
217 N 10TH	N/A	N	Y	1900	1900	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
1209 N 11TH	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
212 N 12TH	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1020 N 13TH	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1020 N 13TH	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
213 N 14TH	N/A	N	Y	1890	1890	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
120 N 15TH	N/A	N	Y	2007	2007	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
123 N 15TH	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)									
212 N 15TH	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
300 N 15TH	N/A	N	Y	1942	1942	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
309 N 15TH	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
401 N 15TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
512 N 15TH	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
513 N 15TH	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
520 N 15TH	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
1005 N 15TH	N/A	N	Y	1978	1978	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1015 N 15TH	N/A	N	Y	1951	1951	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1020 N 15TH	N/A	N	Y	1917	1917	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
108 N 16TH	N/A	N	Y	2009	2009	CUSTOMER SURVEY/VISUAL	U	P	C/P	NL	u	N/R	N			N		
110 N 16TH	N/A	N	Y	1937	1937	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
112 N 16TH	N/A	N	Y			CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
114 N 16TH	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
213 N 16TH	N/A	N	Y			Maintenance records	U	C	C	NL	u	N/R	N			N		
216 N 16TH	N/A	N	Y	1900	1900	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
220 N 16TH	N/A	N	Y	1900	1900	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
306 N 16TH	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
317 N 16TH	N/A	N	Y	1891	1891	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
213 N 18TH	N/A	N	Y	1902	1902	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
208 N 19TH	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
312 N 19TH	N/A	N	Y	1960	1960	CUSTOMER SURVEY	U	G	P	GRR	u	N/R	N			N		
320 N 19TH	N/A	N	Y	1958	1958	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
400 N 19TH	N/A	N	Y	1942	1942	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
416 N 19TH	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
421 N 19TH	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
501 N 19TH	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
520 N 19TH	N/A	N	Y	2005	2005	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
521 N 19TH	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
601 N 19TH	N/A	N	Y	1895	1895	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
709 N 19TH	N/A	N	Y	1947	1947	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1000 N 19TH	N/A	N	Y	1909	1909	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
116 N 1ST	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
212 N 20TH	N/A	N	Y	1925	1925	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
417 N 20TH	N/A	N	Y	1888	1888	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
421 N 20TH	N/A	N	Y	1891	1891	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
521 N 20TH	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
213 N 21ST	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
217 N 21ST	N/A	N	Y	1902	1902	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
221 N 21ST	N/A	N	Y	1892	1892	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
420 N 21ST	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
420 N 21ST	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
600 N 21ST	N/A	N	Y	1871	1871	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
608 N 21ST	N/A	N	Y	1907	1907	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
701 N 21ST	N/A	N	Y	1939	1939	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)		Plastic - PVC, HDPE, PEX (P)								
320 N 21ST CHURCH	N/A	Y	Y	2007	2007	CUSTOMER SURVEY/VISUAL	U	P	P	NL	u	N/R	N			N		
200 N 22ND	N/A	N	Y	1896	1896	MAINTENANCE RECORDS	N U	C	P	NL	u	N/R	N			N		
304 N 22ND	N/A	N	Y	1920	1920	MAINTENANCE RECORDS	N U	C	P	NL	u	N/R	N			N		
510 N 22ND	N/A	N	Y	1900	1900	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
811 N 22ND	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	N U	C	C	NL	u	N/R	N			N		
904 N 22ND	N/A	N	Y	1920	1920	MAINTENANCE RECORDS	N U	G	P	GRR	u	N/R	N			N		
917 N 22ND	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	N U	G	P	GRR	u	N/R	N			N		
719 N 23RD	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	N U	C	P	NL	u	N/R	N			N		
105 N 26TH	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	N U	C	C	NL	u	N/R	N			N		
800 N 27TH	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	N U	C	P	NL	u	N/R	N			N		
309 N 2ND	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
320 N 2ND	N/A	N	Y	1975	1975	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
405 N 30TH	N/A	N	Y	1911	1911	MAINTENANCE RECORDS	N U	C	P	NL	u	N/R	N			N		
213 N 33RD	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
900 N 33RD - DAY CARE	DAYCARE011A	Y	Y	1920	1920	MAINTENANCE RECORDS	N U	C	P	NL	u	N/R	N			N		
1016 N 33RD	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	N U	C	P	NL	u	N/R	N			N		
1013 1/2 N 33RD	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
716 N 4TH	N/A	N	Y			Visual Inspection	U	C	P	NL	u	N/R	N			N		
2020 N CO ROAD 150E	N/A	N	Y			Visual Inspection	U	G	G	GRR	u	N/R	N			N		
2020 N CO ROAD 150E	N/A	N	Y			Visual Inspection	U	G	G	GRR	u	N/R	N			N		
6700 N COUNTRY CLUB	N/A	N	Y			CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
6700 N COUNTRY CLUB	N/A	N	Y			Visual Inspection	U	C	C	NL	u	N/R	N			N		
6700 N COUNTRY CLUB	N/A	N	Y			Visual Inspection	U	C	C	NL	u	N/R	N			N		
7894 N COUNTY RD 10	N/A	N	Y			Visual Inspection	U	P	P	NL	u	N/R	N			N		
316 N DIVISION	N/A	N	Y	1966	1966	MAINTENANCE RECORDS	N U	C	C	NL	u	N/R	N			N		
113 N LOGAN	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	C U	C	C	NL	u	N/R	N			N		
217 N LOGAN	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	N U	C	G	GRR	u	N/R	N			N		
221 N LOGAN	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	N U	G	G	GRR	u	N/R	N			N		
308 N LOGAN A	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	N U	C	P	NL	u	N/R	N			N		
308 N LOGAN B	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	N U	C	P	NL	u	N/R	N			N		
315 N LOGAN	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
319 N LOGAN	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
327 N LOGAN	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	N U	C	P	NL	u	N/R	N			N		
601 N LOGAN	N/A	N	Y			Visual Inspection	U	C	C	NL	u	N/R	N			N		
609 N LOGAN	N/A	N	Y			Visual Inspection	U	P	P	NL	u	N/R	N			N		
800 N ROUTE 45	N/A	N	Y			Visual Inspection	U	C	C	NL	u	N/R	N			N		
1209 N RT 45	N/A	N	Y			Visual Inspection	U	C	C	NL	u	N/R	N			N		
10055 N RT 45	N/A	N	Y			Visual Inspection	U	O	C	NL	u	N/R	N			N		
1905 OAK	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	N U	C	C	NL	u	N/R	N			N		
1920 OAK	N/A	N	Y	1970	1970	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
1921 OAK	N/A	N	Y	1956	1956	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1100 OLD ST RD E	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1509 OLD STATE 1	N/A	N	Y	1998	1998	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
3 OLD STATE RD	N/A	N	Y	1993	1993	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
20 OLD STATE - CHURCH	N/A	Y	Y	2007	2007	MAINTENANCE RECORDS	U	C	C	NL		N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Galvanized (G)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Plastic - PVC, HDPE, PEX (P)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)													Leave blank if no Lead			
1020 OLD STATE RD	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1421 OLD STATE RD	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1500 OLD STATE RD	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1501 OLD STATE RD	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1513 OLD STATE RD	N/A	N	Y	2006	2006	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1601 OLD STATE RD	N/A	N	Y	1999	1999	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
5961 OLD STATE RD	N/A	N	Y	1985	1985	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
5961 OLD STATE RD	N/A	N	Y	1985	1985	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
7547 OLD STATE RD	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
OLD STATE RD EAST	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1309 OLD STATE RD E	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
5182 OLD STATE ROAD	N/A	N	Y	1984	1984	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1828 OLIVE	N/A	N	Y	1991	1991	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1000 PALM - NURSING HOME	N/A	Y	Y	1977	1977	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
4808 PARADISE RD	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	O	O	NL	u	N/R	N			N		
4814 PARADISE RD	N/A	N	Y	2018	2018	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
4922 PARADISE RD	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
111 PEACH CT	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
113 PEACH CT	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
77 PIATT	N/A	N	Y	1979	1979	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
117 PIATT	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
608 PIATT	N/A	N	Y	1923	1923	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
1301 PIATT	N/A	N	Y	2009	2009	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
221 PIATT AVE EAST	N/A	N	Y	1979	1979	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2505 PINE	N/A	N	Y	1975	1975	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2700 PINE	N/A	N	Y	1914	1914	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N		
3000 PINE	N/A	N	Y	1923	1923	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2505 PINE APT B	N/A	N	Y	1975	1975	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
PO BOX 437 (Shelby County Energy)	N/A	N	Y			VISUAL INSPECTION	U	O	O	NL	u	N/R	N			N		
PO BOX 946 (EAWD)	N/A	N	Y			VISUAL INSPECTION	U	O	O	NL	u	N/R	N			N		
3516 POWELL LANE	SCH009A	N	Y	1984	1984	MAINTENANCE RECORDS/V	U	G	G	GRR	u	N/R	N			N		
3522 POWELL LANE WE	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
83 PRAIRIE	N/A	N	Y	2004	2004	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
90 PRAIRIE	N/A	N	Y	1985	1985	MAINTENANCE RECORDS	U	O	O	NL	u	N/R	N			N		
109 PRAIRIE	N/A	N	Y	1964	1964	MAINTENANCE RECORDS	U	O	O	NL	u	N/R	N			N		
701 PRAIRIE	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1101 PRAIRIE - CHURCH	N/A	Y	Y	1941	1941	CUSTOMER SURVEY	U	C	P	NL	u	N/R	N			N		
1116 PRAIRIE	N/A	N	Y	1926	1926	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1117 PRAIRIE	N/A	N	Y	1946	1946	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1121 PRAIRIE	N/A	N	Y	1992	1992	MAINTENANCE RECORDS/V	U	C	P	NL	u	N/R	N			N		
1720 PRAIRIE	N/A	N	Y	1991	1991	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
1801 PRAIRIE	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1911 PRAIRIE	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
2000 PRAIRIE	N/A	N	Y	1999	1999	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
2020 PRAIRIE	N/A	N	Y	1974	1974	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
2100 PRAIRIE	N/A	N	Y	1931	1931	MAINTENANCE RECORDS/	U	C	P	NL	u	N/R	N			N		
2108 PRAIRIE	N/A	N	Y	1949	1949	MAINTENANCE RECORDS/	U	C	C	NL	u	N/R	N			N		
2200 PRAIRIE	N/A	N	Y	1904	1904	MAINTENANCE RECORDS/	U	G	P	GRR	u	N/R	N			N		
2201 PRAIRIE	N/A	N	Y	1925	1925	MAINTENANCE RECORDS/	U	G	C	GRR	u	N/R	N			N		
2204 PRAIRIE #1	N/A	N	Y	1909	1909	MAINTENANCE RECORDS/	U	C	C	NL	u	N/R	N			N		
2208 PRAIRIE	N/A	N	Y	1913	1913	MAINTENANCE RECORDS/	U	G	P	GRR	u	N/R	N			N		
2212 PRAIRIE	N/A	N	Y	1950	1950	MAINTENANCE RECORDS/	U	C	P	NL	u	N/R	N			N		
2400 PRAIRIE	N/A	N	Y	1972	1972	CUSTOMER SURVEY/VISUAL	U	C	G	GRR	u	N/R	N			N		
408 PROGRESS	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
420 PROGRESS	N/A	N	Y	1997	1997	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
917 REMINGTON STE C	N/A	N	Y			Visual Inspection	U	C	C	NL	u	N/R	N			N		
1017 REMINGTON	N/A	N	Y	2021	2021	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
901 REMINGTON RD	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
905 REMINGTON RD - DR	N/A	Y	Y	2017	2017	CUSTOMER SURVEY	U	P	P	NL	u	N/R	N			N		
911 REMINGTON RD	N/A	N	Y			VISUAL INSPECTION	U	P	P	NL	u	N/R	N			N		
60 RICHMOND - CHILDCARE	DAYCARE009A	Y	Y	2000	2000	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
301 RICHMOND -	N/A	Y	Y	1991	1991	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
410 RICHMOND	N/A	N	Y	2000	2000	MAINTENANCE RECORDS/	U	C	P	NL	u	N/R	N			N		
416 RICHMOND	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
418 RICHMOND	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
821 RICHMOND	N/A	N	Y	1979	1979	MAINTENANCE RECORDS/	U	C	C	NL	u	N/R	N			N		
1112 RICHMOND	N/A	N	Y	1938	1938	MAINTENANCE RECORDS/	U	C	P	NL	u	N/R	N			N		
1300 RICHMOND - CHURCH	N/A	Y	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
1412 RICHMOND	N/A	N	Y	2001	2001	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1504 RICHMOND	N/A	N	Y	1958	1958	MAINTENANCE RECORDS/	U	C	P	NL	u	N/R	N			N		
1716 RICHMOND	N/A	N	Y	1933	1933	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
1820 RICHMOND	N/A	N	Y	1911	1911	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1902 RICHMOND	N/A	N	Y	1995	1995	MAINTENANCE RECORDS/	U	C	C	NL	u	N/R	N			N		
1920 RICHMOND - CHURCH	N/A	Y	Y	1954	1954	MAINTENANCE RECORDS		P	P	NL		N/R	N			N		
1921 RICHMOND	N/A	N	Y	1975	1975	CUSTOMER SURVEY/VISUAL	U	C	C	NL	u	N/R	N			N		
2002 RICHMOND	N/A	N	Y			CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
2104 RICHMOND	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2220 RICHMOND	N/A	N	Y	1991	1991	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2300 RICHMOND	N/A	N	Y	1964	1964	MAINTENANCE RECORDS/	U	C	P	NL	u	N/R	N			N		
2301 RICHMOND	N/A	N	Y	1890	1890	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
2305 RICHMOND	N/A	N	Y	1916	1916	MAINTENANCE RECORDS/	U	C	P	NL	u	N/R	N			N		
2308 RICHMOND	N/A	N	Y	1925	1925	MAINTENANCE RECORDS/	U	P	P	NL	u	N/R	N			N		
2312 RICHMOND	N/A	N	Y	1906	1906	VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
2417 RICHMOND	N/A	N	Y	1914	1914	MAINTENANCE RECORDS/	U	C	P	NL	u	N/R	N			N		
2509 RICHMOND	N/A	N	Y	1953	1953	MAINTENANCE RECORDS/	U	C	C	NL	u	N/R	N			N		
2620 RICHMOND	N/A	N	Y	1935	1935	MAINTENANCE RECORDS/	U	C	C	NL	u	N/R	N			N		
200 RICHMOND AVE EA - SBL	N/A	Y	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
201 RICHMOND AVE EA	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
220 RICHMOND AVE EA	N/A	N	Y	1988	1988	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
224 RICHMOND AVE EA	N/A	N	Y	1986	1986	CUSTOMER SURVEY/VISUAL	U	C	P/C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)									
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)									
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead			
225 RICHMOND AVE EA - DENTIST	N/A	Y	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
232 RICHMOND AVE EA	N/A	N	Y	1984	1984	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
300 RICHMOND AVE EA	N/A	N	Y	1998	1998	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
301 RICHMOND AVE EA	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
301 RICHMOND AVE EA	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
301 RICHMOND AVE EA	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
301 RICHMOND AVE EA	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
305 RICHMOND GRIMES - PARK	N/A	Y	Y	1982	1982	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
307 RICHMOND-GRIMES - PARK	N/A	Y	Y	1982	1982	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
EAST ROUTE 16 (Airport)	N/A	N	Y			Visual Inspection	U	O	O	NL	u	N/R	N			N		
EAST ROUTE 16 (Aerinova Aerial)	N/A	N	Y			Visual Inspection	U	C	C	NL	u	N/R	N			N		
EAST ROUTE 16 (Airport)	N/A	N	Y			Visual Inspection	U	O	O	NL	u	N/R	N			N		
EAST ROUTE 16	N/A	N	Y			Visual Inspection	U	O	O	NL	u	N/R	N			N		
EAST ROUTE 16 SPRIN	N/A	N	Y			Visual Inspection	U	O	O	NL	u	N/R	N			N		
ROUTE 4 BOX 148 BOD	N/A	N	Y			Visual Inspection	U	O	O	NL	u	N/R	N			N		
NORTH ROUTE 45 BOD	N/A	N	Y			Visual Inspection	U	O	O	NL	u	N/R	N			N		
RT 4 BOX 148	N/A	N	Y			Visual Inspection	U	O	O	NL	u	N/R	N			N		
N RT 45	N/A	N	Y			Visual Inspection	U	O	O	NL	u	N/R	N			N		
1700 RUDY	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
1804 RUDY	N/A	N	Y	1960	1960	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1808 RUDY	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1816 RUDY	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1300 S 12TH	N/A	N	Y	1976	1976	MAINTENANCE RECORDS	U	O	O	NL	u	N/R	N			N		
800 S 14TH - PARK	N/A	Y	Y	2011	2011	MAINTENANCE RECORDS	U	G	G	GRR		N/R	N			N		
2320 S 14TH	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2408 S 14TH	N/A	N	Y	1990	1990	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2408 S 14TH	N/A	N	Y	1990	1990	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
2401 S 14TH ST	N/A	N	Y	1989	1989	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
412 S 15TH	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
620 S 16TH	N/A	N	Y	1911	1911	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1200 S 16TH	N/A	N	Y	1935	1935	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
116 S 17TH	N/A	N	Y	1951	1951	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
118 S 17TH	N/A	N	Y	1955	1955	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
120 S 17TH	N/A	N	Y	1912	1912	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
121 S 17TH - SCHOOL	DAYCARE010A	Y	Y	1994	1994	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
121 S 17TH - SCHOOL	SCH007A	Y	Y	1994	1994	MAINTENANCE RECORDS	U	G	C	GRR	U	N/R	N			N		
122 S 17TH	N/A	N	Y	1910	1910	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
212 S 17TH	N/A	N	Y	1934	1934	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
215 S 17TH	N/A	N	Y	1998	1998	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
221 S 17TH	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
300 S 17TH	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
413 S 17TH	N/A	N	Y	1992	1992	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
415 S 17TH	N/A	N	Y	1908	1908	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
416 S 17TH	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
606 S 17TH - CHURCH	N/A	Y	Y	2011	2011	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
612 S 17TH	N/A	N	Y	1913	1913	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
618 S 17TH	N/A	N	Y	1913	1913	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
708 S 17TH	N/A	N	Y	1911	1911	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
720 S 17TH	N/A	N	Y	1911	1911	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
912 S 17TH	N/A	N	Y	1970	1970	MAINTENANCE RECORDS	U	C	G	GRR	u	N/R	N			N		
1100 S 17TH - CHURCH	N/A	Y	Y	2011	2011	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1916 S 17TH	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
2116 S 17TH	N/A	N	Y	1986	1986	MAINTENANCE RECORDS	U	O	O	NL	u	N/R	N			N		
2200 S 17TH MAIN	N/A	N	Y	1987	1987	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
113 S 17TH THRU 117 - DAYCARE	N/A	Y	Y	1988	1988	MAINTENANCE RECORDS	U	G	C	GRR	u	N/R	N			N		
716 S 19TH	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
717 S 19TH	N/A	N	Y	1983	1983	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
813 S 19TH	N/A	N	Y	1953	1953	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
817 S 19TH	N/A	N	Y	1898	1898	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
921 S 19TH	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1009 S 19TH	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1013 S 19TH	N/A	N	Y	1980	1980	CUSTOMER SURVEY/VISUAL	U	C	P	NL	u	N/R	N			N		
1109 S 19TH	N/A	N	Y	1994	1994	CUSTOMER SURVEY/VISUAL	U	C	C/P	NL	u	N/R	N			N		
1220 S 19TH	N/A	N	Y	1928	1928	CUSTOMER SURVEY	U	G	C/P	GRR	u	N/R	N			N		
1501 S 19TH	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
2509 S 19TH	N/A	N	Y			Visual Inspection	U	C	C	NL	u	N/R	N			N		
2601 S 19TH ST	N/A	N	Y			Visual Inspection	U	C	P	NL	u	N/R	N			N		
113 S 21ST	N/A	N	Y	1973	1973	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
209 S 21ST	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
213 S 21ST	N/A	N	Y	1983	1983	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
301 S 21ST	N/A	N	Y	1957	1957	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
312 S 21ST	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
313 S 21ST	N/A	N	Y	1908	1908	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
317 S 21ST	N/A	N	Y	1907	1907	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
321 S 21ST	N/A	N	Y	1895	1895	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
421 S 21ST	N/A	N	Y	1940	1940	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
428 S 21ST	N/A	N	Y	1948	1948	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
513 S 21ST	N/A	N	Y	2007	2007	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
309 S 21ST UNIT 4	N/A	N	Y	1984	1984	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
309 S 21ST UNIT 7 &	N/A	N	Y	1984	1984	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
204 S 21ST-SENIOR C	N/A	N	Y	1925	1925	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
502 S 24TH	N/A	N	Y	1972	1972	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
501 S 26TH	N/A	N	Y	1950	1950	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
620 S 26TH	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
320 S 31ST	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
5 32ND	N/A	N	Y			MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
301 S 32ND	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
717 S 34TH	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
613 S 36TH	N/A	N	Y	1987	1987	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
404 S 6TH	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
408 S 6TH	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:							
Total Service Lines - Residential - 7021/Commercial - 991																		
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)								
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)		Plastic - PVC, HDPE, PEX (P)								
602 S 6TH MAIN	N/A	N	Y	1975	1975	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
606 S 6TH MAIN	N/A	N	Y	1975	1975	MAINTENANCE RECORDS/V	U	C	C	NL	u	N/R	N			N		
624 S 6TH	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1201 S 6TH - FRANKL - SCHOOL	SCH004A	Y	Y	2011	2011	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
105 S 8TH	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
120 S 8TH	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
120 S 9TH	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N			N		
708 S 9TH	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
725 S 9TH GARAG	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
725 S 9TH OFFIC	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
725 S 9TH SERCN	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
725 S 9TH STORE	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1205 S 9TH - Church	N/A	Y	Y	2011	2011	MAINTENANCE RECORDS/V	U	G	G	GRR	u	N/R	N			N		
1313 S 9TH B - Church	N/A	Y	Y	1964	1964	MAINTENANCE RECORDS	U	G	P	GRR	u	N/R	N			N		
1804 S 9TH - Church	N/A	Y	Y	2011	2011	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
2008 S 9TH	N/A	N	Y	1999	1999	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2121 S 9TH	N/A	N	Y	1985	1985	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2121 S 9TH - NURSING HOME	N/A	Y	Y	1985	1985	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
2129 S 9TH - CHURCH	N/A	Y	Y	2011	2011	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N			N		
1817 S 9TH A 3009	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1817 S 9TH B 3009	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1817 S 9TH C 3009	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1817 S 9TH D 3009	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1817 S 9TH E 3009	N/A	N	Y	1982	1982	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
725 S 9TH STORE ROO	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
1200 S 9TH-MIDDLE S	SCH001A	Y	Y	1999	1999	MAINTENANCE RECORDS/V	U	G	G	GRR	u	N/R	N			N		
1709 S 9TH-WILLIAMS	SCH002A	Y	Y	2003	2003	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N			N		
212 S LOGAN	N/A	N	Y	2002	2002	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
100 SHELBY	N/A	N	Y	1995	1995	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
108 SHELBY	N/A	N	Y	1979	1979	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
421 SHELBY	N/A	N	Y	2002	2002	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		
504 SHELBY	N/A	N	Y			Visual Inspection	U	P	C	NL	u	N/R	N			N		
713 SHELBY	N/A	N	Y			Visual Inspection	U	G	C	GRR	u	N/R	N			N		
720 SHELBY GARAG	N/A	N	Y	1960	1960	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N			N		
801 SHELBY	N/A	N	Y			Visual Inspection	U	G	C	GRR	u	N/R	N			N		
1109 SHELBY	N/A	N	Y	1900	1900	MAINTENANCE RECORDS/V	U	G	G	GRR	u	N/R	N			N		
1501 SHELBY	N/A	N	Y	1913	1913	MAINTENANCE RECORDS/V	U	G	C	GRR	u	N/R	N			N		
1512 SHELBY	N/A	N	Y	1962	1962	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N			N		
1520 SHELBY	N/A	N	Y			Visual Inspection	U	C	P	NL	u	N/R	N			N		
1801 SHELBY	N/A	N	Y	1923	1923	MAINTENANCE RECORDS/V	U	G	P	GRR	u	N/R	N			N		
2520 SHELBY	N/A	N	Y	1965	1965	CUSTOMER SURVEY	U	P	C	NL	u	N/R	N			N		
2913 SHELBY	N/A	N	Y	1906	1906	MAINTENANCE RECORDS/V	U	C	G	GRR	u	N/R	N			N		
2921 SHELBY	N/A	N	Y	1969	1969	MAINTENANCE RECORDS/V	U	P	P	NL	u	N/R	N			N		
412 SHELBY APT B	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N			N		
500 SHELBY AVE	N/A	N	Y	2000	2000	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N			N		

*Please enter totals in the empty box next to each category	Total Service lines:	8012	Total Lead:	0	Total Non-Lead:	8012	Total Galvanized Requiring replacement:	1378	Total Unknown:	0	Website link to Material Inventory:								
Total Service Lines - Residential - 7021/Commercial - 991																			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material		Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property		
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.		
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)										
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)										
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)										
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)										
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)											
Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)																	
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																	
10500 STATE HWY 16	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		
121 SWORDS	N/A	N	Y	2008	2008	MAINTENANCE RECORDS	N U	C	C	NL	u	N/R	N				N		
105 SWORDS DR	N/A	N	Y	2019	2019	MAINTENANCE RECORDS	N U	C	C	NL	u	N/R	N				N		
105 SWORDS DR SPRI	N/A	N	Y	2019	2019	MAINTENANCE RECORDS	N U	C	P	NL	u	N/R	N				N		
2501 THOMASON DR	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N				N		
2808 THOMASON DR	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N				N		
2808 THOMASON DR	N/A	N	Y			VISUAL INSPECTION	U	C	C	NL	u	N/R	N				N		
5400 US HIGHWAY 45	N/A	N	Y			Visual Inspection	U	C	P	NL	u	N/R	N				N		
3480 US HWY 45 S - CHURCH	N/A	Y	Y			Visual Inspection	U	P	C	NL	u	N/R	N				N		
3840 US HWY 45	N/A	N	Y			Visual Inspection	U	P	C	NL	u	N/R	N				N		
4607 US HWY 45	N/A	N	Y			VISUAL INSPECTION	U	C	P	NL	u	N/R	N				N		
520 WABASH	N/A	N	Y	1949	1949	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N				N		
701 WABASH	N/A	N	Y	1941	1941	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N				N		
1020 WABASH	N/A	N	Y	1903	1903	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N				N		
1204 WABASH	N/A	N	Y	1890	1890	MAINTENANCE RECORDS	N U	P	C	NL	u	N/R	N				N		
1205 WABASH	N/A	N	Y	2017	2017	MAINTENANCE RECORDS	U	P	P	NL	u	N/R	N				N		
1305 WABASH	N/A	N	Y	1930	1930	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N				N		
1308 WABASH	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		
1311 WABASH	N/A	N	Y	1968	1968	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N				N		
1312 WABASH	N/A	N	Y	1881	1881	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		
1320 WABASH	N/A	N	Y	1896	1896	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N				N		
1400 WABASH	N/A	N	Y	1965	1995	CUSTOMER SURVEY	U	C	C	NL	u	N/R	N				N		
1401 WABASH	N/A	N	Y	1980	1980	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N				N		
1409 WABASH	N/A	N	Y	1977	1977	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		
1413 WABASH	N/A	N	Y	1994	1994	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N				N		
1420 WABASH	N/A	N	Y	1937	1937	MAINTENANCE RECORDS	C U	G	C/P	GRR	u	N/R	N				N		
1421 WABASH	N/A	N	Y	1955	1955	CUSTOMER SURVEY	U	C	C/G	GRR	u	N/R	N				N		
1500 WABASH	N/A	N	Y	1954	1954	MAINTENANCE RECORDS	C U	C	C/P	NL	u	N/R	N				N		
1521 WABASH - DENTIST	N/A	Y	Y	1963	1963	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N				N		
1600 WABASH	N/A	N	Y	2011	2011	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		
1617 WABASH APT 1	N/A	N	Y	2014	2014	MAINTENANCE RECORDS	U	P	C	NL	u	N/R	N				N		
1701 WABASH	N/A	N	Y	1952	1952	MAINTENANCE RECORDS	U	C	P	NL	u	N/R	N				N		
1710 WABASH	N/A	N	Y	1969	1969	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		
1901 WABASH	N/A	N	Y	1971	1971	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		
2521 WALNUT-HIGH SC	N/A	Y	Y	2000	2000	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N				N		
2521 WALNUT-SPORT C	N/A	Y	Y	2000	2000	MAINTENANCE RECORDS	U	G	G	GRR	u	N/R	N				N		
WATER DEPARTMENT	N/A	N	Y	1960S	1960S	MAINTENANCE RECORDS	U	O	O	NL	u	N/R	N				N		
101 WEST PARK PLAZA	N/A	N	Y	1960S	1960S	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		
201-208 WEST PARK P	N/A	N	Y	1960S	1960S	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		
301-308 WEST PARK P	N/A	N	Y	1960S	1960S	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		
401-408 WEST PARK P	N/A	N	Y	1960S	1960S	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		
501-508 WEST PARK P	N/A	N	Y	1960S	1960S	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		
601-608 WEST PARK P	N/A	N	Y	1960S	1960S	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		
701-708 WEST PARK P	N/A	N	Y	1960S	1960S	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		
801-902 WEST PARK P	N/A	N	Y	1960S	1960S	MAINTENANCE RECORDS	U	C	C	NL	u	N/R	N				N		

